

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 682-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 37450

Deliver To: *** PROFORMA INVOICE ***

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

Invoice Number:	
Invoice Date	06/01/2026
Location:	07
Work Order Number:	524157
Payment Type:	Account
Page:	1 of 10

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 7610	2920	RW7610H001514	001514	

Service Reminders:
JGLMFWD JD ALL Retail

COMPLAINT:

01 MFWD TRACTOR VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

VALUEMAX GREEN LIGHT SERVICE SPECIAL CHECKLIST

HOURS: _____
 TRACTOR DYNOED AT: _____

 DOES THIS UNIT GET AN VALUEMAX STICKER YES NO
 HAS STICKER BEEN INSTALLED YES NO
 CAB HAS BEEN COMPLETELY CLEANED _____AL_____(INITIAL)
 THIS UNIT HAS HAD A FINAL CHECKOVER _____AL_____(INITIAL)
 THIS UNIT HAS HAD A COMPLETE GREASE JOB _____AL_____(INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMER'S INSTRUCTIONS:

- OIL LEAK- SUMP GASKET, VALVE COVER BREATHER HOSE.
- FAN SHROUD- TAB FOR COOLANT TANK BROKEN- BOLT MISSING ON COOLANT TANK.
- REPLACE CAB AIR FILTERS.
- REPLACE MFWD OUTER AXLE HOUSING SEAL AND U-JOINTS.
- REPLACE TRANSMISSION AND HYDRAULIC OIL AND FILTERS.
- OIL LEAK ON SIDE OF TRANSMISSION, DIAGNOSE AND REPAIR. *- DONE*
- CLASS 1 LEAK ON LH AND RH REAR AXLE HOUSING.
- HYDRAULIC PUMP FLOW TEST FROM SCV BELOW SPEC.
- 3 POINT HITCH NOT WORKING.
- REPLACE MISSING SMV SIGN. *NEW SMV sign is in Cab of Tractor.*
- REPLACE SAFETY DECALS.

John Deere 7610

*changed look at Parts invoices
 changed oil supplied by customer
 page 9*

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY26859	INSPECTION+ 3 FLUID TEST KIT	1.00	85.83	\$85.83	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
DISC	Parts Discount	-1.00	85.83	-\$85.83	Y
DISI	LAB DISC INTERN	-1.00	648.00	-\$648.00	Y
Labor: \$2,415.00	Parts: \$85.83	OL&M: \$0.00	Misc: -\$733.83	Sub-Total: \$1,767.00	

JFCC JD ALL Retail

COMPLAINT:

02 FREE CLEANUP OF CAB

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindarsley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeseville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unlty, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 37450

Deliver To: *** PROFORMA INVOICE ***

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

Invoice Number:
 Invoice Date: 06/01/2026
 Location: 07
 Work Order Number: 524157
 Payment Type: Account
 Page: 2 of 10

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 7610	2920	RW7610H001514	001514	

Service Reminders:

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
LABDIS	LAB DISC CUST	-1.00	172.50	-\$172.50	Y
Labor: \$301.88	Parts: \$0.00	OL&M: \$0.00	Misc: -\$172.50	Sub-Total: \$129.38	

JGEN01- Retail

COMPLAINT:

03 (DO NOT DO REPAIR) STORED CODES- CCU 035 TRANS FILTER RESTRICTED CODE ACTIVE ON START UP

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
----------------------	----------------------	-------------------------	---------------------	--------------------------

JGEN02- Retail

COMPLAINT:

05 VALVE LASH ADJUSTMENT- NO HISTORY IF IT WAS DONE

CORRECTION:

- REMOVE ENGINE HOOD AND SIDE ENGINE COVERS TO GAIN ACCESS.
- REMOVE AIR FILTER HOUSING, AIR DUCT AND BRACKETS TO GAIN ACCESS.
- SET ADJUST VALVE CLEARANCE AND TORQUE ALL BOLTS TO SPEC.
- INSTALL BACK AND RUN UP TO ENSURE ALL WORKS PROPERLY.
- DONE.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
DZ118286	OIL FILTER	1.00	39.07	\$39.07	Y
R123575	O-RING	6.00	1.75	\$10.50	Y
R524481	GASKET	1.00	33.42	\$33.42	Y
TY26679	PLUS-50 II 15W-40 CK4/SN 18.9L PAIL	1.00	170.86	\$170.86	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF300	ENVIRO FEE	1.00	3.00	\$3.00	Y

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preaceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 37450

Deliver To: *** PROFORMA INVOICE ***

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

Invoice Number:
 Invoice Date: 06/01/2026
 Location: 07
 Work Order Number: 524157
 Payment Type: Account
 Page: 3 of 10

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 7610	2920	RW7610H001514	001514	

Service Reminders:	EF50	ENVIRO FEE	1.00	0.55	\$0.55	Y
Labor: \$1,260.00	Parts: \$253.85	OL&M: \$0.00	Misc: \$3.55	Sub-Total:	\$1,517.40	

J01020211 JD 7610 Retail

COMPLAINT:

07 REPLACE FAN BELT TENSIONER IDLER PULLEY.

7610

CORRECTION:

- REMOVE THE DRIVE BELT TO VERIFY THE CONCERN.
- REMOVE OLD WORN OUT ENGINE BELT TENSIONER.
- REPLACE TENSIONER ASSEMBLY FOR ENGINE SERPENTINE DRIVE BELT.
- RE-USE INSTALL DRIVE BELT.
- DONE.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE52490	Track Idler	1.00	283.98	\$283.98	Y
Labor: \$105.00	Parts: \$283.98	OL&M: \$0.00	Misc: \$0.00	Sub-Total:	\$388.98

JELECDIAG1 JD ALL Retail

COMPLAINT:

10 LIGHTS/TURN SIGNALS- LEFT TOP CAB LIGHT NOT WORKING

CORRECTION:

- REMOVE MOUNTING BRACKET TO GAIN ACCESS.
- REPLACE FRONT INNER TOP LH CAB LIGHT.
- ENSURE LIGHTS ARE WORKING GOOD.
- DONE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R161288	LAMP	1.00	72.45	\$72.45	Y
Labor: \$105.00	Parts: \$72.45	OL&M: \$0.00	Misc: \$0.00	Sub-Total:	\$177.45

JELECDIAG2 JD ALL Retail

COMPLAINT:

11 RADIO NOT WORKING

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 376-2302	Preeseville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Keivington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 37450

Deliver To: *** PROFORMA INVOICE ***

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

Invoice Number:
 Invoice Date: 06/01/2026
 Location: 07
 Work Order Number: 524157
 Payment Type: Account
 Page: 5 of 10

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 7610	2920	RW7610H001514	001514	

Service Reminders:

COMPLAINT:

14 STEERING CYLINDERS, AND HOSES- RIGHT CYLINDER LEAKING, REPAIR. PINS AND BUSHINGS WORN BOTH SIDES

CORRECTION:

- REMOVE RH STEERING HYDRAULIC CYLINDER ASSEMBLY.
- DISASSEMBLE FOR FURTHER INSPECTION. NEED TO REPLACE ASSEMBLY.
- REPLACE RH STEERING HYDRAULIC CYLINDER WITH NEW O-RINGS.
- REPLACE WITH NEW PIN AND BUSHING. NEW SPACER AND NEW LOCK PINS.

7610

Friday, May 8, 2026 2:10 PM

- INSTALL CYLINDER BUSHING.
- INSTALL CYLINDER.
- REMOVE HYDRAULIC LINE TO POSITION CYLINDER.
- INSTALL PIN AND SNAP RING.
- USE CRANE TO PUT TIRE ON.
- INSTALL FENDER GUARD.
- LOWER TRACTOR TO CHECK DIFF OIL. ALL GOOD.
- RAISE AND ROTATE TIRES TO CHECK OIL LEVEL
- FILL OIL ON RH PLANETARY. LH WAS FULL TO PLUG.
- TORQUE TIRE TO SPEC.
- DONE.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
34H305	7/32x2 Spring Pin	2.00	2.01	\$4.02	Y
34H421	3/8x2 Spring Pin	2.00	3.27	\$6.54	Y
40M7259	M25 External Snap Ring	2.00	6.79	\$13.58	Y
R153160	PIN	2.00	51.37	\$102.74	Y
R26448	-6ORB o-ring	1.00	2.56	\$2.56	Y
R375R	O-RING	1.00	1.99	\$1.99	Y
R95118	BUSHING	2.00	13.56	\$27.12	Y
R95119	SEAL_2/pkg	4.00	36.39	\$145.56	Y
R95250	BUSHING	1.00	13.43	\$13.43	Y
RE158651	CYLINDER	1.00	1,334.42	\$1,334.42	Y
RE61543	STEERING CYL. KIT	1.00	133.71	\$133.71	Y
T166274	O-Ring	1.00	2.13	\$2.13	Y
T77857	-8FF O-ring	1.00	2.47	\$2.47	Y

Labor: \$997.50 Parts: \$1,790.27 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$2,787.77

JGEN09- Retail

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 763-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Prosser, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 37450

Deliver To: *** PROFORMA INVOICE ***

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

Invoice Number:
 Invoice Date: 06/01/2026
 Location: 07
 Work Order Number: 524157
 Payment Type: Account
 Page: 7 of 10

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 7610	2920	RW7610H001514	001514	

Service Reminders:
 - DONE.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE43464	TOGGLE/ROC	1.00	85.44	\$85.44	Y
Labor: \$52.50	Parts: \$85.44	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$137.94	

JGEN16- Retail

COMPLAINT:

26 FRONT DIFFERENTIAL OIL LEVEL- OIL MILKY, NEED TO REPALCE. SEAL LEAKING

7610

CORRECTION:

- REMOVE WHEEL AND FENDER TO GAIN ACCESS.
- REMOVE FINAL DRIVE ASSEMBLY AND KNUCKLE ARM ASSEMBLY.
- KING PIN STUCK. HAVE TO USE ACETYLENE TO HEAT TO REMOVE KINGPIN ON THE KNUCKLE ARM.
- PULL OUT DRIVE AXLE. NOTE: WORN OUT AXLE OUT SHAFT GROOVE ON THE SHAFT AND CRACKED GUIDE LOCK RING.
- REMOVE WORN OUT LEAKING OIL SEALS.
- REPLACE 2 OIL SEAL FOR THE RH FINAL DRIVE INPUT SHAFT SEAL.
- REPLACE 1 OIL SEAL FOR THE RH AXLE OUTPUT SHAFT.
- DONE.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD J20C 18.9L PAIL	1.00	148.09	\$148.09	Y
H36256	O-RING	2.00	2.87	\$5.74	Y
JD7759	Zerk-2NPT Str8	2.00	1.65	\$3.30	Y
R115881	ADAPTER FI	1.00	32.08	\$32.08	Y
R97605	SET SCREW	2.00	9.35	\$18.70	Y
RE238667	MFWD Kingpin Seal	1.00	27.84	\$27.84	Y
RE40600	SEAL	1.00	57.28	\$57.28	Y
RE48345	KIT	1.00	72.50	\$72.50	Y
RE60269	SEAL	1.00	105.79	\$105.79	Y
RE60270	SEAL	1.00	72.20	\$72.20	Y
RE63382	KINGPIN	1.00	407.95	\$407.95	Y
TY26815	80W90 3.78L GL-5	4.00	50.16	\$200.64	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF300	ENVIRO FEE	1.00	3.00	\$3.00	Y
EF60	ENVIRO FEE	4.00	0.60	\$2.40	Y
Labor: \$150.00	Parts: \$1,152.11	OL&M: \$0.00	Misc: \$5.40	Sub-Total: \$1,307.51	

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9469
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 37450

Deliver To: *** PROFORMA INVOICE ***

[Redacted]
 [Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

[Redacted]
 [Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

Invoice Number:	
Invoice Date	06/01/2026
Location	07
Work Order Number:	524157
Payment Type:	Account
Page:	8 of 10

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 7610	2920	RW7610H001514	001514	

Service Reminders:
JGEN17- Retail

COMPLAINT:

28 DRAIN PLUG LEAKING (HAVE X2 WASHERS INSTALLED ON IT)

CORRECTION:

- CHECK ALL DRAIN PLUGS.
- CONFIRM WITH FOREMAN CORRECT DRAIN PLUG.
- REMOVE STRIPPED ENGINE DRAIN PLUG.
- GET NEW DRAIN PLUG FROM PARTS.
- QUICKLY EXCHANGE PLUGS.
- TIGHTEN DRAIN PLUG TO SPEC.
- CLEAN AREA.
- DONE.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE46685	Fitting Plug	1.00	14.31	\$14.31	Y

Labor: \$210.00 Parts: \$14.31 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$224.31

JELECDIAG5 JD ALL Retail

COMPLAINT:

29 DIAGNOSE FILTER RESTRICTION
 PERFORM ELECTRICAL SYSTEM DIAGNOSTICS

CORRECTION:

- NOTED NEW SENSOR WAS INSTALLED WITH NEW FILTERS.
- FOLLOW STEPS ON SERVICE ADVISOR FOR FAULT CODE CCU 35.
- TEST SENSOR. OK.
- TEST WIRING IN DIAGNOSTIC MODE WITH CCU ADDRESS 12. TEST OK.
- TAKE PRESSURE WITH MANUAL GAUGE. IN SPEC 241 PSI.
- FOUND WHEN STARTED IT TAKES A FEW SECONDS FOR CODE TO BECOME ACTIVE.
- WHEN RPM GOES OVER 1600 THE WARNING GOES AWAY.
- REMOVED FILTER ,OIL VERY MILKY AND NEED TO BE REPLACE.

Labor: \$315.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$315.00

JELECDIAG3 JD ALL Retail

COMPLAINT:

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preecerville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 37450

Deliver To: *** PROFORMA INVOICE ***

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:
Invoice Date: 06/01/2026
Location: 07
Work Order Number: 524157
Payment Type: Account
Page: 9 of 10

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 7610	2920	RW7610H001514	001514	

Service Reminders:

30 PERFORM ELECTRICAL SYSTEM DIAGNOSTICS (CCU 035 TRANS FILTER RESTRICTED CODE ACTIVE ON START UP)

CORRECTION:

RECALL, RECORD AND CLEAR TROUBLE CODES:

CCU 026: TRANSMISSION PRESSURE LOW
 CCU 035: TRANSMISSION OIL FILTER RESTRICTION

CLEAR ERROR CODES
 REMOVE TRANSMISSION FILTER AND FOUND OIL TO BE DIRTY AND NEEDS TO BE REPLACED TO CONTINUE WITH THE FAULT FINDING

CUSTOMER SUPPLIED NEW OIL TO REPLACE TRANSMISSION OIL

GET MACHINE STARTED AND MOVED INTO THE WORKSHOP

DRAIN TRANSMISSION OIL. WAIT TILL ALL THE OIL DRIPS OUT. REFILL OIL AND REPLACE FILTER
 TEST DRIVE TRACTOR FOR 2 HOURS. ERROR CODE DID NOT BECOME ACTIVE AGAIN
 GET SHOP HELP TO TEST DRIVE TRACTOR FOR ANOTHER 3 HOURS AND ERROR DID NOT BECOME ACTIVE AGAIN

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE205726	HYDRAULIC FILTER	2.00	150.29	\$300.58	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.25	\$2.50	Y
Labor: \$1,050.00	Parts: \$300.58	OL&M: \$0.00	Misc: \$2.50	Sub-Total: \$1,353.08	

JDISC JD ALL Retail

COMPLAINT:

31 GREEN LIGHT INSPECTION DISCOUNTS

CORRECTION:

10% PARTS DISCOUNT

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
DISC	Parts Discount	-1.00	417.93	-\$417.93	Y

Miscellaneous Charges:

SERVICE ACCESSORIES

\$150.00

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2636
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No: 37450

Deliver To: *** PROFORMA INVOICE ***

SERVICE INVOICE

[Redacted]
 [Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone:
 Prv Phone:

Invoice Number:
 Invoice Date: 06/01/2026
 Location: 07
 Work Order Number: 524157
 Payment Type: Account
 Page: 10 of 10

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 7610	2920	RW7610H001514	001514	

Service Reminders:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: -\$267.93	Sub-Total: -\$267.93
---------------	---------------	--------------	-----------------	----------------------

Customer PO No:
 Tax Exempt No:
 Advisor: Keisha Taylor

Labor:	\$8,194.38
Parts:	\$4,179.33
OL&M:	\$0.00
Misc:	-\$1,162.81
GST:	\$560.55
PST:	\$0.00
Grand Total:	\$11,771.45

7610

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:

Date: