

T 800 2014

TR Repair Inc
Box 44 Site 206 RR#2
Saskatoon, SK S7K3J5 (tr.repair.sk@gmail.com)
Phone: (306) 370-3454

1 of 1

1

Work Order#: 00000366	Technician: Tyson	Date: 2025-07-21	Completed: - -
Company: Yas-Farms LTD Name: Leonard Yasieniuk Address: RR1 Richard SK S0M2P0 Phone: H W		2014 KENWORTH T8 Series Odometer: 881762 License: VIN: 1XKDDP0XXEJ965515 Tag#: PO#:	

Hrs.	Labor Description	Total
1.50	C&R CEL Check codes, code P228D fuel correction percentage too high. Unplug rear pump and run unit, 13% correction. Unplug front pump, 100% correction. R&R rear unit pump. Road test unit, 38lbs boost, all ok.	205.50
1.20	C&R TRANS TEMP GAUGE ERRATIC Trans temp gauge pins out when cab fan is turned on. Cab lights also flicker when cab fan is turned on. Install temp cab ground, cab fan speeds up. Check cab ground, terminal loose. Tighten cab ground, gauge no longer reacts to cab fan. Run unit, find gauge reading low. R&R trans temp sensor. Replace loose pins and plug.	164.40

Qty.	Part #	Part Description		Total
1.00	2344775PRX	N UNIT PUMP	1,221.89	1,221.89
1.00	2405076PE	N FUEL PIPE	307.02	307.02
2.00	1313122PE	N BOLT	1.28	2.56
1.00	Q21-1002	N TRANS TEMP SENSOR	125.01	125.01
1.00	CN10850	N PLUG	5.04	5.04
2.00	CN26150	N TERMINAL	2.45	4.90

BALANCE is due 30 days from the date of invoice.
TR Repair Inc PST #7768799 GST# 73190 0940

Parts Total: 1,666.42
Labor Total: 369.90
Special Repairs Total: 0.00
Sub-Total: 2,036.32
GST: 102.82
PST: 123.38
Supply Charges: 20.00
Shipping: 0.00

Sub Total: 2,282.52 Discount: 0.00
CC Fee: 0.00 Total: 2,282.52
Paid: 0.00

On Acct: 0.00 Balance: 2,282.52

Authorized by Signature:

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for the loss or damage to vehicle artifacts left in the vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on the streets, highways or elsewhere for the purpose of inspection. An express mechanics loan is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

TR Repair INC is not responsible for any damages or subsequent repairs of any systems that have been modified or altered in any way from OEM standards. Any warranties on parts sold are those made by the manufacturer.