



Hours Of Operation: Parts & Service

Mon - Fri: 8:00AM—5:00PM

Saturday: 9:00AM—3:00PM

Closed Saturdays of Long Weekends

10835—100 ST. WESTLOCK, ALBERTA T7P 2S2 | PHN: (780) 349-3361 | FAX: (780) 349-3329  
 EDMONTON DIRECT: 1-866-755-3673 | WEBSITE: WWW.WESTLOCKFORD.COM

SO # 110185

**SERVICE ORDER  
 CUSTOMER COPY**



Printed 04/23/2026 2:48:55 PM

User KEITHK Page 1

**Customer No**  
 HAZEL BLUFF DAIRY LTD.  
 RR1  
 WESTLOCK, AB T7P 2N9

Home (780) 349-6878 Bus (780) 349-1444  
 Cell Today (780) 349-6878  
 Email

Term CHEQUES

**Advisor** NELL KOHI SMITH  
**Shop** S1  
**Priority**

**Promised** 03/31/2022 5:00 PM  
**Opened** 03/31/2022 8:33 AM  
**Cashiered** 04/07/2022 3:53 PM

**Tag#**  
**Location**  
**PO #**

License	Odom In	Odom Out	In Service Date	Stock No
	167470	167472		
Year	Make	Model	Model Number	Colour
2015	FORD	SUPER DUTY F-550 DRW	X5H	BL/WHITE
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FD0X5HT4FEB27350				
Engine	6.7L 4V POWER STROKE DIESEL V8 Fleet #			

Request	Description	Job	CSR	Status				
382322	replace engine	1	555	Original				
Labour	Description	Type	Hours	Amount				
382322	replace engine	CPGAS	23.31	2,296.31				
Part	Description	Shp	Bin	Type	Retail	Price	Amount	
HC3Z 6030 C	BRACKET	1	SOP	CRO1	272.49	247.99	247.99	
HC4Z 6026 A	PLUG - ENGINE	2	21E4C	CRO1	37.49	34.49	68.98	
W503275 S437	BOLT - HEX. HEAD - F	2	23A007	CRO1	1.49	0.99	1.98	
FC3Z 6079 D	KIT - GASKET	1		CRO1	1,005.49	1,005.33	1,005.33	
JC3Z 6006 B	SERVICE ENGINE ASY	1		CRO1	13,177.64	12,004.00	12,004.00	
CORE CHARGE	CORE CHARGE JC3Z 6006 B	1		CRO1	4,500.00	4,500.00	4,500.00	
C-JC3Z 6006 B	CORE RETURN	-1		CRO1	4,500.00	4,500.00	(4,500.00)	
BC3Z 7A248 A	SEAL ASY - OIL	1	25D006	CRO1	33.49	30.49	30.49	
CVC 13 G	ANTI-FREEZE	4	SOPEND	CRO1	33.49	30.49	121.96	
CXT 10 LV6	ADDITIVE - OIL - FRI	2	OIL	CRO1	9.49	8.99	17.98	
388898 S	SEAL	2	3B3	CRO1	2.49	2.49	4.98	
Rate	159.21			Parts Total			13,503.69	
Technician	02 -			Labour Total			2,296.31	
Cause	drag vehicle in. try to turn engine over = no. remove cab. st time for seized cab bolts, extra wiring, winch plate, remove engine. exchange engine parts. noticed torque seal leaking. r&i torque and replace hub seal. reassemble and install engine. install cab. flush cooling system. add engine oil. refill and bleed both cooling systems. replace fuel filters and bleed fuel systems. clear codes. was area. road test. recheck level and leaks = good. retest pass .on road test noticed a bit of driveline vibration.					Request Sub-total	15,800.00	
Correction	1							

Labour	2,296.31
Parts	13,503.69
Supplies	62.31
<b>Sub-Total</b>	<b>15,862.31</b>
GST	793.12
<b>Total Invoice</b>	<b>16,655.43</b>
CHEQUES	16,655.43

TERMS

ALL CHARGES DUE UPON RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S (EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$\_\_\_\_\_ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: \_\_\_\_\_ DATE: \_\_\_\_\_

GST: 777713694RT0001