



Brandt Tractor Ltd.
10121 Barlow Trail NE
Calgary, Alberta
T3J 3C6
(403)248-0018

Service
Invoice



JOHN DEERE

X33-11
SEP

SOLD TO:

ATLAS LAND SERVICES INC.
90 TUSCANY SUMMIT GREEN N
CALGARY, AB T3L 0B8

INVOICE DATE	BRANCH	INVOICE NO.
29JUN23	04	1427206

PAGE
1
SALE TYPE
CASH
CUSTOMER NO.

S
H
I
P

T
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
		1427206	01	01JUN23	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	850J	1T0850JXKA0191001			

DESCRIPTION	AMOUNT
INSTALL NEW PADS ON NEW RAILS REPLACE ROLLERS IDLERS&SPROCKT RELEASE GREASE VALVE AND PUSH IN IDLERS ON BOTH , REMOVE TRACKS ON BOTH SIDES, REMOVE BOTTOM ROLLERS ON RH SIDE AND SPROCKETS SEGMENTS AND TOP CARRIER ROLLERS ON RH SIDE, REMOVE FRONT IDLER, REMOVE IDLER FROM TRACK TENSIONER PISTON, CLEAN PAINT OFF NEW IDLER PREPARE FOR INSTALL, TAP / CLEAN THREADS ON BOTTOM TRACK FRAME FOR ROLLERS , TAP LH SPROCKET SEGMENTS HOLES. REMOVE TRACK ROLLERS, CARRIER ROLLERS, SPROCKET SEGMENTS AND FRONT IDLER FROM LH SIDE OF MACHINE. INSTALL TOP CARRIER ROLLERS ON RH SIDE AND LH AND TORQUE TO SPEC, BUFF /GRIND BOTOM OF TRACK FRAME FOR ROLLERS INSTALL BOTTOM ROLLERS ON LH SIDE , APPLY NEVERSIEZE TO BOLTS AND TORQUE ALL ROLLER BOLTS ON LH TRACK FRAME TO SPEC, UNROLL LH TRACK NEW CHAIN , PULLED ON TO BENCH AND CLEAN OFF TRACK PAD SURFACE ON CHAIN LIFT NEW PADS ON TO TRACK CHAIN AND INSTALL NEW BOLTS AND NUTS LUBRICATE BOLTS AND TIGHTEN AND THEN TORQUE TO SPEC, PULL CHAIN OFF AND REPEAT FOR RH TRACK CHAIN AND TORQUE BOLTS TO SPEC, LINE UP TRACKS OUTSIDE OF DOOR , READY FOR INSTALL, INSTALL LH SIDE SPROCKET AND TORQUE TO SPEC WITH RED LOCTITE. INSTALL ONE THROUGH BOLT ON RH SIDE ON DAMAGED HOUSING SECTION.	
2 PM38627 LIQUID G	69.17 138.34
1 PM38605 ANTI-SEI	14.04 14.04
1 WD40 WD-40	16.81 16.81
1 75089 BRAKE CL	12.71 12.71
2 CR5534/45 TLA SALT	6,224.75 12,449.50
88 CR4443/36 GRSR 1B	162.78 14,324.64
2 CR3695/36 GRSR MST	171.81 343.62

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X

SIGNATURE

DATE

QST # 1226957240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL	***CONTINUED**



Brandt Tractor Ltd.
10121 Barlow Trail NE
Calgary, Alberta
T3J 3C6
(403)248-0018

Service Invoice



JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29JUN23	04	1427206

SOLD TO:

ATLAS LAND SERVICES INC.
90 TUSCANY SUMMIT GREEN N

CALGARY, AB T3L 0B8

PAGE
2
SALE TYPE
CASH
CUSTOMER NO.

S
H
I
P

T
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
		1427206	01	01JUN23	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	MEYER	AUTHORIZED BY
JD	850J	1T0850JXKA0191001			

DESCRIPTION				AMOUNT
352	6V1792	BOLT, TR	1.93	679.36
352	1S1860	NUT, TRA	.75	264.00
4	CR4800	TCR ASSY	246.15	984.60
8	6V3303	BOLT, RO	1.21	9.68
10	CR6088	S/F RLR	403.90	4,039.00
6	CR6089	D/F RLR	451.25	2,707.50
64	6V5845	BOLT, RO	2.20	140.80
72	8T3282	WASHER,	.23	16.56
2	ID1462	SEGMENT	471.15	942.30
50	01010-62055	BOLT, 20	1.70	85.00
2	ID2687	IDLER GR	2,205.58	4,411.16
8	8T0362	BOLT 20M	4.26	34.08
8	5P8247	WASHER,	.61	4.88
1	19M8639	CAP SCRE	15.55	15.55
1	14M7277	NUTNUT	8.54	8.54
1	01010-62055	BOLT, 20	2.19	2.19
	* LABOR *			6,320.00
	SERVICE ACCESSORIES		568.80	568.80
1	WELDING		350.00	350.00
	CARBON TAX SURCHARGE		126.40	126.40
>>--> SEG# 01 PRT 41,644.86 LAB 6,320.00 MSC 1,045.20 TOTAL				49,010.06
* GST/HST *				2,450.50

RESEAL TRACK ADJUSTERS

2	AT314787ITR	SEAL KIT	206.61	413.22
1	24M7180	WASHER	7.18	7.18
1	19M7872	CAP SCRE	5.92	5.92
28	8T0375	BOLT, 16XY	1.14	31.92
48	5P8247	WASHER, XY	.61	29.28

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X

SIGNATURE

DATE

QST # 1226997240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL	**CONTINUED**

Brandt Tractor Ltd.
10121 Barlow Trail NE
Calgary, Alberta
T3J 3C6
(403)248-0018

Service Invoice



JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29JUN23	04	1427206

SOLD TO:

ATLAS LAND SERVICES INC.
90 TUSCANY SUMMIT GREEN N
CALGARY, AB T3L 0B8

CATGARY, AB T3L 0B8

O T P H S	CASH	CUSTOMER NO.
	SALE TYPE	3

PURCHASE ORDER NO.		PHONE NUMBER		WORK ORDER NO.		SEG.		DATE OPENED		SALES PRSN	
				1427206		02		01JUN23			
MAKE		MODEL		SERIAL NO.		EQUIP. NO.		METER		AUTHORIZED BY	
JD		850J		1T0850JXKA0191001							

DESCRIPTION		AMOUNT	
LABOR * SERVICE ACCESSORIES CARBON TAX SURCHARGE LAB 1,025.00 92.25 20.50 TOTAL 1,625.27 81.26		SEG# 02 PRT 487.52 LAB 1,025.00 MSC 112.75 * GST/HST * INSPECT PINS AND BUSHINGS IN BLADE	
LABOR * SERVICE ACCESSORIES CARBON TAX SURCHARGE LAB 5.28 430.00 38.70 8.60 TOTAL 482.58 24.13		6 01602-02060 LOCKWASH * LABOR * SERVICE ACCESSORIES CARBON TAX SURCHARGE LAB 5.28 LAB 430.00 MSC 47.30 * GST/HST * RECHROME TRACK ADJUSTER PISTONS AND RESEAL	
LABOR * SERVICE ACCESSORIES CARBON TAX SURCHARGE LAB 1,075.00 2,000.00 96.75 21.50 TOTAL 3,193.25 159.66		1 RECHROME ROD * LABOR * SERVICE ACCESSORIES CARBON TAX SURCHARGE LAB 1,075.00 MSC 2,118.25 * GST/HST * REPLACE FUEL CAP AND TRANS SITE GLASS	
INSTALL FUEL CAP, ORDER PARTS FOR HYDROSTATIC TANK LEVEL		AMOUNT	
TOTAL PARTS TOTAL LABOR MISC. CHARGES SALES TAX		THIS TOTAL	

CUSTOMER COPY

LF-11920



Brandt Tractor Ltd.
10121 Barlow Trail NE
Calgary, Alberta
T3J 3C6
(403)248-0018

Service
Invoice



JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29JUN23	04	1427206

SOLD TO:

ATLAS LAND SERVICES INC.
90 TUSCANY SUMMIT GREEN N

CALGARY, AB T3L 0B8

PAGE
4
SALE TYPE
CASH
CUSTOMER NO.

S
H
I
P

T
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALES PRN
		1427206	06	20JUN23	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	850J	1T0850JXKA0191001			

DESCRIPTION								AMOUNT
GUAGE. DRAIN HYDROSTAIC OIL AND REPLACE GUAGE.								
	1	AT156445SH	Fuel Ca					97.42
	1	AT227279	LEVEL GA					186.16
	1	T197300	LABEL XY					15.84
		* LABOR *						320.00
		SERVICE ACCESSORIES						28.80
		CARBON TAX SURCHARGE						6.40
>>-->	SEG# 06	PRT	299.42	LAB	320.00	MSC	35.20	TOTAL 654.62
			* GST/HST *					32.73
REPLACE KEY SWITCH								
	1	R115974	NUT	CY				7.54
	1	AT195301	SWITCH					157.33
		* LABOR *						430.00
		SERVICE ACCESSORIES						38.70
		CARBON TAX SURCHARGE						8.60
>>-->	SEG# 07	PRT	164.87	LAB	430.00	MSC	47.30	TOTAL 642.17
			* GST/HST *					32.11
REPLACE BLADE LIFT CYLINDER HOSES								
REMOVE RH SIDE BLADE HOSES AND REPLACE LIFT HOSE, RE INSTALL HOSES WITH NEW O-RINGS. LH SIDE ROD END HOSE STUCK ON FITTING (CUT OFF HOSE AND REMOVE END) REMOVE BOTH LINES, REPLACE BOTH LINES WITH NEW O-RINGS. LH SIDE ROD END FITTING DAMAGED. INSTALL FITTING AND LINE.								
	6	T77932	O-RING					28.80

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

QST # 1226957240

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X

SIGNATURE

DATE

TOTAL PARTS

TOTAL LABOR

MISC. CHARGES
SALES TAX

PLEASE PAY
THIS TOTAL

➔ **CONTINUED**

CUSTOMER COPY



Brandt Tractor Ltd.
10121 Barlow Trail NE
Calgary, Alberta
T3J 3C6
(403)248-0018

Service Invoice



JOHN DEERE

SOLD TO:

ATLAS LAND SERVICES INC.
90 TUSCANY SUMMIT GREEN N
CALGARY, AB T3L 0B8

INVOICE DATE	BRANCH	INVOICE NO.
29JUN23	04	1427206

PAGE
5
SALE TYPE
CASH
CUSTOMER NO.

S
H
I
P

T
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPER
		1427206	08	20JUN23	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	850J	1T0850JXKA0191001			

DESCRIPTION				AMOUNT	
3	X1J943-10-10	ELBOW FI	52.60	157.80	
2	X1J043-10-10	HOSE FIT	65.48	130.96	
225	X487TC-10-RL	BULK HOS	1.41	317.25	
6	UC22	PLUNGER	.78	4.68	
HOSE AT304659					
HOSE AT304657					
2	T77858	O-RING	4.93	9.86	
1	X1JC43-10-10	HOSE FIT	43.64	43.64	
1	X10F5OLO-S	ADAPTER XY	11.11	11.11	
1	75089	BRAKE CL	12.71	12.71	
	* LABOR *			430.00	
1	ASSEMBLY-NO PST		15.00	15.00	
1	ASSEMBLY-NO PST		15.00	15.00	
1	ASSEMBLY-NO PST		15.00	15.00	
	SERVICE ACCESSORIES		38.70	38.70	
	CARBON TAX SURCHARGE		8.60	8.60	
>>--> SEG# 08 PRT 716.81 LAB 430.00 MSC 92.30 TOTAL				1,239.11	
* GST/HST *				61.96	
REPLACE LEAKING HOSES UNDER CAB TIGHTEN HOSE CLAMPS					
TIGHT HOSE CLAMPS ON SUCTION LINE AND RETURN HOSE ON TRANSMISSION HYDRAULIC TANK (REPLACE CLAMP THAT WAS STRIPPED) REMOVE HYDROSTATIC RETURN LINE. INSTALL LINE WITH NEW O-RINGS, FASTEN LINE WITH ZIP TIES. FILL HYDROSTATIC SYSTEM WITH NEW 10W30 ENGINE OIL. BOOST MACHINE AND RUN, CHECK FOR LEAKS.					
4	T78612	O-RING	4.06	16.24	
1	AR44217	CLAMP	12.70	12.70	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X

SIGNATURE

DATE

QST # 1226957240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL	**CONTINUED**

CUSTOMER COPY



Brandt Tractor Ltd.
10121 Barlow Trail NE
Calgary, Alberta
T3J 3C6
(403)248-0018

Service Invoice



JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29 JUN 23	04	1427206

SOLD TO:

ATLAS LAND SERVICES INC.
90 TUSCANY SUMMIT GREEN N
CALGARY, AB T3L 0B8

PAGE
6
SALE TYPE
CASH
CUSTOMER NO.

S
H
I
P

T
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALES PRN
		1427206	09	20 JUN 23	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	850J	1T0850JXKA0191001			

DESCRIPTION							AMOUNT
1	X1J143-20-20	ELBOW FIXY	279.76				279.76
1	X1JC43-20-20	FITTING	224.03				224.03
6	15118	HOSE	37.63				225.78
2	UC45	PLUNGER	4.16				8.32
103	25852B	1L - BUL	7.21				742.63
103	WDF	WWASTE D	.10				10.30
	* LABOR *						752.50
1	ASSEMBLY-NO PST		15.00				15.00
	SERVICE ACCESSORIES		67.73				67.73
	CARBON TAX SURCHARGE		15.05				15.05
>>--> SEG# 09 PRT 1,519.76 LAB 752.50 MSC 97.78 TOTAL							2,370.04
* GST/HST *							118.50
WELD OUT BROKEN UNDER CARRIAGE BOLTS							
1	WELDING		1,137.50				1,137.50
>>--> SEG# 10 PRT .00 LAB .00 MSC 1,137.50 TOTAL							1,137.50
* GST/HST *							56.88
* TOTAL GST/HST * - GST No. 899544779							3,017.73

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X

SIGNATURE

DATE

QST # 1226957240

DESCRIPTION	AMOUNT
TOTAL PARTS	44,838.52
TOTAL LABOR	10,782.50
MISC. CHARGES	4,733.58
SALES TAX	0.00
PLEASE PAY THIS TOTAL	63,372.33

CUSTOMER COPY