

**KOCH FORD SALES (ATHABASCA) LTD.**

3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochathabasca.com
www.kochfordathabasca.com

Privacy Policy: The personal information this transaction is collected in accordance with our privacy policy. Most of the personal information is collected from you or your vehicle, to provide you with financing or lease of your vehicle, or to provide you with updates and information regarding your vehicle. We will be of interest to you. By providing us with your information, you agree to provide us with your information. Terms: Goods returned for credit must be accompanied by an invoice. No credit on electrical parts. 10% must be returned within 90 days in original condition on overdue accounts.

Z47-2
KOCH FORD ATHABASCA
3801 HWY 2 SOUTH
ATHABASCA, AB. T9S 1A4
780-675-3673

SALE

Clerk #: 000025

SO # 417788

Printed 01/26/2023 10:13:04 AM

**SERVICE ORDER
CUSTOMER COPY**

REF#: 00000001

Batch #: 640
01/26/23

10:38:09

CVV2: M

Inv/Tkt #: 417788
APPR CODE: 04287G
Trace: 1Manual CNP
*****AMOUNT****\$1,176.71**

APPROVED

Customer No	SHERA FORESTRY
Home	Bus
Cell	Today
Email	
Term CASH	

Advisor	Carol	Promised	01/24/2023
Shop	MS	Opened	01/18/2023
Priority	15	Cashiered	

License No	UNIT 147	Odometer In	92245	Odometer Out	92258
Year	2018	Make	FORD	Model	F-150
Vehicle ID No	1FTFW1E5XJKF24975		Selling Dealer	Exter	
Engine Size	5.0L V8		Fleet #		

Request	Description	Job	CSR	Status
KF-36	MANUAL TRANSMISSION & DRIVETRAIN - CHECK & ADVISE ON SLIPPAGE IN 10TH GEAR, THE CUSTOMER REPLACED A LINE DUE TO LEAKING AND IT WORKS GREAT FROM 1-8. customer asks if transmission fluid & filter change is needed. powertrain coverage may apply	1	A172	Original

Labour	Description	Type	Hours	Amount
KF-36	MANUAL TRANSMISSION & DRIVETRAIN - CHECK & ADVISE ON SLIPPAGE IN 10TH GEAR, THE CUSTOMER REPLACED A LINE DUE TO LEAKING AND IT WORKS GREAT FROM 1-8. customer asks if transmission fluid & filter change is needed. powertrain coverage may apply	C	1.00	170.00

Rate	170.00	Parts Total	0.00
Technician	A223 -	Labour Total	170.00
Cause	Tech 223:	Sublet Total	0.00
Checked and confirmed the customer concern.		Request Sub-total	170.00

Transmission does shift abnormally.
Scanned codes, P0218 and P1783 both are related to a transmission over temp condition.
With engine running the transmission fluid was checked, fluid is off the dipstick. This was likely caused by the oil leak from the hose the customer replaced. Shut the engine off and rechecked the fluid, fluid level was now on the dipstick. Fluid condition appears ok but the fluid level has to be corrected prior to any further diagnosis.
Due to the transmission overheat condition (transmission reached over 276F) and the low oil level, it is recommended that a transmission service be performed and the vehicle be driven again.

Correction

Request	Description	Job	CSR	Status
QC550-GYR	QC550-RYG - USED FOR KEY INSPECTION POINTS OF TIRES, BRAKES AND BATTERY. G-GOOD Y-CAUTIONARY R-NEEDS ATTENTION	2	A172	Original

Labour	Description	Type	Hours	Amount
99P	USED FOR CODES - BRAKE TIRE BATTERY	C	0.00	0.00

As part of our continued service, we may contact you via text message. Standards charges may apply.

Warranty Disclaimer: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSED BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY UNAVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR YOUR EMPLOYEE'S PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION.

UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT. I ACKNOWLEDGE THE EXISTENCE OF A MECHANICS LIEN IN FAVOR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN THE RESPECT OF THE MATERIAL SUPPLIED AND THE SERVICES RENDERED FOR THE FULL AMOUNT CHARGED. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN INVOICE/ACCOUNT IS PAID IN FULL. WHILE THE VEHICLE IS IN MY POSSESSION, IT SHALL BE SUBJECT TO REPOSSESSION ON DEMAND BY WITHIN INVOICE/ACCOUNT IS PAID IN FULL

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford, please call 1-800-565-FORD (3673).

**KOCH FORD SALES (ATHABASCA) LTD.**

3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochathabasca.com
www.kochfordathabasca.com

Privacy Policy: The personal information collected on this form and on other documents relating to this transaction is collected in accordance with applicable privacy legislation and is governed by our privacy policy. Most of the personal information which we collect or disclose is necessary for us to sell or lease your vehicle, to provide products and services related to the vehicle, assist you in the financing or lease of your vehicle, or to provide you service to your vehicle, and we cannot do this without that personal information. We may also use or disclose your personal information to provide you with updates and information regarding products and services that we have to offer and which we think will be of interest to you. By providing your information to us, you consent to the use of your information in the future if you do not consent to any of these uses of the information you provide.

Terms: Goods returned for credit must be in resalable condition and must be accompanied by this invoice. No credit on electrical parts. 10% handling charge on all goods and services returned. All parts must be returned within 30 days in original cartons. Service charge of 2% per month (24% per annum) charged on overdue accounts.

SO # 417788**SERVICE ORDER
CUSTOMER COPY**

Printed 01/26/2023 10:13:04 AM

User A172 Page 2

Customer No SHERA FORESTRY	Advisor	Carol	Promised	01/24/2023 5:00 PM	Tag	297
	Shop	MS	Opened	01/18/2023 10:40 AM	Location	
	Priority	15	Cashiered		PO #	
Home Cell Email	License No	UNIT 147	Odometer In	92245	Odometer Out	92258
	Year	2018	Make	FORD	Model	F-150
	Vehicle ID No	1FTFW1E9XJKF24970	Selling Dealer		Model No	W1E
	Engine Size	5.0L V8			Extended Warranty	
					Delivery Date	
					Fleet #	
Term	CASH					

GTIRE	GOOD TIRES	C	0.00	0.00
GBRAKE	GOOD BRAKES	C	0.00	0.00
GBATT	GOOD BATTERY	C	0.00	0.00
Rate	170.00			
Technician	A223 -			
Cause				
Correction				
		Parts Total		0.00
		Labour Total		0.00
		Sublet Total		0.00
		Request Sub-total		0.00

Request	Description	Job	CSR	Status
QC550	Ford Canada Vehicle Report Card - "LOCATE WHEEL LOCKS IF APPLICABLE"	3	A172	Original
Labour	Description	Type	Hours	Amount
QC550	QC550 - "LOCATE WHEEL LOCKS IF APPLICABLE"	1	0.30	
Technician	A223 -			
Cause	Tech 223: Koch ford inspection complete. Windshield is cracked, replace the windshield. Windshield wipers recommended with the new windshield. Both plate light bulbs are out and damaged, replace the assemblies. Passenger side IWE is broken, replacement required. Passenger side inner tie rod is worn, replace the tie rod, boot and clamps. Wheel alignment required with tie rod end replacement.			
		Parts Total		0.00
		Labour Total		0.00
		Sublet Total		0.00
		Request Sub-total		0.00

Request	Description	Job	CSR	Status
KF-31	GASOLINE ENGINE PERFORMANCE - check engine light on. powertrain coverage may apply	4	A172	Original
Labour	Description	Type	Hours	Amount
KF-31	GASOLINE ENGINE PERFORMANCE - check engine light on. powertrain coverage may apply	1	0.00	
Technician	A223 -			
Cause	Tech 223: Check engine light is related to the transmission concern.			
		Parts Total		0.00
		Labour Total		0.00
		Sublet Total		0.00

As part of our continued service, we may contact you via text message. Standards charges may apply.

Warranty Disclaimer: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

EVERY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE AT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSED BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY UNAVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR YOUR EMPLOYEE'S PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION.

UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT, I ACKNOWLEDGE THE EXISTENCE OF A MECHANICS LIEN IN FAVOR OF THE THIN DEALER ON THE VEHICLE DESCRIBED HEREIN THE RESPECT OF THE MATERIAL SUPPLIED AND THE SERVICES RENDERED R THE FULL AMOUNT CHARGED. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN INVOICE/ACCOUNT IS PAID IN FULL. WHILE THE VEHICLE IS IN MY POSSESSION, IT SHALL BE SUBJECT TO REPOSSESSION ON DEMAND BY WITHIN VOICE/ACCOUNT IS PAID IN FULL

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford, please call 1-800-565-FORD (3673).

GSTN 822567871 RT0001

SIGNATURE

**KOCH FORD SALES (ATHABASCA) LTD.**

3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochatha.com
www.kochfordathabasca.com

Privacy Policy: The personal information collected on this form and on other documents relating to this transaction is collected in accordance with applicable privacy legislation and is governed by our privacy policy. Most of the personal information which we collect or disclose is necessary for us to sell or lease you your vehicle, to provide products and services related to the vehicle, assist you in the financing or lease of your vehicle, or to provide you service to your vehicle, and we cannot do this without that personal information. We may also use or disclose your personal information to provide you with updates and information regarding products and services that we have to offer and which we think will be of interest to you. By providing your information to us, you consent to the uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.

Terms: Goods returned for credit must be in resalable condition and must be accompanied by this invoice. No credit on electrical parts. 10% handling charge on all goods and services returned. All parts must be returned within 90 days in original cartons. Service charge of 2% per month (24% per annum) charged on overdue accounts.

SO # 417788

Printed 01/26/2023 10:13:04 AM

**SERVICE ORDER
CUSTOMER COPY**

User A172 Page 3

Customer No SHERA FORESTRY	Advisor Carol Shop MS Priority 15	Promised 01/24/2023 5:00 PM Opened 01/18/2023 10:40 AM Cashiered	Tag 297 Location PO #
Home Cell Email	Bus Today	License No UNIT 147 Year 2018 Make FORD Vehicle ID No 1FTFW1E5XJKF24975 Engine Size 5.0L V8	Odometer In 92245 Odometer Out 92258 Model F-150 Selling Dealer Extended Warranty Fleet #
Term CASH		InServ Date	Stock No Colour Delivery Date

Correction

Request Sub-total 0.00

Request	Description	Job	CSR	Status			
KF-36	MANUAL TRANSMISSION & DRIVETRAIN - check 4x4 system, when hitting a bump check 4wd system message on the dash. powertrain coverage may apply.	5	A172	Original			
Labour	Description	Type	Hours	Amount			
7453D	MANUAL TRANSMISSION & DRIVETRAIN - check 4x4 system, when hitting a bump check 4wd system message on the dash. powertrain coverage may apply.	W	0.50				
7453D6	Integrated Wheel End (IWE) Hub Locking Mechanism - Replace ONE	W	0.90				
Part	Description	Shp	Bin	Type	Retail	Price	Amount
HL1Z 3C247 A	ACTUATOR ASY	1	04F	W			
S15							
N802827 S100A	NUT - HEX. - FLANGED	1	09L02	W			
BOX 3							
W520215 S440	NUT - HEX.	1	09K03	W			
BOX 3							
W520215 S440	NUT - HEX.	1	09K03	W			
BOX 3							
HUB 471	HUB ASY - WHEEL	1	39B	W			
Technician	A223 -						
Parts Total							0.00
Labour Total							0.00
Sublet Total							0.00
Request Sub-total							0.00

As part of our continued service, we may contact you via text message. Standards charges may apply.

Warranty Disclaimer: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSED BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY UNAVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR YOUR EMPLOYEE'S PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION.

UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT. I ACKNOWLEDGE THE EXISTENCE OF A MECHANICS LIEN IN FAVOR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN THE RESPECT OF THE MATERIAL SUPPLIED AND THE SERVICES RENDERED FOR THE FULL AMOUNT CHARGED. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN INVOICE/ACCOUNT IS PAID IN FULL. WHILE THE VEHICLE IS IN MY POSSESSION, IT SHALL BE SUBJECT TO REPOSSESSION ON DEMAND BY WITHIN INVOICE/ACCOUNT IS PAID IN FULL.

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford, please call 1-800-565-FORD (3673).

SIGNATURE

GST# 822567871 RT0001



KOCH FORD SALES (ATHABASCA) LTD.
3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochathabasca.com
www.kochfordathabasca.com

Privacy Policy: The personal information collected on this form and on other documents relating to this transaction is collected in accordance with applicable privacy legislation and is governed by our privacy policy. Most of the personal information which we collect or disclose is necessary for us to sell or lease your vehicle, to provide products and services related to the vehicle, assist you in the financing or lease of your vehicle, or to provide you service to your vehicle, and we cannot do this without that personal information. We may also use or disclose your personal information to provide you with updates and information regarding products and services that we have to offer and which we think will be of interest to you. By providing your information to us, you consent to the uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.

Terms: Goods returned for credit must be in resalable condition and must be accompanied by this invoice. No credit on electrical parts. 10% handling charge on all goods and services returned. All parts must be returned within 90 days in original cartons. Service charge of 2% per month (24% per annum) charged on overdue accounts.

SO # 417788

**SERVICE ORDER
CUSTOMER COPY**



Printed 01/26/2023 10:13:04 AM

User A172 Page 4

Customer No SHERA FORESTRY	Advisor Carol Shop MS Priority 15	Promised 01/24/2023 5:00 PM Opened 01/18/2023 10:40 AM Cashiered	Tag 297 Location PO #
Home Cell Email	Bus Today	License No UNIT 147 Year 2018 Make FORD Vehicle ID No 1FTFW1E6XJKF24975 Engine Size 5.0L V8	Odometer In 92245 Model F-150 Selling Dealer Odometer Out 92258 Model No W1E Extended Warranty Stock No Colour Delivery Date Fleet #
Term CASH			

Cause Tech 223:
Checked and confirmed the customer concern of the intermittent four wheel drive fault.
Scanned codes, C1979 present in the TCCM for the vacuum solenoid.
Inspected the solenoid and found the pigtail broken.
If the pigtail is held a certain way the codes will not return but if the pigtail is moved the codes will return.
This explains why the fault happens on bumpy roads.

In addition to the pigtail issue, it was noted that the passenger side front IWE does not lock to the bearing which allows the wheel to free wheel. Four wheel drive will not work.
Replacement of the IWE and inspection of the wheel bearing and CV axle is required.
Tested the driver side IWE, IWE works properly.

Recommend replacement of the pigtail and the passenger side IWE.

Pigtails is not warrantable, IWE is warrantable.

Removed the IWE and inspected the wheel bearing.
Found excessive damage to the wheel bearing splines which is not repairable.
Removed and replaced the passenger side front wheel bearing assembly and the IWE.
Retested after the repair, all ok.
Repair complete.

Correction

Request	Description				Job	CSR	Status
KF-	Transmission service				6	A172	Approved
Labour	Description				Type	Hours	Amount
KF-	Transmission service				C	1.50	200.00
Part	Description	Shp	Bin	Type	Retail	Price	Amount

As part of our continued service, we may contact you via text message. Standard charges may apply.

Warranty Disclaimer: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE AT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSED BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY UNAVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR YOUR EMPLOYEE'S PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION.

TIL PAYMENT IN FULL OF THE WITHIN ACCOUNT. I ACKNOWLEDGE THE EXISTENCE OF A MECHANICS LIEN IN FAVOR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN THE RESPECT OF THE MATERIAL SUPPLIED AND THE SERVICES RENDERED FOR THE FULL AMOUNT CHARGED. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN INVOICE/ACCOUNT IS PAID IN FULL. WHILE THE VEHICLE IS IN MY POSSESSION, IT SHALL BE SUBJECT TO REPOSSESSION ON DEMAND BY WITHIN INVOICE/ACCOUNT IS PAID IN FULL.

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford, please call 1-800-565-FORD (3673).

GST# 822567871 RT0001

SIGNATURE

**KOCH FORD SALES (ATHABASCA) LTD.**

3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochathabasca.com
www.kochfordathabasca.com

Privacy Policy: The personal information collected on this form and on other documents relating to this transaction is collected in accordance with applicable privacy legislation and is governed by our privacy policy. Most of the personal information which we collect or disclose is necessary for us to sell or lease your vehicle, to provide products and services related to the vehicle, assist you in the financing or lease of your vehicle, or to provide you service to your vehicle, and we cannot do this without that personal information. We may also use or disclose your personal information to provide you with updates and information regarding products and services that we have to offer and which we think will be of interest to you. By providing your information to us, you consent to the uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.

Terms: Goods returned for credit must be in resalable condition and must be accompanied by this invoice. No credit on electrical parts. 10% handling charge on all goods and services returned. All parts must be returned within 30 days in original cartons. Service charge of 2% per month (24% per annum) charged on overdue accounts.

SO # 417788

Printed 01/26/2023 10:13:04 AM

**SERVICE ORDER
CUSTOMER COPY**

User A172 Page 5

Customer No SHERA FORESTRY	Advisor Carol Shop MS Priority 15	Promised 01/24/2023 5:00 PM Opened 01/18/2023 10:40 AM Cashiered	Tag 297 Location PO #
Home Cell Email	Bus Today	License No UNIT 147 Year 2018 Make FORD Vehicle ID No 1FTFW1E5XJKF24975 Engine Size 5.0L V8	Odometer In 92245 Odometer Out 92258 Model F-150 Selling Dealer InServ Date W1E Extended Warranty Stock No Colour Delivery Date Fleet #
Term CASH			

FT 202	SCREEN ASY	1	04B	CSO	77.79	77.79	77.79
S15							
HL3Z 7A191 B	GASKET	1	21C	CSO	86.48	86.48	86.48
S15							
CVC 13 G	ANTI-FREEZE	1	18C	CSO	33.02	33.02	33.02
STK							
ENOIL	ENVIRO FEE	10	ADMIN	CSO	0.10	0.10	1.00
XT 12 QULV	OIL - AUTOMATIC TRAN	10	16F	CSO	11.28	11.28	112.80
Rate	170.00			Parts Total	311.09		
Technician	A223 -			Labour Total	200.00		
Cause	Tech 223:			Sublet Total	0.00		
	Performed the transmission service.			Request Sub-total	511.09		
	Removed and replaced the filter and transmission pan gasket.						
	Reassembled and filled the transmission.						
	Test drove and adjusted the fluid level to spec with the transmission at operating temp.						
	All ok.						
	The transmission shifts properly now.						
	Low fluid level was the cause of the concern.						

Correction

Request	Description					Job,	CSR	Status
34	Remove and replace the pigtail at the four wheel drive vacuum solenoid.					9	A172	Approved
Labour	Description					Type	Hours	Amount
34	Remove and replace the pigtail at the four wheel drive vacuum solenoid.					C	0.60	102.00
Part	Description	Shp	Bin	Type	Retail	Price	Amount	
WPT 441	WIRE ASY	1	08G04	CSO	67.56	67.56	67.56	
BOX 3								
Rate	170.00			Parts Total				67.56
Technician	A223 -			Labour Total				102.00

As part of our continued service, we may contact you via text message. Standards charges may apply.

Warranty Disclaimer: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSED BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY UNAVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR YOUR EMPLOYEE'S PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION.

UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT, I ACKNOWLEDGE THE EXISTENCE OF A MECHANICS LIEN IN FAVOR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN THE RESPECT OF THE MATERIAL SUPPLIED AND THE SERVICES RENDERED FOR THE FULL AMOUNT CHARGED. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN INVOICE/ACCOUNT IS PAID IN FULL. WHILE THE VEHICLE IS IN MY POSSESSION, IT SHALL BE SUBJECT TO REPOSSESSION ON DEMAND BY WITHIN INVOICE/ACCOUNT IS PAID IN FULL

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford, please call 1-800-565-FORD (3673).

SIGNATURE

GST# 822567871 RTD001

KOCH FORD SALES (ATHABASCA) LTD.

3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochathabasca.com
www.kochfordathabasca.com

Privacy Policy: The personal information collected on this form and on other documents relating to this transaction is collected in accordance with applicable privacy legislation and is governed by our privacy policy. Most of the personal information which we collect or disclose is necessary for us to sell or lease your vehicle, to provide products and services related to the vehicle, assist you in the financing or lease of your vehicle, or to provide you service to your vehicle, and we cannot do this without that personal information. We may also use or disclose your personal information to provide you with updates and information regarding products and services that we have to offer and which we think will be of interest to you. By providing your information to us, you consent to the uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.

Terms: Goods returned for credit must be in resalable condition and must be accompanied by this invoice. No credit on electrical parts. 10% handling charge on all goods and services returned. All parts must be returned within 90 days in original cartons. Service charge of 2% per month (24% per annum) charged on overdue accounts.



SO # 417788

Printed 01/26/2023 10:13:04 AM

SERVICE ORDER CUSTOMER COPY



User A172 Page 6

Customer No SHERA FORESTRY		Advisor Carol	Promised 01/24/2023 5:00 PM	Tag 297
Home		Shop MS	Opened 01/18/2023 10:40 AM	Location
Cell		Priority 15	Cashiered	PO #
Email		License No UNIT 147	Odometer In 92245	Odometer Out 92258
Term CASH		Year Make 2018 FORD	Model F-150	InServ Date W1E
		Vehicle ID No 1FTFW1E6XJKF24075	Selling Dealer	Model No
		Engine Size 5.0L V8	Extended Warranty	Colour
			Fleet #	Delivery Date

Cause	Tech 223: Removed and replaced the pigtail, retested all ok. Repair complete.	Sublet Total	0.00
		Request Sub-total	169.56

Correction

Request	Description	Job	CSR	Status
KF-BELT	Accessory drive is noisy, diag required.	11	A172	Approved
Labour	Description	Type	Hours	Amount
6209A	Accessory drive is noisy, diag required.	W	0.30	
ADD	ADD OPERATION - CHECK AND ADVISE	W	0.00	
Part	Description	Shp	Bin	Type
BT 103	TENSIONER	1	04101	W
Technician	A223 -			
Cause	Tech 223: Checked and confirmed the accessory drive noise. Isolated the noise to the primary accessory drive tensioner. Removed the belt and inspected pulley, pulley is noisy. Started the engine with the belt off to confirm the secondary system is ok, all ok. Alternator and water pump were checked and are ok. Remove and replace the primary accessory drive belt tensioner. Parts are covered under powertrain warranty. Removed and replaced the primary belt tensioner. Reassembled and retested, all ok. Repair complete.	Parts Total		0.00
		Labour Total		0.00
		Sublet Total		0.00
		Request Sub-total		0.00

Correction

Request	Description	Job	CSR	Status
KF-34	Park brake fault, diag required.	14	A172	Approved
Labour	Description	Type	Hours	Amount
KF-34	Park brake fault, diag required.	C	1.10	187.00
Rate	170.00			
		Parts Total		0.00

As part of our continued service, we may contact you via text message. Standards charges may apply.

Warranty Disclaimer: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE AT THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSED BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY 'AVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR YOUR EMPLOYEE'S PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION.

UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT, I ACKNOWLEDGE THE EXISTENCE OF A MECHANICS LIEN IN FAVOR OF THE THIN DEALER ON THE VEHICLE DESCRIBED HEREIN IN THE RESPECT OF THE MATERIAL SUPPLIED AND THE SERVICES RENDERED R THE FULL AMOUNT CHARGED. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN INVOICE/ACCOUNT IS PAID IN FULL. WHILE THE VEHICLE IS IN MY POSSESSION, IT SHALL BE SUBJECT TO REPOSSESSION ON DEMAND BY WITHIN INVOICE/ACCOUNT IS PAID IN FULL.

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford, please call 1-800-565-FORD (3673).

SIGNATURE

GSTM 822567871 RT0001

**KOCH FORD SALES (ATHABASCA) LTD.**

3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochatha.com
www.kochfordathabasca.com

Privacy Policy: The personal information collected on this form and on other documents relating to this transaction is collected in accordance with applicable privacy legislation and is governed by our privacy policy. Most of the personal information which we collect or disclose is necessary for us to sell or lease you your vehicle, to provide products and services related to the vehicle, assist you in the financing or lease of your vehicle, or to provide you service to your vehicle, and we cannot do this without that personal information. We may also use or disclose your personal information to provide you with updates and information regarding products and services that we have to offer and which we think will be of interest to you. By providing your information to us, you consent to the uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.

Terms: Goods returned for credit must be in resalable condition and must be accompanied by this invoice. No credit on electrical parts. 10% handling charge on all goods and services returned. All parts must be returned within 90 days in original cartons. Service charge of 2% per month (24% per annum) charged on overdue accounts.

SO # 417788

Printed 01/26/2023 10:13:05 AM

**SERVICE ORDER
CUSTOMER COPY**

User A172 Page 7

Customer No SHERA FORESTRY
Home Cell Email
Bus Today
Term CASH

Advisor Carol	Promised 01/24/2023 5:00 PM	Tag 297
Shop MS	Opened 01/18/2023 10:40 AM	Location
Priority 15	Cashiered	PO #

License No UNIT 147	Odometer In 92245	Odometer Out 92258	InServ Date	Stock No
Year Make 2018 FORD	Model F-150	Model No W1E	Colour	
Vehicle ID No 1FTFW1E5XJKF24975	Selling Dealer	Extended Warranty	Delivery Date	
Engine Size 5.0L V8		Fleet #		

Technician A223 -
Cause Tech 223:
Confirmed the park brake fault.
Scanned codes, C1034:78 present.
Tested wiring and found high resistance in the driver side park brake motor power circuit.
Located and repaired the wiring, retested all ok.
Repair complete.

Labour Total	187.00
Sublet Total	0.00
Request Sub-total	187.00

Correction

As part of our continued service, we may contact you via text message. Standards charges may apply.

Warranty Disclaimer: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE HAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSED BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY UNAVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR OUR EMPLOYEE'S PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION.

UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT. I ACKNOWLEDGE THE EXISTENCE OF A MECHANICS LIEN IN FAVOR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN THE RESPECT OF THE MATERIAL SUPPLIED AND THE SERVICES RENDERED OR THE FULL AMOUNT CHARGED. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN INVOICE/ACCOUNT IS PAID IN FULL. WHILE THE VEHICLE IS IN MY POSSESSION, IT SHALL BE SUBJECT TO REPOSSESSION ON DEMAND BY WITHIN INVOICE/ACCOUNT IS PAID IN FULL.

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford, please call 1-800-363-FORD (3673).

SIGNATURE

GST# 822567871 RT0001

**KOCH FORD SALES (ATHABASCA) LTD.**

3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochathabasca.com
www.kochfordathabasca.com

Privacy Policy: The personal information collected on this form and on other documents relating to this transaction is collected in accordance with applicable privacy legislation and is governed by our privacy policy. Most of the personal information which we collect or disclose is necessary for us to sell or lease your vehicle, to provide products and services related to the vehicle, assist you in the financing or lease of your vehicle, or to provide you service to your vehicle, and we cannot do this without that personal information. We may also use or disclose your personal information to provide you with updates and information regarding products and services that we have to offer and which we think will be of interest to you. By providing your information to us, you consent to the uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.

Terms: Goods returned for credit must be in resalable condition and must be accompanied by this invoice. No credit on electrical parts. 10% handling charge on all goods and services returned. All parts must be returned within 90 days in original cartons. Service charge of 2% per month (24% per annum) charged on overdue accounts.

SO # 417788**SERVICE ORDER
CUSTOMER COPY**

Printed 01/26/2023 10:13:05 AM

User A172 Page 8

Customer No SHERA FORESTRY Home Cell Email Bus Today Term CASH	Advisor Carol Shop MS Priority 15	Promised 01/24/2023 5:00 PM Opened 01/18/2023 10:40 AM Cashiered	Tag 297 Location PO #
	License No UNIT 147 Year Make 2018 FORD Vehicle ID No 1FTFW1E5XJKF24976 Engine Size 5.0L V8	Odometer In 92245 Model F-150 Selling Dealer	Odometer Out 92258 Model No W1E Extended Warranty

Labour	659.00
Parts	378.65
ENVIRO FEE FOR ENVIROMENTAL WASTE	3.95
Supplies	79.08
SUB-TOTAL	1,120.68
GST	56.03
TOTAL INVOICE	1,176.71

Additional Work Authorization

Date/Time	Contact	Phone Number	Comments	Amount
01/20/2023 10:51:23 AM	SHERA FORESTRY	(780) 623-8707		\$538.39
01/20/2023 10:50:16 AM	SHERA FORESTRY	(780) 623-8707		\$190.40
01/25/2023 9:25:23 AM	SHERA FORESTRY	(780) 623-8707		\$190.40

Recommended/Deferred Services

Code	Description	Amount
<F-33	Remove and replace the passenger side inner tie rod end.	\$314.07
<F-WHEELALIGN	Wheel alignment required	\$149.95
<F-LITEEXT	Both plate light bulb are out/damaged.	\$300.32
<F-WSGLASS	Windshield is cracked, replace the windshield	\$391.46
<F-WIPER	Wipers are recommended with new windshield/s	\$53.36
<F-LITEINOP	Passenger side plate lamp assembly is missing replace the assembly	
<F-POWM	Passenger side mirror glass is cracked, replace the glass.	

* Deferred Services prices are subject to change

As part of our continued service, we may contact you via text message. Standards charges may apply.

Warranty Disclaimer: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

BY AUTHORIZING THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSED BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY UNAVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR YOUR EMPLOYEE'S PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. I WILL PAYMENT IN FULL OF THE WITHIN ACCOUNT. I ACKNOWLEDGE THE EXISTENCE OF A MECHANICS LIEN IN FAVOR OF THE FINANCIAL DEALER ON THE VEHICLE DESCRIBED HEREIN THE RESPECT OF THE MATERIAL SUPPLIED AND THE SERVICES RENDERED. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN INVOICE/ACCOUNT IS PAID IN FULL. WHILE THE VEHICLE IS IN MY POSSESSION, IT SHALL BE SUBJECT TO REPOSSESSION ON DEMAND BY WITHIN INVOICE/ACCOUNT IS PAID IN FULL.

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford, please call 1-800-565-FORD (3673).

SIGNATURE

GST# 822567871 RTD001

REPAIR ORDER

R67672

(Copy)

SOLD TO:

SHERA FORESTRY LTD

CONTACT:

MOBILE :
BUSINESS:
EMAIL :

HOME: 780-798-3945
FAX :

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
WHITE	2018 FORD F150 4XX 5.0	CGL4809	147		61056
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
1FTFW1E5XJKF24975				AM	61056
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
1:08 PM		NET 30			61056
QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
2h	ML	CHECK OIL LEAK FRONT DIFF MECHANICAL LABOUR 21 Nov 09 DIAG OIL LEAK ON FRONT, REMOVE 2 WHEEL BARROWS OF MUD, TRACE LEAK TO FRONT PINION SEAL AND PLUGGED DIFF VENT. REPLACE SEAL AND TOP UP DIFF SEAL FORD NEW		68.50	280.00
1*	2L1Z3N134AA	FREIGHT SPECIAL ORDER FROM FORD		22.50	68.50
1*	FR	OASIS GEAR OIL SYNTHETIC		19.95	22.50
2*	GEAOILSYN	PARTS CLEANER, PENETRATING OIL		9.95	39.90
1*	PARCLE	OASIS DIFFERENTIAL ADDITIVE POSI		21.95	9.95
1*	DIFADD				21.95
1	MSS	SHOP/SERVICE/TOW TRUCK SUPPLIES Warranty on mechanical parts is subject to the manufacturer's offered warranty policy. Warranty term lengths vary by manufacturer. In some cases parts and/or labour may not be covered		23.80	23.80

BILL TO:

For your safety please ensure wheel fasteners are retorqued within the first 100 km's

TERMS AND CONDITIONS

I hereby authorize the repairs as listed above to be performed and completed. I acknowledge the shop supply fee of 8.5% to a max of \$80.00. Old parts will be disposed of after repair unless a core is charged or the customer requests them.

Signature: _____

Date: _____

PARTS:	162.80
LABOUR:	280.00
OTHER:	23.80
SUB-TOTAL:	466.60
GST/HST:	23.35
PST:	N/C
TOTAL:	489.95



KOCH FORD SALES (ATHABASCA) LTD.
3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochathabasca.com
www.kochfordathabasca.com

Privacy Policy: The personal information collected on this form and on other documents relating to this transaction is collected in accordance with applicable privacy legislation and is governed by our privacy policy. Most of the personal information which we collect or disclose is necessary for us to sell or lease you your vehicle, to provide products and services related to the vehicle, assist you in the financing or lease of your vehicle, or to provide you service to your vehicle, and we cannot do this without that personal information. We may also use or disclose your personal information to provide you with updates and information regarding products and services that we have to offer and which we think will be of interest to you. By providing your information to us, you consent to the uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.

Terms: Goods returned for credit must be in resalable condition and must be accompanied by this invoice. No credit on electrical parts. 10% handling charge on all goods and services returned. All parts must be returned within 90 days in original cartons. Service charge of 2% per month (24% per annum) charged on overdue accounts.

SO # 410411

SERVICE ORDER



Printed 01/22/2022 7:40:34 AM **CUSTOMER COPY - ** IN PROGRESS **** User A351 Page 1

Customer No SHERA FORESTRY	Advisor Renee	Shop MS	Priority 602	Promised 01/21/2022 5:00 PM	Tag 761	
						Opened 01/06/2022 8:26 AM
Home Cell Email	Bus Today	License No	Odometer In 69109	Odometer Out	InServ Date	Stock No
		Vehicle ID No 1FTFW1E5XJKF24975	Selling Dealer	Extended Warranty	Delivery Date	
Term CASH						

Request	Description	Job	CSR	Status
35	CLIMATE CONTROL SYSTEMS - CHECK FOR NOT BLOWING HOT ENOUGH ON EITHER SIDE.	1	A351	Original
Labour	Description	Type	Hours	Amount
35	CLIMATE CONTROL SYSTEMS - CHECK FOR HEATER BLOWING COLD ON ONE SIDE AND WARM ON THE OTHER SIDE.	C	0.00	0.00
Rate	160.00			
Technician	A223 -			
Cause	Checked and confirmed customer concern of the lack of heat. Found poor air flow from vents as well. Checked the cabin air filter, filter is dirty. Removed the filter and retested heat concern, lack of heat still present. Checked OASIS. Two TSB may apply. TSB 21-2199 Lack of heat and or cooling with DTC B1081:07. Scanned for codes, no codes present. TSB 20-2034. Lack of heat when operating below 20C. Ran engine up to temp, ran engine at 3000RPM for 30 seconds. Let the vehicle idle for 30 seconds then took heater core inlet and outlet temperatures. It was noted that there is 35 degree difference between the inlet and outlet. Heater core replacement and coolant flush is required as per TSB.	Parts Total		0.00
		Labour Total		0.00
		Request Sub-total		0.00
Correction	To correct the concern recommend replacement of the heater core, coolant, cabin filter, block heater, thermostat and seal.			
	18472 was the basic used, no coverage.			

Request	Description	Job	CSR	Status
QC550-RYG	QC550-RYG - USED FOR KEY INSPECTION POINTS OF TIRES, BRAKES AND BATTERY. G-GOOD Y-CAUTIONARY R-NEEDS ATTENTION - QC550-RYG SPECIAL CODING FOR BRAKES-TIRES-BATTERY	2	A351	Original

Repair

KOCH FORD ATHABASCA
3801 HWY 2 SOUTH
ATHABASCA, AB T9S 1A4
780-675-3673

SALE

Clerk #: 000025

Batch #: 306

01/22/22

Inv/Tkt #: 410411

APPR CODE: 03723G

Tracer: 3

Manual CP

REF#: 00000003

100123

AMOUNT \$1,125.87

APPROVED

THANK YOU / MERCI

a text message. Standards charges may apply.

er hereby expressly disclaims all warranties, either express or implied, including any implied other person to assume for it any liability in connection with the sale of said products.

AND AGREE ARTICLES LEFT IN BY NT YOU AND/OR WHERE FOR THE FAVOR OF THE ES RENDERED AT ALL TIMES ACCOUNT IS Y WITHIN

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford, please call 1-800-565-FORD (3673).

**KOCH FORD SALES (ATHABASCA) LTD.**

3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochathas.com
www.kochfordathabasca.com

Privacy Policy: The personal information collected on this form and on other documents relating to this transaction is collected in accordance with applicable privacy legislation and is governed by our privacy policy. Most of the personal information which we collect or disclose is necessary for us to sell or lease you your vehicle, to provide products and services related to the vehicle, assist you in the financing or lease of your vehicle, or to provide you service to your vehicle, and we cannot do this without that personal information. We may also use or disclose your personal information to provide you with updates and information regarding products and services that we have to offer and which we think will be of interest to you. By providing your information to us, you consent to the uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.

Terms: Goods returned for credit must be in resalable condition and must be accompanied by this invoice. No credit on electrical parts. 10% handling charge on all goods and services returned. All parts must be returned within 90 days in original cartons. Service charge of 2% per month (24% per annum) charged on overdue accounts.

SO # 410411**SERVICE ORDER**

Printed 01/22/2022 7:40:35 AM

CUSTOMER COPY - ** IN PROGRESS **

A351

Page 2

Customer No SHERA FORESTRY	Advisor Renee Shop MS Priority 602	Promised 01/21/2022 5:00 PM Opened 01/06/2022 8:26 AM Cashiered	Tag 761 Location PO #
Home Cell Email	Bus Today	License No 69109 Year Make 2018 FORD Model F-150 Vehicle ID No 1FTFW1E5XJKF24975 Engine Size 5.0L V8	Stock No Colour Delivery Date Model No W1E Extended Warranty Fleet #
Term CASH			

Labour	Description	Type	Hours	Amount
99P	USED FOR CODES - BRAKE TIRE BATTERY	C	0.00	0.00
GBATT	GOOD BATTERY	C	0.00	0.00
GTIRE	GOOD TIRES	C	0.00	0.00
GBRAKE	GOOD BRAKES	C	0.00	0.00
Rate	160.00			
Technician	A223 -			
Parts Total				0.00
Labour Total				0.00
Request Sub-total				0.00

Request	Description	Job	CSR	Status
QC550	Ford Canada Vehicle Report Card - *LOCATE WHEEL LOCKS IF APPLICABLE*	3	A351	Original
Labour	Description	Type	Hours	Amount
QC550	Ford Canada Vehicle Report Card - *LOCATE WHEEL LOCKS IF APPLICABLE*	1	0.30	
Technician	A223 -			
Cause	Passenger side plate lamp is missing replace the assembly. Cabin air filter requires replacement. Passenger side mirror glass is broken, replace the glass.			
Parts Total				0.00
Labour Total				0.00
Request Sub-total				0.00

Correction

Request	Description	Job	CSR	Status			
32	Perform TSB 20-2034 heater core replacement and coolant flush.	4	A351	Approved			
Labour	Description	Type	Hours	Amount			
32	Perform TSB 20-2034 heater core replacement and coolant flush.	W	9.40				
Part	Description	Shp	Bin	Type	Retail	Price	Amount
VC 1	CLEANER - OXIDATION	1	20H	W			
TOP2							
FP 92	FILTER - POLLEN	1	03A	W			
TOP2							
HL3Z 6A051 A	HEATER ASY	1	06L01	W			
TOP 2							

As part of our continued service, we may contact you via text message. Standards charges may apply.

Warranty Disclaimer: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSED BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY UNAVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR YOUR EMPLOYEE'S PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION.

UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT, I ACKNOWLEDGE THE EXISTENCE OF A MECHANICS LIEN IN FAVOR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN THE RESPECT OF THE MATERIAL SUPPLIED AND THE SERVICES RENDERED FOR THE FULL AMOUNT CHARGED. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN INVOICE/ACCOUNT IS PAID IN FULL. WHILE THE VEHICLE IS IN MY POSSESSION, IT SHALL BE SUBJECT TO REPOSSESSION ON DEMAND BY WITHIN INVOICE/ACCOUNT IS PAID IN FULL.

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford, please call 1-800-565-FORD (3673).

GST# 822567871 RT0001

SIGNATURE



KOCH FORD SALES (ATHABASCA) LTD.

3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochatha.com
www.kochfordathabasca.com

Privacy Policy: The personal information collected on this form and on other documents relating to this transaction is collected in accordance with applicable privacy legislation and is governed by our privacy policy. Most of the personal information which we collect or disclose is necessary for us to sell or lease you your vehicle, to provide products and services related to the vehicle, assist you in the financing or lease of your vehicle, or to provide you service to your vehicle, and we cannot do this without that personal information. We may also use or disclose your personal information to provide you with updates and information regarding products and services that we have to offer and which we think will be of interest to you. By providing your information to us, you consent to the uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.

Terms: Goods returned for credit must be in resalable condition and must be accompanied by this invoice. No credit on electrical parts. 10% handling charge on all goods and services returned. All parts must be returned within 30 days in original cartons. Service charge of 2% per month (24% per annum) charged on overdue accounts.

SO # 410411

SERVICE ORDER



Printed 01/22/2022 7:40:35 AM

CUSTOMER COPY - ** IN PROGRESS **

User A351

Page 3

Customer No SHERA FORESTRY		Advisor Renee	Promised 01/21/2022 5:00 PM	Tag 761
Home		Shop MS	Opened 01/06/2022 8:26 AM	Location
Cell		Priority 602	Cashiered	PO #
Email				
Bus Today		License No	Odometer In 69109	Odometer Out
Term CASH		Year 2018	Make FORD	Model F-150
		Vehicle ID No 1FTFW1E5XJKF24975	Selling Dealer	Model No W1E
		Engine Size 5.0L V8	Extended Warranty	Colour
		Fleet #		Delivery Date

N808684 S101	BOLT	1	09J03	W
TOP2				
HC 84	RADIATOR AND SEAL AS	1	33C	W
TOP2				
BC3Z 8287 C	CLAMP - HEATER HOSE	1	03F01	W
TOP2				
RT 1251	THERMOSTAT ASY	1	06H03	W
TOP2				
RG 630	SEAL - THERMOSTAT	1	06F01	W
TOP2				
CVC 13 G	ANTI-FREEZE	2	18C	W
TOP2				
YF 37489	"O" RING	1	09I02	W
TOP 2				
Technician	A223 -		Parts Total	0.00
Cause	Performed TSB 20-2034 as per diag.		Labour Total	0.00
	Flushed the coolant and installed new hardware, seals and replaced the heater core.		Request Sub-total	0.00
	Filled the cooling system up with yellow coolant.			
	Test drove and rechecked coolant, all ok.			
	Coolant is rated for -45c.			
	Good Heat in the cab now.			

Correction

Request	Description	Job	CSR	Status
38	BRAKES-BRAKE FEELS SPONGY - HVAE TO PUSH PEDAL FAR TO GET BRAKE REPSONSE.	7	A172	Approved
Labour	Description	Type	Hours	Amount
38	BRAKES-BRAKE FEELS SPONGY - HVAE TO PUSH PEDAL FAR TO GET BRAKE REPSONSE.	C	1.00	160.00
Rate	160.00		Parts Total	0.00

As part of our continued service, we may contact you via text message. Standards charges may apply.

Warranty Disclaimer: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSED BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY UNAVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR YOUR EMPLOYEE'S PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION.

UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT. I ACKNOWLEDGE THE EXISTENCE OF A MECHANICS LIEN IN FAVOR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN THE RESPECT OF THE MATERIAL SUPPLIED AND THE SERVICES RENDERED

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by

**KOCH FORD SALES (ATHABASCA) LTD.**

3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochathabasca.com
www.kochfordathabasca.com

Privacy Policy: The personal information collected on this form and on other documents relating to this transaction is collected in accordance with applicable privacy legislation and is governed by our privacy policy. Most of the personal information which we collect or disclose is necessary for us to sell or lease you your vehicle, to provide products and services related to the vehicle, assist you in the financing or lease of your vehicle, or to provide you service to your vehicle, and we cannot do this without that personal information. We may also use or disclose your personal information to provide you with updates and information regarding products and services that we have to offer and which we think will be of interest to you. By providing your information to us, you consent to the uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.

Terms: Goods returned for credit must be in resalable condition and must be accompanied by this invoice. No credit on electrical parts. 10% handling charge on all goods and services returned. All parts must be returned within 90 days in original cartons. Service charge of 2% per month (24% per annum) charged on overdue accounts.

SO # 410411**SERVICE ORDER**

Printed 01/22/2022 7:40:35 AM

CUSTOMER COPY - ** IN PROGRESS **

User

A351

Page 4

Customer No SHERA FORESTRY	Advisor Renee Shop MS Priority 602	Promised 01/21/2022 5:00 PM Opened 01/06/2022 8:26 AM Cashiered	Tag 761 Location PO #
Home Cell Email	Bus Today	License No 69109 Year 2018 Make FORD Model F-150 Vehicle ID No 1FTFW1E5XJKF24975 Engine Size 5.0L V8	Odometer In Odometer Out InServ Date Model No W1E Colour Extended Warranty Delivery Date Fleet #
Term CASH			

Technician A223 - Labour Total 160.00
Cause Checked and confirmed customer concern. Request Sub-total 160.00
The driver side rear brake caliper was missing a bolt, installed a new bolt and retested.
Brakes are still spongy.
Bleed the master cylinder all ok.
Bleed the calipers, lots of air came from the rear.
Retested after the brake fluid was topped up, all ok.

Correction

Request	Description	Job	CSR	Status
55C	KOCH PORTION ON AWA REPAIR	8	A351	Approved
Labour	Description	Type	Hours	Amount
55C	KOCH PORTION ON AWA REPAIR	C	0.00	(273.68)
55C	KOCH PORTION ON AWA REPAIR	I	0.00	
Rate	160.00	Parts Total		0.00
Technician	A223	Labour Total		(273.68)
		Request Sub-total		(273.68)

As part of our continued service, we may contact you via text message. Standards charges may apply.

Warranty Disclaimer: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSED BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY UNAVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR YOUR EMPLOYEE'S PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION.
UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT. I ACKNOWLEDGE THE EXISTENCE OF A MECHANICS LIEN IN FAVOR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN THE RESPECT OF THE MATERIAL SUPPLIED AND THE SERVICES RENDERED FOR THE FULL AMOUNT CHARGED. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN INVOICE/ACCOUNT IS PAID IN FULL. WHILE THE VEHICLE IS IN MY POSSESSION, IT SHALL BE SUBJECT TO REPOSSESSION ON DEMAND BY WITHIN INVOICE/ACCOUNT IS PAID IN FULL

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford, please call 1-800-565-FORD (3673).

GST# 822567871 RT0001

SIGNATURE



KOCH FORD SALES (ATHABASCA) LTD.

3801 Hwy 2 South
Athabasca, AB T9S 1A4
Phone: (780) 675-1310
Toll Free: 1-800-290-3494
service@kochatha.com
www.kochfordathabasca.com

Privacy Policy: The personal information collected on this form and on other documents relating to this transaction is collected in accordance with applicable privacy legislation and is governed by our privacy policy. Most of the personal information which we collect or disclose is necessary for us to sell or lease your vehicle, to provide products and services related to the vehicle, assist you in the financing or lease of your vehicle, or to provide you service to your vehicle, and we cannot do this without that personal information. We may also use or disclose your personal information to provide you with updates and information regarding products and services that we have to offer and which we think will be of interest to you. By providing your information to us, you consent to the uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.

Terms: Goods returned for credit must be in resalable condition and must be accompanied by this invoice. No credit on electrical parts. 10% handling charge on all goods and services returned. All parts must be returned within 90 days in original cartons. Service charge of 2% per month (24% per annum) charged on overdue accounts.

SO # 410411

SERVICE ORDER



Printed 01/22/2022 7:40:35 AM

CUSTOMER COPY - ** IN PROGRESS **

User

A351

Page 5

Customer No SHERA FORESTRY		Advisor Renee	Promised 01/21/2022 5:00 PM	Tag 761
		Shop MS	Opened 01/06/2022 8:26 AM	Location
		Priority 602	Cashiered	PO #

License No	Odometer In	Odometer Out	InServ Date	Stock No
	69109			
Year	Make	Model	Model No	Colour
2018	FORD	F-150	W1E	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FTFW1E5XJKF24975				
Engine Size 5.0L V8		Fleet #		

Home	Bus
Cell	Today
Email	
Term CASH	

Labour	(113.68)
Parts	0.00
Supplies	0.00
Warr Deductible	1,185.94
SUB-TOTAL	1,072.26
GST	53.61
TOTAL INVOICE	1,125.87

Additional Work Authorization

Date/Time	Contact	PhoneNumber	Comments	Amount
01/10/2022 5:20:52 PM	SHERA FORESTRY	(780) 623-8707		560.10

Recommended/Deferred Services

Code	Description	Amount
02HL01	Passenger side plate lamp assembly is missing replace the assembly	\$105.99
09EPM	Passenger side mirror glass is cracked, replace the glass.	\$231.10

** Deferred Services prices are subject to change

As part of our continued service, we may contact you via text message. Standards charges may apply.

Warranty Disclaimer: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSED BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY UNAVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR YOUR EMPLOYEE'S PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION.

UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT. I ACKNOWLEDGE THE EXISTENCE OF A MECHANICS LIEN IN FAVOR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN THE RESPECT OF THE MATERIAL SUPPLIED AND THE SERVICES RENDERED FOR THE FULL AMOUNT CHARGED. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN INVOICE/ACCOUNT IS PAID IN FULL. WHILE THE VEHICLE IS IN MY POSSESSION, IT SHALL BE SUBJECT TO REPOSSESSION ON DEMAND BY WITHIN INVOICE/ACCOUNT IS PAID IN FULL.

Important Privacy Information: Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford, please call 1-800-565-FORD (3673).

GST# 822567871 RT0001

X

SIGNATURE

REPAIR ORDER
R67672 (Copy)

pd Dec 9/2021
ck# 016225

SOLD TO:
SHEFOR
SHERA FORESTRY LTD

CONTACT:

MOBILE :
BUSINESS:
EMAIL :

HOME:
FAX :

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
WHITE	2018 FORD F150 4XX 5.0	CGL4809	147		61056
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
1FTFW1E5XJKF24975				AM	61056
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
1:08 PM		NET 30			61056
QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
2h	ML	CHECK OIL LEAK FRONT DIFF MECHANICAL LABOUR 21 Nov 09 DIAG OIL LEAK ON FRONT, REMOVE 2 WHEEL BARROWS OF MUD, TRACE LEAK TO FRONT PINION SEAL AND PLUGGED DIFF VENT. REPLACE SEAL AND TOP UP DIFF SEAL FORD NEW FREIGHT SPECIAL ORDER FROM FORD OASIS GEAR OIL SYNTHETIC PARTS CLEANER, PENETRATING OIL OASIS DIFFERENTIAL ADDITIVE POSI		68.50 22.50 19.95 9.95 21.95	280.00 68.50 22.50 39.90 9.95 21.95
1	MSS	SHOP/SERVICE/TOW TRUCK SUPPLIES Warranty on mechanical parts is subject to the manufacturer's offered warranty policy. Warranty term lengths vary by manufacturer. In some cases parts and/or labour may not be covered		23.80	23.80

BILL TO:

For your safety please ensure wheel fasteners are retorqued within the first 100 km's

TERMS AND CONDITIONS

I hereby authorize the repairs as listed above to be performed and completed. I acknowledge the shop supply fee of 8.5% to a max of \$80.00. Old parts will be disposed of after repair unless a core is charged or the customer requests them.

Signature: _____ Date: _____

PARTS: 162.80
LABOUR: 280.00
OTHER: 23.80
SUB-TOTAL: 466.60
GST/HST: 23.35
PST: N/C
TOTAL: 489.95

Avenir Mechanical Ltd

AVENIRMECHANICAL@outlook.com
780-520-2215



Invoice: 278

Date: 6/11/2021

Bill To
Sera Forestry Ltd.

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
1293	COD	6/11/2021	Simon		Plamondon, Cody	147a

Item	Description	Quantity	Rate	Amount
Complaint: No 4x4 and oil leak				
Cause: Customer request				
Labor	Correction: Chassis / Chassis / Repaired broken vacuum line and leveled out brake fluid that was way over full spewing out .	1.50000	\$125.00	\$187.50
Subtotal				\$187.50

Unit: 147a **VIN:** 1FTFW1E5XJKF24975
2018 Ford F-150
Chassis: 54,444 Kilometers

Labor	\$187.50
Shop Supplies	\$15.00
Pre Tax Total	\$202.50
GST (5.0000% of \$202.50)	\$10.13
Total	\$212.63
Payments & Credits	\$0.00
Balance Due	\$212.63

GST 839434594

CUSTOMER #:
UNIT# 155123

SHERA FORESTRY

HOME:
BUS:

CONT:
CELL:

DUPLICATE 1
PAGE 1

SERVICE ADVISOR: 9357 JAMIE MCARA

18208 Stony Plain Road
Edmonton, Alberta T5S 1A7
Phone: (780) 489-9999
TOLL FREE: 1-800-252-9303
Fax: (780) 930-3187
www.dennyandrewsford.com

COLOUR		YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/OUT		TAG
YZ		19	FORD F150 PICKUP		1FTFW1E48KFA69416	CHW3235	24023/24030		T601
IN SVC. DATE		PROD. DATE	WARR. EXP.	PROMISED	PD NO.	CASH PAY AMOUNT RATE	PAYMENT	INV. DATE	
04MAR19		DD07JAN19		17:00 16JUL21		0.00	OK	26JUL21	
R.O. OPENED		READY		OPTIONS: DLR:B6280 ENG:3.5_Liter_GTDI TRN:10SPEED					
13-54 15 JUL 21		08-27 26 JUL 21		AXL:3.31 1)UNIT 155123					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CONTACT IS TONY @ 780 623 0170
INFO INFORMATION LINE ONLY

99 CF 0.00 0.00 0.00 0.00 TOTAL LINE A: 0.00

B INSPECT FOR CUSTOMER STATES THERE IS LEAKING FROM TRANSMISSION PAN
S33 DIAGNOSE

8642 CF 139.95 139.95
S36 REPLACED TRANS PAN
8642 CF 587.79 587.79
1 HL3Z*7A194*C PAN ASY. - TRANSMISST 131.14 131.14
DEPOT
10 CXT*10*LVFLT MERCON LV 7.95 7.95 79.50
S36 INSTALLED AFTERMARKET METAL TRANS PLATE COVER
8642 CF 79.98 79.98
1 F150TRANNNY TRANS SPLASH SHIELD 345.00 250.00 250.00
PARTS: 460.64 LABOR: 807.72 OTHER: 0.00 TOTAL LINE B: 1268.36

5.70 SCAN TEST FOR TRANSMISSION DTC'S, P0C29 AND P0C2C PRESENT. R
AND R TRANSMISSION FLUID COOLER AND HEAT SHIELDS, REPLACED CRACKED
TRANSMISSION PAN AND RE-FILLED FLUID. INSTALLED METAL SKID PLATE UNDER
TRANSMISSION. CLEARED DTC'S AND TEST DROVE TO CONFIRM TRANSMISSION IS
SHIFTING PROPERLY. RE-SCANNED, NO DTC'S PRESENT. 8642

C VEHICLE WAS TOWED IN - SEE ADVISOR FOR MORE INFORMATION
INFO INFORMATION LINE ONLY

99 CF 0.00 0.00 0.00 0.00 TOTAL LINE C: 0.00

CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER 75.00

DENNY ANDREWS FORD
SALES

18208 STONY PLAIN RD NW
EDMONTON, AB T5S 1A7
7809303164

Cashier: JAMIE M.

Transaction 700484

Invoice #: 512390

Total

CA\$1,410.53

CREDIT CARD SALE CA\$1,410.53

VISA 6543

Station: Ranch Service

26-Jul-2021 9:53:37A

CA\$1,410.53 | Method: KEYED

MANUALLY ENTERED

Reference ID: 120700503607

Auth ID: 001366

AthNtwkNm:

SIGNATURE VERIFIED

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

Service Hours

MONDAY TO FRIDAY 7:00 am to 6:00 pm

SATURDAY
9:00 am to 4:00 pm