

206-36  
BLUE-MAR

**Coppertop Truck Repair**  
16638 110 ave  
Edmonton, AB T5P 1G9, CA  
accounts@coppertoptruck.com  
780-668-9068



Invoice: **33478**  
Date: **2/10/2026**

**Bill To**  
Ritchie Bros Auctioneer  
1500 Sparrow Drive  
Nisku, AB T9E 8H6, CA  
P: (780) 955-4609

**Remit Payment To**  
Bay #1  
16638 110 ave  
Edmonton, AB T5P 1G9, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
17036	Net 30	3/12/2026	Sarah Kirtzinger		Burchak, Kirk	Z06/36

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

**Complaint:** Traced out all wiring for s terminal. All is good no break, good continuity. Try cranking no power to s terminal. Scan truck no com to engine ecu. Checked all fuses and all has good power. Checked read out on lcd screen telling me can't read coms to ecu short to ground. Check power to ecu is good. Appears that we have an ecu issue. Jumped the starter to crank over engine and cranks over really well but can tell nothing turning on engine. At this point a dealer is needed to scope out all the wiring and confirm if the ECU needs to be replaced

**Cause:** Customer request

Labor	<b>Correction:</b> Engine / Starting & Charging / Drove to site located unit hooked up computer and found cpc not connecting and multiple can /data link codes active , went to check out wiring at cpc and found cpc is not plugged in and missing from truck . Advised unit will need to cpc installed to continue diagnosing. Pick up programmed cpc and drove back to site installed unit on truck and not truck will start and drive but still has check engine light on and 4 cpc configuration codes active , removed cpc went back to dealer to check programming and found codes that are active are for communication between multiple different modules and unit will need to be at dealer to be flashed properly , had dealer flash cpc back to factory settings instead of latest available version and went back to unit installed cpc again and tested but no change , unit will need to be brought to freightliner upon sale to have all modules programmed together and possible further diagnosis. As of right now unit will start run and drive . All good drove back . - Completed: 2/5 /2026	6.00000	\$136.50	\$819.00
Parts	cpc	1.00000	\$2,492.988	\$2,492.99
Parts	programming	1.00000	\$275.00	\$275.00
Parts	cpc core as its missing	1.00000	\$435.00	\$435.00
			<b>Subtotal</b>	<b>\$4,021.99</b>

**Unit:** Z06/36 VIN: 3AKJHHR8RSUU3140  
2024 Freightliner Cascadia  
**Chassis:** 275,423 Kilometers  
**Engine:** 0 Kilometers

<b>Labor</b>	<b>\$819.00</b>
<b>Parts</b>	<b>\$3,202.99</b>
<b>Shop Supplies</b>	<b>\$81.90</b>
<b>Pre-Charge Subtotal</b>	<b>\$4,103.89</b>
<b>GST</b> <b>(5% of \$4,103.89)</b>	<b>\$205.19</b>
<b>Total</b>	<b>\$4,309.08</b>
<b>Payments &amp; Credits</b>	<b>\$0.00</b>
<b>Balance Due</b>	<b>\$4,309.08</b>

GST #839565405

eTransfer payments can be made to [accounts@coppertoptruck.com](mailto:accounts@coppertoptruck.com)

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that Coppertop Truck Repair Ltd is not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you/or your employee's permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. If wheels have been removed as part of the above repairs than the driver must re-torque all wheels within 150 km. Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that Coppertop Truck Repair Ltd makes no warranties of any kind unless expressed in writing. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Vehicles left for more than 48 hours after completion may be subject to storage fees at a minimum of \$50 per day. Units that have been left for more than 90 days will be considered abandoned. Interest of 2.4% per month will be added to all outstanding invoices over 30 days.