



Hart Transmission Repair Ltd.
 110 Ordze Ave
 Sherwood Park, AB. T8B 1M6
 Phone: 780-467-1424 Fax: 780-464-1230
 GST # 865174643RC0001

V13-1
 BLUE-MAR

INVOICE
116992

Org. Est. # 013743

Choice from History

Printed Date: 01/13/2023

Work Completed: 01/11/2023

MUNDO UNDERGROUND
 3 MCKENZIE DRIVE
 RED DEERE, AB T4S2H4
 Home 780-886-7715

2005 Hino - 338 - Hino J08E 338 6 CYL

Lic #: CKV4893

Odometer In : 484287

Odometer Out : 484297

VIN #: 5PVNF8JR7 52S10042

Part Description	Qty	Sale	Ext	Labor Description	Ext
FLUIDMATIC LV ATF	11.50	10.68	122.82	DIAGNOSE FOR TRANSMISSION PROBLEM, UNIT	1,572.50
ALLISON SPIN ON FILTER	1.00	40.83	40.83	NEUTRALIZES AFTER DRIVING ON HWY. AND	
ALLISON TRANSMISSION GASKET	1.00	110.01	110.01	REPAIRS	
ALLISON BLACK FILTER	1.00	50.73	50.73	STARTED THE ENGINE AND CHECKED THE TRANSMISSION OIL	
MLPS EXTERNAL SWITCH	1.00	206.88	206.88	LEVEL AND FOUND NO FLUID ON THE DIPSTICK. FOUND	
EXTERNAL HARNESS REPAIR	1.00	133.44	133.44	MULTIPLE ENGINE OIL LEAKS, AND FOUND MULTIPLE	
HARNESS WITH CONNECTOR	1.00	216.06	216.06	TRANSMISSION OIL LEAKS MAINLY COMING FROM THE COOLER	
Shop Supplies			206.69	LINES AT THE TRANS. FOUND A COOLANT LEAK UP FRONT,	
				APPEARS TO BE COMING FROM THE RADIATOR HOSE	
				CONNECTION TO THE ENGINE. TOPPED UP THE	
				TRANSMISSION OIL 1.5L AND CYCLED THROUGH THE GEARS	
				AND THE GEAR ICON ON DASH TURNS ON AND PRNLD	
				INDICATOR ON DASH STOPPED WORKING. SCANNED UNIT FOR	
				CODES AND FOUND 4 PCM CODE, WON'T READ TRANSMISSION.	
				SHIFT TOWER SEEMS A BIT OUT OF ADJUSTMENT, BUT STILL	
				GOES THROUGH ALL THE GEARS. CHECKED ALL OF THE	
				CONNECTIONS AT THE NEUTRAL START BACKUP SWITCH AND	
				APPEARS TO BE OKAY. CHECKED THE VALVE BODY	
				CONNECTOR AND IT WON'T STAY LOCKED IN THE VALVE BODY	
				AND TRANSMISSION HOUSING AND ALSO FOUND OIL SEAPING	
				THROUGH THE BULKHEAD CONNECTOR IN THE	
				TRANSMISSION HOUSING. DRAINED THE TRANSMISSION OIL	
				AND REMOVED THE PAN. CLEANED UP THE SILICONE FROM	
				THE TRANSMISSION AND PAN. REPLACED THE NEUTRAL START	
				BACKUP SWITCH AND REPLACED INTERNAL VALVE BOD	
				HARNESS. REPLACED UNIT WITH A NEW SPIN ON FILTER AND	
				REINSTALLED THE PAN WITH A NEW GASKET AND INTERNAL	
				FILTER. REFILLED THE TRANSMISSION WITH FLUID. REPLACED	
				THE TRANSMISSION (TRUCK SIDE) HARNESS VALVE BODY	
				CONNECTOR. TOOK UNIT ON TEST DRIVE AND TOPPED UP	
				FLUIDS.	
				ELECTRONIC SCAN ON DIESEL UNIT	149.95
				PREFORM SCAN ON DIESEL VEHICLE. MONITOR AND RECORD	
				DTC'S AND/OR INFORMATION AVAILABLE	
				U1001: MALFUNCTION OF CAN COMMUNICATION	
				P0045: MALFUNCTION OF VNT	
				P0088: ABNORMALITY IN COMMON RAIL PRESSURE	
				U010: CON COMMUNICATION BLACKOUT (TRANSMISSION)	
				Hazardous Materials	52.06



Hart Transmission Repair Ltd.
 110 Ordze Ave
 Sherwood Park, AB. T8B 1M6
 Phone: 780-467-1424 Fax: 780-464-1230
 GST # 865174643RC0001

INVOICE

116992

Org. Est. # 013743

Invoice from History

Printed Date: 01/13/2023

Work Completed: 01/11/2023

MUNDO UNDERGROUND
 3 MCKENZIE DRIVE
 RED DEERE, AB T4S2H4
 Home 780-886-7715

2005 Hino - 338 - Hino J08E 338 6 CYL

Lic # : CKV4893

Odometer In : 484287

Odometer Out : 484297

VIN # : 5PVNF8JR7 52S10042

Part Description	Qty	Sale	Ext	Labor Description	Ext
------------------	-----	------	-----	-------------------	-----

Org. Estimate 3,005.07 Revisions 0.00 Current Estimate 3,005.07

Labor:	1,722.45
Parts:	1,087.46
HazMat:	52.06
SubTotal:	2,861.97
Tax:	143.10
Total:	3,005.07
Bal Due:	\$0.00

[Payments - MasterCard - \$3,005.07]

Vehicle Received: 2023-01-11

Customer Number : 17885

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

HART TRANSMISSION REPAIR LTD will not be held responsible for loss or damage to vehicle or items left in it. Labor & Parts are guaranteed for 1 year or 20,000kms, whichever occurs first. All other guarantees are made by the manufacturer. NO WARRANTY FOR DAMAGE DUE TO MISSUSE, ABUSE, OVERHEATING OR VEHICLE MODIFICATIONS. WARRANTY IS NON TRANSFERABLE. ***WHEELS MUST BE RETORQUED WITHIN 200KM IF REMOVED*** ALL WARRANTY CLAIMS MUST BE REPAIRED IN HOUSE, TOWING CHARGES ARE NOT COVERED.

Signature _____ Date _____

Visit us on the web: www.harttransmission.ca

Email Address: info@harttransmission.ca

Service Advisor : D, Stacy, Tech :

Gallant Mechanical

211 27240 Twp Rd 392
 Red Deer County, AB T4S1X5
 Phone: (403) 505-0302
 E-mail: gallantmechanical@gmail.com

INVOICE

Date Invoice #
 7/23/2021 2221

Invoice To

Etherington Excavating
 121-23045 Twp Rd 514
 Sherwood Park, AB T8B 1K9

Serviced	Item	Description	Hours	Rate	Amount
7/16/2021	Shop	V 07. Hino. 472,731 km Inspected truck. Ordered parts	1	100.00	100.00
7/22/2021	Shop	Drained transmission fluid. Pulled pan. cleaned and flushed system and oil cooler. Installed pan and new filter. Filled with fluid. Ran and topped fluid.	6.5	100.00	650.00
	Supplies			15.00	15.00
	Parts T1			482.33	482.33

Regular rate applied from 7:00am - 7:00pm
 \$15/hr Additional After hours rate applied

DUE UPON RECEIPT!
 2% Interest charged on 30 days past due

Subtotal \$1,247.33

GST@5.0%
 62.37

Total \$1,309.70

Make Cheques payable to Gallant Mechanical. If you have any questions concerning this invoice, please contact Mike Klassen @ (403) 505-0302

GST/HST No. 839054418

THANK YOU FOR YOUR BUSINESS!

Gallant Mechanical

211 27240 Twp Rd 392
 Red Deer County, AB T4S1X5
 Phone: (403) 505-0302
 E-mail: gallantmechanical@gmail.com

INVOICE

Date Invoice #
 6/24/2021 2194

Invoice To

Etherington Excavating
 121-23045 Twp Rd 514
 Sherwood Park, AB T8B 1K9

Serviced	Item	Description	Hours	Rate	Amount
6/23/2021	Truck 1	Hino Truck. 472,404 km Ran truck and tested cooling system. Pressure tested turbo and EGR cooler. Inspected and flushed rad out. Tested fan to make sure it is working properly. Drained coolant and removed thermostat. Tested and found it was not opening properly. Ordered new one. Installed new thermostat and filled with coolant. Test ran truck and all temps are proper. Coolant flow is good now.	7	100.00	700.00
	Supplies Parts T1			14.00 126.29	14.00 126.29

Regular rate applied from 7:00am - 7:00pm
 \$15/hr Additional After hours rate applied

DUE UPON RECEIPT!
 2% Interest charged on 30 days past due

Subtotal \$840.29

GST@5.0% 42.01

Total \$882.30

Make Cheques payable to Gallant Mechanical. If you have any questions concerning this invoice, please contact Mike Klassen @ (403) 505-0302

GST/HST No. 839054418

THANK YOU FOR YOUR BUSINESS!

Murrys Truck Parts Locators

BOX 1221
 47017-HWY 21
 CAMROSE, Alberta T4V 1X2
 Canada
 murry11@syban.net

INVOICE

Invoice No.: 12643
 Date: 03/09/2021
 Ship Date:
 Page: 1
 Re: Order No. 4171

Sold to:

ETHERINGTON EXCAVATING
 DWIGHT
 121-23045 TWP RD514
 SHERWOOD PARK, AB T8B 7K9

Ship to:

ETHERINGTON EXCAVATING
 DWIGHT
 121-23045 TWP RD514
 SHERWOOD PARK, AB T8B 7K9

Business No.: 811512904RT0001

Item No.	Unit	Quantity	Description	Tax	Base Price	Disc %	Unit Price	Amount
HOP 51120	Each	1	2005 HINO SN# 5PVNF8JR752S10042 ODO; 471226 KMS GET TRAILER HITCH MADE & WIRE IN BRAKE CONTROLLER & LIGHT PLUG ELEC BRAKE CONTROLLER 2-4-6 WHEEL	G	120.00		120.00	120.00
PIC 9483-BP	Each	1	7 WAY RV FEMALE SOCKET	G	11.50		11.50	11.50
PRE 160	Each	1	PINTLE HITCH	G	275.00		275.00	275.00
PIC 988-BP	Each	2	12GA FUSE HOLDER W/CAP	G	4.35		4.35	8.70
PIC 5142-B	Each	7	1/2 HI TEMP SPLIT LOOM	G	0.90		0.90	6.30
PIC 8148-C	Each	32	2 WIRE 14 GA CABLE	G	1.00		1.00	32.00
SS	Each	14	10 GAUGE WIRE	G	0.40		0.40	5.60
PIC 889P-11	Each	1	BRASS POS BATTERY TERM	G	13.00		13.00	13.00
WELDING	Each	1	BUILD AND INSTALL TRAILER HITCH	G	1,800.00		1,800.00	1,800.00
TEC 76-8581	Each	6	4 WIRE 14GA CABLE	G	1.80		1.80	10.80
LABOUR	Each	6	WIRED IN AND INSTALLED BRAKE CONTROLLER, RAN WIRE TO REAR OF TRUCK, INSTALLED RV PLUG & WIRED IN LIGHTS & CONTROLLER TO PLUG	G	120.00		120.00	720.00
SS	Each	1	SHOP SUPPLIES	G	42.00		42.00	42.00
Subtotal:								3,044.90
G - GST 5%								152.26
GST								

Shipped By:	Tracking Number:	Total Amount	3,197.16
Comment:	THANK YOU FOR YOUR BUSINESS. WE ARE GRATEFUL.	Amount Paid	0.00
Sold By:	MURRY SHERMACK	Amount Owing	3,197.16