



**Truck Doctor Inc**  
 1-3952 52 St SE  
 Calgary, AB. T2B3H1  
 Phone: 587-971-6444 Fax: 000- -

Job-1  
 #41

**INVOICE**  
**5900**

d0855

**Invoice from History**

Printed Date: 02/04/2026 Work Completed: 02/03/2026

**Alpha Mega Towing Services - Kingsley**

2015 International - WorkStar Series - 7600 - International N13 I  
 Lic # : Odometer In : 396104

Cellular

VIN # : 1HTGSSNT4 FH604994

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
New FLT Brake Shoe FLT4707QP23KNSP	4.00	85.04	340.16	CVIP Inspection Symptoms: Commercial Vehicle Inspection	312.50
Drum, Brake FLT4400B	4.00	133.40	533.60	Remove Wheels Inspect Brakes Symptoms: Inspect Brakes	200.00
Tie Rod Assembly ZCPQT108SB	1.00	570.09	570.09	Diag - Check Engine Light (Non Safety) - Connected diagnostic laptop and retrieved fault codes related to fog lights. Repaired fog light circuits/connections as needed. Verified operation of fog lights and cleared codes. Engine warning light resolved following repairs.	62.50
Serpentine Belt 3815648C2	1.00	96.73	96.73	Replace - A2 & A3 Brake Shoes - Tapered (Safety)	187.50
V-Belt, Fan 3664150C2	1.00	100.53	100.53	Install new drums Replace - A2 & A3 Drums - Tapered & Heat Cracked (Safety)	62.50
Windshield Windshield	1.00	361.11	361.11	Replace - Tie Rod Assembly (Safety)	187.50
Wiper Blade TRICO37225	2.00	16.77	33.54	Replace - ACC Belt	125.00
BULB FLTH355W	1.00	10.27	10.27	Replace - Fan Belt	125.00
Shop Supplies			141.00	Replace - Both Wiper Blades (Safety)	31.25
				Install - Silver Tape (Safety)	62.50
				Replace - Red & White Tape on Side - Damaged (Safety) Removed old deteriorated reflective tape. Scraped and cleaned mounting surfaces to remove adhesive residue, dirt, and contamination. Prepped surfaces to ensure proper adhesion and installed new reflective tape per regulations.	250.00
				Replace - Fog Lights - Inop (Safety) - Removed and inspected front/rear lights. Found corroded/dirty ground connections inside lights; cleaned and reinstalled to restore proper function. Replaced H3 bulb in fog light. Verified all lights operating correctly.	125.00
				Repair - Mudflap Bolt - Missing (Safety)	31.25



**Truck Doctor Inc**  
 1-3952 52 St SE  
 Calgary, AB. T2B3H1  
 Phone: 587-971-6444 Fax: 000- -

**INVOICE**

**5900**

d0855

**Invoice from History**

Printed Date: 02/04/2026 Work Completed: 02/03/2026

**Alpha Mega Towing Services - Kingsley**

2015 International - WorkStar Series - 7600 - International N13 I  
 Lic # : Odometer In : 396104

VIN # : 1HTGSSNT4 FH604994

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----

Org. Estimate 4,147.01 Revisions 0.00 Current Estimate 4,147.01

<b>Labor:</b>	<b>1,762.50</b>
<b>Parts:</b>	<b>2,187.03</b>
<b>SubTotal:</b>	<b>3,949.53</b>
<b>Tax:</b>	<b>197.48</b>
<b>Total:</b>	<b>4,147.01</b>
<b>Bal Due:</b>	<b>\$0.00</b>

[ Payments - Visa - \$4,147.01 ]

Vehicle Received: 2026-02-03

Customer Number : 293

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

All customer supplied parts WILL NOT be warrantied.

**\*\*Interest After 30 Days\*\***

We will be charging a 1.5% interest fee on all invoices that are not paid within 30 days. This fee is designed to encourage timely payment and help us manage our cash flow.

Signature \_\_\_\_\_ Date \_\_\_\_\_

Visit us on the web: [www.truckdoctor.ca](http://www.truckdoctor.ca)

Email Address: [Rob@truckdoctor.ca](mailto:Rob@truckdoctor.ca)