

6/31
3 Y

Maxi Pots: Slack Adjusters: Camshafts: Brakes Adjusted:

Lights: Light Plugs: Junctions:

Air System: Valves: Air Lines: Air Tanks: Glad Hands:

Suspension: Springs: NA U-bolts: Airbags: Shocks: Slider: NA

King Pin: NA Winches/J-hooks: NA Decking: NA

Doors: NA Door Hold Back: NA Side Panels: NA

Landing Gear: NA Greased: NA Dolly Cranks: NA Support Braces: NA

Structure: Frame: Bumper: Tie Rails: NA

All wheel nuts torqued: 500 lbs

Has the trailer been completely greased?

Torque all wheels to specs:

COMMENTS:

- ^{Right} ~~Left~~ wheel seal leaks
- needs reflective tape
- lots of lights not working

Signature: [Signature]

Date: June 2, 2025

BOOSTER 428

M.K.S. Trailer & Equipment Repairs Ltd

716 Carter Crest Way
Edmonton, Alberta T6R 2N3
Shop: 780-451-3861
Cell: 780-966-2963

INVOICE 77593

DATE: JUL 15 2024

QTY.	PART NO. AND DESCRIPTION	PRICE
8	³ / ₈ " x 1 1/2" bolts, nuts, fender & flat washers	6108
20	E6000A	5620
2	66305	1.88
4	66462	1224

NAME BOYD VENTURES		
ADDRESS RR 3, Site 302, Comp 88		
CITY ONOWAY		PROVINCE AB.
POSTAL CODE TOE 1V0		PURCHASE ORDER
LICENSE NO. 6SH575	YEAR 2009	MAKE/MODEL Gerrys
SERIAL NO. 2A9TD10179N125186		UNIT NO.

Provide replacement sticker
 Installed mudflaps properly
 Installed tires
 Checked air & lights
 Drill holes in pins on step deck and provide retaining pins

3 hrs 115 ⁰⁰	TOTAL LABOR	345.00
	TOTAL PARTS	76.40
	SHOP SUPPLIES	18.00
	SUB TOTAL	439.40
	GST # 877828343	21.97
	TAX	
	TOTAL	461.37