

Sold to:

023.20
MAY

Envirobore Drilling Ltd
Ryan Bowes
26103 Hwy 12
Lacombe County, AB T4L 0H6

Item	Qty	Unit	Description	Unit Price	Amount
A CVIP - Truck (2A) Service (Hourly)	1 12	Each Hrs	Tandem Drive Axle Truck - Type A Brake Inspection (Drum Off) See Items Listed Below Free up and lube slack aduster pins Replaced leaky dash control valve Adjusted clutch Replaced leaking exhaust flex pipes under right side cab Replaced 1RS wheel seal Replaced 3LS wheel seal Replaced 2LS axle gasket Tightened clamp on power steering hose off of bottom of reservoir Replaced junction box on deck between #2 & #3 axles with crushed and shorted wires Replaced wire from junction box to left & right rear deck markers Replaced wire from junction box to right mid turn/marker light Replaced fuse for deck marker lights Repaired ground wiring to right tail/stop/turn light Repaired loose right tail light panel Repaired front left fender turn signal light	700.00 170.00	700.00 2,040.00
Part	1	Ea	MV3 Dash Valve (800840)	493.28	493.28
Part	2	Ft	4" SS Flex Exhaust Pipe	40.00	80.00
Part	4	Ea	4" SS Exhaust Clamp	21.50	86.00
Part	1	Ea	4" U-Bolt Exahust Clamp	15.00	15.00
Part	1	Ea	Steer Axle Wheel Seal	82.95	82.95
Part	1	Ea	Wheel Hub Oil	10.00	10.00
Part	1	Ea	Drive Axle Wheel Seal	92.95	92.95
Part	1	Ea	Axle Gasket	8.50	8.50
Part	1	Ea	Wiring Junction Box	18.50	18.50
Part	1	Lot	Wire & Wiring Supplies	40.00	40.00
Parts	1	Lot	Misc. & Shop Supplies	25.00	25.00
Freight	1	Ea	Freight Charges	38.00	38.00
			Subtotal:		3,730.18
			G - GST 5%		
			GST		186.52
				Total	3,916.70