

K&A Repairs Ltd.

102-9390 Rock Island Rd
 Prince George, British Columbia V2N 5T4
 Canada
 karepairsLtd@gmail.com

INVOICE

Invoice No.: 3896
 Date: 2025-10-07
 Ship Date:
 Page: 1
 Re: Order No.

Sold to:

ZERO POINT CONTRACTING LTD.
 BUTCH HILMAN
 BOX 3835
 SPRUCE GROVE, AB T7X 3B1

Ship to:

ZERO POINT CONTRACTING LTD.
 BUTCH HILMAN
 BOX 3835
 SPRUCE GROVE, AB T7X 3B1

Business No.: 795858687RT0001

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
TRCVI	Each	1.0	TRAILER INSPECTION UNIT#290 VIN#078720 REG#13365291 DECAL#GK56906 - REPLACED #1 LH AND RH CAMS, CAM TUBES, BRAKES, AND BRAKE ANCHOR PINS REPLACED #2 LH AND RH BRAKES REPLACED #2 LH GREASE HOSE REPLACED #2 LH AIR BAG CHAIN LINK TROUBLESHOOT ABS REPLACED #2 LH ABS LEAD REPAIRED #2 RH ABS LEAD REPLACED OUTSIDE REAR MARKERS AND PIGTAILS REPLACED ABS LIGHT AND PIGTAIL REPLACED #2 RH MAXI PUSHROD REPLACED #3 LH CLAMP AND DIAPHRAGM MODIFIED BUMPER MOUNTS ON TRUCK TO TAKE NEW BUMPER INSTALLED BUMPER AND WIRED LIGHTS - **RETORQUE #1 AND #2 LH AND RH TIRES 150 KM** -	GP	200.00	200.00
LABOUR	Each	20.5	LABOUR	GP	140.00	2,870.00
SS	Each	20.5	SHOP SUPPLIES	GP	9.80	200.90
			-			
SUPPLIED PARTS	Each	3.0	SEAL	GP	7.40	22.20
SUPPLIED PARTS	Each	4.0	BRAKE SHOE	GP	29.92	119.68
SUPPLIED PARTS	Each	6.0	HARDWARE KIT	GP	18.21	109.26
SUPPLIED PARTS	Each	1.0	BRACKET	GP	21.79	21.79
SUPPLIED PARTS	Each	2.0	CAMTUBE	GP	165.46	330.92
SUPPLIED PARTS	Each	2.0	PIGTAIL	GP	5.75	11.50

Comment: FOR ANY QUESTIONS OR CONCERNS CALL ASHLEY @ 250-640-7651

Continue...

K&A Repairs Ltd.

102-9390 Rock Island Rd
 Prince George, British Columbia V2N 5T4
 Canada
 karepairsLtd@gmail.com

INVOICE

Invoice No.: 3896
 Date: 2025-10-07
 Ship Date:
 Page: 2
 Re: Order No.

Sold to:

ZERO POINT CONTRACTING LTD.
 BUTCH HILMAN
 BOX 3835
 SPRUCE GROVE, AB T7X 3B1

Ship to:

ZERO POINT CONTRACTING LTD.
 BUTCH HILMAN
 BOX 3835
 SPRUCE GROVE, AB T7X 3B1

Business No.: 795858687RT0001

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
SUPPLIED PARTS	Each	1.0	ABS LIGHT	GP	10.49	10.49
SUPPLIED PARTS	Each	1.0	PIGTAIL	GP	2.51	2.51
SUPPLIED PARTS	Each	2.0	LED AMBER	GP	14.21	28.42
SUPPLIED PARTS	Each	2.0	LED RED	GP	13.44	26.88
SUPPLIED PARTS	Each	2.0	CLAMP	GP	8.19	16.38
SUPPLIED PARTS	Each	2.0	DIAPHRAGM	GP	13.98	27.96
SUPPLIED PARTS	Each	1.0	PUSHROD	GP	35.54	35.54
SUPPLIED PARTS	Each	1.0	FITTING	GP	7.43	7.43
SUPPLIED PARTS	Each	1.0	LED LIGHT	GP	28.50	28.50
SUPPLIED PARTS	Each	1.0	GREASE WHIP	GP	12.22	12.22
SUPPLIED PARTS	Each	1.0	COUPLER	GP	3.51	3.51
SUPPLIED PARTS	Each	1.0	MID LINK	GP	14.51	14.51
SUPPLIED PARTS	Each	1.0	ABS SENSOR	GP	22.36	22.36
			-			
			PARTS SUBTOTAL = \$852.06			
			-			
			Subtotal:			4,122.96
			GP - GST 5%, PST 7%			
			GST/HST			206.17
			PST			288.64
K&A Repairs Ltd. GST/HST: #705858687rt001						
K&A Repairs Ltd. PST: #11042471						
Shipped By: Tracking Number:					Total Amount	4,617.77
Comment: FOR ANY QUESTIONS OR CONCERNS CALL ASHLEY @ 250-640-7651					Amount Paid	0.00
Sold By:					Amount Owing	4,617.77