



**DRAYTON VALLEY TRUCK AND TRL**  
 7-1631 HAMMOND CRES  
 Edmonton, AB. T6M 0T2  
 Phone: (780)-514-0888  
 www.dvttts.ca | malcolm@dvttts.ca  
 DONE RIGHT THE FIRST TIME

*C40-16  
JUN*  
 Invoice # 000805  
 Original Est # 825

**Invoice**

**Balance Due: \$3,605.62**

**NEWAY OILFIELD SERVICE...**  
 18 WESTWARD COURT  
 FORT SASKATCHEWAN, AB. T8...  
 Home: 403-846-6954

**2013 HEIL TANKER - TRA/REM**  
 VIN: 5HTDL4931 E5L26912  
 Odometer: In 1 Out 1

License Plate: AB  
 Color:  
 Unit: 319

Work Complete: 09-25-2025  
 Service Advisor: Malcolm Tshu...  
 Customer ID: 101

Type	Description	Part #	Qty/Hr	Sale/Rate	Total
<b>REMOVE WHEELS FOR INSPECTION</b>					<b>\$390.00</b>
Labor	REMOVE WHEELS FOR INSPECTION REMOVED WHEELS FOR INSPECTION		3.00 hr	\$130.00	\$390.00
Parts:	\$0.00	Labor:	\$390.00	Tax:	\$19.50
					Total: \$390.00
<b>A INSPECTION AND SERVICE</b>					<b>\$372.00</b>
Part	CVIP THREE AXLE	CVIP 3	1.00	\$372.00	\$372.00
Parts:	\$372.00	Labor:	\$0.00	Tax:	\$18.60
					Total: \$372.00
<b>REPAIR 2 WHEEL SEAL LEAKS</b>					<b>\$803.28</b>
Labor	REPAIR 2 WHEEL SEAL LEAKS REMOVED HUB AND CLEANED PARTS THEN INSTALLED ADJUSTING BEARING TO SPEC. REPLACED SOAKED BRAKE SHOES. INNER WHEEL BEARING WAS STUCK ON THE SPINDLE.		6.00 hr	\$130.00	\$780.00
Part	FS5990-LARGE WHEEL HUB PLUG	STE3595990	6.00	\$3.88	\$23.28
Parts:	\$23.28	Labor:	\$780.00	Tax:	\$40.16
					Total: \$803.28
<b>REPLACE THREE S-CAM TUBES AND BUSHINGS</b>					<b>\$1,433.72</b>
Labor	REPLACE THREE S-CAMS AND TUBES ON P/S REPLACED S-CAMS AND TUBE ON FIRST AXLE THEN HAD TROUBLE WITH THE LAST TWO. THE S-CAMS WERE SEIZED IN THE SLACK ADJUSTER. ENDED UP CUTTING THE HEAD OF THE S-CAMS THEN THE NECKS TO REMOVE THEM, THEN PRESSED OUT THE S- CAMS. INSTALLED NEW S-CAMS AND TUBES.		11.00 hr	\$130.00	\$1,430.00
Part	CLEVIS PINS	ANCSB10031	2.00	\$1.86	\$3.72
Parts:	\$3.72	Labor:	\$1,430.00	Tax:	\$71.69
					Total: \$1,433.72
<b>REPAIR BURNT LIGHTS</b>					<b>\$130.00</b>
Labor	REPAIR BURNT LIGHTS		1.00 hr	\$130.00	\$130.00
Parts:	\$0.00	Labor:	\$130.00	Tax:	\$6.50
					Total: \$130.00
<b>REAR AIRBAG FOLDED IN</b>					<b>\$130.00</b>
Labor	REAR AIRBAG FOLDED IN		1.00 hr	\$130.00	\$130.00
Parts:	\$0.00	Labor:	\$130.00	Tax:	\$6.50
					Total: \$130.00
<b>Order</b>					<b>\$174.92</b>
Misc	Haz Mat.				\$11.97

Order [Continued]

\$174.92

Misc Shop Supplies

\$162.95

Total: \$174.92

**Thank you for your business.**

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. All repairs or part sales will be paid upon completion of requested tasks. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts are based on the manufacturer's policy and are processed by Drayton Valley Truck and Trailer Service inc. (DVTTS) only if supplied by DVTTS and labor is three months as long as it is not a failed part issue. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Labor	\$2,860.00
Parts	\$399.00
HazMat	\$11.97
Supplies	\$162.95
<b>Subtotal</b>	<b>\$3,259.00</b>
Labor Tax	\$143.00
Parts Tax	\$28.70
<b>Order Total:</b>	<b>\$3,605.62</b>

Signature \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_