

R04-10
JUN

Hopf Mechanical & Hydraulics
660 Aquaduct Drive East
Box 1658
Brooks, AB T1R 1C5, CA
admin@hopfmechanical.com
403-501-0190



Invoice: **29094**
Date: **2/17/2026**

Bill To
Rafter 9 Oilfield Services

Remit Payment To
Hopf Mechanical & Hydraulics
660 Aquaduct Drive East
Box 1658
Brooks, AB T1R 1C5, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
16160	Net 45	4/3/2026	Darcy Wotherspoon		T-1

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: CVIP

Cause: Customer request

Labor	Correction: Chassis / Chassis / CVIP TRAILER 3 AXLE WITH WHEELS OFF COMPLETE INSPECTION AND DO PAPERWORK	4.30000	\$135.00	\$580.50
			Subtotal	\$580.50

Complaint: REPLACE SUSPENSION BUSHINGS

Cause: Customer request

(Inspection)

Labor	Trailer / Suspension / REPLACE SUSPENSION BUSHINGS	6.00000	\$135.00	\$810.00
Parts	PIVOT BUSH KIT - S-24691	6.00000	\$209.00	\$1,254.00
Parts	WASHER ECCENTRIC - S-20925	1.00000	\$32.85	\$32.85
Parts	FLANGED INNER WASHER - S-20924	2.00000	\$32.88	\$65.76
			Subtotal	\$2,162.61

Complaint: REPLACE BRAKES AND SCAMS AS NEEDED

Cause: Customer request

(Inspection)

Labor	Trailer / Brakes / REPLACE BRAKES AND SCAMS AS NEEDED	6.50000	\$135.00	\$877.50
Parts	CAM 15 28SP - CAM349L	1.00000	\$48.63	\$48.63
Parts	CAM 1.5 28SP - CAM349R	1.00000	\$48.63	\$48.63
Parts	CAM ENCLOSURE KIT - CSK4181	2.00000	\$28.36	\$56.72
Parts	SEAL,WHEEL - 372-7099	2.00000	\$78.79	\$157.58
Parts	HUB CAP W/3118 - 343-4195	2.00000	\$74.22	\$148.44
Parts	HUB CAP GASKET - 330-3118	1.00000	\$5.45	\$5.45

Parts	3600A DRUM 16.5X7 - 3600A	4.00000	\$126.23	\$504.92
Parts	BRAKE SHOE KIT (TRB046S23-6N) - 4707QP	4.00000	\$85.95	\$343.80
Parts	75W90 SYNTHETIC GEAR OIL - 75W90	3.00000	\$15.15	\$45.45
			Subtotal	\$2,237.12

Complaint: REPAIR AIR LEAK FROM RELAY VA;VE

Cause: Customer request

(Inspection)

Labor	Trailer / Brakes / REPAIR AIR LEAK FROM RELAY VA;VE	1.00000	\$135.00	\$135.00
Parts	AIR VALVE - 102626X	1.00000	\$55.91	\$55.91
Parts	BRASS FITTING - BRASS	6.00000	\$9.81	\$58.86
			Subtotal	\$249.77

Complaint: REPAIR ABS LIGHT ON

Cause: Customer request

(Inspection)

Labor	Correction: Trailer / Brakes / REPAIR ABS LIGHT ON REPAIR WIRING TO ABS VALVE	1.50000	\$135.00	\$202.50
			Subtotal	\$202.50

Complaint: LIGHTS WIRING AND REFLECTIVE TAPE

Cause: Customer request

(Inspection)

Labor	Chassis / Lighting & Electrical / LIGHTS WIRING AND REFLECTIVE TAPE	1.00000	\$135.00	\$135.00
			Subtotal	\$135.00

Complaint: FENDER AND LANDING GEAR REPAIR

Cause: Customer request

(Inspection)

Labor	Correction: Chassis / Frame / FENDER AND LANDING GEAR REPAIR WELD BRACKETS FOR LANDING GEAR AND FENDER BRACKETS	2.00000	\$135.00	\$270.00
			Subtotal	\$270.00

FREIGHT/SHIPPING

1.00 \$0.00 \$0.00

Unit: T-1 VIN: 1T0SL47397S000151

License Plate: 6MK6-03

2007 Trail-rite

Labor	\$3,010.50
Parts	\$2,827.00
Shop Supplies	\$240.84
Pre-Charge Subtotal	\$6,078.34
FREIGHT/SHIPPING	\$0.00
GST	\$303.92
(5% of \$6,078.34)	
Total	\$6,382.26
Payments & Credits	\$0.00
Balance Due	\$6,382.26

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.