

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780-

*C17-10
JUN*

INVOICE

35485

INVOICE

Date: 06/07/2021

PLATINUM HYDROVAC AND HDD

3135-4TH STREET

NISKU, ALBERTA T9E 8L1

Home 780-440-1152 -- Office 780-886-8148

2017 ROADCLIPPER - TRI AXLE TRAILER UNIT#TR263 -

Lic # : 5GC248

Unit # : UNIT#TR263

VIN # : 46UFU2234 H1183501

Odometer In : 0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----

Shop Supplies

6.50

(1) REPAIRS AS REQUIRED ON SITE

130.00

* OPERATOR COMPLAINED OF DECK NOT TILTING. FOUND SAFETY LATCH SEIZED. ATTEMPT TO FREE-UP, WITH NO LUCK. UNIT NEEDS TO COME BACK TO SHOP FOR REPAIRS.

Org. Estimate 143.33 Revisions 0.00 Current Estimate 143.33

Labor:	130.00
Parts:	6.50
SubTotal:	136.50
Tax:	6.83
Total:	143.33
Bal Due:	\$143.33

[Payments -]
Vehicle Received: 6/7/2021

STK-7

Customer Number : 3735

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780-

INVOICE

33952

Org. Est. # 050701

INVOICE

Date: 11/05/2020

PLATINUM HYDROVAC AND HDD

3135-4TH STREET
NISKU, ALBERTA T9E 8L1
Home 780-440-1152 -- Office 780-886-8148

2017 ROADCLIPPER - TRI AXLE TRAILER UNIT#TR263 -
Lic # : 5GC248 Odometer In : 0
Unit # : UNIT#TR263
VIN # : 46UFU2234 H1183501

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
MALE TRAILER PLUG-STK 12-706	1.00	6.66	6.66	(1) INSPECT FOR TILT LATCH BEING SEIZED, AND PLUG NEEDING REPLACEMENT?	325.00
3/4" LED RED LIGHT/GROMMET-STK 33050-R	1.00	9.59	9.59	* REPLACE PLUG AND WHIP CORD * UNSEIZE TILT LATCH * INSTALL BALL STYLE HITCH * VERIFY 2 ARGOS FIT	
3/4" LED AMBER LIGHT/GROMMET-STK 33050-Y	1.00	13.09	13.09	* REPLACE 2 MARKER LIGHTS * REPLACE BREAKAWAY BATTERY * CHECK OVER UNIT	
BREAKAWAY BATTERY-STK 2023	1.00	41.57	41.57	* REMOVE TOOL BOX AND BRACKETS FROM DECK (2) PERFORM INSPECTION AS PER CHECKLIST, SERVICE UNIT AS REQUIRED (OIL SAMPLE IF REQ), VERIFY OPERATIONS.	65.00
2 5/16" HITCH COUPLER-ORDER NTP81906	1.00	43.78	43.78	* SEE ABOVE	
HITCH CHANNEL MOUNT-ORDER NTP8978XL	1.00	44.24	44.24		
3/4 HITCH PLATE-ORDER NTP716625750	1.00	150.84	150.84		
Shop Supplies			19.50		

Org. Estimate 286.65 Revisions 0.00 Current Estimate 286.65

Labor:	390.00
Parts:	329.27
SubTotal:	719.27
Tax:	35.96
Total:	755.23
Bal Due:	\$755.23

[Payments -]
Vehicle Received: 2020-10-29

GST#865376503RT0001

Signature _____ Date _____

Customer Number : 3735

STK-91

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

033952

Org. Est. # 050701

REPAIR ORDER - RO

Scheduled : 10/29/2020 04:17 PM

Print Date : 10/29/2020

PLATINUM HYDROVAC AND HDD
3135-4TH STREET
NISKU, ALBERTA T9E 8L1
Home 780-440-1152 --- Office 780-886-8148
Cust ID :
Last Service : 2018-02-16

2017 ROADCLIPPER - TRI AXLE TRAILER UNIT#TR263 -
Lic # : 5GC248 - ALBERTA
Unit # : UNIT#TR263
VIN # : 46UFU2234 H1183501
MFG Date : 9/18/2017
Current Odom : 0
Elapsed : 0

<i>Labor Requested / Part SubTotal</i>	Extended
(1) INSPECT FOR TILT LATCH BEING SEIZED, AND PLUG NEEDING REPLACEMENT?	65.00
(2) PERFORM INSPECTION AS PER CHECKLIST, SERVICE UNIT AS REQUIRED (OIL SAMPLE IF REQ), VERIFY OPERATIONS.	195.00
Shop Supplies	13.00
	Parts Subtotal 0.00

Parts: 0.00
Labor: 260.00

Supplies: 13.00

Tax: 13.65

Total: 286.65
Balance: 286.65

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

2017 ROADCLIPPER - TRI AXLE TRAILER UNI

Hat # :

Repair Order #

VIN # : 46UFU2234 H1183501

Color :

033952

Engine :

Location :

Lic # : 5GC248

Lic. State : ALBERTA

PLATINUM HYDROVAC AND HDD

Home 780-440-1152 --- Office 780-886-8148

Schedule : 10/29/20 4:30 P.M.

Promised Date : 10/29/20 5:00 P.M.

Inspection Date : 9/18/17

Status :

Last Service : 2/16/18

Unit # : UNIT#TR263

Current Odometer : 0

Trans :

Previous Mileage : 0

Brakes :

Elapsed Mileage : 0

Manufacture Date : 9/18/17

Labor Description

Charged Hours

<input type="checkbox"/> (1) INSPECT FOR TILT LATCH BEING SEIZED, AND PLUG NEEDING REPLACEMENT?	1.00
Technician : <none>	
<input type="checkbox"/> (2) PERFORM INSPECTION AS PER CHECKLIST, SERVICE UNIT AS REQUIRED (OIL SAMPLE IF REQ), VERIFY OPERATIONS.	3.00
Technician : <none>	

OUT ODOMETER :

Total Hours Charged : 4.00

Hours out: 0.00

Tech Notes
