

#162 402-49 SEP



CUSTOMER #:
UNIT# R162

110991

PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1-844-526-4460

RONCO OILFIELD HAULING LTD.
BOX 338
MEDICINE HAT, AB T1A 7G1
HOME: CONT:403-526-4873
BUS: 403-526-4873 CELL:

INVOICE

PAGE 1

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
RED	14	KENWORTH T800	1NKDX4TX8ER968149	J35740	747485/747485	190845

IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
18OCT13 DD			11:02 08NOV25	162-1129	192.00	CHG	29NOV25

R.O. OPENED READY OPTIONS: STK:ER968149 DLR:M068 ENG:79669441

14:51 03NOV25 11:40 29NOV25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A ENGINE HOURS 18621
EH ENGINE HOURS 18621
9999 C 0.00 0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00
747485

B Peterbilt Platinum Courtesy Inspection
PPCI Peterbilt Platinum Courtesy Inspection
7001 C 0.00 0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00
747485 7001-PERFORM COURTESY INSPECTION.

C DIAGNOSE AND ADVISE ON ENGINE KNOCK
04-100 DIAGNOSE AND ADVISE ON ENGINE KNOCK
7001 CL 775.00 775.00
PARTS: 0.00 LABOR: 775.00 OTHER: 0.00 TOTAL LINE C: 775.00
747485 7001- BRING UNIT INTO SHOP FOUND ENGINE HAS FUEL KNOCK

NOISES. CONNECT TO ENGINE ECM AND CHECK CODES FOUND NO RELATED CODES
CLEAR CODES. WARM UP UNIT AND PERFORM 2 BACK TO BACK IPT TEST FOUND #2
AND #5 INJECTORS FAILED BOTH TIMES. REMOVE EGR CROSSOVER TUBE AND
REMOVE VALVE COVER INSPECT CAMSHAFT FOUND GOOD. REMOVE INJECTOR LINES
FOR #2 AND #5 CYLINDER. REMOVE HPC RETAINING NUTS REMOVE HPC'S REMOVE
INJECTOR HARNESS FROM #2 AND #5 INJECTORS REMOVE HOLD DOWN BOLTS TO
MOVE HARNESS OUT OF THE WAY TO ACCESS INJECTOR HOLD DOWN BOLTS. REMOVE
INJECTORS. INSPECT BORES FOUND COOLANT COMING IN #5 CYLINDER INSPECT
FUEL WATER SEPARATOR DRAIN FOUND COOLANT COMING FROM DRAIN. INJECTOR
CUPS SEALS ARE FAILED AND UNIT WILL NEED INJECTOR CUP RINS OR CYLINDER
HEAD REPLACED TO PROPERLY REPAIR THE UNIT. AIR UP UNIT AND TOW INTO
ENGINE BAY.

D** REMOVE AND REPLACE FRONT DIFF D/S BRAKE POT
018-301 REMOVE AND REPLACE FRONT DIFF D/S BRAKE
POT
7005 CL 232.50 232.50

OUT	DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.	LABOUR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES	
	TOTAL CHARGES	
	LESS INSURANCE	
	G.S.T.	
	PLEASE PAY THIS AMOUNT	
\$		
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.		
SIGNATURE		
DATE RELEASED		



CALGARY PETERBILT LTD
11550 44th Street S.E.
Calgary, AB T2Z 4A2
Phone: (403) 235-2550
Fax: (403) 235-1322
Toll Free: 1-800-332-1296

PETERBILT LETHBRIDGE PETERBILT RED DEER
4110 - 18th Avenue North
Lethbridge, AB T1H 6N7
Phone: (403) 328-0500
Fax: (403) 328-0225
Toll Free: 1-888-777-3112

27 Burnt Lake Crescent
Red Deer County, AB T4S 2L4
Phone: (403) 342-5100
Fax: (403) 342-5153
Toll Free: 1-877-348-5100

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# R162

110991



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1-844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 2

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
RED	14	KENWORTH T800	1NKDX4TX8ER968149	J35740	747485/747485	190845	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
18OCT13 DD			11:02 08NOV25	162-1129	192.00	CHG	29NOV25
R.O. OPENED		READY	OPTIONS: STK:ER968149 DLR:M068 ENG:79669441				

14:51 03NOV25 11:40 29NOV25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

1 890*108742 PER L BRAKE CLEAN (DS) 11.01 11.01 11.01
1 SB3030CC (WH)CHAMBER-3030 COMBO W/CLEVI HVOL 101.74 48.59 48.59
PARTS: 59.60 LABOR: 232.50 OTHER: 0.00 TOTAL LINE D: 292.10
747485 7005. DISCONNECT AIR LINES. REMOVE CLEVIS PIN AND REMOVE
BRAKE POT. MEASURE PUSHROD LENGTH. CUT TO LENGTH NEW BRAKE POT PUSH
ROD. INSTALL NEW BRAKE POT. TRANSFER OVER FITTINGS AND RECONNECT AIR
LINE. AIR UP UNIT AND CHECK FOR LEAKS. CHECKS OK. SETUP BRAKE. CLEAN UP
TOOLS AND AREA.

E** REMOVE AND REPLACE D/S DRAG LINK

015-309 REMOVE AND REPLACE D/S DRAG LINK

7005 CL

155.00 155.00

1 463*DS7584* Drag Link 31.000in C to C

Peterbilt

223.44 155.77 155.77

1 FREIGHT CHARGE

25.00 25.00 25.00

PARTS: 180.77 LABOR: 155.00 OTHER: 0.00 TOTAL LINE E: 335.77

747485 7005. REMOVE DRAGLINK. CLEAN UP MOUNTING AREA. INSTALL NEW

DRAG LINK. GREASE LINK ENDS. CLEAN UP TOOLS AND AREA.

F** REMOVE AND REPLACE MIDDLE DIFF OUTPUT UJOINT

022-303 REMOVE AND REPLACE MIDDLE DIFF OUTPUT

UJOINT

7005 CL

310.00 310.00

1 SPL170-4X (WH)KIT-UNIVERSAL JOINT

415.48 170.51 170.51

2 170-70-18X (WH)KIT-BEARING RETAINER

79.11 33.82 67.64

PARTS: 238.15 LABOR: 310.00 OTHER: 0.00 TOTAL LINE F: 548.15

747485 7005. REMOVE JACK SHAFT. REMOVE FAILED U JOINT. CLEAN YOKE

AND INSTALL NEW U JOINT. REINSTALL JACK SHAFT AND GREASE BOTH U JOINTS.

CLEAN UP TOOLS AND AREA.

G** CUM-CYLHEAD R&R Cylinder Head

CUM-CYLHEAD SEE LINE H FOR OUT OF FRAME OVERHAUL

7005 CL

9005 REILING,MIKE LIC#: A

L1

OUT		DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE. \$ ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE. SIGNATURE DATE RELEASED	 CALGARY PETERBILT LTD 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296 PETERBILT LETHBRIDGE 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112 PETERBILT RED DEER 27 Burnt Lake Crescent Red Deer County, AB T4S 2L4 Phone: (403) 342-5100 Fax: (403) 342-5153 Toll Free: 1-877-348-5100	LABOUR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		LESS INSURANCE	
		G.S.T.	
		PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# R162

110991

INVOICE



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1-844-526-4460

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 3

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
RED	14	KENWORTH T800	1NKDX4TX8ER968149	J35740	747485/747485	190845	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
18OCT13 DD			11:02 08NOV25	162-1129	192.00	CHG	29NOV25
R.O. OPENED		READY		OPTIONS: STK:ER968149 DLR:M068 ENG:79669441			
14:51 03NOV25		11:40 29NOV25					
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
CL							

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE G: 0.00

747485 7005. DRAIN ENGINE COOLANT. REMOVE UPPER AND LOWER RAD HOSES. CONNECT AC MACHINE AND RECOVER REFRIGERANT. 2.8LBS OF REFRIGERANT WAS RECOVERED. DISCONNECT AC LINES TO THE COMPRESSOR. CAP AND PLUG LINES. DISCONNECT LOWER AC LINE TO THE CONDENSER. CAP AND PLUG LINES. REMOVE TURBO TO CHARGE AIR COOLER AIR PIPING. REMOVE CHARGE AIR COOLER TO INTAKE AIR PIPING. REMOVE SURGE TANK TO ENGINE COOLANT HOSES. SETUP OVERHEAD CRANE. REMOVE RAD SUPPORT STRUT RODS. REMOVE LOWER RAD MOUNTING NUTS. REMOVE RADIATOR/CHARGE AIR COOLER ASSEMBLY. REMOVE ENGINE COOLING FAN AND HALO SHROUD. REMOVE FAN HUB. REMOVE CRANK PULLEY AND HARMONIC DAMPER. REMOVE INJECTOR WIRING HARNESS. REMOVE INJECTORS. REMOVE ROCKER ARM ASSEMBLIES. BLOCK UP TURBO AND REMOVE EXHAUST MANIFOLD BOLTS. REMOVE REAR COOLANT MANIFOLD. DISCONNECT AND REMOVE UPPER ENGINE WIRING HARNESS AND SET ASIDE. DISCONNECT REAR FUEL RETURN LINE. REMOVE INTAKE MANIFOLD. REMOVE FRONT UPPER TIMING COVER. REMOVE CAM AND IDLER GEARS. REMOVE CAM AND IDLER THRUST PLATES. REMOVE CAMSHAFT. REMOVE CYLINDER HEAD BOLTS. SETUP OVERHEAD CRANE AND REMOVE CYLINDER HEAD. INSPECT AND FOUND WORN CYLINDERS. ALSO FOUND THE FRONT AND REAR MOTOR MOUNTS ARE WORN OUT AND COMING APART. THE REAR STRUCTURE GASKET IS ALSO LEAKING. CLEAN BLOCK DECK SURFACE AREA AND MEASURE LINER PROTRUSIONS. LINER PROTRUSIONS CHECK OK AND ARE IN SPEC AND RANGE. ATTACH MEASUREMENTS TO WORK ORDER. CUSTOMER OK'D A OUT OF FRAME OVERHAUL DUE TO THE REAR STRUCTURE GASKET LEAKING. REMOVE EXHAUST DOWN PIPE. REMOVE COOLANT LINES AND OIL LINES TO TURBO. REMOVE EGR COOLER BELLOWS V BAND CLAMP. REMOVE TURBO AND EXHAUST MANIFOLD ASSEMBLY. REMOVE LOWER COOLANT HOSE TO REAR OF BLOCK. REMOVE STARTER BOLTS AND SET STARTER ASIDE. DISCONNECT AND REMOVE OEM HARNESS FROM THE ENGINE AND SET ASIDE. REMOVE CLUTCH INSPECTION COVER AND REMOVE PRESSURE PLATE BOLTS. SETUP TRANS STANDS. SETUP OVERHEAD CRANE. REMOVE FRONT AND REAR MOTOR MOUNT BOLTS. REMOVE BELL HOUSING BOLTS. REMOVE ENGINE AND PLACE ON STANDS. REMOVE FLYWHEEL. REMOVE FRONT MOUNT BRACKET. REMOVE REAR STRUCTURE. REMOVE FRONT STRUCTURE. REMOVE ENGINE WIRING HARNESS ON THE

OUT		DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE. \$ ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.	 CALGARY PETERBILT LTD 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296	LABOUR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
SIGNATURE	PETERBILT LETHBRIDGE PETERBILT RED DEER 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112	TOTAL CHARGES	
		LESS INSURANCE	
		G.S.T.	
DATE RELEASED		PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# R162

110991

INVOICE



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1- 844-526-4460

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 4

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT	TAG
RED	14	KENWORTH T800		1NKDX4TX8ER968149	J35740	747485/747485	190845
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
18OCT13 DD			11:02 08NOV25	162-1129	192.00	CHG	29NOV25
R.O. OPENED		READY		OPTIONS: STK:ER968149 DLR:M068 ENG:79669441			

14:51 03NOV25 11:40 29NOV25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

RIGHT SIDE OF ENGINE. REMOVE TURBO OIL DRAIN LINE. REMOVE WATER PUMP ASSEMBLY. REMOVE OIL FILTER AND COOLANT FILTER. REMOVE OIL COOLER ASSEMBLY. REMOVE OIL PUMP AND PICKUP TUBE. REMOVE BLOCK STIFFENER PLATE. REMOVE PISTON COOLING NOZZLES. REMOVE PISTON AND CONNECTING RODS. REMOVE CYLINDER LINERS USING THE LINER REMOVAL TOOLING. REMOVE AIR COMPRESSOR AND FUEL PUMP ASSEMBLY. ROLL ENGINE UPSIDE DOWN AND REMOVE MAIN CAPS. REMOVE CRANKSHAFT. REMOVE MAIN BEARINGS. CLEAN BLOCK AND LOW OUT COOLANT AND OIL PASSAGES. INSTALL NEW UPPER MAIN BEARINGS. CLEAN CRANKSHAFT AND BLOW OUT OIL PASSAGES. INSPECT CRANK. CRANKSHAFT IS IN GOOD SERVICEABLE CONDITION AND IS GOOD FOR REUSE. PRELUBE MAIN BEARINGS AND INSTALL CRANKSHAFT USING THE OVERHEAD CRANE AND LIFTING TOOLING. CLEAN MAIN CAPS AND INSTALL NEW BEARINGS. INSTALL MAIN CAPS AND TORQUE TO SPEC AND PROCEDURE. SETUP MEASURE TOOLING AND MEASURE CRANKSHAFT END PLAY. CRANK END PLAY IS IN SPEC. CRANKSHAFT END PLAY IS AT 0.010" AND IS IN SPEC. ROLL ENGINE OVER AND PLACE ON STAND. CLEAN LINER BORES AND BLOCK DECK. INSTALL NEW LINERS AND O RINGS USING REQUIRED VEGETABLE OIL AND INSTALLATION TOOLING. ASSEMBLE NEW CONNECTING RODS ONTO NEW PISTONS. INSTALL NEW PISTON RINGS AND CONNECTING ROD BEARINGS. PRELUBE BEARINGS AND INSTALL PISTON AND ROD ASSEMBLIES AS PER PROCEDURE AND SPEC. TORQUE CONNECTING ROD CAPS TO SPEC AND PROCEDURE. MEASURE CONNECTING ROD SIDE CLEARANCE. SIDE CLEARANCE IS IN SPEC AND CHECKS OK. INSTALL NEW PISTON COOLING NOZZLES AND BANJO BOLTS AND TOQUE TO SPEC. CLAN AND INSTALL BLOCK STIFFENER PLATE AND TORQUE TO SPEC. PRELUBE NEW OIL PUMP. INSTALL NEW OIL PUMP AND TOQUE TO SPEC. MEASURE OIL PUMP GEAR BACKLASH. BACKLASH IS IN SPEC. CLEAN AND INSTALL OIL PICKUP TUBE WITH NEW O RING AND TORQUE MOUNTING BOLTS. CLEAN FRONT AND REAR ENGINE BLOCK AREA. CLEAN FRONT AND REAR STRUCTURES. INSPECT BLOCK AND FRONT AND REAR STRUCTURES. CHECKS OK AND IS IN GOOD SERVICEABLE CONDITION. INSTALL FRONT STRUCTURE WITH NEW GASKET. TORQUE FRONT STRUCTURE TO SPEC AND PROCEDURE. INSTALL FRONT CRANK SEAL USING SEAL INSTALLATION TOOLING. INSTALL REAR STRUCTURE WITH NEW GASKET. TORQUE REAR STRUCTURE TO SPEC AND PROCEDURE. INSTALL NEW REAR CRANK SEAL. REPLACE TRANSMISSION PILOT BEARING AND INSTALL FLYWHEEL. TOQUE FLYWHEEL TO SPEC. UNPACK NEW CYLINDER HEAD AND INSPECT.

OUT			CALGARY PETERBILT LTD. 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296	DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.				LABOUR AMOUNT	
\$		PETERBILT LETHBRIDGE 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112	PETERBILT RED DEER 27 Burnt Lake Crescent Red Deer County, AB T4S 2L4 Phone: (403) 342-5100 Fax: (403) 342-5153 Toll Free: 1-877-348-5100	PARTS AMOUNT	
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.				GAS, OIL, LUBE	
SIGNATURE				SUBLET AMOUNT	
DATE RELEASED				MISC. CHARGES	
				TOTAL CHARGES	
				LESS INSURANCE	
				G.S.T.	
				PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# R162

110991



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1- 844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 5

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
RED	14	KENWORTH T800	1NKDX4TX8ER968149	J35740	747485/747485	190845	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
18OCT13 DD			11:02 08NOV25	162-1129	192.00	CHG	29NOV25
R.O. OPENED		READY	OPTIONS: STK:ER968149 DLR:M068 ENG:79669441				

14:51 03NOV25 11:40 29NOV25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

CHECK OK. CLEAN BLOCK DECK SURFACE AREA AND BOLT HOLES. INSTALL CYLINDER HEAD ONTO ENGINE WITH NEW GASKET USING LIFTING TOOLING. REPLACE 2 RUST PITTED HEAD BOLTS. INSTALL HEAD BOLTS AND TOQUE TO SPEC AND PROCEDURE. CLEAN AND INSTALL OIL PAN WITH NEW GASKET. UNPACK NEW FUEL PUMP MAIN BODY AND INSPECT. CHECK OK. REMOVE PUMP HEAD OFF OLD HIGH PRESSURE PUMP. CLEAN HEAD AND REPLACE THE PLUNGERS AND PLUNGER BODIES WITH THE NEW ONES SUPPLIED IN THE OVERHAUL KIT. INSTALL HIGH PRESSURE PUMP MAIN BODY. INSTALL NEW PUMP LIFTERS THAT WERE SUPPLIED IN THE KIT. CLEAN AND TRANSFER OVER THE FUEL GEAR PUMP ONTO THE NEW HIGH PRESSURE PUMP WITH NEW O RING. INSTALL AIR COMPRESSOR WITH NEW GASKET. TIME FUEL PUMP AND CRANK GEAR. INSTALL CRANK PINNING TOOLING. INSPECT GEARTRAIN GEARS AND SHAFTS. CHECKS OK. GEARS AND BUSHINGS ARE IN GOOD SERVICEABLE CONDITION. INSTALL LOWER SCISSOR GEAR AND TORQUE TO SPEC AND PROCEDURE. INSTALL HIGH PRESSURE PUMP IDLER GEAR AND CONFIRM PUMP TIMING. TOQUE TO SPEC AND PROCEDURE. INSTALL UPPER IDLER GEAR AND TORQUE TO SPEC AND PROCEDURE. CLEAN AND INSEPECT CAMSHAFT. CAMSHAFT IS IN GOOD SERVICEABLE CONDITION AND CHECK OK. PRELUBE AND INSTALL CAMSHAFT. INSTALL REAR CAM THRUST PLATE WITH NEW O RING SEAL. INSTALL CAM WEDGE TOOLING. CLEAN AND INSTALL FRONT CAM AND IDLER THRUST PLATES WITH NEW O RING SEALS CLEAN AND INSTALL CAM AND CAM IDLER GEARS. SETUP GEAR BACK LASH AND TORQUE CAM AND CAM IDLER GEARS TO SPEC AND PROCEDURE. GEAR BACKLASH IS IN SPEC. CLEAN AND INSTALL FRONT LOWER AND UPPER TIMING COVERS. CLEAN AND INSPECT VALVE BRIDGES. CHECKS OK. INSTALL VALVE BRIDGES. UNPACK NEW INJECTORS AND FUEL TUBES THAT WERE SUPPLIED IN THE KIT. INSTALL INJECTORS AND FUEL TUBES AND TORQUE AS PER SPEC AND PROCEDURE. REMOVE CAM AND CRANK PIN AND WEDGE TOOLING. CLEAN AND INSPECT ROCKER ARMS AND SHAFTS. CHECKS OK. BLOW OUT OIL PASSAGES. PRELUBE AND INSTALL ROCKER ARM ASSEMBLIES. TOQUE TO SPEC AND PROCEDURE. PERFORM A OVER HEAD VALVE AND ENGINE BRAKE ADJUSTMENT. CHECK ENGINE BRAKE ROCKER ARM RUNNING CLEARANCE. CHECKS OK, RUNNING CLEARANCE IS IN SPEC. INSTALL INJECTOR WIRING HARNESS. INSTALL NEW VALVE COVER WITH SUPPLIED GASKET. CLEAN BLOCK AREA AND INSTALL NEW WATER PUMP THAT WAS SUPPLIED IN KIT. REPLACE OIL COOLER ELEMENT. REPLACE OIL THERMOSTAT AND SNAP RING. CLEAN BLOCK AREA AND OIL COOLER HOUSING GASKET MATING

OUT			CALGARY PETERBILT LTD. 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296	DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.				LABOUR AMOUNT	
\$			PETERBILT LETHBRIDGE 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112	PARTS AMOUNT	
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.				GAS, OIL, LUBE	
SIGNATURE			PETERBILT RED DEER 27 Burnt Lake Crescent Red Deer County, AB T4S 2L4 Phone: (403) 342-5100 Fax: (403) 342-5153 Toll Free: 1-877-348-5100	SUBLET AMOUNT	
DATE RELEASED				MISC. CHARGES	
GST # R100731918				TOTAL CHARGES	
				LESS INSURANCE	
				G.S.T.	
				PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

CUSTOMER #:
UNIT# R162

110991

INVOICE



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1- 844-526-4460

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 6

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
RED	14	KENWORTH T800	1NKDX4TX8ER968149	J35740	747485/747485	190845	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
18OCT13 DD			11:02 08NOV25	162-1129	192.00	CHG	29NOV25
R.O. OPENED		READY	OPTIONS: STK:ER968149 DLR:M068 ENG:79669441				

14:51 03NOV25 11:40 29NOV25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

SURFACE. INSTALL OIL COOLER ASSEMBLY WITH NEW GASKET AND TORQUE TO SPEC. INSTALL COOLANT FILTER HOUSING WITH NEW GASKET AND O RING. INSTALL NEW COOLANT FILTER. PRIME AND INSTALL NEW OIL PUMP. INSTALL EGR COOLER AND REAR COOLANT MANIFOLD WITH NEW O RINGS AND O RING SEAL. CLEAN AND INSTALL EXHAUST MANIFOLD WITH NEW GASKETS. INSTALL NEW TURBO ASSEMBLY. CONNECT COOLANT AN OIL LINES. INSTALL INTAKE MANIFOLD WITH NEW GASKET. INSTALL EGR VALVE AND MOUNTING BRACKET. INSTALL REAR EGR COOLER PIPING WITH NEW GASKET. INSTALL EGR CROSS OVER TUBE. INSTALL AND CONNECT ENGINE WIRING HARNESS. INSTALL FRONT ENGINE MOUNT BRACKET. INSTALL CRANK PULLEY AND HARMONIC DAMPER. THE HARMONIC DAMPER HAS BEEN RECENTLY REPLACED AND IS IN NEW CONDITION. INSTALL FAN HUB ASSEMBLY. INSTALL ACCESSORY MOUNTING BRACKET WITH ALTERNATOR AND AC COMPRESSOR. REPLACE BAD AC BELT IDLER PULLEY. INSTALL DRIVE BELTS. PAINT ENGINE ASSEMBLY. REPLACE FRONT AND REAR ENGINE MOUNTS. SETUP OVER HEAD CRANE AND ENGINE LIFTING TOOLING. REINSTALL ENGINE INTO TRUCK. INSTALL NEW BELL HOUSING AND PRESSURE PLACE BOLTS AND TOQUE TO SPEC. ADJUST CLUTCH. INSTALL FAN AND HALO SHROUD. CONNECT OEM WIRING HARNESS. WASH OUT RADIATOR AND CHARGE AIR COOLER. WASH OUT AC CONDENSER. SETUP OVERHEAD AND LIFTING TOOLING. INSTALL RADIATOR/CHARGE AIR COOLER ASSEMBLY. REPLACE HOT SIDE BOOST HOSES AND CLAMPS DUE TO HOSES WERE IN POOR CONDITION. INSTALL NEW EXHAUST DOWN PIPE AND FLEX PIPE DUE TO THE OLD ONES WERE IN POOR CONDITION. INSTALL CHARGE AIR COOLER TO INTAKE AIR PIPING. INSTALL AIR CLEANER TO TURBO AIR PIPING,. REPLACE AIR CLEANER ELEMENTS. VACUUM FILL COOLING SYSTEM. FILL ENGINE OIL. REPLACE POWER STEERING SUCTION HOSE DUE TO POOR CONDITION. FILL POWER STEERING SYSTEM. CONNECT COMPUTER AND PERFORM A EGT ACTUATOR INSTALLATION PROCEDURE. INSTALL VGT ACTUATOR. PERFORM A VGT ACTUATOR CALIBRATION PROCEDURE. VGT CALIBRATION PASSED. RESET INJECTORS. CONNECT AC LINES. CONNECT AC MACHINE AND RECHARGE SYSTEM. START AND RUN ENGINE. FOUND THE COOLING FAN WILL NOT TURN OFF. MONITOR AC PRESSURE SWITCH USING INSITE. PRESSURE SWITCH SAYS ON WITH THE CONNECTOR DISCONNECTED AND WITH THE CONNECTOR JUMPED. THERE IS A AC SYSTEM WIRING PROBLEM. TRACE WIRING BACK AND INSPECT. FOUND BROKEN WIRE AT THE POWER STEERING RESERVOIR SWITCH. REPAIR WIRING AND RECHECK. CHECKS OK. COOLING FAN NOW OPERATES

OUT			CALGARY PETERBILT LTD 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296	DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.				LABOUR AMOUNT	
\$		PETERBILT LETHBRIDGE 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112	PETERBILT RED DEER 27 Burnt Lake Crescent Red Deer County, AB T4S 2L4 Phone: (403) 342-5100 Fax (403) 342-5153 Toll Free: 1-877-348-5100	PARTS AMOUNT	
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.				GAS, OIL, LUBE	
SIGNATURE				SUBLET AMOUNT	
DATE RELEASED				MISC. CHARGES	
				TOTAL CHARGES	
				LESS INSURANCE	
				G.S.T.	
				PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# R162

110991

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 7



PETERBILT MEDICINE HAT

2250 South Highway Dr SE

Redcliff, AB. T0J 2P0

Tel: 403-526-4460

Fax: 403-525-5299

Toll-Free: 1-844-526-4460

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR		YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
RED		14	KENWORTH T800		1NKDX4TX8ER968149	J35740	747485/747485		190845
IN SVC. DATE		PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE	
18OCT13 DD				11:02 08NOV25	162-1129	192.00	CHG	29NOV25	
R.O. OPENED			READY		OPTIONS: STK:ER968149 DLR:M068 ENG:79669441				
14:51 03NOV25			11:40 29NOV25						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

NORMALLY. RUN ENGINE TO OPERATING TEMP AND CHECK FOR LEAKS AND
OPERATION. CHECKS OK. REINSPECT FOR LEAKS AND OPERATION AFTER ROAD
TEST. CHECK OK. CLEAN UP TOOLS AND AREA. PACK UP AND RETURN CORES TO
PARTS WEARHOUSE.

H** OVERHAUL Overhaul Engine Inframe

OUTFRAME PERFORM OUT OF FRAME OVERHAUL

7005 CL		13950.00	13950.00
1 5693839RXCUM KIT, ELITE OVERHAUL	47945.05	36576.70	36576.70
CORE CHARGE C		2720.00	2720.00
2 M17495 MOTOR MOUNT REAR KENWORTH	322.74	223.15	446.30
2 M203041 MOTOR MOUNT BUSHING KENWORTH	15.82	11.75	23.50
2 M203039 MOTOR MOUNT BUSHING FRONT KENWORTH	25.66	19.06	38.12
1 4393176CUM GASKET, FLYWHEEL HOUSING	183.96	156.88	156.88
1 6609787CUM KIT, SEAL	119.06	101.56	101.56
1 4955831CUM KIT - OIL COOLER	1010.59	839.81	839.81
1 3685173CUM SEAL-OIL	136.58	116.47	116.47
1 4393089CUM GASKET, GEAR HOUSING	153.24	130.69	130.69
1 FREIGHT CHARGE	30.00	30.00	30.00
1 3688113CUM PLUG - GEAR	26.88	22.92	22.92
-1 REBATE CUMMINS ELITE OVERHAUL KIT	2000.00	2000.00	-2000.00
COUPON: M25NOV8749 AUTH: 112125-V84D8			
-1 REBATE INSTALL OF ELITE OVERHAUL KIT	600.00	600.00	-600.00
COUPON: M25NOV7426 AUTH:112125-V84D8			
1 5458260RXCUM KIT, TURBOCHARGER	13428.76	10336.11	10336.11
CORE CHARGE C		770.00	770.00
-1 5458260RXCUM CORE RETURN	13428.76	770.00	-770.00
-1 5693839RXCUM CORE RETURN	47945.05	2720.00	-2720.00
1 3689760CUM .VALVE COVER	875.83	683.46	683.46
1 FS19764FLG -FILTER F/W SEP	63.49	48.25	48.25
1 FU8 EHCC8-	0.50	0.50	0.50
1 FREIGHT CHARGE	300.76	300.76	300.76
1 89120DYC (WH) PULLEY-TENSIONER/IDLER ATRHR	95.81	71.38	71.38
1 EBPB11861 BELLOW-EXHAUST AM KIT M66-7091-03			

OUT
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.
\$
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.
SIGNATURE
DATE RELEASED



CALGARY PETERBILT LTD.

11550 44th Street S.E.
Calgary, AB T2Z 4A2
Phone: (403) 235-2550
Fax: (403) 235-1322
Toll Free: 1-800-332-1296

PETERBILT LETHBRIDGE PETERBILT RED DEER

4110 - 18th Avenue North
Lethbridge, AB T1H 6N7
Phone: (403) 328-0500
Fax: (403) 328-0225
Toll Free: 1-888-777-3112

27 Burnt Lake Crescent
Red Deer County, AB T4S 2L4
Phone: (403) 342-5100
Fax: (403) 342-5153
Toll Free: 1-877-348-5100

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
G.S.T.	
PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# R162

110991



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1-844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

PAGE 8

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
RED	14	KENWORTH T800	1NKDX4TX8ER968149	J35740	747485/747485	190845

IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
18OCT13 DD			11:02 08NOV25	162-1129	192.00	CHG	29NOV25

R.O. OPENED READY OPTIONS: STK:ER968149 DLR:M068 ENG:79669441

14:51 03NOV25 11:40 29NOV25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
			(WH)		460.93	373.36	373.36
1			M66-6647 EPA/PIPE-EXHAUST MBEND 4" SS ALMZ		1118.63	760.67	760.67
1			890*108742 PER L BRAKE CLEAN (DS)		11.01	11.01	11.01
3			3163075 CUMMINS RED PAINT		68.34	46.86	140.58
1			3M2929 3M TAPE 2929 SILVER DUCT TAPE ALEX		18.29	13.14	13.14
1			96825 BLUE PAINT PEN IHJ		6.19	6.19	6.19
1			3688012CUM TUBE-LUBE OIL DRAIN		95.19	81.18	81.18
2			4965698CUM SCREW-HEX		14.34	12.23	24.46
2			3678506CUM HEAD BOLT		45.82	39.07	78.14
1			4988280CUM GASKET P/S		8.11	6.92	6.92
1			5440813CUM GASKET, ACC DRIVE SUPPORT		31.71	27.04	27.04
2			PRX24209CTN BLUE MED STRENGTH 242 THREADLOCK		12.06	8.96	17.92
1			38625CAP GSKT MAKER 515		37.95	37.65	37.65
1			890*108742 PER L BRAKE CLEAN (DS)		11.01	11.01	11.01
1			3685556CUM GASKET - ADAPTER		25.21	21.50	21.50
1			3688317CUM HOSE,FUEL		107.04	91.28	91.28
1			3689169CUM TUBE,FUEL SUPPLY		72.66	61.96	61.96
-1			REBATE TRP EXHAUST BELLOW		8.00	8.00	-8.00
COUPON: M25NOV7426 AUTH: 112125-V84D8							
50 0502*550314 WIRE TIE COLD TEMP UV BLK							
4.6X371M TIE5					0.20	0.20	10.00
1			894*1319 3M ELECTRICAL TAPE		3.57	3.57	3.57
1			3684338CUM GASKET		49.23	41.98	41.98
1			WF2127FLG ES FILTER		89.17	67.77	67.77
1			FU8 EHCC8-		0.50	0.50	0.50
1			4059172CUM SEAL ORING		14.57	12.42	12.42
1			9216TRP CLAMP		3.98	2.42	2.42
1			4952629CUM THERMOSTAT OIL		226.20	192.91	192.91
1			3089025CUM ORING		24.69	21.05	21.05
1			4376196CUM KIT OIL COOLER		198.43	169.22	169.22
1			3411881CUM SNAP RING		12.11	10.32	10.32
1			3104230CUM GASKET EX		76.44	65.19	65.19
1			3683144CUM CLAMP-V BAND		112.25	95.73	95.73
1			6306LLUA1C3NTN PILOT BEARING		42.94	27.91	27.91

OUT
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.
\$
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.
SIGNATURE
DATE RELEASED



CALGARY PETERBILT LTD.
11550 44th Street S.E.
Calgary, AB T2Z 4A2
Phone: (403) 235-2550
Fax: (403) 235-1322
Toll Free: 1-800-332-1296

PETERBILT LETHBRIDGE PETERBILT RED DEER
4110 - 18th Avenue North
Lethbridge, AB T1H 6N7
Phone: (403) 328-0500
Fax: (403) 328-0225
Toll Free: 1-888-777-3112

27 Burnt Lake Crescent
Red Deer County, AB T4S 2L4
Phone: (403) 342-5100
Fax: (403) 342-5153
Toll Free: 1-877-348-5100

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
G.S.T.	
PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# R162

110991

INVOICE



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1-844-526-4460

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 9

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
RED	14	KENWORTH T800	1NKDX4TX8ER968149	J35740	747485/747485	190845	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
18OCT13 DD			11:02 08NOV25	162-1129	192.00	CHG	29NOV25
R.O. OPENED		READY	OPTIONS: STK:ER968149 DLR:M068 ENG:79669441				

14:51 03NOV25 11:40 29NOV25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	105FBC	(WH)	GREASE-MOTOR ASSY	10 OZ L0034-094			
			HVOL		19.81	14.33	14.33
2	074*34*5	3/4X5	BOLT		4.40	4.40	8.80
4	422*34*	3/4	FLAT		0.53	0.53	2.12
2	373*034	3/4	NUT NYLON UNC		0.93	0.93	1.86
2	AF4195FLG	AIR	FILTER-PRIMARY		231.62	176.03	352.06
8	074*716*212	7/16-14X2-1/2	UNC HEX BOLT GR8				
			YZ		0.75	0.75	6.00
12	422*716	7/16	FLAT WASHER		0.08	0.08	0.96
8	444*716	7/16	LW		0.08	0.08	0.64
2	PRX24209CTN	BLUE	MED STRENGTH 242	THREADLOCK	12.06	8.96	17.92
12	074*716*112	7/16-14X1-1/2	UNC HEX BOLT GR8				
			YZ		0.48	0.48	5.76
3	D1030-3950	1"HOSE-HEATER	#16X25' J20R3		18.97	17.60	52.80
2	9216TRP	CLAMP			3.98	2.42	4.84
1	9208TRP	CLAMP			3.70	2.18	2.18
2	9210TRP	CLAMP			3.84	2.42	4.84
1	4966441CUM	GASKET			35.71	30.45	30.45
2	2866636CUM	GASKET			27.35	23.32	46.64
1	2866337CUM	GASKET 5"			27.35	23.32	23.32
1	4966454CUM	CLAMP			110.69	94.40	94.40
1	HE27141	HOSE-#12	PUSH ON HYD 25'		18.79	12.41	12.41
2	9210TRP	CLAMP			3.84	2.42	4.84
3	AC10650	#6	ORING		1.02	0.72	2.16
2	221854-483C	ATF	HVOL		8.52	8.15	16.30
2	1LEHC	EHCC			0.17	0.17	0.34
16	227811-487C	CHEVRON 50/50	MIX HVOL (DS)		19.04	13.69	219.04
50	257000-990C	CHV DELO400XLE	SYNBLN 10W30BULK				
			(DS) BULK OIL		7.56	6.11	305.50
50			OIL EHCC		0.06	0.06	3.00
1	545*34	3/4"	ZNC PLTD CLAMP W/RUB INSERT 3/		1.16	1.16	1.16
1	422*58	5/8	FLAT WASHER373012		0.29	0.29	0.29
1	E*CLIP	E	CLIP		0.17	0.17	0.17
2	HE9622	(WH)HOSE-CAC 4"	SIL BELLOW X		44.75	42.51	85.02

OUT
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.
\$
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.
SIGNATURE
DATE RELEASED



CALGARY PETERBILT LTD.

11550 44th Street S.E.
Calgary, AB T2Z 4A2
Phone: (403) 235-2550
Fax: (403) 235-1322
Toll Free: 1-800-332-1296

PETERBILT LETHBRIDGE PETERBILT RED DEER

4110 - 18th Avenue North
Lethbridge, AB T1H 6N7
Phone: (403) 328-0500
Fax: (403) 328-0225
Toll Free: 1-888-777-3112

27 Burnt Lake Crescent
Red Deer County, AB T4S 2L4
Phone: (403) 342-5100
Fax: (403) 342-5153
Toll Free: 1-877-348-5100

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
G.S.T.	
PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# R162

110991



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1- 844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 10

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT	TAG
RED	14	KENWORTH T800		1NKDX4TX8ER968149	J35740	747485/747485	190845
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
18OCT13 DD			11:02 08NOV25	162-1129	192.00	CHG	29NOV25
R.O. OPENED		READY		OPTIONS: STK:ER968149 DLR:M068 ENG:79669441			

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
4	B9224-0406	TRP	CAC	LARGE SPR CLAMP	21.34	12.92	51.68
2	R134A	30	LBS	FREON	19.76	19.76	39.52
1	774*05*18	PRI.	WIRE	PVC COATED 100 FT BLUE			
	18GA				0.24	0.24	0.24
5	555*5161*	18-22	HTSHR	CRIMP BUTT CONN RED	0.68	0.68	3.40
-1	REBATE	REBATE	-	CUMMINS TURBO	100.00	100.00	-100.00
112925-J6JGE	CUMMINS	REBATE	TURBO	, M25NOV8639			
-1	REBATE	REBATE	INSTALL	TURBO	100.00	100.00	-100.00
112925-J6JGE	-	REBATE	-	INSTALL TURBO			
PARTS:	51011.06	LABOR:	13950.00	OTHER:	4.34	TOTAL LINE H:	64965.40
747485							

ESTIMATE: 0.00 07NOV25 15:45 SA: 94
CONTACT:

ESTIMATE: 0.00 03NOV25 14:51 SA: 94
CONTACT:

Technology Fee 300.00
DECISIV CASE # 19084565

** ANY DENIED WARRANTY OR PORTION THEREOF
WILL BE THE RESPONSIBILITY OF THE CUSTOMER **

NOTE: AS A MAINTENANCE REQUIREMENT, CUSTOMERS
MUST RETORQUE ALL WHEEL NUTS 100-150KM AFTER
WHEELS HAVE BEEN REINSTALLED.

GST (#: R100731918) (#: 100731918RT0001) 3360.83

OUT	DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.	LABOUR AMOUNT	15422.50
	PARTS AMOUNT	51489.58
	GAS, OIL, LUBE	0.00
	SUBLET AMOUNT	0.00
	MISC. CHARGES	304.34
	TOTAL CHARGES	67216.42
	LESS INSURANCE	0.00
	G.S.T.	3360.83
	PLEASE PAY THIS AMOUNT	70577.25

CALGARY PETERBILT LTD.
11550 44th Street S.E.
Calgary, AB T2Z 4A2
Phone: (403) 235-2550
Fax: (403) 235-1322
Toll Free: 1-800-332-1296

PETERBILT LETHBRIDGE
4110 - 18th Avenue North
Lethbridge, AB T1H 6N7
Phone: (403) 328-0500
Fax: (403) 328-0225
Toll Free: 1-888-777-3112

PETERBILT RED DEER
27 Burnt Lake Crescent
Red Deer County, AB T4S 2L4
Phone: (403) 342-5100
Fax: (403) 342-5153
Toll Free: 1-877-348-5100

Peterbilt

Peterbilt

CUSTOMER COPY