

Fleetgo Heavy Duty Inc

17405 109 Ave
Edmonton, Alberta, T5S 1H7
(780) 455 - 8131

**Invoice: INV-S-26399**

Invoice Date: Jun 15, 2026

Due date: Jun 15, 2026

G17-1
SEP**Bill To**

Sprinter Shipping

Remit payment to

Fleetgo Heavy Duty Inc
17405 109 Ave
Edmonton, Alberta, T5S 1H7
(780) 455 - 8131

Unit	VIN/Serial #	Asset	Mileage	Eng Hrs
	3WKDDP9X1LF965925	2020 KENWORTH	486,212	0
Service Order	Terms	Due date	Customer PO	Authorizer
S-26399	COD	Jun 15, 2026		

Description	Quantity	Rate	Amount
CHECK FIFTH WHEEL			
Labor Fifth wheel was out of adjustment and rubber bushing was broken so replace bushing and did	1.05	\$144.95	\$152.20
		Line Total	\$152.20
STEERING ALIGNMENT ISSUE - SAS FAULT CODE			
Labor MENTIONED TIE RODS, TRACTION CONTROL LIGHT WAS ON			
Inspect front end			
checked kingpin, shackle pins, draglink			
Drove unit in a straight line and checked steering wheel position. Adjusted the steering wheel to match straight operation. Hooked up software to the unit and had to update the communication hardware to gain link to the unit. Reset the steering angle sensor to zero when steering wheel centered.	4.05	\$144.95	\$587.05
		Line Total	\$587.05
VALVE SET			
Labor Removed the air cleaner housing, piping and bracket to access the valve cover. Tried removing the valve cover and found two bolts severely corroded into the valve cover holding it to the intermediate cover with the injector harness. Had to extract the injector connections with the valve cover siezed on one end to the intermediate cover. Removed both the valve cover and intermediate cover as one. Performed the valve adjustment as per spec.			
Was able to extract one of the broken bolts with vise grip. The other was corroded off almost flush. Tried to drill out and remove what was left of the bolt and the brass insert spun in	7	\$144.95	\$1,014.65

the intermediate cover. Got EZ loc insert and tapped the cover to install. Tested the fit. Installed the covers with two new bolts. OEM bolts days away not available at this time.

Reinstalled the air cleaner housing, Piping and bracket to complete the repair.

Parts	BOLT	2	\$0.93	\$1.86
Parts	THREAD INSERT	1	\$8.36	\$8.36
			Line Total	\$1,024.87
				Labor \$1,753.90
				Parts \$10.22
				Shop supplies \$140.31
				Subtotal \$1,904.43
				GST (5%) \$95.22
				Total \$1,999.65
				Payments
				Balance \$1,999.65

Thank you for your business.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Fleetgo Heavy Duty Inc. shall not be liable for special, indirect or consequential damages, e.g.: down time, loss of revenue, loss of vehicle, towing charges, driver's expenses, loss of perishable cargo, etc. Failed parts return requests must be made when the unit is checked in. Please be aware that any aftermarket modifications to OEM components are customer responsibility. Warranty on a defective part as per OWM failure is one year, unlimited km from date of invoice. Warranty on a labor/workmanship issue is one year, unlimited km from date of invoice. Warranty work has to be performed in our shop and cannot exceed the original cost of repair.

****IF WHEELS ARE REMOVED OR IF ANY SUSPENSION WORK IS PERFORMED - RETORQUE MUST BE DONE TO REQUIRED SPECS WITHIN 100-150 KM****

Customer signature: _____

Printed name: _____ **Date:** _____

Daysland Truck and Trailer
Repair GST NO:
823951066RT0001
 21451 Fort Road NE
 Edmonton, AB T5Y6G7, CA
 Daysland@gmail.com
 (780) 263-8000



Invoice: 11226

Date: 1/24/2026

Bill To
 Sprinter Shipping

Remit Payment To
 Primary
 21451 Fort Road NE
 Edmonton, AB T5Y6G7, CA

P:

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
6729	COD	1/24/2026	Rick		1

Item	Description	Quantity	Rate	Amount
Labor	Chassis / Chassis / CVIP with wheel removal - Completed: 1/24/2026	1.00000	\$750.00	\$750.00
	Subtotal			\$750.00
Labor	Chassis / Chassis / R&R #2,3 axle LHS brake chambers - Completed: 1/24/2026	2.00000	\$150.00	\$300.00
Parts	brake chamber	2.00000	\$85.50	\$171.00
	Subtotal			\$471.00
Labor	Chassis / Chassis / R&R Fifth wheel bushings - Completed: 1/24/2026	1.50000	\$150.00	\$225.00
Parts	fifth wheel bushing kit	1.00000	\$176.98	\$176.98
Parts	insert kit	1.00000	\$87.40	\$87.40
	Subtotal			\$489.38
Labor	Chassis / Chassis / R&R #2,3 axle both sides S-cams excessive play - Completed: 1/24/2026	6.00000	\$150.00	\$900.00
Parts	S-cam	4.00000	\$125.50	\$502.00
Parts	S-cam bushing kit	4.00000	\$52.30	\$209.20
	Subtotal			\$1,611.20
Labor	Chassis / Chassis / R&R #2,3 axle both sides drums excessive cracks - Completed: 1/24/2026	0.00000		\$0.00
Parts	drum	4.00000	\$135.50	\$542.00
	Subtotal			\$542.00
Labor	Chassis / Chassis / Diagnose and repair RHS tail lamp signal function. - Completed: 1/24/2026	2.00000	\$150.00	\$300.00
	Subtotal			\$300.00
Labor	Chassis / Chassis / R&R air dryer. - Completed: 1/24/2026	2.00000	\$150.00	\$300.00
Parts	Air dryer	1.00000	\$540.56	\$540.56

			Subtotal	\$840.56
Labor	Chassis / Chassis / R&R #1 axle both sides leaf spring bushings - Completed: 1/24 /2026	8.00000	\$150.00	\$1,200.00
Parts	leaf spring bushing (Front)	2.00000	\$49.50	\$99.00
Parts	Leaf spring bushing (Rear)	4.00000	\$39.26	\$157.04
			Subtotal	\$1,456.04
Labor	Chassis / Chassis / R&R AC compressor - Completed: 1/24/2026	1.50000	\$150.00	\$225.00
Parts	AC compressor	1.00000	\$550.85	\$550.85
			Subtotal	\$775.85
Unit: 1 VIN: 3WKDDP9X1LF965925			Labor	\$4,200.00
2020 Kenworth T8 Series			Parts	\$3,036.03
Chassis: 486,114 Miles			Pre-Charge Subtotal	\$7,236.03
			GST	\$361.80
			(5% of \$7,236.03)	
			Total	\$7,597.83
			Payments & Credits	\$0.00
			Balance Due	\$7,597.83

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer Signature: _____

Printed Name: _____ Date: _____