

P47-1
SEP

2721524 Alberta Ltd. DBA Bulls Truck & Auto Repair

4205 76 Ave NW

Edmonton AB T6B 2H7

+17802033288

accounting@bullstruckrepair.com

GST/HST Registration No.: 754151561RT0001

INVOICE

BILL TO

Nunes Holdings

Nunes Holdings Ltd

4304 76 Ave NW

Edmonton Alberta T6B 2H8

INVOICE

2700

DATE

15/09/2026

TERMS

Due on receipt

DUE DATE

15/09/2026

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Labour	After hours outside service call	1	150.00	150.00
Parts	Air Dryer	1	380.00	380.00
Labour	Air Dryer r & r	2	100.00	200.00

International Truck
VIN No-3HSDJAPR5FN512661

SUBTOTAL

730.00

GST @ 5%

36.50

TOTAL

766.50

BALANCE DUE

\$766.50

EDMONTON DIESEL TRUCK REPAIR

4205 76th. Avenue

Edmonton AB T6B2H7

204-898-3913

edtrepair8401@gmail.com

GST/HST Registration No.: 800669046

INVOICE

BILL TO

TONY NUNES

NUNES HOLDINGS LTD.

4304- 76 ave NW

edmonton alberta t6b 2h8

INVOICE # 6171**DATE** 10-02-2022**DUE DATE** 12-03-2022**TERMS** Net 30

ACTIVITY	QTY	RATE	TAX	AMOUNT
Parts FRONT AND REAR TORQUE RODS	2	138.00	GST	276.00
REPAIR:LABOUR REPLACED THE TORQUE RODS	1	99.00	GST	99.00
Parts BOLTS, NUTS AND WASHERS FOR TORQUE ROD	1	28.00	GST	28.00
Parts 2ND AXLE BOTH SIDE SHOCKS	2	78.00	GST	156.00
REPAIR:LABOUR REPLACED THE SHOCKS	1	99.00	GST	99.00
Parts BRAKE PADS FOR ALL 3 AXLES	3	197.00	GST	591.00
REPAIR:LABOUR REPLACED THE BRAKE PADS FOR ALL 3 AXLES	3	99.00	GST	297.00
Parts TAIL LIGHTS	1	45.00	GST	45.00
REPAIR:LABOUR REPLACED THE TAIL LIGHTS, FIXED THE WIRING FOR BACKUP LIGHTS, RIGHT SIDE UTILITY LIGHTS AND FRONT FOG LIGHT	3	99.00	GST	297.00
Parts WIRE CONNECTORS, LOOM, ZIP TIES	1	30.00	GST	30.00
Parts QUARTER FENDER	1	65.00	GST	65.00

ACTIVITY	QTY	RATE	TAX	AMOUNT
REPAIR:LABOUR REPLACED THE QUARTER FANDER AND REPLACED THE FRONT BAR AND 7-WIRE ELECTRICAL CORD	1	99.00	GST	99.00
Parts FIFTH WHEEL PINS AND BUSHINGS	1	86.00	GST	86.00
REPAIR:LABOUR REPLACED THE FIFTH WHEEL PINS AND BUSHINGS	1	99.00	GST	99.00
REPAIR:LABOUR SAFETY STICKER	1	250.00	GST	250.00

UNIT - 982-0670	SUBTOTAL	2,517.00
KM - 1080428	GST @ 5%	125.85
VIN - FN512661	TOTAL	2,642.85
PLEASE MAKE SURE THAT ALL THE WHEEL NUTS ARE RE TORQUED AFTER 100 KM CUSTOMER IS SOLELY RESPONSIBLE FOR THIS	BALANCE DUE	\$2,642.85

TAX SUMMARY

	RATE	TAX	NET
	GST @ 5%	125.85	2,517.00

EDMONTON DIESEL TRUCK REPAIR

4205 76th. Avenue

Edmonton AB T6B2H7

204-898-3913

edtrepair8401@gmail.com

GST/HST Registration No.: 800669046

INVOICE

BILL TO

NUNES HOLDINGS LTD.

NUNES HOLDINGS LTD.

4304- 76 ave NW

edmonton alberta t6b 2h8

INVOICE # 7644**DATE 05-03-2023****DUE DATE 04-04-2023****TERMS Net 30**

ACTIVITY	QTY	RATE	TAX	AMOUNT
Parts ROTOR	4	512.00	GST	2,048.00
Parts WHEEL SEAL	4	66.00	GST	264.00
Parts BRAKE PAD	2	148.00	GST	296.00
REPAIR:LABOUR REPLACED AXLE2 BOTH SIDE ROTOR,BRAKE PAD AND WHEEL SEAL	8	99.00	GST	792.00
REPAIR:LABOUR REPLACED AXLE3 BOTH SIDE ROTOR,BRAKE PAD AND WHEEL SEAL	8	99.00	GST	792.00
Parts SPRING BUSHING	2	56.00	GST	112.00
REPAIR:LABOUR REPLACED AXLE-3 BOTH SIDE SPRING BUSHING	5	99.00	GST	495.00
Parts SHOCK	1	76.00	GST	76.00
REPAIR:LABOUR REPLACED AXLE-3 LEFT SIDE SHOCK	0.50	99.00	GST	49.50
Parts MUD FLAP HANGER	1	112.00	GST	112.00
Parts MUD FLAP	1	22.00	GST	22.00
Parts QUARTER FENDER	1	87.00	GST	87.00

ACTIVITY	QTY	RATE	TAX	AMOUNT
REPAIR:LABOUR REPLACED LEFT SIDE QUARTER FENDER AND MUDFLAP WITH HANGER	1	99.00	GST	99.00
Parts HUB NUT	1	39.00	GST	39.00
Parts BRAKE CHAMBETR	1	152.00	GST	152.00
REPAIR:LABOUR REPLACED AXLE-3 RIGHT SIDE BRAKE CHAMBER	1	99.00	GST	99.00
Parts HUB GASKET	6	8.00	GST	48.00
Parts 5TH WHEEL BUSHING	1	92.00	GST	92.00
REPAIR:LABOUR REPLACED 5TH WHEEL BUSHING	1	99.00	GST	99.00
Parts GLAD HAND	2	9.00	GST	18.00
REPAIR:LABOUR REPLACED BOTH GLAD HAND	0.50	99.00	GST	49.50
Parts BACK UP ALARM	1	36.00	GST	36.00
Parts TAIL LIGHT	2	59.00	GST	118.00
Parts PIG TAIL	2	9.00	GST	18.00
REPAIR:LABOUR REPLACED BACK UP ALARM,REPLACED BOTH TAIL LIGHT AND FIXED THE WIRING FROM THE CAB,FIXED THE CITY HORN WIRING	2.50	99.00	GST	247.50
Parts WHEEL SEAL	1	66.00	GST	66.00
REPAIR:LABOUR REPLACED AXLE -1 RIGHT SIDE WHEEL SEAL	2	99.00	GST	198.00
Shop supplies. WIRE ,CONNECTOR ,NUT,BOLT, WASHER,ETC	1	120.00	GST	120.00
Parts CVIP STICKER	1	250.00	GST	250.00

UNIT:982-0670

VIN:FN512661

KM:1162307

PLEASE MAKE SURE THAT ALL THE WHEEL NUTS ARE RE
TORQUED AFTER 100 KM CUSTOMER IS SOLELY RESPONSIBLE
FOR THIS

SUBTOTAL

6,894.50

GST @ 5%

344.74

TOTAL

7,239.24

BALANCE DUE

\$7,239.24

TAX SUMMARY