



FOUNTAIN TIRE (GRANDE PRAIRIE 100 STREET) LTD.

13003 100 ST
GRANDE PRAIRIE AB T8V 4H3

INVOICE

Order Number: 034SWO00189691
Service Contact: ANDREW ISLEIFSONPhone: 780.539.1710
Fax: 780.539.0664
F034@fountaintire.com
101857589RT0071Date: 20/06/2025
Invoice: 0341174829
PO#:

Terms of payment Net_30

Bill to Customer 034C00029024

Ship to Customer: 034C00029024

Year: 2010 Unit:
Make: GMC TRUCK
Model: YUKON
Design:
Engine: V8-325 5.3L
License: CPM4390, AB Colour: GRAY
Vin: 1GKUKCE06AR266114
Mileage: 206778 Hours: 0

| Item number | Item description | Qty | Unit price | Discount | Total |
|---|---|-------|------------|-----------|----------|
| Pickup / SUV Tires, Wheels and Service | | | | | |
| TSR021 | Rotate tires and adjust air pressure for longer-lasting, more even wear | 4.00 | \$18.00 | (\$72.00) | \$0.00 |
| Oil and Other Fluids | | | | | |
| LOF | Oil Service with AutoServe1 Digital Vehicle Report | 1.00 | \$55.00 | | \$55.00 |
| 5W30-DAX | 5W30 Conventional Oil | 6.00 | \$8.00 | | \$48.00 |
| 7060-NGF | OIL FILTER | 1.00 | \$12.72 | | \$12.72 |
| ENV-002 | Environmental Fee - Oil Filter | 1.00 | \$1.00 | | \$1.00 |
| ENV-001 | Environmental Fee - Fluids | 6.00 | \$0.50 | | \$3.00 |
| Brake and Wheel Bearing Parts and Service | | | | | |
| EHT1367H-RAY | F HYBRID PADS | 1.00 | \$194.59 | | \$194.59 |
| FRC12031-RCA | Brake Caliper, Front | 1.00 | \$159.94 | | \$159.94 |
| Quantity : 1.00 Item Type : PART | | | | | |
| EHT1194H-RAY | R HYBRID PADS | 1.00 | \$187.79 | | \$187.79 |
| 034-H16129 | HARDWARE | 1.00 | \$24.75 | | \$24.75 |
| BF31L-FLX | Heavy Duty DOT 3 Brake Fluid, 1 L | 1.00 | \$21.71 | | \$21.71 |
| 580279FZN-RAY | F DISC BRAKE ROTOR | 2.00 | \$194.14 | | \$388.28 |
| 580422FZN-RAY | R DISC BRAKE ROTOR | 2.00 | \$208.08 | | \$416.16 |
| FRC12031-RCA | Brake Caliper, Front | -1.00 | \$60.00 | | -\$60.00 |
| Quantity : -1.00 Item Type : Dirty CORE | | | | | |
| FRC12031-RCA | Brake Caliper, Front | 1.00 | \$60.00 | | \$60.00 |
| Quantity : 1.00 Item Type : CORE | | | | | |
| BRL | Remove & Replace Brake pads & rotors - all | 1.80 | \$155.00 | | \$279.00 |
| BRL | **Remove & Replace RF Caliper | 0.70 | \$155.00 | | \$108.50 |
| BRL | **Replace Rear Caliper Bushings | 0.50 | \$155.00 | | \$77.50 |
| ENV-007 | Environmental Fee - Brake Fluid | 1.00 | \$0.50 | | \$0.50 |
| Electrical Parts and Service | | | | | |
| ELL | Repair Wiring for Backup Sensors | 0.70 | \$155.00 | | \$108.50 |
| Engine Parts and Service | | | | | |
| ENL | Replace EVAP Canister and Vent System | 1.40 | \$155.00 | | \$217.00 |
| Fuel and Emissions Parts and Service | | | | | |
| CP434-BLU | Fuel Vapor Storage Canister | 1.00 | \$404.96 | | \$404.96 |
| CP516-STD | Canister Vent Solenoid | 1.00 | \$182.47 | | \$182.47 |
| Vision and Miscellaneous Parts and Service | | | | | |
| 7443-NLG | TAIL LIGHT | 1.00 | \$10.65 | | \$10.65 |
| MS2423 | Scan, Test & Retrieve DTC Codes (1/2 Hour Diagnosis) | 1.00 | \$105.00 | | \$105.00 |
| Other Miscellaneous Items | | | | | |
| SHOP | Shop Supplies | 1.00 | \$57.03 | | \$57.03 |

These parts and services were recommended for replacement or repair

| Item Description | Qty | Unit price | Net amount |
|------------------------------------|------|------------|------------|
| LOWER BALL JOINT | 2.00 | \$148.48 | \$296.96 |
| SWAY BAR LINK/KIT | 2.00 | \$42.82 | \$85.63 |
| Strut | 2.00 | \$361.32 | \$722.64 |
| shock | 2.00 | \$128.35 | \$256.71 |
| 4 Wheel Alignment - Improves Tire | 1.00 | \$159.95 | \$159.95 |
| Remove & Replace Both Front Sway | 0.60 | \$155.00 | \$93.00 |
| Remove & Replace Both Lower Ball | 4.20 | \$155.00 | \$651.00 |
| Remove & Replace Both Front Struts | 1.60 | \$155.00 | \$248.00 |

Fountain Tire is committed to protecting your personal information. Please refer to our Privacy Commitment at www.fountaintire.com. The personal information collected by Fountain Tire will be stored in Canada or in the United States for the purposes set out in our Privacy Code, and will be subject to the laws of the jurisdiction in which it is stored.



FOUNTAIN TIRE (GRANDE PRAIRIE 100 STREET) LTD.

13003 100 ST
GRANDE PRAIRIE AB T8V 4H3

INVOICE

Order Number: 034SWO00189691
Service Contact: ANDREW ISLEIFSON

Phone: 780.539.1710
Fax 780.539.0664
F034@fountaintire.com
101857589RT0071

Date: 20/06/2025
Invoice: 034I174829
PO#:
AirMiles # : *****83034921238
Terms of payment Net_30

Bill to Customer 034C00029024

Ship to Customer: 034C00029024

Year: 2010 Unit:
Make: GMC TRUCK
Model: YUKON
Design:
Engine: V8-325 5.3L
License: CPM4390, AB Colour: GRAY
Vin: 1GKUKCE06AR266114
Mileage: 206778 Hours: 0

Item number Item description

| | Qty | Unit price | Discount | Total |
|----------------------------|------|------------|----------|------------|
| Remove & Replace Both Rear | 0.80 | | | |
| | | \$155.00 | | \$124.00 |
| | | Sub Total: | | \$2,637.89 |

This estimate is valid for 30 days and excludes sales taxes

Air Miles: 150


Invoice comment

I acknowledge: (1) receipt of goods and services; and (2) Fountain Tire may conduct a registry search to verify the VIN on my vehicle if required for collection purposes on unpaid invoices related to my vehicle.

The customer is to ensure all wheel lugs are re torqued by a qualified technician before the vehicle has travelled 100 kilometers.

| | |
|--------------|------------|
| Parts: | \$2,052.02 |
| Services: | \$1,012.03 |
| Sub Total: | \$3,064.05 |
| GST: | \$153.20 |
| Total: (CAD) | \$3,217.25 |

Pay type: AR \$3,217.25


X