

609 Main Street N. Mossbank, SK S0H 3G0 Phone: 306-354-2411 www.southcountry.ca

306-692-2371 Moose Jaw, SK 306-354-2411 Mossbank, SK 306-642-3366 Assiniboia, SK 306-721-5050 Emerald Park, SK 306-842-4686 Weyburn, SK 306-726-2155 Southey, SK 306-746-2110 Raymore, SK 306-424-2212 Montmartre, SK



Total:

\$2,908.55

Invoice To Account No:		Deliver To:			SERV	/ICE INV	DICE
				Invoice Numb Invoice D Locati Work Order Numb Payment Ty Authorization Numb	ate on: per:	08/2	8/2024
	falls.				ge:		1 of 1
Make/Model:		Meter Serial-I	Number:	EQ ld:	- 1	Fleet No:	
Service Reminders:							
COMPLAINT:							
1 REPAIR HYDRAU	JLICS (#2 & #3 CREEP	PING)					
Details:							
CAUSE:							
CORRECTION:							
	MOVE 1 & 3, DISASSE	BLE, RESEAL & TEST. #1 & # MBLE, FOUND SHUT OFFS	#3 DO NOT FU TO BE STUCK	NCTION PROPER OPEN WITH PIEC	RLY AT AL CES OF S	L & PRESSUI EAL, RESEAL	RE UP ., RESET,
PartNumber	Description						
			2	Quantity	Net Price	Extended Price	Taxed Ind
AR86535	VALVE		2	8.00	Net Price \$79.74	Extended Price \$637.92	Taxed Ind
AR86535 R72653			<u>c</u>			The second second	Taxed Ind Y
the second secon	VALVE			8.00 3.00 2.00	\$79.74 \$1.65 \$80.59	\$637.92 \$4.95 \$161.18	Taxed Ind Y Y Y
R72653	VALVE SNAP RING			8.00 3.00	\$79.74 \$1.65 \$80.59 Net Price	\$637.92 \$4.95 \$161.18 Extended Price	Taxed Ind Y Y Y Taxed Ind
R72653 RE10924	VALVE SNAP RING KIT	RIES		8.00 3.00 2.00	\$79.74 \$1.65 \$80.59	\$637.92 \$4.95 \$161.18	Taxed Ind Y Y Y
R72653 RE10924 Miscellaneous	VALVE SNAP RING KIT Description	RIES OL&M: \$0.00	Ç	8.00 3.00 2.00 Quantity 1.00	\$79.74 \$1.65 \$80.59 Net Price	\$637.92 \$4.95 \$161.18 Extended Price	Taxed Ind Y Y Y Taxed Ind
R72653 RE10924 Miscellaneous SERVACCESS	VALVE SNAP RING KIT Description SERVICE ACCESSO		Ç	8.00 3.00 2.00 Quantity 1.00	\$79.74 \$1.65 \$80.59 Net Price \$96.00	\$637.92 \$4.95 \$161.18 <u>Extended Price</u> \$96.00 \$2,770.05	Taxed Ind Y Y Y Taxed Ind
R72653 RE10924 Miscellaneous SERVACCESS	VALVE SNAP RING KIT Description SERVICE ACCESSO	OL&M: \$0.00	Ç	8.00 3.00 2.00 Quantity 1.00	\$79.74 \$1.65 \$80.59 <u>Net Price</u> \$96.00 Sub-Total:	\$637.92 \$4.95 \$161.18 <u>Extended Price</u> \$96.00 \$2,770.05 r: \$1,8 s: \$8 M: c: \$	Taxed Ind Y Y Y Taxed Ind Y

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held resposible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by: Date:	
--------------------	--



609 Main Street N. Mossbank, SK S0H 3G0 Phone: 306-354-2411 www.southcountry.ca

 Moose Jaw, SK
 308-692-2371

 Mossbank, SK
 306-354-2411

 Assiniboia, SK
 306-642-3366

 Emerald Park, SK
 306-721-5050

 Weyburn, SK
 306-842-4688

 Southey, SK
 306-726-2155

 Raymore, SK
 306-746-2110

 Montmartre, SK
 306-424-2212



	• •	Deliver To:			30		V 8/ E 990
nvoice To Account No	J.	Conver 10.				RVICE	44010
				Work Or Pa	Invoice Date Location: rder Number: syment Type: tion Number:		09/07/202
Make/Model:		L	Carial Musekası	EQI	Page:	Fleet No:	1011
viake/iviodei.		Meter	Serial Number:	EQI	0.	Fiest No.	
Service Reminders:							
Sen1- Retail							
COMPLAINT:							
1 REPAIR A/C							
CAUSE:							
REPLACED BURNT SYSTEM WAS EMP	YTY	24 HOURS AND NO LEA	KS WERE FOU	IND			
REPLACED BURNT SYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED	PTY VITH NITROGEN FOR ADAPTERS WERE LE TERS		KS WERE FOU	IND			
REPLACED BURNT SYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4	OTY VITH NITROGEN FOR ADAPTERS WERE LE FERS LBS R-134A		KS WERE FOU	IND Quantity	Net Price	Extended Price	Taxed Inc
REPLACED BURNT SYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4	PTY VITH NITROGEN FOR ADAPTERS WERE LE TERS		KS WERE FOU		Net Price \$18.91	Extended Price \$18.91	
REPLACED BURNT SYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4 PartNumber AR77344	OTY VITH NITROGEN FOR ADAPTERS WERE LE TERS LBS R-134A Description		KS WERE FOU	Quantity			Taxed Inc
REPLACED BURNT SYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4 PartNumber AR77344	VITY VITH NITROGEN FOR ADAPTERS WERE LEFERS LBS R-134A Description FUSE		KS WERE FOU	Quantity 1.00	\$18.91	\$18.91	Y
REPLACED BURNT SYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4 PartNumber AR77344 RE212794	PTY VITH NITROGEN FOR ADAPTERS WERE LEFERS LBS R-134A Description FUSE ELBOW FITTI		KS WERE FOU	Quantity 1.00 1.00 1.00 Quantity	\$18.91 \$40.88 \$52.65 Net Price	\$18.91 \$40.88	Y Y Y Taxed Ind
REPLACED BURNT BYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4 PartNumber AR77344 RE212794 RE212795 Miscellaneous 134ASHOP	PTY VITH NITROGEN FOR ADAPTERS WERE LEFERS LBS R-134A Description FUSE ELBOW FITTI ELBOW FITTI Description 134 FREON	AKING	KS WERE FOU	Quantity 1.00 1.00 1.00 Quantity 4.00	\$18.91 \$40.88 \$52.65 <u>Net Price</u> \$30.00	\$18.91 \$40.88 \$52.65 <u>Extended Price</u> \$120.00	Y Y Y Taxed Ind Y
REPLACED BURNT BYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4 PartNumber AR77344 RE212794 RE212795 Miscellaneous 134ASHOP SERVACCESS	PTY VITH NITROGEN FOR ADAPTERS WERE LEFERS LBS R-134A Description FUSE ELBOW FITTI ELBOW FITTI Description 134 FREON SERVICE ACCESSO	RIES		Quantity 1.00 1.00 1.00 Quantity 4.00 1.00	\$18.91 \$40.88 \$52.65 <u>Net Price</u> \$30.00 \$33.66	\$18.91 \$40.88 \$52.65 <u>Extended Price</u> \$120.00 \$33.66	Y Y Y Taxed Ind
REPLACED BURNT BYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4 PartNumber AR77344 RE212794 RE212795 Miscellaneous 134ASHOP SERVACCESS	PTY VITH NITROGEN FOR ADAPTERS WERE LEFERS LBS R-134A Description FUSE ELBOW FITTI ELBOW FITTI Description 134 FREON	AKING	KS WERE FOU	Quantity 1.00 1.00 1.00 Quantity 4.00	\$18.91 \$40.88 \$52.65 <u>Net Price</u> \$30.00	\$18.91 \$40.88 \$52.65 <u>Extended Price</u> \$120.00	Y Y Y Taxed Ind Y
REPLACED BURNT BYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4 PartNumber AR77344 RE212794 RE212795 Miscellaneous 134ASHOP SERVACCESS Labor: \$561.00	PTY VITH NITROGEN FOR ADAPTERS WERE LEFERS LBS R-134A Description FUSE ELBOW FITTI ELBOW FITTI Description 134 FREON SERVICE ACCESSO	RIES OL&M: \$0.00 Credit Card Information		Quantity 1.00 1.00 1.00 Quantity 4.00 1.00	\$18.91 \$40.88 \$52.65 <u>Net Price</u> \$30.00 \$33.66 Sub-Total:	\$18.91 \$40.88 \$52.65 <u>Extended Price</u> \$120.00 \$33.66 \$827.10	Y Y Y Taxed Ind Y Y
REPLACED BURNT SYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4 PartNumber AR77344 RE212794 RE212795 Miscellaneous 134ASHOP SERVACCESS Labor: \$561.00	PTY VITH NITROGEN FOR ADAPTERS WERE LEFERS LBS R-134A Description FUSE ELBOW FITTI ELBOW FITTI Description 134 FREON SERVICE ACCESSO	RIES OL&M: \$0.00 Credit Card Information Type:		Quantity 1.00 1.00 1.00 Quantity 4.00 1.00	\$18.91 \$40.88 \$52.65 <u>Net Price</u> \$30.00 \$33.66 Sub-Total:	\$18.91 \$40.88 \$52.65 <u>Extended Price</u> \$120.00 \$33.66 \$827.10 r: \$56	Y Y Y Taxed Ind Y Y
REPLACED BURNT BYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4 PartNumber AR77344 RE212794 RE212795 Miscellaneous 134ASHOP SERVACCESS Labor: \$561.00 Customer PO No: Tax Exempt No:	PTY VITH NITROGEN FOR ADAPTERS WERE LEFERS LBS R-134A Description FUSE ELBOW FITTI ELBOW FITTI Description 134 FREON SERVICE ACCESSO	RIES OL&M: \$0.00 Credit Card Information Type: Auth No:		Quantity 1.00 1.00 1.00 Quantity 4.00 1.00	\$18.91 \$40.88 \$52.65 <u>Net Price</u> \$30.00 \$33.66 Sub-Total: Labo Parts	\$18.91 \$40.88 \$52.65 Extended Price \$120.00 \$33.66 \$827.10 r: \$56 \$: \$11 1: \$	Y Y Y Taxed Ind Y Y S1.00 (2.44 (0.00)
REPLACED BURNT SYSTEM WAS EMP PRESSURED UP W SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4 PartNumber AR77344 RE212794 RE212795 Miscellaneous 134ASHOP SERVACCESS Labor: \$561.00	PTY VITH NITROGEN FOR ADAPTERS WERE LEFERS LBS R-134A Description FUSE ELBOW FITTI ELBOW FITTI Description 134 FREON SERVICE ACCESSO	RIES OL&M: \$0.00 Credit Card Information Type:		Quantity 1.00 1.00 1.00 Quantity 4.00 1.00	\$18.91 \$40.88 \$52.65 Net Price \$30.00 \$33.66 Sub-Total: Labo Parts OL&N Misc	\$18.91 \$40.88 \$52.65 Extended Price \$120.00 \$33.66 \$827.10 r: \$56 \$: \$11 1: \$ 2: \$15	Y Y Y Taxed Ind Y Y S1.00 2.44 60.00 3.66
REPLACED BURNTSYSTEM WAS EMPPRESSURED UP WENTER SURED UP WENTER SURED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4 PartNumber AR77344 RE212794 RE212795 Miscellaneous 134ASHOP SERVACCESS Labor: \$561.00 Customer PO No: Tax Exempt No:	PTY VITH NITROGEN FOR ADAPTERS WERE LEFERS LBS R-134A Description FUSE ELBOW FITTI ELBOW FITTI Description 134 FREON SERVICE ACCESSO	RIES OL&M: \$0.00 Credit Card Information Type: Auth No:		Quantity 1.00 1.00 1.00 Quantity 4.00 1.00	\$18.91 \$40.88 \$52.65 <u>Net Price</u> \$30.00 \$33.66 Sub-Total: Labo Parts	\$18.91 \$40.88 \$52.65 Extended Price \$120.00 \$33.66 \$827.10 r: \$56 \$: \$11 1: \$ 2: \$15	Y Y Y Taxed Ind Y Y S1.00 12.44 50.00 3.66 1.36
SUSPECTED R134 REPLACED ADAPT VACUUMED CHARGED WITH 4 PartNumber AR77344 RE212794 RE212795 Miscellaneous 134ASHOP SERVACCESS Labor: \$561.00 Customer PO No: Tax Exempt No:	PTY VITH NITROGEN FOR ADAPTERS WERE LEFERS LBS R-134A Description FUSE ELBOW FITTI ELBOW FITTI Description 134 FREON SERVICE ACCESSO	RIES OL&M: \$0.00 Credit Card Information Type: Auth No:		Quantity 1.00 1.00 1.00 Quantity 4.00 1.00	\$18.91 \$40.88 \$52.65 Net Price \$30.00 \$33.66 Sub-Total: Labo Parts OL&N Misc GST	\$18.91 \$40.88 \$52.65 Extended Price \$120.00 \$33.66 \$827.10 r: \$56 s: \$11 d: \$ s: \$15 d: \$4 d: \$4	Y Y Y Taxed Ind Y Y S1.00 2.44 60.00 3.66

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held resposible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:	Date:
received by.	Date.