

Andrews Autos TA Weightman Automotive

Factory 3 / 30 Michael street
Pakenham VIC 3810
ABN 33 557 172 616
Tel: 03 5941 7450 Fax: 03 5941 7452
Email: ian@weightinvest.com.au
Website: www.andrewsautos.com.au
Rta no. Au47170



Tax Invoice

Inv. No.	43322	Date	17/11/25	Order No.	-	Sales ID	-
----------	-------	------	----------	-----------	---	----------	---

Client Details	Vehicle Details
Linct Group 2 / 4 Purton Road Pakenham VIC 3175	Rego: LINCT5 Odo: 413679 Ref: 28/10/2026 Make/Model: TOYOTA HI-LUX Type: 4WD Year: 2015 VIN: MR0KA3CD601186967 Next service: SCHEDULED SERVICE - LARGER VEHICLE Due: 17/05/26 Kms: 423679

Account	11896	Home	-	Work	-	Mobile	0418140661
---------	-------	------	---	------	---	--------	------------

Work Done

SCHEDULED SERVICE replacing parts as listed . Checks include all fluid levels on top and underneath vehicle and their condition. General visual check of underbody components including steering, suspension, mountings and pipes. Checks of wiper/washer operation, lighting, battery and charge and other checks specific to the kms and age of vehicle. Road tested vehicle on completion of all works to ensure customer satisfaction.

Replaced engine oil and oil filter.
Replaced sump plug washer.
Replaced air and cabin filter.
Replaced MAP filter.

PUNCTURE REPAIR RHR.

DIESEL FUEL FILTER REPLACEMENT entailed removing any attached hardware, remove then replace filter ensuring leak proof seal and bleeding system on completion.

AUTOMATIC TRANSMISSION SERVICE - Required raise vehicle, drain transmission fluid, remove pan and filter assemblies, inspect for any loose or foreign material, replace filter, add conditioner and reassemble. Refill transmission, check for leaks and correct operation on completion.

FRONT AND REAR DIFF` OIL REPLACEMENT Drained And Then Refilled The Diff With New Gear Oil.

Services, Parts & Labour

Qty	Description	Unit Price	Total (Ex)	Tax	Total (Inc)
1	SCHEDULED SERVICE - LARGER VEHICLES	\$236.36	\$236.36	\$23.64 GST	\$260.00
1	Sundries- Inc` Small Quantities Grease, Top Up Fluids, W`screen washer additive ,Sealants, Hardware.	\$18.18	\$18.18	\$1.82 GST	\$20.00
1	Engine oil flush treatment.	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Epa Levy , Waste Disposal Inc. Hazardous Waste.	\$9.09	\$9.09	\$0.91 GST	\$10.00
7.7	VANTAGE MV 5W-30	\$17.24	\$132.73	\$13.27 GST	\$146.00
1	Oil filter	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Sump Plug Washer	\$4.55	\$4.55	\$0.45 GST	\$5.00
1	FILTER - AIR	\$65.45	\$65.45	\$6.55 GST	\$72.00
1	FILTER - CABIN AIR	\$60.00	\$60.00	\$6.00 GST	\$66.00
1	Filter, Gas	\$80.00	\$80.00	\$8.00 GST	\$88.00
1	PUNCTURE REPAIR	\$40.91	\$40.91	\$4.09 GST	\$45.00
1	FUEL FILTER REPLACEMENT- DIESEL	\$59.09	\$59.09	\$5.91 GST	\$65.00
1	FILTER - FUEL	\$61.82	\$61.82	\$6.18 GST	\$68.00
1	TRANSMISSION SERVICE	\$180.00	\$180.00	\$18.00 GST	\$198.00
1	FILTER SERVICE KIT - TRANSMISSION	\$110.91	\$110.91	\$11.09 GST	\$122.00

Andrews Autos TA Weightman Automotive

Factory 3 / 30 Michael street
Pakenham VIC 3810
ABN 33 557 172 616
Tel: 03 5941 7450 Fax: 03 5941 7452
Email: ian@weightinvest.com.au
Website: www.andrewsautos.com.au
Rta no. Au47170



Tax Invoice

Inv. No.	43322	Date	17/11/25	Order No.	-	Sales ID	-
5	ATF LV			\$16.00	\$80.00	\$8.00 GST	\$88.00
1	DIFF OIL REPLACEMENT & TRANSFER CASE OIL REPLACEMENT			\$80.00	\$80.00	\$8.00 GST	\$88.00
6.2	PRO GEAR GL5 75W85 FULL SYN 20L			\$31.09	\$192.73	\$19.27 GST	\$212.00

Vehicle Report

Approx Brake Lining Thickness - (3mm is low but still ok)
Front 8mm, Rear 3mm

During repairs to this vehicle, these items were noted
Reported Fault Codes

IM: Immediate

EA: Early attention

N: Next service

O: Monitor/Observation

- O: Engine noisy on start up, timing chain a little noisy
- O: Steering rack ends have minor play.
- O: Secondary battery @ 3.7V
- O: Battery @ 42% health.
- O: Shackle bushes worn.
- O: Steering, right hand down.
- O: Tyres scoloping, Fronts heavily.
- O: Right hand rear warning not working.

Financial Summary

Total (Ex. Tax)	\$1,453.64	Terms	Cash on delivery
Tax Total	\$145.36	Paid	\$0.00
Total (Inc. Tax)	\$1,599.00	Balance	\$1,599.00

Andrews Autos
Business account

Bsb 083 547 acc no 747698419

Our goods and services come with guarantees that cannot be excluded under the Australian consumer law. For major failures with the service, you are entitled: 1. To cancel your service contract with us; and 2. To a refund for the unused portion, or to compensation for its reduced value. You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or a service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done, you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service. For details visit repcoservice.com

Andrews Autos TA Weightman Automotive

Factory 3 / 30 Michael street
Pakenham VIC 3810
ABN 33 557 172 616
Tel: 03 5941 7450 Fax: 03 5941 7452
Email: ian@weightinvest.com.au
Website: www.andrewsautos.com.au
Rta no. Au47170



Tax Invoice

Inv. No.	41810	Date	14/04/25	Order No.	-	Sales ID	-
----------	-------	------	----------	-----------	---	----------	---

Client Details	Vehicle Details
Linct Group 2 / 4 Purton Road Pakenham VIC 3175	Rego: LINCT5 Odo: 382802 Ref: 28/10/2025 Make/Model: TOYOTA HI-LUX Type: 4WD Year: 2015 VIN: MR0KA3CD601186967 Next service: SCHEDULED SERVICE - LARGER VEHICLE Due: 14/10/25 Kms: 392802

Account	11896	Home	-	Work	-	Mobile	0418140661
---------	-------	------	---	------	---	--------	------------

Work Done

SCHEDULED SERVICE replacing parts as listed . Checks include all fluid levels on top and underneath vehicle and their condition. General visual check of underbody components including steering, suspension, mountings and pipes. Checks of wiper/washer operation, lighting, battery and charge and other checks specific to the kms and age of vehicle. Road tested vehicle on completion of all works to ensure customer satisfaction.

Replaced engine oil and oil filter.
Replaced sump plug washer.
Replaced air and cabin filters.

DIESEL FUEL FILTER REPLACEMENT entailed removing any attached hardware, remove then replace filter ensuring leak proof seal and bleeding system on completion.

FRONT BRAKE DISC REPLACEMENT required raising vehicle and removing wheels and calliper assemblies, removing and replacing disc then reassembly and test on completion.

FRONT BRAKE PADS REPLACEMENT Removed wheels and disassembled callipers to ensure proper operation of calliper slides and reassembled then road tested.

BRAKE FLUID FLUSH Drained the fluid from the master cylinder. Cleaned the cap & reservoir. Refilled with fluid, then raised the vehicle and pressure bled the new fluid through the system, Removed any air and refilled the chamber. Rechecked operation.

REPLACED WIPER BLADES ensuring correct location in arms to ensure full contact with windscreen.

NUMBER PLATE GLOBE REPLACEMENT- accessed globe holder, inspected condition, replaced globe, reassembled and checked operation.

Services, Parts & Labour

Qty	Description	Unit Price	Total (Ex)	Tax	Total (Inc)
1	SCHEDULED SERVICE - LARGER VEHICLES	\$218.18	\$218.18	\$21.82 GST	\$240.00
1	Sundries- Inc` Small Quantities Grease, Top Up Fluids, W`screen washer additive ,Sealants, Hardware.	\$18.18	\$18.18	\$1.82 GST	\$20.00
1	Engine oil flush treatment.	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Epa Levy , Waste Disposal Inc. Hazardous Waste.	\$9.09	\$9.09	\$0.91 GST	\$10.00
7.7	VANTAGE MV 5W-30	\$17.00	\$130.91	\$13.09 GST	\$144.00
1	Oil filter	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Sump Plug Washer	\$4.55	\$4.55	\$0.45 GST	\$5.00
1	FILTER - AIR	\$61.82	\$61.82	\$6.18 GST	\$68.00
1	FILTER - CABIN AIR	\$56.36	\$56.36	\$5.64 GST	\$62.00
1	FUEL FILTER REPLACEMENT- DIESEL	\$50.00	\$50.00	\$5.00 GST	\$55.00
1	FILTER - FUEL	\$61.82	\$61.82	\$6.18 GST	\$68.00
1	BRAKE DISCS REPLACEMENT - front	\$63.64	\$63.64	\$6.36 GST	\$70.00
2	REPCO ARMOUR BRAKE ROTOR	\$117.28	\$234.55	\$23.45 GST	\$258.00

Andrews Autos TA Weightman Automotive

Factory 3 / 30 Michael street
Pakenham VIC 3810
ABN 33 557 172 616
Tel: 03 5941 7450 Fax: 03 5941 7452
Email: ian@weightinvest.com.au
Website: www.andrewsautos.com.au
Rta no. Au47170



Tax Invoice

Inv. No.	41810	Date	14/04/25	Order No.	-	Sales ID	-
1	BRAKE PAD REPLACEMENT- front			\$63.64	\$63.64	\$6.36 GST	\$70.00
1	PAD SET-DISC BRAKE			\$101.82	\$101.82	\$10.18 GST	\$112.00
1	BRAKE FLUID FLUSH			\$54.55	\$54.55	\$5.45 GST	\$60.00
1	BRAKE / CLUTCH FLUID			\$35.45	\$35.45	\$3.55 GST	\$39.00
1	WIPER BLADE REPLACEMENT x2			\$12.73	\$12.73	\$1.27 GST	\$14.00
2	Wiper Insert			\$10.91	\$21.82	\$2.18 GST	\$24.00
1	NUMBER PLATE GLOBE REPLACEMENT			\$7.27	\$7.27	\$0.73 GST	\$8.00
1	GLOBEWEDGE 5W 10X26MM			\$4.55	\$4.55	\$0.45 GST	\$5.00

Vehicle Report

Approx Brake Lining Thickness - (3mm is low but still ok)
Front NEW, Rear 3 mm

During repairs to this vehicle, these items were noted

Reported Fault Codes

IM: Immediate

EA: Early attention

N: Next service

O: Monitor/Observation

N: Transmission pan gasket leaking.

O: Engine noisy on start up, timing chain a little noisy

O: Steering rack ends have minor play.

Financial Summary

Total (Ex. Tax)	\$1,252.75	Terms	Cash on delivery
Tax Total	\$125.25	Paid	\$0.00
Total (Inc. Tax)	\$1,378.00	Balance	\$1,378.00

Andrews Autos
Business account

Bsb 083 547 acc no 747698419

Our goods and services come with guarantees that cannot be excluded under the Australian consumer law. For major failures with the service, you are entitled: 1. To cancel your service contract with us; and 2. To a refund for the unused portion, or to compensation for its reduced value. You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or a service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done, you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service. For details visit repcoservice.com

Andrews Autos TA Weightman Automotive

Factory 3 / 30 Michael street
Pakenham VIC 3810
ABN 33 557 172 616
Tel: 03 5941 7450 Fax: 03 5941 7452
Email: ian@weightinvest.com.au
Website: www.andrewsautos.com.au
Rta no. Au47170



Tax Invoice

Inv. No.	42901	Date	17/09/25	Order No.	-	Sales ID	-
----------	-------	------	----------	-----------	---	----------	---

Client Details	Vehicle Details
Linct Group 2 / 4 Purton Road Pakenham VIC 3175	Rego: LINCT5 Odo: 397051 Ref: 28/10/2025 Make/Model: TOYOTA HI-LUX Type: 4WD Year: 2015 VIN: MR0KA3CD601186967 Next service: SCHEDULED SERVICE - LARGER VEHICLE Due: 17/03/26 Kms: 407051

Account	11896	Home	-	Work	-	Mobile	0418140661
---------	-------	------	---	------	---	--------	------------

Work done

SCHEDULED SERVICE replacing parts as listed . Checks include all fluid levels on top and underneath vehicle and their condition. General visual check of underbody components including steering, suspension, mountings and pipes. Checks of wiper/washer operation, lighting, battery and charge and other checks specific to the kms and age of vehicle. Road tested vehicle on completion of all works to ensure customer satisfaction.

Replaced engine oil and oil filter.
Replaced sump plug washer.
Replaced cabin filter.

REPLACED WIPER BLADES ensuring correct location in arms to ensure full contact with windscreen.

Services, Parts & Labour

Qty	Description	Unit Price	Total (Ex)	Tax	Total (Inc)
1	SCHEDULED SERVICE - LARGER VEHICLES	\$236.36	\$236.36	\$23.64 GST	\$260.00
1	Sundries- Inc` Small Quantities Grease, Top Up Fluids, W'screen washer additive ,Sealants, Hardware.	\$18.18	\$18.18	\$1.82 GST	\$20.00
1	Engine oil flush treatment.	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Epa Levy , Waste Disposal Inc. Hazardous Waste.	\$9.09	\$9.09	\$0.91 GST	\$10.00
7.7	VANTAGE MV 5W-30	\$17.24	\$132.73	\$13.27 GST	\$146.00
1	Oil filter	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Sump Plug Washer	\$4.55	\$4.55	\$0.45 GST	\$5.00
1	FILTER - CABIN AIR	\$52.73	\$52.73	\$5.27 GST	\$58.00
1	WIPER BLADE REPLACEMENT x2	\$7.27	\$7.27	\$0.73 GST	\$8.00
2	Wiper Insert	\$10.00	\$20.00	\$2.00 GST	\$22.00

Vehicle report

Approx Brake Lining Thickness - (3mm is low but still ok)
Front 8.5mm, Rear 3 mm

During repairs to this vehicle, these items were noted
Reported Fault Codes

IM: Immediate
EA: Early attention
N: Next service
O: Monitor/Observation

N: Transmission pan gasket leaking.
O: Engine noisy on start up, timing chain a little noisy
O: Steering rack ends have minor play.
O: Secondary battery @ 3.7V

Andrews Autos TA Weightman Automotive

Factory 3 / 30 Michael street
Pakenham VIC 3810
ABN 33 557 172 616
Tel: 03 5941 7450 Fax: 03 5941 7452
Email: ian@weightinvest.com.au
Website: www.andrewsautos.com.au
Rta no. Au47170



Tax Invoice

Inv. No.	42901	Date	17/09/25	Order No.	-	Sales ID	-
----------	-------	------	----------	-----------	---	----------	---

O: Battery @ 42% health.
O: Shackle bushes worn.
O: Steering, right hand down.
O: Front tyres scoloped.
O: Right hand rear warning not working.
O: Map filter.

Financial Summary

Total (Ex. Tax)	\$522.73	Terms	Cash on delivery
Tax Total	\$52.27	Paid	\$0.00
Total (Inc. Tax)	\$575.00	Balance	\$575.00

Andrews Autos
Business account

Bsb 083 547 acc no 747698419

Our goods and services come with guarantees that cannot be excluded under the Australian consumer law. For major failures with the service, you are entitled: 1. To cancel your service contract with us; and 2. To a refund for the unused portion, or to compensation for its reduced value. You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or a service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done, you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service. For details visit repcoservice.com