

Work Order History Report

07-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		Plant Hire 51 Volvo A40F ADT					
	53586	Reman Transmission - 7434hrs - Replaced batteries. Replaced suction hose to pump 1. Drained fluids and disassembled all connecting components and wiring. Removed transmission and prepped for transport, strapped onto skid. Fitted Reco oil cooler and cleaned transmission lines. Replaced various hydraulic hoses. Replace bonnet pump. Replaced rear main seal. Refit flywheel and transmission and reassemble all components. Replace operators seat and wire into truck (charged to unit 1090). Replaced rear PTO elbow fitting O-ring. Re-sealed LH steer cylinder. Reseal injector harness.	13/12/2024 2:	Hours	.00	.00	\$41381.06
	54043	Replace starter isolator - 7437hrs + Replace lock handle on beacon slide. Update fire extinguisher. Topped up hyd oil.	13/02/2025 8:	Hours	.00	.00	\$489.80
	54081	Off/Pre-Hire - 7555hrs - Resealed injector harness. Replaced RH low beam bulb. Replaced beacon. Replaced front A-arm bush & fit Reco lower vertical hitch pin. Replaced RH bottom step and ropes, replaced mounting Orings on pumps 1 & 2, Replace Case drain hose from pump 2. Replace Battery isolator.	9/05/2025 8:0	Hours	.00	.00	\$7794.51
	54288	Off/Pre hire - 7618hrs - Fit fire extinguisher. Fit new lynch pins to belly guards. repair bent wheel chocks + prep and paint.	29/05/2025 1:	Hours	.00	.00	\$891.07
	54649	4,000 Hr Service - 7,988 Hrs.	9/09/2025 12:	Hours	.00	.00	\$8409.31
	54635	Off / Pre Hire Inspection - hrs rectify coolant leak, replace faulty UHF mic.	10/11/2025 1	Hours	.00	.00	\$2873.21
		: <u>6</u>	Asset Total:	1062	0.0	0.0	\$61,838.96
		: <u>6</u>	Parent Total:	TPH	0.0	0.0	\$61,838.96

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		Grand Total		<u>6</u>	<u>0.0</u>	<u>0.0</u>	<u>\$61,838.96</u>