

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3704	A/C Fan, bonnet strut, Brakes, Cab, clearance lights, leak oil, mudflap, seat, steer wheel, tail lights, tyres	17/03/2026	17/03/2026	639,010	0	0		Internal Workshop 4x drive tyres 1st axle replaced reverse lights repair clearance lights replace brakes straighten steer wheel shaft seals leak fixed oil leak on input shaft repaired cab shock replaced a/c control replaced oil leak @ fuel pump repaired bonnet struts replaced tidied up mud flaps seat cushions replaced	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3418	ELECTRICAL, Hydraulics, Signage	07/02/2026	07/02/2026	87,664	0	0		Internal Workshop Repair and relocate number plate, replaced D/S and P/S taillights from damage, re-positioned hydraulic coupling to control fitting leaks.	\$0.00
S-1719	C - 100k	05/12/2025	12/12/2025	637,000 69,993	0	0		Internal Workshop Completed C service	\$0.00
R-3065	Steering	05/12/2025	05/12/2025	652,454		0		Internal Workshop Removed and replaced bent steering arm Sent for wheel alignment	\$0.00
R-3064	Steering, uhf	05/12/2025	05/12/2025	651,940		0		Internal Workshop Replaced UHF and microphone Diognosed bent steering arm and ordered	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3069	Air System, Steering	03/12/2025	03/12/2025	652,163	0	0		Internal Workshop Replaced air fittings and couplings, Removed and replaced drag link realigned steering column with steering box, dry and wet bled Power steering system, rotated tyres, sent truck to pro-axle for wheel alignment. Road tested vehicle, tested all components for correct operation - all in working condition.	\$0.00
R-3491	ELECTRICAL	24/11/2025	24/11/2025	648,806	0	0		Internal Workshop Re-wired taillight assembly, inspected for any faults - all in working condition.	\$0.00
R-3035	ELECTRICAL	24/11/2025	24/11/2025	648,806	0	0		Internal Workshop Rewired taillight assembly, completed "A" service.	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
S-1825	A - 10k	24/11/2025	24/11/2025	648,806 11,806	0	0		Internal Workshop Completed "A" service.	\$0.00
R-3343	air compressor	20/11/2025	20/11/2025	647,603	0	0		Internal Workshop Inspected cooling system, found failed internal seals on compressor. Drained coolant, replaced compressor and gaskets between power steering pump, filled and bled cooling system. Tested all components for serviceability - all in working condition.	\$0.00
R-3026	Hydraulics	07/11/2025	07/11/2025	643,061	0	0		Internal Workshop Degreased affected area, removed and replaced hydraulic fitting. Topped up oil and operated bins, tested for correct operation - all in working condition.	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
S-1641	A - 10k	01/10/2025	01/10/2025	648,806 73,742	0	0		Internal Workshop Completed A service	\$0.00
R-2682	TYRE	08/07/2025	08/07/2025			0	1681		\$0.00
R-2493	Brakes	02/06/2025	02/06/2025	617,202	0	0	1463		\$0.00
R-2491	fire extinguisher	02/06/2025	02/06/2025	617,202	0	0	1464		\$0.00
R-2490	coolant leaks	02/06/2025	02/06/2025	617,202	0	0	1462		\$0.00
R-2480	coolant leaks	29/05/2025	29/05/2025	616,081	0	0	1442		\$0.00
R-2474	fire extinguisher	29/05/2025	29/05/2025	616,081	0	0	1443		\$0.00
R-2464	Coolant Top Up	27/05/2025	27/05/2025	614,736	0	0	1415		\$0.00
R-2437	number plate	23/05/2025	23/05/2025	613,396	0	0	1388		\$0.00

Generated at: 28/05/2026, 4:57:07 pm