

DAIMLER TRUCKS SHEPPARTON

Operated by TriStar Truck and Bus Pty Ltd
ATF TriStar Unit Trust



SERVICE TAX INVOICE

ABN 12 241 713 151 / ACN 637 808 792

TriStar Truck and Bus Pty Ltd
Authorised Mercedes-Benz, Freightliner
& Fuso Sales, Service & Parts

*** DOCUMENT COPY ***

Invoice To: 3129
Hamilton Contracting (Nsw) Pty Ltd
P.O. Box 256
MULWALA NSW 2647

Deliver To:
Hamilton Contracting P/L
Warrawilla
JERILDERIE NSW 2716

Document No.:	768723
Document Date:	14/01/2026
Repair Order No.:	497934
Rego No.:	XV52NI
Make/Model:	2020 Freightliner CASCADIA
Vehicle ID No.:	1FVJHYD1XMLMH2239
Paint:	
Odometer:	752983
Engine Hrs:	
Delivery Date:	
Invoice To:	3129
Customer ABN:	44105773877
Tax Exempt No.:	
P/Order No.:	
Page:	1 of 3

ZR1

750,000KM M2 INSPECTION SERVICE

\$371.74

CARRIED OUT M2 INSPECTION SERVICE.
TOP UP ENGINE OIL 4L

Part Number	Part Description	Quantity	Nett Value	Total Cost
GLOBAL	PRIME ENGINE GLOBAL 10W-40	4.00	9.97	39.88

Parts Totals: 4.00 \$39.88

ZR2

CHECK A/C

\$92.94

CHECKED A/C FOUND CAB FILTER BLOCKED
REMOVED AND REPLACED CAB FILTER
CHECKED ALL PRESSURES ALL OK.

Part Number	Part Description	Quantity	Nett Value	Total Cost
QABPN10G91559	FILTER-AIR	1.00	31.07	31.07

Parts Totals: 1.00 \$31.07

ZR4

REPLACE WINDSCREEN
REPLACE WINDSCREEN

\$375.00

Part Number	Part Description	Quantity	Nett Value	Total Cost
QFLCA18-71102-004	"GLASS-WSHLD,1PC,ROPED,MPC"	1.00	730.52	730.52

Parts Totals: 1.00 \$730.52

ZR5

TRAILER LIGHTS (LHS) NOT WORKING WHEN CONNECTED TO THIS TRUCK

\$340.76

DIAGNOSED TRUCK AND FOUND SOME LIGHTS ON THE TRAILER NOT WORKING.

212-216 Numurkah Road
Shepparton VIC 3630
Tel 03 4811 5300
www.daimlertrucksshepparton.com.au
MCT-0012706 / RTA-AU62149

DAIMLER TRUCKS SHEPPARTON

Operated by TriStar Truck and Bus Pty Ltd
ATF TriStar Unit Trust



SERVICE TAX INVOICE

ABN 12 241 713 151 / ACN 637 808 792

TriStar Truck and Bus Pty Ltd
Authorised Mercedes-Benz, Freightliner
& Fuso Sales, Service & Parts

*** DOCUMENT COPY ***

Invoice To: 3129
Hamilton Contracting (Nsw) Pty Ltd
P.O. Box 256
MULWALA NSW 2647

Deliver To:
Hamilton Contracting P/L
Warrawilla
JERILDERIE NSW 2716

Document No.:	768723
Document Date:	14/01/2026
Repair Order No.:	497934
Rego No.:	XV52NI
Make/Model:	2020 Freightliner CASCADIA
Vehicle ID No.:	1FVJHYD1XMLMH2239
Paint:	
Odometer:	752983
Engine Hrs:	
Delivery Date:	
Invoice To:	3129
Customer ABN:	44105773877
Tax Exempt No.:	
P/Order No.:	
Page:	2 of 3

ZR5

CHECKED 7 PIN PLUG AND VOLTAGE
FOUND A MISSING EARTH
REPLACED EARTH CABLE
ALL OK.

Part Number	Part Description	Quantity	Nett Value	Total Cost
QNAV68012BL	RELAY 12V 4 PIN 70A R B	1.00	22.65	22.65

Parts Totals: 1.00 \$22.65

ZR7

LH REAR HUB SEAL LEAKING

\$557.61

REMOVE THE TYRE, UNBOLTED ALL THE OLD HUB SEAL AND REMOVE THE HUB. INSTALLED NEW HUB SEAL. TIGHTEN ALL THE BOLTS ON THE TYRE WITH 600NM TORQUE.
TEST DRIVE ALL OK.

Part Number	Part Description	Quantity	Nett Value	Total Cost
QFLC11-30728-000	"O-RING SEAL, AXLE SHAFT"	1.00	42.14	42.14
QFLC11-14418-000	GASKET-AXLE SHAFT 7.00 8	1.00	7.77	7.77
QTDAKIT2902	BREATHER & TUBERPL'S A119	1.00	19.96	19.96
QSKF47693	SCOTSEAL CLASSIC LONGLIFE	1.00	42.01	42.01

Parts Totals: 4.00 \$111.88

ZR8

AIR TANKS FULL OF WATER

\$105.33

INSPECTED AND FOUND THE AIR DRIER WAS BLOCKED
REMOVED AND REPLACED AIR DRIER,
FILLED WITH AIR TESTED ALL OK

Part Number	Part Description	Quantity	Nett Value	Total Cost
-------------	------------------	----------	------------	------------

DAIMLER TRUCKS SHEPPARTON

Operated by TriStar Truck and Bus Pty Ltd
ATF TriStar Unit Trust



SERVICE TAX INVOICE

ABN 12 241 713 151 / ACN 637 808 792

TriStar Truck and Bus Pty Ltd
Authorised Mercedes-Benz, Freightliner
& Fuso Sales, Service & Parts

*** DOCUMENT COPY ***

Invoice To: 3129
Hamilton Contracting (Nsw) Pty Ltd
P.O. Box 256
MULWALA NSW 2647

Deliver To:
Hamilton Contracting P/L
Warrawilla
JERILDERIE NSW 2716

Document No.:	768723
Document Date:	14/01/2026
Repair Order No.:	497934
Rego No.:	XV52NI
Make/Model:	2020 Freightliner CASCADIA
Vehicle ID No.:	1FVJHYD1XMLMH2239
Paint:	
Odometer:	752983
Engine Hrs:	
Delivery Date:	
Invoice To:	3129
Customer ABN:	44105773877
Tax Exempt No.:	
P/Order No.:	
Page:	3 of 3

ZR8

QWAB4329012482 CARTRIDGE AIR DRYER

1.00 171.04 171.04

Parts Totals: 1.00 \$171.04

ZR9

AIR LEAK

\$371.74

INSPECTED AND FOUND BOTH AIRBAGS ON THE 2ND AXLE LEAKING AIR.

REMOVED AND REPLACED AIRBAGS TESTED ALL OK.

Part Number	Part Description	Quantity	Nett Value	Total Cost
QFIW013778536	AIR SPRING-AIR BAG/PISTON	2.00	213.20	426.40

Parts Totals: 2.00 \$426.40

ZR6

AUXILIRAY HIGH BEAM ALWAYS ON

\$278.81

CHECKED THE ABOVE COMPLAINT

CHECKED THE CONNECTORS OK

CHECKED REALY AND FOUND THE BURNT AND SHORT CIRCUIT

REPLACED REALY AND RE WITRED CONNECTOR

TESTED ALL OK

Part Number	Part Description	Quantity	Nett Value	Total Cost
QNAV68012BL	RELAY 12V 4 PIN 70A R B	1.00	22.65	22.65

Parts Totals: 1.00 \$22.65

Advisor: Josh O'Dwyer

Sub Total for All: \$4,050.02

Rounding: \$0.00

GST: \$405.00

Total: \$4,455.02

Bank Account Details for Direct Payments:

Bank: NAB Branch: Wagga

BSB: 082-811 Account No: 254952255 Account Name: TriStar Truck & Bus

212-216 Numurkah Road

Shepparton VIC 3630

Tel 03 4811 5300

www.daimlertrucksshepparton.com.au

MCT-0012706 / RTA-AU62149

Mercedes-Benz - are registered trademarks of Daimler AG. Stuttgart, Germany

Freightliner is a registered trademark of Freightliner LLC, USA

Fuso is a registered trademark of Mitsubishi Fuso Trucks & Bus Corporation, Japan