

DAIMLER TRUCKS SHEPPARTON

Operated by TriStar Truck and Bus Pty Ltd
ATF TriStar Unit Trust



SERVICE TAX INVOICE

ABN 12 241 713 151 / ACN 637 808 792

TriStar Truck and Bus Pty Ltd
Authorised Mercedes-Benz, Freightliner
& Fuso Sales, Service & Parts

*** DOCUMENT COPY ***

Invoice To: 3129
Hamilton Contracting (Nsw) Pty Ltd
P.O. Box 256
MULWALA NSW 2647

Deliver To:
Hamilton Contracting P/L
Warrawilla
JERILDERIE NSW 2716

Document No.:	758959
Document Date:	6/09/2025
Repair Order No.:	493154
Rego No.:	XV52NI
Make/Model:	2020 Freightliner CASCADIA
Vehicle ID No.:	1FVJHYD1XMLMH2239
Paint:	
Odometer:	699095
Engine Hrs:	
Delivery Date:	
Invoice To:	3129
Customer ABN:	44105773877
Tax Exempt No.:	
P/Order No.:	
Page:	1 of 2

ZW1

TRANSMISSION ISSUES

\$2,230.47

BRING TRUCK INTO WORKSHOP, UNSECURE TCM HARNESS, UNBOLT PTO TAILSHAFT AND EXHAUST. DRAIN GEARBOX OIL THEN REMOVE ALL BRACKETRY ON TOP OF THE GEARBOX. LIFTED TRUCK UP ON HOISTS, SECURED WITH GEARBOX JACK. UNBOLTED BELL HOUSING BOLTS AND REMOVED THE GEARBOX.

USED DIAL INDICATOR TO MEASURE END FLOAT AND FOUND TO BE 0.8MM RAISED ICC CASE ADVICE WAS TO REMOVE FLOAT COVER AND MEASURE BEARING PRELOAD. ADVISED TO FLIP BOX AROUND AND REMOVE AX HOUSING AND MEASURE CLEARANCE BETWEEN THE MAIN SHAFT SPEED SENSOR AND THE TONE WHEEL IT WAS WITHIN SPEC RE-FIT AX HOUSING ORDERED SHIMS 1.3MM FOR MAINSHAFT 2.3MM FOR THE COUNTER SHAFT. ONCE SHIMS ARRIVED. FIT FRONT COVER WITH NEW SHIMS AND TENSION. THEN FIT NEW CPC AND TENSION.

REPLACED CLUTCH AS THE OLD HAD SUBSEQUENT DAMAGE FROM THE END FLOAT, RE-FIT GEARBOX IN REVERSE ORDER AND FILLED WITH OIL, CARRIED OUT A RELEARN THEN WASHED AND ROA TESTED ALL OK.

ZR1

WEIGHT GAUGE NOT WORKING ON B TRAILER

ZR2

COOLANT LEAK

\$675.63

BRING TRUCK INTO WORKSHOP LOWERED BULLBAR AND RAISED BONNET.

DRAINED COOLANT, BOOST HOSE, RADIATOR HOSES, HEADER TANK TOP RADIATOR SUPPORT, BONNET STRAPS FAN AND TRANS COOLER. THEN SWING CONDENSOR OUT OF THE WAY. UNBOLTED BOTTOM RADIATOR MOUNTS THEN REMOVED RADIATOR WITH INTERCOOLER.

REMOVED INTERCOOLER, SHROUD, MOUNTING POINTS AND BRACKETS FROM OLD RADIATOR AND FIT TO NEW ONE.

CLEANED CONDENSOR AND INTERCOOLER THEN REFIT RADIATOR AND INTERCOOLER.

Part Number	Part Description	Quantity	Nett Value	Total Cost
0057825	M8X25 METRIC SCREW	1.00	0.59	0.59
0057620	M6X20 METRIC SCREW	1.00	0.42	0.42

212-216 Numurkah Road
Shepparton VIC 3630
Tel 03 4811 5300
www.daimlertrucksshepparton.com.au
MCT-0012706 / RTA-AU62149

DAIMLER TRUCKS SHEPPARTON

Operated by TriStar Truck and Bus Pty Ltd
ATF TriStar Unit Trust



SERVICE TAX INVOICE

ABN 12 241 713 151 / ACN 637 808 792

TriStar Truck and Bus Pty Ltd
Authorised Mercedes-Benz, Freightliner
& Fuso Sales, Service & Parts

*** DOCUMENT COPY ***

Invoice To: 3129
Hamilton Contracting (Nsw) Pty Ltd
P.O. Box 256
MULWALA NSW 2647

Deliver To:
Hamilton Contracting P/L
Warrawilla
JERILDERIE NSW 2716

Document No.:	758959
Document Date:	6/09/2025
Repair Order No.:	493154
Rego No.:	XV52NI
Make/Model:	2020 Freightliner CASCADIA
Vehicle ID No.:	1FVJHYD1XMLMH2239
Paint:	
Odometer:	699095
Engine Hrs:	
Delivery Date:	
Invoice To:	3129
Customer ABN:	44105773877
Tax Exempt No.:	
P/Order No.:	
Page:	2 of 2

ZR2

0411620	Fender Washer 6.4mm*15*1.25	1.00	0.11	0.11
04078	8MM FLAT WASHER	1.00	0.08	0.08
QFLC23-12485-250	CLAMP-CONSTANT TORQUE HOS	1.00	47.43	47.43
QDDEA0229979548	O-RING RELEASE CYL	1.00	6.54	6.54
QTXE1004227A	HOUSED RADIATOR	1.00	3,800.00	3,800.00
POWERCOOL	POWERCOOL PREMIX	1.00	5.60	5.60
SP7185-1	SHOCKER STRAP KIT	4.00	39.08	156.32

Comments: Part of trailerwork. Was not charged - See John

Parts Totals: 12.00 \$4,017.09

Advisor: Josh O'Dwyer

Sub Total for All:	\$6,923.19
Rounding:	\$0.00
GST:	\$692.32
Total:	\$7,615.51

Bank Account Details for Direct Payments:

Bank: NAB Branch: Wagga
BSB: 082-811 Account No: 254952255 Account Name: TriStar Truck & Bus

Mercedes-Benz - are registered trademarks of Daimler AG, Stuttgart, Germany
Freightliner is a registered trademark of Freightliner LLC, USA
Fuso is a registered trademark of Mitsubishi Fuso Trucks & Bus Corporation, Japan

212-216 Numurkah Road
Shepparton VIC 3630
Tel 03 4811 5300
www.daimlertrucksshepparton.com.au
MCT-0012706 / RTA-AU62149