

407-1



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To:

2237 ENG HRS
1487 SEP HRS

Branch N. BATTLEFORD *REPRINT*		
Date 07/08/24	Time 23:31:31 (B)	Page 01
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237	C7900690		
	760 LEXION	1487			

SEGMENT# 1 C INTER NA 06/05/24 06/05/24

#1 2000HR SERVICE

CORRECTION:

TECH 305:

-REPLACE LEAKING VALVE COVER GASKET --REMOVED EGR HEAT SHIELD, REMOVED TOP BRACING, REMOVED VALVE COVER, CLEANED ALL MATING SURFACES, CLEANED VALVE COVER AND REPLACED GASKET, REASSEMBLED IN REVERSE ORDER.

---PERFORMED 2000HR SERVICE:

TECH 261:

- CHANGED ENGINE OIL AND FILTER
- CHANGED FUEL FILTERS
- CHANGED AIR FILTER
- CHANGED DEF FILTER
- CHANGED HYDRAULIC OIL AND FILTER
- CHANGED MAIN GEARBOX OIL

TECH 190:

-CHANGED TRANSMISSION OIL, BOTH FINAL DRIVE OILS, 2-SPEED GEARBOX OIL, UNLOAD AUGER GEARBOX OIL, BOTH ROTOR GEARBOX OILS, BOTH REAR HUB OILS, AND BOTH RADIAL SPREADER GEARBOX OILS.

-GREASED MACHINE

-CLEANED ALL BREATHERS

-CLEANED DIRTY STEP FLOOR

-CLEANED SPILLED OIL.

-CLEANED WORK BAY AFTER REPAIR.

ADDITIONAL DESCRIPTION:

PERFORM 2000HR SERVICE

CHANGE ENGINE OIL AND FILTER

CONTINUED ON PAGE 02


TERMS:

All amounts owing for goods or services provided must be settled before they are released. A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns. No returns after 30 days. No returns on electrical or special ordered parts.

X

Received By

CUSTOMER'S SIGNATURE



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To [REDACTED]
 2237 ENG HRS
 1487 SEP HRS

Invoice To:

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 02
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237 C7900690		
	760 LEXION	1487		
REPLACE LEAKING VALVE COVER GASKET				
CHANGE FUEL FILTERS				
CHANGE AIR FILTER				
CHANGE DEF FILTER				
CHANGE HYDRAULIC OIL AND FILTER				
CHANGE TRANSMISSION OIL, BOTH FINAL DRIVE OILS, 2-SPEED				
GEARBOX OIL, UNLOAD AUGER GEARBOX OIL, MAIN GEARBOX OIL,				
BOTH ROTOR GEARBOX OILS, BOTH REAR HUB OILS, AND BOTH				
RADIAL SPREADER GEARBOX OILS.				
GREASE MACHINE				
CLEAN ALL BREATHERS				
ENV1	ENVIRO FEE OIL	106	.20	21.20
ENV3	ENVIRO FEE >8"	RETAIL	2.00	
		1	1.00	1.00
FILO8	ENVFEE	10	2.00	20.00
FREE	FREE AEROS	RETAIL	30.00	
		1	23.48	23.48
	FREE AEROSOL, CAN			
0773672	FILTER ELE	RETAIL	310.51	
		1	251.97	251.97
	FILTER ELEMENT			
0773821	FILTER SAF	RETAIL	265.86	
		1	216.14	216.14
	FILTER SAFTEY CARTRIDGE			
11700530	FILTER	RETAIL	148.87	
		1	124.29	124.29
1473990L	80W90	RETAIL	8.69	
		34	5.20	176.80
	80W90 PER LITRE			
1474460L	HY OIL LIT	RETAIL	7.75	

CONTINUED ON PAGE 03

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.

X _____
 Received By

CUSTOMER'S SIGNATURE _____



CLAAS



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To:

2237 ENG HRS
 1487 SEP HRS

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 03
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

Invoice To:

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237 C7900690		
	760 LEXION	1487		
			39	4.63
	HYDRAULIC OIL BY LITRE			180.57
1474780L	15W40 LITR		RETAIL	7.11
			33	4.19
	15 W 40 SOLD BY LITRE			138.27
1474932	AGRISHIFT		RETAIL	111.11
			1	107.62
	AGRISHIFT SYN FE 75W-90			107.62
229-5711	SEAL		RETAIL	351.95
			1	259.17
	2417931	AGRIGREASE	RETAIL	8.90
			2	7.62
	AGRIGREASE EP 3			15.24
5100541	FILTER ELE		RETAIL	226.34
			1	188.43
	FILTER ELEMENT			188.43
7983031	ENGINE OIL		RETAIL	76.53
			1	60.28
	ENGINE OIL FILTER			60.28
7992081	FUEL FILTE		RETAIL	43.96
			2	34.62
	FUEL FILTER			69.24
7992091	FILTER ELE		RETAIL	89.60
			1	69.57
	FILTER ELEMENT			69.57
				1923.27
				1201.20
13010002			SEGMENT TOTAL==>	3124.47

SEGMENT# 2 C INTER NA 06/05/24 06/05/24


CONTINUED ON PAGE 04

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.

X

Received By

CUSTOMER'S SIGNATURE



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To: [REDACTED]
 2237 ENG HRS
 1487 SEP HRS

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 04
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

Invoice To:

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237 C7900690		
	760 LEXION	1487		
#2 REEL DRIVE TENSIONER PULLEY				
<u>CORRECTION:</u>				
- LOOSENED BELT TENSIONER AND REMOVED REEL DRIVE TENSIONER PULLEY. REPLACED WORN BEARING IN HYDRAULIC REEL DRIVE TENSIONER PULLEY, INSTALLED PULLEY AND TENSIONED BELT				
<u>ADDITIONAL DESCRIPTION:</u>				
REPLACE WORN BEARING IN HYDRAULIC REEL DRIVE TENSIONER PULLEY				
2155400	BEARING GR	RETAIL	16.64	
		1	12.74	12.74
	BEARING GRVD. BALL			
2351550	CIRCLIP	RETAIL	.22	
		1	.18	.18
2351810	CIRCLIP	RETAIL	2.88	
		2	2.14	4.28
6657980	V-BELT SET	RETAIL	690.86	
		1 M	558.14	558.14
			PARTS	575.34
			LABOR	139.70
13010002		SEGMENT TOTAL==>		715.04

SEGMENT# 3 C INTER NA	06/05/24	06/17/24		
#3 1ST STAGE SIEVE DRIVE BELT				
<u>CORRECTION:</u>				
ADJUSTED 1ST STAGE SIEVE DRIVE BELT				
<u>ADDITIONAL DESCRIPTION:</u>				
ADJUST 1ST STAGE SIEVE DRIVE BELT				
			LABOR	33.00
13010002		SEGMENT TOTAL==>		33.00

CONTINUED ON PAGE 05

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.


X

Received By

CUSTOMER'S SIGNATURE _____



CLAAS



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To:

2237 ENG HRS
 1487 SEP HRS

Invoice To:

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 05
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237 C7900690		
	760 LEXION	1487		
SEGMENT# 4 C INTER NA		06/05/24 06/05/24		
#4 STRAW CHOPPER SUPPORT BRACE				
<u>CORRECTION:</u>				
REPLACED BROKEN 2ND TO 3RD STAGE STRAW CHOPPER SUPPORT BRACE AND INSTALLED FEED GUARD.				
<u>ADDITIONAL DESCRIPTION:</u>				
REPLACE BROKEN 2ND TO 3RD STAGE STRAW CHOPPER SUPPORT BRACE				
2355580	BOLT HEXAG	RETAIL	4.47	
		1	3.29	3.29
	BOLT HEXAGONAL			
2393951	WASHER, CO	RETAIL	2.06	
		1	1.56	1.56
	WASHER, CONTACT			
6297012	BRACE	RETAIL	276.36	
		1	216.91	216.91
7929300	FEED GUARD	RETAIL	78.27	
		1 N	58.84	58.84
			PARTS	280.60
			LABOR	55.00
13010002		SEGMENT TOTAL==>		335.60

SEGMENT# 5 C INTER NA		06/05/24 06/05/24		
#5 UNLOAD AUGER DRIVE BELT				
<u>CORRECTION:</u>				
REPLACED DAMAGED UNLOAD AUGER DRIVE BELT				
<u>ADDITIONAL DESCRIPTION:</u>				
REPLACE DAMAGED UNLOAD AUGER DRIVE BELT				
6607621	POWER BAND	RETAIL	215.73	
		1	180.09	180.09
	POWER BAND BELT			

CONTINUED ON PAGE 06

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.

X

Received By

CUSTOMER'S SIGNATURE




Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To: 
 2237 ENG HRS
 1487 SEP HRS

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 06
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237	C7900690		
	760 LEXION	1487			
	13010002			PARTS	180.09
				LABOR	220.00
				SEGMENT TOTAL==>	400.09

SEGMENT# 6 C INTER NA 06/05/24 06/17/24
 #6 UNLOAD AUGER DRIVE CHAIN
CORRECTION:
 TENSIONED UNLOAD AUGER DRIVE CHAIN TO PROPER POSITION
ADDITIONAL DESCRIPTION:
 TENSION UNLOAD AUGER DRIVE CHAIN TO PROPER POSITION

				LABOR	33.00
	13010002			SEGMENT TOTAL==>	33.00

SEGMENT# 7 C INTER NA 06/05/24 06/05/24
 #7 UNLOAD AUGER CHAIN GUIDES
CORRECTION:
 REPLACED WORN UNLOAD AUGER DRIVE CHAIN GUIDES
ADDITIONAL DESCRIPTION:
 REPLACE WORN UNLOAD AUGER DRIVE CHAIN GUIDES

7349391-1	TENSIONING BLOC	RETAIL	4.05		
		2	2.94		5.88
				PARTS	5.88
				LABOR	33.00
	13010002			SEGMENT TOTAL==>	38.88

SEGMENT# 8 C INTER NA 06/05/24 06/05/24
 #8 TRANSITION PLATE
CORRECTION:
 -PREPARATION FLOOR COVER HAS DAMAGED GASKET AND BROKEN
 CLAMP RAIL. DRILLED OUT RIVETS AND INSTALLED NEW CASKET AND


CONTINUED ON PAGE 07

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.

X

Received By

CUSTOMER'S SIGNATURE _____



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To:

2237 ENG HRS
 1487 SEP HRS

Invoice To:

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 07
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237	C7900690		
	760 LEXION	1487			
CLAMP RAIL. INSTALLED NEW RIVETS. -REPLACED WORN THROUGH TRANSITION PLATE. ADDITIONAL DESCRIPTION: REPLACE WORN THROUGH TRANSITION PLATE					
2379501	BLIND RIVE			RETAIL 1.40	
				16 1.04	16.64
	BLIND RIVET				
5327491	FEED PLATE			RETAIL 829.14	
				1 660.88	660.88
7360400	GASKET			RETAIL 75.97	
				1 59.70	59.70
7360531	CLAMP RAIL			RETAIL 47.39	
				1 35.38	35.38
	CLAMP RAIL LEFT				
				PARTS 772.60	
				LABOR 302.50	
	13010002			SEGMENT TOTAL==>	1075.10

SEGMENT# 9 C INTER NA 06/05/24 06/05/24
 #9/10 FEEDERCHAIN

CORRECTION:

INSTALLED HALF LINKS IN FEEDER CHAIN AND INSTALLED NEWCHAIN LOCKING LINKS.

REPAIRED BROCKEN CHAIN:REMOVED RH SIDE FEEDRER SLAT, CUT OFF DAMAGED SECTION ON THE SECOND CHAIN ROW FROM RHS.

INSTALLED NEW SEGMENT WITH CHAIN LOCKING LINK. INSTALLED FEEDER SLAT.

REPLACE 5 BENT FEEDER SLATS

ADDITIONAL DESCRIPTION:

INSTALL HALF LINKS IN FEEDER CHAIN

CONTINUED ON PAGE 08

TERMS:

All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.


X

Received By

CUSTOMER'S SIGNATURE _____



CLAAS



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To: [REDACTED]
 2237 ENG HRS
 1487 SEP HRS

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 08
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		Salesperson 222

Invoice To:

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760	LEXION COMBINE	2237 C7900690	
	1487	760 LEXION		
REPLACE 5 BENT FEEDER SLATS				
0030530		LOCK WIRE	RETAIL 1.60	
			4 1.10	4.40
5322381		CONVEYOR B	RETAIL 61.13	
			5 47.51	237.55
		CONVEYOR BAR		
6805841		CHAIN LOCK	RETAIL 18.99	
			4 13.72	54.88
		CHAIN LOCK BEND.		
			PARTS 296.83	
			LABOR 312.40	
		13010002	SEGMENT TOTAL==>	609.23

SEGMENT#10 C INTER NA 06/05/24 06/05/24

#11 LOWER GUIDE ROLLER

CORRECTION:

DIAGNOSED WHY GUIDE ROLLER IS NOT CENTERED IN FEEDERHOUSE - LHS BEARING WORN OUT, ONE LINK IN FEEDER CHAIN IS BROKEN AND NOT PROPER CHAIN ADJUSTMENT. THE REPAIR WAS PERFORMED IN THE SEGMENT #9.

- DISCONNECTED FEEDER CHAIN. REMOVED AND REPLACED DENTED LOWER GUIDE ROLLER AND BEARINGS. INSTALLED AND TESTED NEW LOWER GUIDE ROLLER - OK

ADDITIONAL DESCRIPTION:

REPLACE DENTED LOWER GUIDE ROLLER AND BEARINGS
 DIAGNOSE AND REPAIR WHY GUIDE ROLLER IS NOT CENTERED IN FEEDERHOUSE.

2146300		BEARING GR	RETAIL 40.19	
			2 31.87	63.74
		BEARING GRVD.BALL		

CONTINUED ON PAGE 09

TERMS:

All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.

X

Received By

CUSTOMER'S SIGNATURE _____



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To:

2237 ENG HRS
 1487 SEP HRS

Invoice To:

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 09
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760	LEXION COMBINE	2237	C7900690
	760	LEXION	1487	
2388862		PLUG	RETAIL	2.58
			6	1.95
				11.70
5188492		DEFLECTING	RETAIL	2703.96
			1	2159.62
				2159.62
		DEFLECTING ROLLER		
6039491		LOCKING LI	RETAIL	12.54
			5	9.01
				45.05
		LOCKING LINK		
6805401		CHAIN TRAC	RETAIL	33.44
			1	26.46
				26.46
		CHAIN TRACK END		
			PARTS	2306.57
			LABOR	330.00
			SEGMENT TOTAL==>	2636.57

SEGMENT#11 C INTER NA	06/05/24	06/05/24		
#12 DUST EXTRACTION				
<u>CORRECTION:</u>				
REPLACED CRACKED DUST EXTRACTION FAN BELT AND TIGHTENED IT.				
<u>ADDITIONAL DESCRIPTION:</u>				
REPLACE CRACKED DUST EXTRACTION FAN BELT				
3257281	V-BELT		RETAIL	39.60
			1	31.07
				31.07
			PARTS	31.07
			LABOR	33.00
			SEGMENT TOTAL==>	64.07

SEGMENT#12 C INTER NA	06/05/24	06/05/24		
#13 FEEDERHOUSE SIDE GUARDS				
<u>CORRECTION:</u>				


CONTINUED ON PAGE 10

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.

X

Received By

CUSTOMER'S SIGNATURE



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To:

2237 ENG HRS
 1487 SEP HRS

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 10
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

Invoice To:

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760	LEXION COMBINE	2237	C7900690
	760	LEXION	1487	
INSTALLE MISSING FEEDERHOUSE FRONT SIDE GUARDS WITH NEW BOLTS, WASHERS AND NUTS.				
<u>ADDITIONAL DESCRIPTION:</u>				
INSTALL MISSING FEEDERHOUSE FRONT SIDE GUARDS				
2349530		BOLT COACH	RETAIL	.93
			4	.70
				2.80
2361700		NUT HEXAGO	RETAIL	.25
			4	.19
				.76
		NUT HEXAGONAL		
2362000		BOLT' HEXAG	RETAIL	.45
			2	.33
				.66
		BOLT HEXAGONAL		
2393870		WASHER, CO	RETAIL	.20
			6	.14
				.84
		WASHER, CONTACT		
3514173		END PIECE	RETAIL	286.41
			1 S	231.65
				231.65
		END PIECE LEFT		
3514183		END PIECE	RETAIL	286.41
			1 S	230.23
				230.23
		END PIECE R.H.		
			PARTS	466.94
			LABOR	55.00
		13010002	SEGMENT TOTAL==>	521.94

SEGMENT#13 C INTER NA 06/05/24 06/05/24

#14 APS COVER

CORRECTION:

REPLACED BENT FEEDRHOUSE COVER PLATE AND DAMAGED BOLTS.
 REPLACED DAMAGED APS DRUM COVER. REMOVED BENT APS DRUM

CONTINUED ON PAGE 11


TERMS:

All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.

X

Received By

CUSTOMER'S SIGNATURE



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To:

2237 ENG HRS
 1487 SEP HRS

Invoice To:

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 11
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760	LEXION COMBINE	2237	C7900690
	760	LEXION	1487	
COVER LOCKS, STRAIGHTENED AND INSTALLED. ADJUSRED APS DRUM COVER.				
<u>ADDITIONAL DESCRIPTION:</u>				
REPLACE DAMAGED APS DRUM COVER				
18169110		DRUM COVER	RETAIL	1635.59
			1	1298.15
2374610		BOLT HEXAG	RETAIL	2.33
			3	1.73
		BOLT HEXAGONAL		5.19
5323871		COVER PLAT	RETAIL	723.42
			1	574.18
		COVER PLATE		
			PARTS	1877.52
			LABOR	55.00
		13010002	SEGMENT TOTAL==>	1932.52

SEGMENT#14 C INTER NA 06/05/24 06/05/24

#15 APS DRUM

CORRECTION:

REPLACED 4 DAMAGED APS MOUNT'S
 ALL APS MOUNTS HAVE BENDS AND MOUNT HEADS HAVE MUSHROOM FORMATIONS (THE OLD WORN CAPS WERE CONCAVE). REMOVED OLD CAPS, STRAIGHTENED ALL APS MOUNTS AND INSTALLED ALL NEW APS CAPS AND HARDWARE. THIS WORK TOOK MORE TIME. CLEANED WORK AREA.

ADDITIONAL DESCRIPTION:

REPLACE ALL APS CAPS AND HARDWARE

REPLACE 4 DAMAGED APS MOUNTS

2164010		BOLT COACH	RETAIL	2.17
			63	1.57
				98.91

CONTINUED ON PAGE 12

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.


X

Received By

CUSTOMER'S SIGNATURE _____



CLAAS



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To:
 2237 ENG HRS
 1487 SEP HRS

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 12
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

Invoice To: _____

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760	LEXION COMBINE	2237	C7900690
	760	LEXION	1487	
2380060		NUT SECURI	RETAIL	2.10
			63	1.56
		NUT SECURING		98.28
2393880		WASHER, CO	RETAIL	.33
			63	.24
		WASHER, CONTACT		15.12
29419980		CAP	RETAIL	17.69
			63	13.50
				850.50
6176310		PADDLE	RETAIL	24.82
			4	18.65
				74.60
				PARTS
				1137.41
				LABOR
				550.00
				13010002
			SEGMENT TOTAL==>	1687.41

SEGMENT#15 C INTER NA 06/05/24 06/05/24

#16 CONCAVE
 CORRECTION:

LOOSEND AND REMOVED THRESHING DRUM, APS DRUM, IMPELLER AND FEEDER HOUSE DRIVE BELTS. REMOVED FEEDER HOUSE, RHS DUAL WHEELS, RETURN ELEVATOR, TWO SPEED PULLEY AND GEARBOX, APS DRUM, THRESHING DRUM, PRE CONCAVE AND CONCAVE FROM MACHINE. INSTALLED SUNNY BROK CONCAVE, PRE CONCAVE, THRESHING DRUM WITH NEW BEARINGS, APS DRUM DRUM WITH NEW BEARINGS. ADJUSTED CONCAVE. INSTALLED ALL PERVIOUSLY REMOVED PARTS. INSTALLED AND ADJUSTED DRIVE BELTS. TORQUED RHS DUAL WHEELS NUTS. CLEANED WORK AREA. REMOVED REEL DRIVE BELT, FRONT ATTACHMENT DRIVE BELT AND REPLACED DAMAGED FEEDERHOUSE DRIVE BELTS. INSTALLED REMOVED BELTS AND TENSIONED THEM.

ADDITIONAL DESCRIPTION:

CONTINUED ON PAGE 13

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.

X

Received By _____

CUSTOMER'S SIGNATURE _____



CLAAS



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To:

2237 ENG HRS
 1487 SEP HRS

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 13
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

Invoice To:

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237 C7900690		
	760 LEXION	1487		
THRESHING CONCAVE IS OUT OF ADJUSTMENT REPLACE CONCAVE WITH SUNNYBROOK CONCAVE				
SBLX0023	CONCAVE		RETAIL	3300.00
			1	2362.09
				2362.09
0028600	SUNNYBROOK SMALL GRAIN BOX CONCAVE		RETAIL	11.04
	CONNECTING		1	7.62
				7.62
	CONNECTING LINK			
2130510	BEARING SP		RETAIL	372.66
			1	309.27
				309.27
	BEARING SPHERICAL ROLLER			
2130550	TAPER LOCK		RETAIL	40.57
			1	31.65
				31.65
	TAPER LOCK SLEEVE			
2358820	TAPER LOCK		RETAIL	36.74
			1	27.61
				27.61
	TAPER LOCK SLEEVE			
2373830	BOLT HEXAG		RETAIL	1.40
			6	1.01
				6.06
	BOLT HEXAGONAL			
2391230	BEARING SP		RETAIL	288.83
			1	236.33
				236.33
	BEARING SPHERICAL ROLLER			
2393880	WASHER, CO		RETAIL	.33
			6	.24
				1.44
	WASHER, CONTACT			
3557020	BEARING UN		RETAIL	311.75
			1 N	257.16
				257.16
	BEARING UNIT			
3557030	BEARING UN		RETAIL	681.33

CONTINUED ON PAGE 14

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.

X

Received By

CUSTOMER'S SIGNATURE _____



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To:

2237 ENG HRS
 1487 SEP HRS

Invoice To:

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 14
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237 C7900690		
	760 LEXION	1487		
	BEARING UNIT		1	556.92
6103380	LOCKING PL		RETAIL	7.99
	LOCKING PLATE		1	6.04
6103591	NUT SLOTTE		RETAIL	25.49
	NUT SLOTTED		1	19.15
6696390	NUT SLOTTE		RETAIL	37.24
	NUT SLOTTED		1	29.04
6696400	LOCKING PL		RETAIL	10.65
	LOCKING PLATE		1	7.76
7772473	STRAP		RETAIL	99.62
			2	75.93
				PARTS
				LABOR
	13010002		SEGMENT TOTAL==>	4010.00
				4400.00
				8410.00

SEGMENT#16 C INTER NA 06/05/24 06/17/24

#17 RETURNS ELEVATOR CHAIN

CORRECTION:

ADJUSTED RETURNS ELEVATOR CHAINS TENSION

ADDITIONAL DESCRIPTION:

ADJUST RETURNS ELEVATOR CHAIN TENSION

13010002

LABOR 33.00
 SEGMENT TOTAL==> 33.00

SEGMENT#17 C INTER NA 06/05/24 06/05/24

CONTINUED ON PAGE 15


TERMS:

All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.

X

Received By

CUSTOMER'S SIGNATURE _____



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To:

2237 ENG HRS
 1487 SEP HRS

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 15
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

Invoice To:

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237 C7900690		
	760 LEXION	1487		
#18 CHOPPER DOOR				
<u>CORRECTION:</u>				
REMOVED BENT CHOPPER FLAP DOOR AND COVER. ASSEMBLED NEW FLAP DOOR AND NEW COVER WITH NEW PINS AND ROLL PINS. INSTALLED CHOPPER FLAP ON MACHINE WITH NEW BOLTS, WASHERS AND BOLTS. FOUND TWO CRACKS ON LH AND RH SIDE OF STRAW CHOPPER BODY PROFILE. DISCONNECTED BATTERIES, BROUGHT WELDING MACHINE, WELDED CRACKS AND PAINTED. CLEANED WORK AREA. PERFORMED TEST AFTER REPAIR.				
<u>ADDITIONAL DESCRIPTION:</u>				
REPLACE BENT CHOPPER DOOR				
18001700	PIN	RETAIL	58.93	
		2 M	46.96	93.92
18154453	COVER	RETAIL	1582.84	
		1 N	1260.52	1260.52
18154561	FLAP ASS.	RETAIL	1944.23	
		1 N	1548.30	1548.30
2362000	BOLT HEXAG	RETAIL	.45	
		3	.33	.99
	BOLT HEXAGONAL			
2389010	NUT HEXAGO	RETAIL	.22	
		4	.18	.72
	NUT HEXAGONAL			
2393931	WASHER, CO	RETAIL	.29	
		7	.19	1.33
	WASHER, CONTACT			
9580023	SPRING PIN	RETAIL	1.81	
		2	1.34	2.68
				PARTS 2908.46
				LABOR 343.20

CONTINUED ON PAGE 16

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.


X

Received By

CUSTOMER'S SIGNATURE



CLAAS



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To: [REDACTED]
 2237 ENG HRS
 1487 SEP HRS

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 16
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
	Salesperson 222	

Invoice To: _____

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237	C7900690		
	760 LEXION	1487			
	13010002			SEGMENT TOTAL==>	3251.66

SEGMENT#18 C INTER NA 06/05/24 06/05/24

#19 RADIAL SPREADER CYLINDER ARM BOLT

CORRECTION:

REPLACED BROKEN RHS RADIAL SPREADER ARM CYLINDER BOLT

ADDITIONAL DESCRIPTION:

REPLACE BROKEN RHS RADIAL SPREADER ARM CYLINDER BOLT

2113450	BOLT HEXAG	RETAIL	5.32		
		1	3.95		3.95
	BOLT HEXAGONAL				
2333230	NUT SECURI	RETAIL	2.33		
		1	1.70		1.70
	NUT SECURING				
2393890	WASHER, CO	RETAIL	.85		
		2	.59		1.18
	WASHER, CONTACT				
			PARTS		6.83
			LABOR		33.00
	13010002		SEGMENT TOTAL==>		39.83

SEGMENT#19 C INTER NA 06/05/24 06/05/24

#20 RADIAL SPREADER RETAINER BEARINGS

CORRECTION:

REMOVED LOOSE LH AND RH RADIAL SPREADER RETAINER BEARINGS AND LOCKING COLLARS. CLEANED SHAFT FROM RUST. INSTALLED NEW LOCK COLLAR BEARINGS, METAL FLANGES AND ECCENRIC LOCK COLLARS. ADJUSTED RADIAL SPREADER RETAINERS ON THE SHAFTS AND LOCKED BEARINGS.

ADDITIONAL DESCRIPTION:

CONTINUED ON PAGE 17

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.


X

Received By _____

CUSTOMER'S SIGNATURE _____



CLAAS



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To:

[REDACTED]
 2237 ENG HRS
 1487 SEP HRS

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 17
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

Invoice To:

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760	LEXION COMBINE	2237 C7900690	
	760	LEXION	1487	
REPLACE LOOSE LH AND RH RADIAL SPREADER RETAINER BEARINGS				
6363410		BEARING LO	RETAIL	39.71
			2	30.41
		BEARING LOCK COLLAR		60.82
6363421		ECCENTRIC	RETAIL	9.67
			2	6.87
		ECCENTRIC LOCKING COLLAR		13.74
6363430		METAL FLAN	RETAIL	5.95
			4	4.44
		METAL FLANGE		17.76
			PARTS	92.32
			LABOR	550.00
13010002			SEGMENT TOTAL==>	642.32

SEGMENT#20 C INTER NA 06/05/24 06/18/24

#21 HOPPER PANELS

CORRECTION:

MOVED MACHINE IN ANOTHER WORK BAY. INSPECTED CRACKS ON HOPPER PANELS. CRACKS PRESENT INSIDE AND OUTSIDE OF HOPPER ON LHS AND RHS FRONT CORNERS. STRAIGHTENED BENTS ON THE CRACKS, CLEANED CRACKS FROM PAINT AND RUST. DISCONNECTED BATTERY. BROUGHT FORKLIFT AND WELDING MACHINE, LOADED WELDING MACHINE ON FORKLIFT AND LIFTED CLOSE TO HOPPER ON LHS. WELDED CRACKED HOPPER PANELS ON LHS. MOVED FOKLIFT TO RHS AND LIFTED CLOSE TO HOPPER. WELDED CRACKED HOPPER PANELS ON RHS. CLEANED AND PAINTED PLACES OF WELDING. UNLOADED WELDING MACHINE AND CONNECTED BATTERY.

ADDITIONAL DESCRIPTION:

WELD CRACKED HOPPER PANELS

LABOR 275.00

CONTINUED ON PAGE 18

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.


X

Received By

CUSTOMER'S SIGNATURE _____



CLAAS



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To:

2237 ENG HRS
 1487 SEP HRS

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 18
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
	Salesperson 222	

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237	C7900690		
	760 LEXION	1487			
	13010002			SEGMENT TOTAL==>	275.00

SEGMENT#21 C INTER NA 06/05/24 06/05/24

#22 CLEAN GRAIN ELEVATOR

CORRECTION:

REPLACED WORN CLEAN GRAIN ELEVATOR CHAIN AND SPROCKETS
 LOOSENED AND REMOVED DRIVE BELT, LOOSENED CONVEYOR CHAIN
 TENSIONER AND REMOVED CHAIN. REMOVED LOWER BEARING, COVER
 AND TRIED TO REMOVE LOWER SPROCKET USING PULLER AND SNAP-ON
 IMPACT. THE SPROCKET JAMMED ON THE SHAFT. USING TORCH TO
 HEAT SPROCKET AND TRIED TO REMOVE AGAIN - WITHOUT RESULT.
 IN THE END IT WAS NECESSARY TO CUT THE SPROCKET USING
 TORCH. IT TOOK TIME TO REMOVE THE LOWER SPROCKET. CLEANED
 SHAFT, INSTALLED NEW SPROCKET, COVER AND NEW BEARING ON THE
 SHAFT. DISASSEMBLED CLEAN GRAIN ELEVATOR HEAD, REPLACED
 SPROCKET AND BEARINGS, ASSEMBLED AND ADJUSTED SHAFT AND
 SPROCKET. INSTALLED NEW CONVEYOR CHAIN. INSTALLED ALL
 PERVIOUSLY REMOVED PARTS. INSTALLED AND ADJUSTED DRIVE
 BELT. CLEANED WORK AREA. CREATED SERVICE REPORT.

ADDITIONAL DESCRIPTION:

STK#	DESCRIPTION	UNIT	RETAIL		
2163300	BEARING LO	1	121.15		
			99.79		99.79
	BEARING LOCK COLLAR				
5602131	LOCK COLLA	1	16.59		
			12.44		12.44
	LOCK COLLAR				
5602140	METAL FLAN	1 M	16.35		
			12.33		12.33
	METAL FLANGE				

CONTINUED ON PAGE 19

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.


X

Received By

CUSTOMER'S SIGNATURE



CLAAS



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To [REDACTED]
 2237 ENG HRS
 1487 SEP HRS

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 19
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

Invoice To:

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237 C7900690		
	760 LEXION	1487		
6000732	SPROCKET		RETAIL 247.22	
			2 196.21	392.42
6011980	CONVEYOR C		RETAIL 2470.93	
			1 2019.71	2019.71
	CONVEYOR CHAIN			
6104460	METAL FLAN		RETAIL 6.96	
			2 5.30	10.60
	METAL FLANGE			
6104471	LOCK COLLA		RETAIL 10.79	
			1 8.10	8.10
	LOCK COLLAR			
6104480	BEARING LO		RETAIL 49.14	
			2 38.91	77.82
	BEARING LOCK COLLAR			
			PARTS	2633.21
			LABOR	880.00
	13010002		SEGMENT TOTAL==>	3513.21

SEGMENT#22 C INTER NA 06/05/24 06/07/24

#23 FINAL RUN UP

CORRECTION:

261-Hooked up the old green italian machine and am currently throwing electrical juices through the battery to try and start it.

190-PERFORMED FINAL RUN UP ALL WORKED AS IT SHOULD

ADDITIONAL DESCRIPTION:

PERFORM FINAL RUN UP AFTER ALL REPAIRS ARE COMPLETED

	LABOR	220.00
13010002	SEGMENT TOTAL==>	220.00

CONTINUED ON PAGE 20

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.

X

Received By

CUSTOMER'S SIGNATURE _____



CLAAS



Thank You For Your Business!



Lloydminster
 Hwy 16 West & Range Road 21
 Box 11336, T9V 3B6
 Ph: 780-875-8010

North Battleford
 Hwy 16 East & East Hill Road
 Box 1778, S9A 3W8
 Ph: 306-445-8010 F: 306-445-8011

Vegreville
 14426 Hwy 16 Service Road
 Box 310, T9C 1R3
 Ph: 780-632-3246 F: 780-632-3247

Ship To: [REDACTED]
 2237 ENG HRS
 1487 SEP HRS

Invoice To:

Branch N. BATTLEFORD		
Date 07/08/24	Time 23:31:31 (B)	Page 20
Account No	Phone No	Inv No W01511
Ship Via INSP 403962203	Purchase Order	
Tax ID No		
		Salesperson 222

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
14146	760 LEXION COMBINE	2237	C7900690		
	760 LEXION	1487			

***** WORK ORDER TOTALS *****

PARTS	19504.94
LABOR	10087.00
SHOP SUPPLIES	300.00
INTERNAL TOTAL	29891.94

TERMS:
 All amounts owing for goods or services provided must be settled before they are released.
 A 30% restocking charge will apply to returned parts. Original receipt must accompany all returns.
 No returns after 30 days. No returns on electrical or special ordered parts.

X _____
 Received By

CUSTOMER'S SIGNATURE _____



CLAAS



Thank You For Your Business!