

NEW BANKING INFORMATION - For all future payments Bank#. 241 Transit#: 56792 Account #: 711458214206

INVOICE 220-101767

Remit To: 3750 13 Street Nisku, AB T9E 1C6 Phone: (780) 979-8502 www.uniontractor.com

Union Tractor Ltd. 11123 97 Ave. Grande Prairie, AB T8V 3J6 (780) 532-5587

Bill To		Customer No			Ship To Cus	stomer No.		4	
		000020		HOU		00020	HOU	4	
e.	CASI	I SALES GRAN	DE PRAIRIE	*PERSONAL PROGRAMMATION AND AND AND AND AND AND AND AND AND AN		E K RANCH	ноо	8	2 OF 2 K ORDER*
	GRAN CANA	DE PRAIRIE, DA	AB 000 000	MINOCONTRACTOR AND	GRAND	E PRAIRIE, AB	000 000	And the second s	
Branch	***************************************		***************************************					CHAP	RGE
	e Prairi	е					GST Number	Re	eference Number
Month/0	Day/Year	Writer	Order No.	Customer P.C			105448161		220-101767
11/2	5/22	TRS	1/18/22 101767	Kirk	,	Terms NET 30 DAYS			**DUPLICATE*
Quantity Ordered	Quar Ship	ntity Back ped Orden		Part Numbe	er and Description	Code	Y	HOP	BVW Net
25		25	BRA 6V0937		BOLT, SEGMENT	TG		1 000	Amoun
^-			- D5H, D	6M, D6N, D6E	1, 953	16		1.303	32.5
25		25	BRA 2S5658		WASHER	TG		1 000	
25		25	BRA 7H3607		NUT, SEGMENT	TG		1.023	25.5
			- 5/8" н			16		.809	20.2
1		1	UTR 2652299 - D6T		EX FINAL DRIVE	TG	18898	3.050	18898.0
1 4		1	UTR 2652299	CORE	CORE DEPOSIT	G	Q E O O	.000	0500 0
		4	BRA 9S1838 - D6C/D6	D/D6H/D6R/D6	MASTER LINK BOLT	TG		. 636	8500.0 14.5
2 2		2	GRZ 8D4771		O-RING, BUNA N	TG	1.4	.275	00.5
13		2	GRZ 2R0098		SEAL-O-RING	TG		.774	28.5
		13		31 J DELO BULK	SAE 30W TOROFORCE	TG		.388	37.55 96.04
1 24.00	24	1	AMP 2230567		GEAR-SUN	TG	2605	040	2605 04
24.00	24.	00	LAB LABSHP1		SHOP REGULAR LABOUR	R TG		.000	2605.04 3960.00
	PARTS.	21851.53			SHOP SUPPLIES	TG			277.20
	CORES:		LABOR:	3960.00	SUBLETS:	0.00	SUPPLIES:	277.20	277.20
REQUEST	T 4: O	JTGOING INSP	ECTION						
1.00	1.(LAB LABSHP1		SHOP REGULAR LABOUR	TG TG	165.	000	165.00
	PARTS:	0.00	LABOR:	165.00	SUBLETS:	0.00	SUPPLIES:	11.55	11.55
EQUEST	5: RE	PLACE LEFT	HAND SIDE FINAL I	ORIVE SEAL					
	PARTS:	0.00	LABOR:	0.00	SUBLETS:	0.00	SUPPLIES:	0.00	
AL	PARTS: CORES:	21891.48 8500.00	LABOR:	4455.00	SUBLETS:	0.00	SUPPLIES:	311.85	
					GOODS & SERVICES TAX	K (CODE G) 5	1,757.92		
Recieve Print N	ved By: Name	00000000000000000000000000000000000000	Sigr	nature		+	SUBTOTAL		35158.33
nt: Terms	. Positively r	o goods accepted		authorization and	In color many		TAX		1757.92
Goods	s returned su	bject to restocking	charges when supplied a	s ordered.	nivode fumber	Time Prepare 16:45	TOTAL		36916.25

THE UNDERSIGNED HEREBY WAIVES ENTITLEMENT UNDER THE PERSONAL PROPERTY SECURITY ACT TO RECEIVE A COPY IN WRITING OF ANY FINANCIAL STATEMENT OF FINANCING CHANGE STATEMENT REGISTERED PURSUANT HERETO.

THE UNDERSIGNED AGREES TO PAY ALL COSTS INCURRED FOR THE RECOVERY OF ANY AMOUNT OWING, INCLUDING LEGAL COSTS ON A SOLICITOR AND CLIENT BASIS INCLUSIVE OF STORAGE FEES.

TERMS: NET 30 DAYS FOLLOWING INVOICE DATE.

A SERVICE CHARGE WILL BE CHARGED TO YOU ON ANY OUTSTANDING BALANCE AT THE END OF EACH MONTH AT THE RATE OF 1.5% PER MONTH CALCULATED AND COMPOUNDED MONTHLY (19.57% PER ANNUM).





INVOICE

Remit To: 3750 13 Street Nisku, AB T9E 1C6 Phone: (780) 979-8502 www.uniontractor.com

Union Tractor Ltd. 11123 97 Ave. Grande Prairie, AB T8V 3J6 (780) 532-5587

220-101767

	Custome	er No.		Ship To	Customer No.			7	
	00002	20	HOU		000020		HOU	→ 500	1 05 0
					000020		HOU		1 OF 2 RK ORDER*
	CASH SALES	GRANDE PRAIRIE		es I	OUBLE K RANCH			_ ~WO!	RK ORDER*
	CDANIDE DDAT	DTE 3D 000 000							
	CANADA	RIE, AB 000 000		(RANDE PRAIRIE	AB 00	00 000		
Branch								CHA	ARGE
Grande 1							GST Number 105448161	F	Reference Number
Month/Day		Order 140).	Terms			1	220-101767 **DUPLICATE*
11/25/2	22 TRS	11/18/22 101767	Kirk		NET 30 DA	YS		Ship Via HOP	BVW
Machine S	/N· CATIO	OD CHI MOGOO CI I							BVW
Init Number		DD6TLWCG00611	License 1			Cust.	Contact: KIR	K SUTHER	LAND
viii viii viii viii viii viii viii vii	-1.		Machine N	Make: CAT					
lachine:	HOURS	3: 12891.0							
achine Mo			Machine V	Year: 2010					
				2010		Locat	ion: UTL	GP SHOP	
Quantity Ordered	Quantity	Back	D-4 N			_			
		Ordered	Part Numbe	er and Description		Code	Price		Net Amoun
REQUEST	1: INCOMING	INSPECTION							Amoun
ACTION	1. COMPT DED	D 71/201/201							
ACTION		D INCOMING INSPECTI							
	CHANGED	ENGINE OIL FILTER O	NLY PER CUSTO	MERS REQUEST					
1	1	PAT P7200							
1	1	BAL B7299 INT EH2AB		OIL FILTER		TG	38	.947	38.9
2.00	2.00	LAB LABSHP	1	ENVIRO LEVY FI		G	1	.000	1.00
2.00		THE THESH	1				-	.000	1.00
2.00				SHOP REGULAR I	ABOUR	TG		.000	
	PARTS: 39	. 95 I.ABO	B. 330 00	SHOP SUPPLIES		TG	165	.000	330.00
	PARTS: 39	. 95 LABO	R: 330.00	SHOP SUPPLIES	ABOUR ETS: 0.00	TG		.000	330.00 23.10
	PARTS: 39		R: 330.00	SHOP SUPPLIES		TG	165	.000	330.00 23.10
REQUEST	2: WASH/STE	AM/CLEAN		SHOP SUPPLIES		TG	165	.000	330.00 23.10
1	2: WASH/STE			SHOP SUPPLIES		TG	165	.000	330.00 23.10
REQUEST ACTION	2: WASH/STEA	AM/CLEAN Y DIRTY. PRESSURE W	ASHED UNIT	SHOP SUPPLIES		TG	165	.000	330.00 23.10
REQUEST ACTION	2: WASH/STEA	AM/CLEAN	ASHED UNIT	SHOP SUPPLIES	ETS: 0.00	TG	165	23.10	330.00 23.10
REQUEST ACTION	2: WASH/STEA 2: UNIT VERY PARTS: 0.	AM/CLEAN Y DIRTY. PRESSURE W	ASHED UNIT	SHOP SUPPLIES SUBL	ETS: 0.00	TG	165	.000	330.00 23.10
REQUEST ACTION	2: WASH/STEA 2: UNIT VERY PARTS: 0.	AM/CLEAN Y DIRTY. PRESSURE W	ASHED UNIT	SHOP SUPPLIES SUBL	ETS: 0.00	TG	165	23.10	330.00 23.10
REQUEST ACTION FREQUEST	2: WASH/STEA 2: UNIT VERY PARTS: 0. 3: R&I RIGHT	AM/CLEAN Y DIRTY. PRESSURE W. 00 LABOI T HAND SIDE FINAL DE	ASHED UNIT R: 0.00	SHOP SUPPLIES SUBL	ETS: 0.00	TG	165	23.10	330.00 23.10
REQUEST ACTION	2: WASH/STEA 2: UNIT VERY PARTS: 0. 3: R&I RIGHT 3: BRING UNI	AM/CLEAN Y DIRTY. PRESSURE W. OO LABO HAND SIDE FINAL DE	ASHED UNIT R: 0.00 RIVE PLIT TRACK. RE	SHOP SUPPLIES SUBL	ETS: 0.00	TG	165	23.10	330.00 23.10
REQUEST ACTION FREQUEST	2: WASH/STEA 2: UNIT VERY PARTS: 0. 3: R&I RIGHT 3: BRING UNI DRIVE AND	AM/CLEAN Y DIRTY. PRESSURE W. 00 LABOR HAND SIDE FINAL DR T IN AND SET UP. SE	ASHED UNIT R: 0.00 RIVE PLIT TRACK. RE	SHOP SUPPLIES SUBL	ETS: 0.00	TG	165	23.10	330.00 23.10
REQUEST ACTION FREQUEST	2: WASH/STEA 2: UNIT VERY PARTS: 0. 3: R&I RIGHT 3: BRING UNI DRIVE AND PUT OIL I	AM/CLEAN Y DIRTY. PRESSURE W. 00 LABOR HAND SIDE FINAL DE T IN AND SET UP. SE REPLACE WITH UTR F N FINAL DRIVE. REIN	ASHED UNIT R: 0.00 RIVE PLIT TRACK. RE REMAN FINAL DR	SHOP SUPPLIES SUBL SUBL MOVE OLD FINAL RIVE. PUT TRACK BACK	ETS: 0.00	TG	165	23.10	330.00 23.10
REQUEST ACTION FREQUEST	2: WASH/STEA 2: UNIT VERY PARTS: 0. 3: R&I RIGHT 3: BRING UNI DRIVE AND PUT OIL I ON, SET T	AM/CLEAN Y DIRTY. PRESSURE W. OO LABOU HAND SIDE FINAL DE T IN AND SET UP. SE REPLACE WITH UTR F N FINAL DRIVE. REIN RACK TENSION, CHECK	ASHED UNIT R: 0.00 RIVE PLIT TRACK. RE REMAN FINAL DR ISTALL AXLES,	SHOP SUPPLIES SUBL SUBL MOVE OLD FINAL RIVE. PUT TRACK BACK	ETS: 0.00	TG	165	23.10	330.00 23.10
REQUEST ACTION FREQUEST	2: WASH/STEA 2: UNIT VERY PARTS: 0. 3: R&I RIGHT 3: BRING UNI DRIVE AND PUT OIL I ON, SET T	AM/CLEAN Y DIRTY. PRESSURE W. 00 LABOR HAND SIDE FINAL DE T IN AND SET UP. SE REPLACE WITH UTR F N FINAL DRIVE. REIN	ASHED UNIT R: 0.00 RIVE PLIT TRACK. RE REMAN FINAL DR ISTALL AXLES,	SHOP SUPPLIES SUBL SUBL MOVE OLD FINAL RIVE. PUT TRACK BACK	ETS: 0.00	TG	165	23.10	330.00 23.10
REQUEST ACTION FREQUEST	2: WASH/STEA 2: UNIT VERY PARTS: 0. 3: R&I RIGHT 3: BRING UNI DRIVE AND PUT OIL I ON, SET T	AM/CLEAN Y DIRTY. PRESSURE W. OO LABOUT HAND SIDE FINAL DE T IN AND SET UP. SE REPLACE WITH UTR F N FINAL DRIVE. REIN RACK TENSION, CHECK TION. REPLACED WITH	ASHED UNIT R: 0.00 RIVE PLIT TRACK. RE REMAN FINAL DR ISTALL AXLES, TRANSMISSION NEW FILTER.	SHOP SUPPLIES SUBLE SUBLE CMOVE OLD FINAL RIVE. PUT TRACK BACK FILTER FOR	ETS: 0.00	TG	SUPPLIES:	23.10 0.00	330.00 23.10
REQUEST ACTION FREQUEST ACTION	2: WASH/STEA 2: UNIT VERY PARTS: 0. 3: R&I RIGHT 3: BRING UNI DRIVE AND PUT OIL I ON, SET T CONTAMINA	AM/CLEAN Y DIRTY. PRESSURE W. OO LABOU HAND SIDE FINAL DE T IN AND SET UP. SE REPLACE WITH UTR F N FINAL DRIVE. REIN RACK TENSION, CHECK	ASHED UNIT R: 0.00 RIVE PLIT TRACK. RE REMAN FINAL DR ISTALL AXLES, TRANSMISSION NEW FILTER.	SHOP SUPPLIES SUBL SUBL MOVE OLD FINAL RIVE. PUT TRACK BACK	ETS: 0.00	TG	SUPPLIES:	23.10	330.00 23.10
REQUEST ACTION FREQUEST ACTION 1	2: WASH/STEA 2: UNIT VERY PARTS: 0. 3: R&I RIGHT 3: BRING UNI DRIVE AND PUT OIL I ON, SET T CONTAMINA 1	AM/CLEAN Y DIRTY. PRESSURE W. OO LABOU HAND SIDE FINAL DE T IN AND SET UP. SE REPLACE WITH UTR F N FINAL DRIVE. REIN RACK TENSION, CHECK TION. REPLACED WITH BAL PT9429-	ASHED UNIT R: 0.00 RIVE PLIT TRACK. RE REMAN FINAL DR ISTALL AXLES, TRANSMISSION NEW FILTER.	SHOP SUPPLIES SUBLE SUBLE MOVE OLD FINAL RIVE. PUT TRACK BACK FILTER FOR HYD. FILTER	ETS: 0.00	TG	SUPPLIES: SUPPLIES:	0.000 0.000	330.00 23.10 92.37
REQUEST ACTION FREQUEST ACTION 1 1 1 2 ds Recieve	2: WASH/STEA 2: UNIT VERY PARTS: 0. 3: R&I RIGHT 3: BRING UNI DRIVE AND PUT OIL I ON, SET T CONTAMINA 1 1	AM/CLEAN Y DIRTY. PRESSURE W. OO LABOU T HAND SIDE FINAL DE T IN AND SET UP. SE REPLACE WITH UTR F N FINAL DRIVE. REIN RACK TENSION, CHECK TION. REPLACED WITH BAL PT9429— — D6N INT EH2AB	ASHED UNIT R: 0.00 RIVE PLIT TRACK. RE REMAN FINAL DR ISTALL AXLES, I TRANSMISSION I NEW FILTER. MPG	SHOP SUPPLIES SUBLE SUBLE CMOVE OLD FINAL RIVE. PUT TRACK BACK FILTER FOR	ETS: 0.00	TG	SUPPLIES: SUPPLIES:	23.10 0.00	330.00 23.10
REQUEST ACTION FREQUEST ACTION 1 1 1 ds Recieve se Print Na	2: WASH/STEA 2: UNIT VERY 2: UNIT VERY 2: R&I RIGHT 3: BRING UNI DRIVE AND PUT OIL I ON, SET T CONTAMINA 1 1 1 1	AM/CLEAN Y DIRTY. PRESSURE W. OO LABOU HAND SIDE FINAL DE T IN AND SET UP. SE REPLACE WITH UTR F N FINAL DRIVE. REIN RACK TENSION, CHECK TION. REPLACED WITH BAL PT9429— — D6N INT EH2AB	ASHED UNIT R: 0.00 RIVE PLIT TRACK. RE REMAN FINAL DR ISTALL AXLES, TRANSMISSION NEW FILTER. MPG ignature	SHOP SUPPLIES SUBLE SUBL	ETS: 0.00	TG	SUPPLIES: SUPPLIES: SUPPLIES:	0.000 0.000	330.00 23.10 92.37
REQUEST ACTION FREQUEST ACTION 1 1 2 ds Recieve se Print Na ent. Terms: P	2: WASH/STEA 2: UNIT VERY PARTS: 0. 3: R&I RIGHT 3: BRING UNI DRIVE AND PUT OIL I ON, SET T CONTAMINA 1 1 1 d By:	AM/CLEAN Y DIRTY. PRESSURE W. OO LABOU T HAND SIDE FINAL DE T IN AND SET UP. SE REPLACE WITH UTR F N FINAL DRIVE. REIN RACK TENSION, CHECK TION. REPLACED WITH BAL PT9429- - D6N INT EH2AB	ASHED UNIT R: 0.00 RIVE PLIT TRACK. RE REMAN FINAL DR ISTALL AXLES, I TRANSMISSION I NEW FILTER. MPG ignature	SHOP SUPPLIES SUBLE SUBL	ETS: 0.00	TG	SUPPLIES: SUPPLIES:	0.000 0.000	330.00 23.10 92.37

THE UNDERSIGNED HEREBY WAIVES ENTITLEMENT UNDER THE PERSONAL PROPERTY SECURITY ACT TO RECEIVE A COPY IN WRITING OF ANY FINANCIAL STATEMENT OF FINANCING CHANGE THE UNDERSIGNED AGREES TO PAY ALL COSTS INCURRED FOR THE RECOVERY OF ANY AMOUNT OWING, INCLUDING LEGAL COSTS ON A SOLICITOR AND CLIENT BASIS INCLUSIVE OF STORAGE FEES.

TERMS: NET 30 DAYS FOLLOWING INVOICE DATE.
A SERVICE CHARGE WILL BE CHARGED TO YOU ON ANY OUTSTANDING BALANCE AT THE END OF EACH MONTH AT THE RATE OF 1.5% PER MONTH CALCULATED AND COMPOUNDED MONTHLY (19.57% PER ANNUM).

