

Edge Fleet Maintenance (1998) Ltd.
 PO Box 519
 Wembley AB T0H 3S0
 780-532-8911
 edgefleet@hotmail.com
 GST Registration No.: 881387625RT0001

Invoice

BILL TO
 585061 AB LTD.
 8610-112 ST.
 AB.
 GRANDE PRAIRIE AB T8V 5X4

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
13049	16/04/2026	\$4,735.31	16/05/2026	Net 30	

UNIT # 470
 VIN# 1FUJA6CK65PU09757

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
CVIP HEAVY TRUCK	CVIP HEAVY TRUCK CVIP #8700910	1	445.00	445.00
*CVIP/WHEEL REMOVAL	CVIP WHEEL REMOVAL .8/HR	5	123.20	616.00
				Subtotal: 1,061.00
Perform complete service on unit. Change oil and fuel filters. Check all levels. Check for any obvious issues. Change coolant filter. Change air filter. Change cab air filter. Grease unit throughout. Top up windshield washer fluid, coolant and trans oil.				
SHOP RATE	SHOP RATE	3.50	154.00	539.00
*LFP-2160	OIL FILTER/LG	2	25.05	50.10
EHC-LG	ENVIRONMENTAL CHARGE	2	1.25	2.50
*ROTT41540/L	ROTELLA T4 15W40/L	34	7.03	239.02
EHC-L	ENVIRONMENTAL CHARGE	34	0.12	4.08
DISPOSAL FEE	DISPOSAL FEE/L	34	0.06	2.04
*FS19624/PF7748	FUEL/WATER SEPARATOR/LG	1	33.39	33.39
EHC-LG	ENVIRONMENTAL CHARGE	1	1.25	1.25
*FIB5134	WATER FILTER/SM	1	15.33	15.33
EHC-SM	ENVIRONMENTAL CHARGE	1	0.55	0.55
*FIRS3518	AIR FILTER	1	110.50	110.50
*FIPA4857	CAB AIR FILTER	1	27.69	27.69
*WINTERGRS	WINTER GREASE S2	2	8.18	16.36
*WINTERWASH	WINTER WNDSHLD FLUID	2	7.19	14.38
*PREMIX	PREMIX ANTIFREEZE/JUG	1	12.48	12.48
*50WSYNMOB/L	50W SYN/L	1	17.16	17.16
EHC-L	ENVIRONMENTAL CHARGE	1	0.12	0.12
DISPOSAL FEE	DISPOSAL FEE/L	1	0.06	0.06

POSTED

Thank you for choosing Edge Fleet. We appreciate your business.

If paying by e-transfer please use edgefleet@hotmail.com. We accept credit cards with 3% processing fee.

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
				Subtotal: 1,086.01
	Replace upper cab clearance lamp. Verify.			
SHOP RATE	SHOP RATE	0.50	154.00	77.00
*PI5408BP	PIGTAIL	1	4.23	4.23
*194	194 BULB	1	0.76	0.76
				Subtotal: 81.99
	Replace (2x) engine belts. Confirm pulleys, idlers, tensioner. Verify operation.			
SHOP RATE	SHOP RATE	0.75	154.00	115.50
*01-35660-427	BELT, 8 RIB	1	36.68	36.68
*01-35605-275	BELT, 10 RIB	1	64.00	64.00
				Subtotal: 216.18
	Replace (2x) rear mud flaps, including reflective hangers. Re-secure loose fenders.			
SHOP RATE	SHOP RATE	2	154.00	308.00
MUDHNGR	MUD FLAP HANGER BAR	2	22.45	44.90
*24X30HDMF/24X30	24X30 HD MUDFLAP	2	26.38	52.76
*NRS3000	REFLECTOR STRIP, STRAIGHT	1	28.25	28.25
				Subtotal: 433.91
	Replace (2x) brake pots, including clevis. Tie-up loose air lines-secure. Replace air lines as required. Repair air leak.			
SHOP RATE	SHOP RATE	5	154.00	770.00
*3030LCB20-FLT/FT3030L	3030 BRAKEPOT LONG STROKE	2	70.05	140.10
*179.YK5005	CLEVIS KIT MER T 5/8-18	2	10.54	21.08
HAB622C	22" 3/8 NPT HOSE ASSY	1	12.83	12.83
*6506-06-08	06FP-08FJS STRAIGHT	1	4.89	4.89
				Subtotal: 948.90
	Have left side windshield replaced.			
WINDSHIELD	WINDSHIELD	1	357.50	357.50
				Subtotal: 357.50
	Repair mirror bracket (upper) right side door.			
SHOP RATE	SHOP RATE	1	154.00	154.00
*PA5000-313	1/4X1 1/2NC STAIN/STEEL BOLT	1	0.47	0.47
*PA5055-214	1/4 STAIN/STEEL FLAT WASHER	2	0.11	0.22
*PA5034-014	1/4NC STAIN/STEEL NYLOCK NUT	1	0.23	0.23
				Subtotal: 154.92
SHOP SUPPLIES	MISC. SUPPLIES	1	169.40	169.40
				Subtotal: 169.40
	TORQUE WHEELS			

Thank you for choosing Edge Fleet. We appreciate your business.

If paying by e-transfer please use edgefleet@hotmail.com. We accept credit cards with 3% processing fee.

UNIT LIC# 0BD304
KMS_1521699
HRS 5244
RE-TORQUE WHEELS @ 100 KMS

SUBTOTAL	4,509.81
GST @ 5%	225.50
TOTAL	4,735.31
BALANCE DUE	\$4,735.31

Thank you for choosing Edge Fleet. We appreciate your business.
If paying by e-transfer please use edgefleet@hotmail.com. We accept credit cards with 3% processing fee.