

KP Mechanical & Farm Ltd

PO Box 373
 Blackfoot AB T0B 0L0
 kpmechanicalttd@gmail.com
 GST/HST Registration No.: 798820825



2009 Wilson Syenics

INVOICE

BILL TO

INVOICE
 DATE 19/03/2025
 TERMS Net 15
 DUE DATE 03/04/2025

| DATE | ACTIVITY | DESCRIPTION | QTY | RATE | AMOUNT |
|------------|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--------|----------|
| 14/03/2025 | Alberta CVIP | <ul style="list-style-type: none"> -Performed AB CVIP A inspection on lead trailer -Raised unit up supported on stands, removed all tires & drums -Took all proper measurements inspected unit | 1 | 450.00 | 450.00 |
| 14/03/2025 | CVIP REPAIRS | <ul style="list-style-type: none"> -Removed 1st, 2nd, 3rd axle RH hubs & bearings -Removed wheel seals from hubs -Cleaned all 3 hubs and spindles -Cleaned all bearings -Installed new wheel seals -Reinstalled all 3 hubs set bearing pre load -Cleaned & installed hub caps filled hubs with oil -Removed 1st axle L&R air bags disconnected air lines removed fittings, nuts seized had to cut to extract airbag -Installed air bags L&R reinstalled air fittings connected air lines -Removed L&R shock absorbers 2nd axle -Installed new shock absorbers 2nd axle -Removed 2nd axle L&R air bags disconnected air lines removed fittings -Nuts seized had to cut to extract air bags -Installed new air bags 2nd axle L&R, reinstalled air fittings reconnected air lines -Removed 3rd axle L&R shock absorbers -Installed new shock absorbers 3rd axle L&R -Removed 3rd axle LH air bags, disconnected air line removed air | 24 | 130.00 | 3,120.00 |

| | | | | |
|------------|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|--------|
| | | fitting -Nuts seized had to cut to extract bag -Installed new air bag, reinstalled air fitting reconnected air line -Removed fifth wheel side pins & bushings, flipped fifth wheel over -Removed fifth wheel jaw pins -Removed fifth wheel jaws -Installed new fifth wheel jaws & pins -Reinstalled fifth wheel plate with new side pins & bushings -Adjusted 5th wheel -Installed new brake shoes & drums 1st, 2nd, 3rd axle L&R -Reinstalled all tires torqued to spec -Adjusted brakes | | |
| 14/03/2025 | Alberta CVIP | -Performed AB CIVIP A inspection on pup -Raised unit up supported on stands -Removed all tires & drums -Took all proper measurements, inspected unit | 1 | 336.00 |
| 14/03/2025 | CVIP REPAIRS | -Removed hubs & bearings 1st axle L&R -Removed wheel seals -Cleaned hubs, spindles & bearings -Installed new wheel seals -Reinstalled both hubs set bearing pre load -Cleaned & installed hub caps, filled hubs with oil -2nd axle RH slack adjuster holding up causing brakes to stay on -Tried to remove slack adjuster but seized onto scam -Cut slack adjuster off of scam -Installed new slack adjuster -Tire craft replaced all tires on pup -Installed new brake shoes & drums L&R 1st & 2nd axle -Reinstalled all tires torqued to spec -Adjusted all brakes -Disconnected air lines running to air suspension dump switch -Installed new air suspension dump switch reconnected air lines -Reconnected trailer pulled trailers out cleaned bay | 10 | 130.00 |
| 14/03/2025 | Parts | Shop Supplies | 1 | 218.40 |
| 14/03/2025 | Parts | 80w-90 gear oil | 7 | 9.00 |
| 14/03/2025 | Parts | SSD6722 DRUMS | 10 | 121.02 |
| 14/03/2025 | Parts | XSS714707QPK Brakes shoes | 10 | 67.98 |
| 14/03/2025 | Parts | AS9974P air bags | 3 | 204.96 |
| 14/03/2025 | Parts | 3727097 wheel seal | 5 | 55.26 |
| 14/03/2025 | Parts | 3303009 hub cap gasket, | 5 | 2.94 |
| | | | | 14.70 |

| | | | | | |
|------------|-------|-------------------------------------------|---|--------|--------|
| 14/03/2025 | Parts | RK35107296 Fifth wheel jaws | 1 | 447.78 | 447.78 |
| 14/03/2025 | Parts | RK069731 fifth wheel side pins & bushings | 1 | 143.46 | 143.46 |
| 14/03/2025 | Parts | 83150 shock absorbers | 4 | 75.54 | 302.16 |
| 14/03/2025 | Parts | 40010211 slack adjuster | 1 | 145.68 | 145.68 |

Wilson Trailer 2009 Lead
VIN: 1W115FJT98B252143

Wilson trailer 2009 Pup
VIN: 1W125FLA99B252144

| | |
|--------------|-----------------|
| SUBTOTAL | 9,322.36 |
| GST @ 5% | 466.12 |
| TOTAL | 9,788.48 |

| | |
|--------------------|-------------------|
| BALANCE DUE | \$9,788.48 |
|--------------------|-------------------|

TAX SUMMARY

| | RATE | TAX | NET |
|----------|------|--------|----------|
| GST @ 5% | | 466.12 | 9,322.36 |

WARD // TIRECRAFT

WardTirecraft Lloydminster

6207 43 Street

Lloydminster AB T9V 2W9

Phone: 780-875-8473 Fax: 780-875-8481

203-1

PAGE: 1

DATE: 25 Mar 19

GST REG#: 70694 1481 RT0001

PST REG#:

INVOICE

LL36250

SOLD TO:

CONTACT:

MOBILE

HOME:

BUSINESS:

FAX :

EMAIL :

| COLOUR | VEHICLE DESCRIPTION | | UNIT# | ODO IN | |
|----------|---------------------|------------------------------------------------|-------------|-----------|-----|
| PLATE | VIN | | | 0 | |
| TIME IN | PROMISED | TERMS | GST EXEMPT# | P.O. | TAG |
| 12:45 PM | | CASH | | | |
| QTY | ITEM | DESCRIPTION | NET | EXT.PRICE | |
| 8 | 157732 | GREATWAY DT966 RIB A/P LRH 20/32 11R24.5 | 358.95 | 2871.60 | |
| 8 | TRF-SK-MED | TIRE RECYCLE FEE - MEDIUM TRUCK | 14.00 | 112.00 | |
| 8 | TCO | TRUCK CHANGEOVER EE 25 Mar 17 | 45.00 | 360.00 | |
| | | <i>LOOSE</i> | | | |
| 8 | A-545 | 545 ALCOA VALVE STEM | 10.95 | 87.60 | |
| 1 | TRE | TRUCK REPAIR JA 25 Mar 17 | 50.00 | 50.00 | |
| | | <i>NEW STEM</i> | | | |
| 1 | A-545 | 545 ALCOA VALVE STEM | 10.95 | 10.95 | |
| 1 | SS | SHOP SUPPLIES | 41.00 | 41.00 | |
| | | TOTAL DISCOUNT GIVEN---> 1048.40 | | | |
| | | Payment Method: Cheque (001387)=3709.81 | | | |
| | | ***** REMINDER ***** | | | |
| | | PLEASE ENSURE THAT YOU HAVE THE TORQUE ON YOUR | | | |
| | | WHEEL NUTS CHECKED WITHIN THE FIRST 100KM AND | | | |

INVOICE TO:

Terms and Conditions: I hereby acknowledge my indebtedness in the amount of the invoice plus any costs incurred in order to collect the balance outstanding. Interest at the rate of 2% per month (24% per annum) will be charged on overdue. All products remain the property of 2177261 Alberta Ltd. o/a WARDTIRECRAFT Lloydminster until paid in full. I authorize you, your agents or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third- parties. I will be responsible for any and all charges that any third-party warranty company fails to pay for. 2177261 Alberta Ltd. o/a WARDTIRECRAFT Lloydminster does not assume responsibility or liability for vehicles and contents left at our premises. I grant 2177261 Alberta Ltd. o/a WARDTIRECRAFT Lloydminster informed prior consent to have personal information released to them such as name, DOB, address, personal and non-personal motor vehicle information for the purpose of filing a garageman's lien within 21 days of invoice date on the above vehicle.

Signature: _____ Print Name: _____

| | |
|---------------|----------------|
| PARTS: | 2970.15 |
| LABOUR: | 410.00 |
| OTHER: | 153.00 |
| SUB-TOTAL: | 3533.15 |
| GST/HST: | 176.66 |
| PST: | N/C |
| TOTAL: | 3709.81 |