

Maintenance Da Plant		Maintenance Short Description	Maintenance Supplied By	Meter Reading	Cost	Notes
17/06/2024	PR-39 Wheel Loader	Fit new quick hitch	Harris Heavy Mechanics	635 hours	1,928.41	Fit new quick hitch. Weld stoppers onto hitch. Test & fill with oil.
						Travel to machine 20/12/23. Try to remove cylinders. Cylinder pins were seized & couldn't get pin with press. Travel to machine 21/12/23. Cut out pin on tilt cylinder. Press out pin while heating. Press out quick hitch pins. Disassemble cylinder & drop off for repairs. Travel to machine 6/3/24. Put cylinder back together. Fit new pin & test machine.
6/3/2024	PR-39 Wheel Loader	Seized cylinder pins	Harris Heavy Mechanics	624 hours	1,919.50	
31/01/2024	PR-39 Wheel Loader	Hydraulic cylinder rerod & replace seals. Assembled & tensioned on cylinder bench.	Harris Heavy Mechanics	???	5,750.80	
28/11/2023	PR-39 Wheel Loader	500hr service	Harris heavy mechanical	528 hours		500hr service completed next service @ 750hrs