

Number	Operational View	Operational Asset	Work Type	Description	Work Done	Completed	Status	
WO-MON-000-335	[MON] Monty	FEL00096	Corrective Maintenance (Unscheduled)	24300 - Top up self greaser. Grease drive line.	Travel to ROM. Top up self greaser - grease driveline. Travel back to workshop.	01/19/2020	Completed	Unchecked
WO-MON-000-319	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	CARRIED OUT TYRE INSPECTION ADJUST PRESSURES TO BRIDGESTONE SPEC 100 PSI FRONT - 90 PSI REAR	01/20/2020	Completed	Checked
WO-MON-000-322	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	100PSI front, 90PSI rear, specs for D lug tyre Inspect/tyre checks, top up self greaser	01/29/2020	Completed	Checked
WO-MON-000-329	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Inspection Grease Top up self greaser POS1 - slight cut on outside wall	02/05/2020	Completed	Checked
WO-MON-000-330	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Inspection grease Top up self greaser POS1 - Slight cut on outside wall	02/11/2020	Completed	Checked
WO-MON-000-357	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTIONS, TOP UP SELF GREASER, WHEEL BOLT RE TORQUE	02/23/2020	Completed	Checked
WO-MON-000-354	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	A service Top up greaser Re-torque wheels Oil filter/trans filter to be replaced Scheduled to come to workshop	02/23/2020	Completed	Unchecked
WO-MON-000-353	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Tyre inspection & grease POS1 - Slight cut on outside wall	02/28/2020	Completed	Checked
WO-MON-000-390	[MON] Monty	FEL00096	Corrective Maintenance (Unscheduled)	16587 - ENGINE SERVICE, TRANS SERVICEM CAB CLEAN OUT, TOP UP SELF GREASER	ENGINE SERVICE/TRANS SERVICE WASH UNIT ON WASH PAD TOP UP SELF GREASER	03/01/2020	Completed	Unchecked
WO-MON-000-362	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	CARRIED OUT TYRE CHECKS POS1 - slight cut on outside wall	03/01/2020	Completed	Checked
WO-MON-000-379	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Tyre inspection/grease POS1 Tear through side of tread out side	03/14/2020	Completed	Checked
WO-MON-000-384	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Carried out tyre inspection/grease Top up self greaser POS1 - tear through side of tread out side	03/17/2020	Completed	Checked
WO-MON-000-387	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	CARRIED OUT TYRE INSPECTION/GREASE	03/21/2020	Completed	Checked
WO-MON-000-401	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Inspection Grease Tyre checks POS1 - Tear through side of tread outside	04/09/2020	Completed	Checked
WO-MON-000-405	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Inspection Grease Tyre checks POS1 - Tear through side wall of tread	04/13/2020	Completed	Checked
WO-MON-000-420	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	inspect tyre, pump the uplift tyre, check the oil water 2 X FRONT VALVE CAPS MISSING LH FRONT TYRE HAS TO BIG SLASHES ON OUTSIDE TREAD TRAVELING UPSIDE WALL TYRE IS LOSING PRESSURE	04/22/2020	Completed	Checked
WO-MON-000-425	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	CARRIED OUT TYRE INSPECTION WASH DOWN FOR SERVICE BUCKET INSPECTION NEED NEW HEEL PLATE	05/04/2020	Completed	Checked
WO-MON-000-408	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (B service)	Carried out 500hr as per s/s service maintenance intervals. Found cylinder head leaking from bottom side of spacer plate. Photos have been taken, had to top up coolant (11L) could not see any visible signs of leaks from hoses, radiator water pump & engine block. Will pay to monitor this to see if coolant drops again, engine oil sample has been taken. Repaired broken grease fitting to the bottom of RH cylinder lift centre, greased up driveline, front shaft support & centre hitch bearings. Bleed fuel system, ran up machine & adjusted oil levels. Blow air filter out with air, filter as bit full. Also, there were no replacement air filters on site.	05/04/2020	Completed	Unchecked
WO-MON-000-447	[MON] Monty	FEL00096	Corrective Maintenance (Unscheduled)	16709 - 2x Front tyres and rims	Fit new 2x tyres and rims to front	05/18/2020	Completed	Unchecked
WO-MON-000-446	[MON] Monty	FEL00096	Corrective Maintenance (Unscheduled)	16709 - 2X FRONT TYRE AND RIMS	FIT NEW 2 X TYRES AND RIMS TO FRONT	05/18/2020	Completed	Unchecked
WO-MON-000-445	[MON] Monty	FEL00096	00 - Preventative Maintenance	Loadrite Calibration - Yearly	CARRIED OUT BY SITECH CALIBRATION REPORT RECEIVED	05/22/2020	Completed	Unchecked
WO-MON-000-439	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Fill grease pod, general check of loader, tyre service	05/23/2020	Completed	Checked
WO-MON-000-459	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	CARRIED OUT TYRE INSPECTION FILL UP GREASE POD CHECK TYRE PRESSURE GENERAL CHECKOVER ON LOADER	06/04/2020	Completed	Checked

WO-MON-000-450	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Tyre inspection, fill up grease pad, put 5 litres oil in engine, general checkover	06/10/2020	Completed	Checked
WO-MON-000-487	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (C service) (Westrac)	CARRIED OUT BY ALLEN AS PER CALVIN 3/7/20 WESTRAC SERVICE CANCELLED	06/23/2020	Completed	Unchecked
WO-MON-000-475	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Full tyre inspection POS1 slight cut right hand front tyre	06/23/2020	Completed	Checked
WO-MON-000-473	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	Pull heel plates off Weld old grader plates on bottom Refit, full service	06/23/2020	Completed	Unchecked
WO-MON-000-490	[MON] Monty	FEL00096	02 - Breakdown Maintenance	16738 - Starting issues	Completed	06/28/2020	Completed	Unchecked
WO-MON-000-483	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	999.7 Hr Fill grease pod, grease tail shaft, tyre service, top up engine oil, fix isolation switch	06/30/2020	Completed	Checked
WO-MON-000-485	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	tyre inspection fill grease pod grease tail shaft general inspection full wash	07/05/2020	Completed	Checked
WO-MON-000-499	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Tyre service Fill grease pod grease tail shaft bucket inspection POS1 - slight cut RH outside tyre front	07/18/2020	Completed	Checked
WO-MON-000-502	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	cut arrow bar weld onto new heel plates tyre inspection general checkover grease tailshaft fill grease pod	07/20/2020	Completed	Checked
WO-MON-000-516	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Tyre inspection Fill grease pod Grease tail shaft Tighten heel plates POS1 - slight cut RH tyre POS2 - RH front rim damage POS3 - Both rear tyres cuts in thread from wheel rim	08/04/2020	Completed	Checked
WO-MON-000-518	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	full service check loader over new air filter new cab air filter	08/10/2020	Completed	Unchecked
WO-MON-000-524	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Tyre inspection, fill grease pod, grease tail shaft, fit new heel plates to bucket	08/17/2020	Completed	Checked
WO-MON-000-529	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION GREASE TAIL SHAFT FILL GREASE POD GENERAL INSPECTION FIT NEW TEETH TO BUCKET RH FRONT RIM DAMAGE SLIGHT CUT RH TYRE FRONT BOTH REAR TYRE CUTS IN TREAD 1317.6 HR PARTS USED: 8X BUCKET TEETH	09/01/2020	Completed	Checked
WO-MON-000-540	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	tyre inspection grease tailshaft fill grease pod blow out air cleaners POS1 - slight cut RH front tyre POS2 - RH front rim damage POS3 - both rear tyres wheel spin cuts	09/06/2020	Completed	Checked
WO-MON-000-545	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE SERVICE BLOW OUT AIR CLEANERS GREASE TAIL SHAFT FILL GREASE POD 1396 HR SLIT CUT RH FRONT TYRE RH FRONT RIM DAMAGED BOTH REAR TRES WHEEL SPINS CUT	09/17/2020	Completed	Checked

WO-MON-000-555	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Tyre inspection. General check over Slight cut RH front tyre RH front rim damage Both rear tyres wheel spin cuts 1455 Hr	09/24/2020	Completed	Checked
WO-MON-000-554	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (B service)	CARRY OUT B SERVICE FILL GREASE POD 1501.5 HRS	09/28/2020	Completed	Unchecked
WO-MON-000-566	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION, FILL GREASE POD, GREASE TAILSHAFT, FIT NEW HEAL PLATES 2 X NEW HEEL PLATES	10/06/2020	Completed	Checked
WO-MON-000-563	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	Tyre service, fill grease pod, grease tail shaft RH front rim damage RH front tyre slight cut side wall Both rear tyre cuts in tread wheel spin 1520 Hr Parts used: 1x valve cap	10/13/2020	Completed	Checked
WO-MON-000-567	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION GENERAL CHECK OVER GREASE TAIL SHAFT FILL GREASE POD BLOWOUT ALL AIR CLEANERS 1536 HR RH FRONT RIM DAMAGE RH FRONT TYRE SLIGHT CUT SIDE WALL BOTH REAR TYRES WHEEL SPIN CUTS	10/19/2020	Completed	Checked
WO-MON-000-581	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION GENERAL CHECK OVER GREASE TAIL SHAFT FILL GREASE POD FIT NEW AIR CLEANER	11/03/2020	Completed	Checked
WO-MON-000-582	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION GENERAL CHECK OVER GREASE TAIL SHAFT FILL GREASE POD PULL OF ALL BUCKET TEETH FABRICATE ALL NEW HEELS WELD ONTO TEETH	11/08/2020	Completed	Checked
WO-MON-000-592	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION, FILL GREASEPOD, GREASE TAILSHAFT CENTRE BEARINGS, FIT NEW WHEEL PLATES POS1 RH FRONT RIM DAMAGE POS2 RH FRONT SLIGHT OUTSIDE WALL POS3 CUTS IN EAR FROM WHEEL SPIN	11/24/2020	Completed	Checked
WO-MON-000-595	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION, FILL GREASEPOD, GREASE TAILSHAFT POS1 - RH FRONT RIM DAMAGE POS2 - RH FRONT SLIGHT SIDEWALL DAMAGE POS3 - CUTS IN REAR TYRES WHEEL SPIN	11/27/2020	Completed	Checked
WO-MON-000-596	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION FILL GREASE POD GREASE TAIL SHAFT AND CENTRE BEARING BLOW AIR CLEANERS	11/29/2020	Completed	Checked
WO-MON-000-586	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	CARRY OUT A SERVICE FILL GREASE POD GREASE TAIL SHAFT, CENTRE BEARINGS FULL WASH	11/30/2020	Completed	Unchecked
WO-MON-000-614	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION GENERAL CHECK OVER GREASE TAIL SHAFT FIT NEW AIR CLEANERS FILL GREASE POD	12/09/2020	Completed	Checked
WO-MON-000-618	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION FILL GREASE POD GENERAL CHECK OVER FIT HEEL PLATES POS1 - RH FRONT RIM DAMAGE POS2 - RH FRONT SLIGHT SIDE WALL DAMAGE POS3 - CUTS IN REAR TYRES FROM WHEEL SPIN	12/28/2020	Completed	Unchecked

WO-MON-000-624	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (D service)	CARRY OUT D-SERVICE CHANGE HEEL PLATES FIT HEEL PLATES	01/21/2021	Completed	Unchecked
WO-MON-000-636	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION GENERAL CHECK OVER BLOW OUT AIR CLEANERS POS1 - RH FRONT RIM DAMAGE POS2 - RH FRONT SIDE WALL DAMAGE POS3 - CUTS IN REAR TREAD WHEEL SPIN	01/28/2021	Completed	Unchecked
WO-MON-000-660	[MON] Monty	FEL00096	Corrective Maintenance (Unscheduled)	26108 - BUCKET TEETH	ROTATE BUCKET TEETH	01/31/2021	Completed	Unchecked
WO-MON-000-648	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION GENERAL CHECK OVER FILL GREASE POD GREASE TAIL SHAFT	02/01/2021	Completed	Unchecked
WO-MON-000-656	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION, FILL GREASE POD GREASE TAILSHAFT, GENERAL CHECK OVER POS1 - RH FRONT RIM DAMAGE POS2 - RH FRONT SIDEWALL POS3 - REAR WHEEL SPIN	02/10/2021	Completed	Unchecked
WO-MON-000-670	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION FILL GREASEPOD GREASE TAILSHAFT FIT NEW AIR CLEANERS TAP UP ENG OIL BUCKET INSPECTION PARTS USED: 2X ENG AIR CLEANERS 2X AIRCON AIR CLEANERS POS1 - RH FRONT RIM DAMAGE POS2 - RH FRONT SIDE WALL DAMAGE POS3 - CUT IN REAR TREAD WHEEL SPIN	02/21/2021	Completed	Unchecked
WO-MON-000-671	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	CARRY OUT A SERVICE PARTS USED: 2X ENG AIR CLEANERS, 2X A/C AIR CLEANERS	02/21/2021	Completed	Unchecked
WO-MON-000-675	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION GENERAL CHECKOVER GREASE POS1 - RH FRONT RIM DAMAGE POS2 - RH FRONT SIDE WALL DAMAGE POS3 - CUT ON REAR TREADS WHEEL SPIN	02/24/2021	Completed	Unchecked
WO-MON-000-676	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSP GENERAL CHECKOVER GREASE FILL GREASEPOD POS1 - RH FRONT RIM DAMAGE POS2 - RH FRONT SIDEWALL DAMAGE POS3 - CUT IN REAR TREADS WHEEL SPIN	03/01/2021	Completed	Unchecked
WO-MON-000-695	[MON] Monty	FEL00096	Corrective Maintenance (Unscheduled)	26120 - HEEL PLATES	FIT HEEL PLATES 2676 HR	03/05/2021	Completed	Unchecked
WO-MON-000-684	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION POS1 - RH FRONT RIM DAMAGE POS2 - RH FRONT SIDEWALL DAMAGE PO3 - CUT IN REAR TREAD CUTS FROM WHEEL SPIN	03/12/2021	Completed	Unchecked
WO-MON-000-686	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (B service)	CARRY OUT B SERVICE PARTS USED: 1X FILTER KIT, AIRCLEANERS, MOTOR & A/C 7X BUCKET TEETH	03/12/2021	Completed	Unchecked
WO-MON-000-690	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION POS1 - RH FRONT RIM DAMAGE (NO SAFETY ISSUE) POS2 - RH FRONT MINOR SIDEWALL DAMAGE POS3 - CUTS IN REAR TREAD FROM WHEEL SPIN	03/18/2021	Completed	Unchecked

WO-MON-000-691	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSP, FILL GREASEPOD, GREASE TAIL SHAFT POS1 - RH FRONT RIM DAMAGE MINOR POS2 - RH FRONT SIDEWALL DAMAGE MINOR POS3 - CUT IN REAR TREAD WHEEL SPIN	03/22/2021	Completed	Unchecked
WO-MON-000-704	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	GENERAL CHECKOVER GREASE, TYRE INSPECTION	04/03/2021	Completed	Unchecked
WO-MON-000-705	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION, GREASE POD, GREASE TAILSHAFT, GENERAL CHECKOVER	04/13/2021	Completed	Unchecked
WO-MON-000-716	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSP FULL GREASE POD GREASE TAIL SHAFT	04/23/2021	Completed	Unchecked
WO-MON-000-722	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION FILL GREASEPOD GREASE TAILSHAFT GENERAL CHECKOVER	04/26/2021	Completed	Unchecked
WO-MON-000-723	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSP FILL GREASEPOD GREASE TAILSHAFT GENERAL CHECKOVER	04/30/2021	Completed	Unchecked
WO-MON-000-729	[MON] Monty	FEL00096	00 - Preventative Maintenance	Loadrite Calibration - Yearly (Sitech)	CALIBRATION REPORT RECEIVED BY SITECH	05/12/2021	Completed	Unchecked
WO-MON-000-733	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE SERVICE	05/13/2021	Completed	Unchecked
WO-MON-000-721	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (C service)	CARRY OUT C SERVICE FIX OIL LEAK HYD TANK	05/13/2021	Completed	Unchecked
WO-MON-000-738	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION GENERAL INSPECTION GREASE TAILSHAFT FILL GREASEPOD	05/20/2021	Completed	Unchecked
WO-MON-000-737	[MON] Monty	FEL00096	00 - Preventative Maintenance	Inspection & Tyre Checks	TYRE INSPECTION GREASE TAILSHAFT FILL GREASEPOD	05/24/2021	Completed	Unchecked
WO-MON-000-750	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	TYRE INSPECTION	06/04/2021	Completed	Unchecked
WO-MON-000-749	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	A SVC FIX HYD LEAK FIX GREASE LINE FILL GREASE POD	06/06/2021	Completed	Unchecked
WO-MON-000-757	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	TYRE INSP, FILL GREASE POD, GENERAL CHECKOVER	06/11/2021	Completed	Unchecked
WO-MON-000-758	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	TYRE INSPECTION FILL GREASE POD SERVICE CHANGE AIR CLEANERS FIT NEW GREASE LINES	06/15/2021	Completed	Unchecked
WO-MON-000-775	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	TYRE INSPECTION FILL GREASEPOD GREASE TAILSHAFT	06/25/2021	Completed	Unchecked
WO-MON-000-780	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	TYRE INSPECTIONS, GENERAL CHECKOVER, WASH DOWN	06/30/2021	Completed	Unchecked
WO-MON-000-781	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	TYRE INSPECTION, FILL GREASE POD, GREASE TAILSHAFT, GENERAL INSPECTION	07/04/2021	Completed	Unchecked
WO-MON-000-795	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	TYRE INSPECTION. GENERAL INSP, FILL GREASE POD, GREASE TAIL SHAFT	07/13/2021	Completed	Unchecked
WO-MON-000-802	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	TYRE INSPECTION GENERAL CHECKOVER	07/19/2021	Completed	Unchecked
WO-MON-000-789	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (B service)	WASH DOWN B SERVICE PARTS USED: 1X FILTER KIT	07/24/2021	Completed	Unchecked
WO-MON-000-803	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	WASH DOWN LOADER, GENERAL CHECKOVER FILL GREASE POD, BUCKET INSP	07/27/2021	Completed	Unchecked
WO-MON-000-818	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	TYRE INSPECTION, GENERAL CHECKOVER, FILL GREASE POD, GREASE TAIL SHAFT	08/04/2021	Completed	Unchecked
WO-MON-000-819	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	TYRE INSPECTION, GENERAL CHECKOCER, FILL GREASE POD, GREASE TAILSHAFT	08/09/2021	Completed	Unchecked
WO-MON-000-821	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	Tyre inspection Fill grease pod General check over	08/15/2021	Completed	Unchecked
WO-MON-000-828	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	4069 Hours TYRE INSP GENERAL CHECKOVER	08/27/2021	Completed	Unchecked

WO-MON-000-846	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (D service)	A SVC FIT NEW SEAT COMPRESSOR PARTS USED: 1X SEAT COMPRESSOR, SVC KIT NEW ENG AIR FILTER NEW CAB AIR FILTER	09/02/2021	Completed	Unchecked
WO-MON-000-836	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	TYRE INSPECTION FILL GREASE POD GENERAL CHECKOVER	09/06/2021	Completed	Unchecked
WO-MON-000-837	[MON] Monty	FEL00096	05 - Predictive Maintenance	Rim & Tyre Inspection	TYRE INSP FILL GREASE POD GENERAL CHECKOVER	09/07/2021	Completed	Unchecked
WO-MON-000-874	[MON] Monty	FEL00096	02 - Breakdown Maintenance	26004 - Broken Grease Line, Change Oil, Change Bucket Teeth	Make new grease line Change engine oil Change bucket teeth 4497 Hours	09/22/2021	Completed	Unchecked
WO-MON-000-852	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TYRE INSPECTION. FILL GREASE POD	10/06/2021	Completed	Unchecked
WO-MON-000-866	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (B service)	B SERVICE, BUCKET TEETH, ROTATE AND FIT NEW TYRES PARTS USED: 1X NEW TYRE, 1X FILTER KIT, 1X AIRCLEANER KIT, 8X NEW BUCKET TEETH	10/13/2021	Completed	Unchecked
WO-MON-000-867	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TYRE INSPECTION	10/16/2021	Completed	Unchecked
WO-MON-000-868	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TYRE INSPECTION FILL GREASE POD FIX GREASE LINE FIT NEW HEEL PLATES INSTALLED & SETUP DASH CAMERA	10/19/2021	Completed	Unchecked
WO-MON-000-898	[MON] Monty	FEL00096	01 - Corrective Maintenance	DASH CAM INSTALL	PARTS USED: 1X DASH CAMERA 1X USB 1X 1TB HDD	10/26/2021	Completed	Unchecked
WO-MON-000-885	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TYRE INSPECTION, FIT ALL NEW GET TO BUCKET PARTS USED: HEEL PLATES TEETH GET	10/27/2021	Completed	Unchecked
WO-MON-000-887	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TYRE INSPECTION, FILL GREASE POD, GREASE TAILSHAFT FIT NEW BUCKET GET PARTS USED: GET FOR BUCKET	11/02/2021	Completed	Unchecked
WO-MON-000-888	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TYRE INSPECTION FILL GREASE POD GENERAL CHECKOVER	11/09/2021	Completed	Unchecked
WO-MON-000-909	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TYRE INSPECTION, FILL GREASE POD, GREASE TAILSHAFT	11/21/2021	Completed	Unchecked
WO-MON-000-908	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	A SERVICE, WASH DOWN FILL GREASE POD PARTS USED: FILTER KIT	11/22/2021	Completed	Unchecked
WO-MON-000-915	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TYRE INSPECTION FILL GREASE POD	11/25/2021	Completed	Unchecked
WO-MON-000-916	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	RIM & TYRE INSPECTION DONE	12/07/2021	Completed	Unchecked
WO-MON-000-925	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TYRE INSPECTION, WASH, GREASE, FILL GREASEPOD	12/17/2021	Completed	Unchecked
WO-MON-000-926	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TYRE INSPECTION, FIT NEW GREASE LINES TO BOOM FILL GREASE POD, GENERAL CHECKOVER CHANGE ENG OIL AIR CLEANERS PARTS USED: 4X GREASE LINES ON BOOM 1X AIR CLEANER KITS OIL FILTER	01/03/2022	Completed	Unchecked
WO-MON-000-939	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TYRE INSPECTION, FIT NEW GREASE LINES GREASE LOADER GENERAL CHECKOVER	01/14/2022	Completed	Unchecked

WO-MON-000-937	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (C service)	C SERVICE, WASH DOWN, FIX LH STEPS STRAIGHTEN OUT ISOLATION BOX, FIX 2X BROKEN GREASELINE PARTS USED: 1X FILTER KIT NEEDS NEW RH HEADLIGHT DRIVER'S DOOR STICKY FILLED AUTO LUBE FRONT TYRE MARKED NO KIT TO REPLACE TRANSMISSION OIL FILTER & O-RINGS	01/26/2022	Completed	Unchecked
WO-MON-000-968	[MON] Monty	FEL00096	Corrective Maintenance (Unscheduled)	G01436 - HEEL PLATES & GREASE LINE REPAIRS.	HEEL PLATES (NEED OXY TO FINISH). GREASE LINE REPAIRS.	02/10/2022	Completed	Unchecked
WO-MON-000-958	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TRAVEL TO MONTY CHECK TYRES AND TRAVEL BACK TO DEGRUSSA	02/15/2022	Completed	Unchecked
WO-MON-000-984	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TYRE INSPECTION DRIVE TO MONTY CONDUCT INSPECTION DRIVE BACK TO YARD	03/30/2022	Completed	Unchecked
WO-MON-000-993	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (D service)	COMPLETE 2000HR SERVICE AS LISTED ABOVE BUCKET GUMS STARTING TO WEAR HEAD GASKET STARTING TO LEAK PANEL FOR KEY BROKEN FRONT TYRES HEAVILY DAMAGED	04/20/2022	Completed	Unchecked
WO-MON-001-023	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	COMPLETE TYRE INSPECTION MANY SMALL CUTE AND CHUNKS MISSING P1, P2, P3, P4 P4 WORN LOW	05/07/2022	Completed	Unchecked
WO-MON-001-014	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	DRIVE TO MONTY & COMPLETE TYRE INSP TYRES WILL NEED ROTATING AND CHANGING	05/18/2022	Completed	Unchecked
WO-MON-001-028	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	TRAVELLED TO MONTY AND CARRIE OUT TYRE AND RIM INSPECTION WHEELS WILL BE ROTATED AND CHANGED OVER THE WEEKEND 21-23/5	05/20/2022	Completed	Unchecked
WO-MON-001-035	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	Travel to Monty Carry out tyre & rim inspection Travel back to Degruusa Carry out service	06/16/2022	Completed	Unchecked
WO-MON-001-054	[MON] Monty	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (B service)	Parts used: 500-0483 Eng oil filter x1 500-0480 Fuel filter x2 436-7077 Fuel/water separator x1 493-5371 Cabin filter x1 231-0167 Cab pressure filter x1 577-1436 Primary air filter x1 331-8111 Secondary air filter x1 Bucket cutting edges - c/o next service Bucket tips - c/o next service Replaced air filters Replaced cabin air filters	07/05/2022	Completed	Unchecked
WO-MON-001-044	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	Drive to Monty Check tyres and rims and return to Degruusa	07/06/2022	Completed	Unchecked
WO-MON-001-058	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	Tyre inspection POS1 & 2 tyres in excellent condition POS3 & 4 tyres in poor condition, heavily worn & damaged	07/11/2022	Completed	Unchecked
WO-MON-001-050	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	Tyre inspection POS1 & 2 tyres in excellent condition POS3 & 4 tyres in poor condition, heavily worn & damaged	07/11/2022	Completed	Unchecked
WO-MON-001-079	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	POS1&2 Good condition POS3 Cut up side wall splits ?POS4 Lots of chunks/treads missin, cut up badly (hard rock)	08/18/2022	Completed	Unchecked
WO-MON-001-092	[MON] Monty	FEL00096	05 - Predictive Maintenance	Pilbara Mobile: Rim & Tyre Inspection	As above POS3 Tyre wear excessive right rear	09/01/2022	Completed	Unchecked
WO-GFN-002-362	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (C service)	Service asset as per attached service sheet	02/02/2023	Completed	Unchecked
WO-GFN-002-455	Goldfields North	FEL00096	02 - Breakdown Maintenance	OIL LEAK	REPLACED DAMAGED OIL COOLER WASHED DOWN AND CLEANED RAN AND INSPECTED OK	02/04/2023	Completed	Unchecked
WO-GFN-002-379	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (B service)	Service asset as per attached service sheet OLD FORCATSE WO	02/16/2023	Completed	Unchecked
WO-MON-001-108	[MON] Monty	FEL00096	01 - Corrective Maintenance	03358 Driver defect - Trans/brake harsh and jerky while tipping	Work Orders completed as backlog cleanup	04/04/2023	Completed	Unchecked
WO-MON-001-101	[MON] Monty	FEL00096	01 - Corrective Maintenance	03855 Defect - Blocked Air Filters - Parts Ordered	Work Orders completed as backlog cleanup	04/04/2023	Completed	Unchecked
WO-MON-001-100	[MON] Monty	FEL00096	01 - Corrective Maintenance	03855 Defect - Bucket Tilt Sensor Fault - Parts Ordered	Work Orders completed as backlog cleanup	04/04/2023	Completed	Unchecked

WO-MON-001-071	[MON] Monty	FEL00096	01 - Corrective Maintenance	03201 Driver defect - LH headlight damaged & headlights n/w - Parts On Order	WO-MON-001-071/070/069= Awaiting parts, some parts ex America up to 12 weeks plus	04/04/2023	Completed	Unchecked
WO-MON-001-070	[MON] Monty	FEL00096	01 - Corrective Maintenance	03201 Driver defect - RH bottom step damaged - Parts On Order	WO-MON-001-071/070/069= Awaiting parts, some parts ex America up to 12 weeks plus	04/04/2023	Completed	Unchecked
WO-MON-001-069	[MON] Monty	FEL00096	01 - Corrective Maintenance	03201 Driver defect - LH safety ladder gone & back step missing - Parts On Order	WO-MON-001-071/070/069= Awaiting parts, some parts ex America up to 12 weeks plus	04/04/2023	Completed	Unchecked
WO-GFN-002-731	Goldfields North	FEL00096	01 - Corrective Maintenance	REPLACE TYRE / DAMAGED HAND RAIL	REPLACE R/Side RER TYRE, replaced both INSPECT R/Side HAND RAIL FOR DAMAGES	04/20/2023	Completed	Unchecked
WO-GFN-002-882	Goldfields North	FEL00096	01 - Corrective Maintenance	No Mine Radio Left tyre - Steel in tyre	replaced tire	05/05/2023	Completed	Unchecked
WO-GFN-003-163	Goldfields North	FEL00096	02 - Breakdown Maintenance	No Start	Jump started loader and check charging	05/25/2023	Completed	Unchecked
WO-GFN-003-058	Goldfields North	FEL00096	01 - Corrective Maintenance	defects	Fitted Mine Radio	06/09/2023	Completed	Unchecked
WO-GFN-003-083	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	Service asset as per attached service sheet	06/09/2023	Completed	Unchecked
WO-GFN-003-320	Goldfields North	FEL00096	01 - Corrective Maintenance	Crowding Fault	repaired wiring harness	06/29/2023	Completed	Unchecked
WO-GFN-003-605	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	completed as part of b-service	08/01/2023	Completed	Unchecked
WO-GFN-003-417	Goldfields North	FEL00096	01 - Corrective Maintenance	REPLACE LEAKING HOSES + defects	complete	08/02/2023	Completed	Unchecked
WO-GFN-003-629	Goldfields North	FEL00096	01 - Corrective Maintenance	REPAIRS	complete	08/03/2023	Completed	Unchecked
WO-GFN-003-400	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (B service)	Service asset as per attached service sheet	08/03/2023	Completed	Unchecked
WO-GFN-003-878	Goldfields North	FEL00096	01 - Corrective Maintenance	SEAT NOT INFLATING	FOUND ELECTRICAL PLUG DISCONNECTED	09/11/2023	Completed	Unchecked
WO-GFN-003-800	Goldfields North	FEL00096	00 - Preventative Maintenance	Fire Suppression Systems	inspected ok	10/03/2023	Completed	Unchecked
WO-GFN-004-117	Goldfields North	FEL00096	01 - Corrective Maintenance	Bucket repairs	Replaced GET	10/08/2023	Completed	Unchecked
WO-GFN-004-098	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (C service)	COMPLETED ON 003-889	10/08/2023	Completed	Unchecked
WO-GFN-004-018	Goldfields North	FEL00096	01 - Corrective Maintenance	SEAT REPAIR	COMPLETED	10/08/2023	Completed	Unchecked
WO-GFN-003-889	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (D service)	COMPLETED	10/08/2023	Completed	Unchecked
WO-GFN-004-144	Goldfields North	FEL00096	01 - Corrective Maintenance	BUCKET REPAIR	YAKA completed bhp	10/10/2023	Completed	Unchecked
WO-GFN-004-156	Goldfields North	FEL00096	01 - Corrective Maintenance	missing bucket tooth	Replaced missing bucket tooth	10/17/2023	Completed	Unchecked
WO-GFN-004-344	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	REF WO-GFN-004-448	11/28/2023	Completed	Unchecked
WO-GFN-004-264	Goldfields North	FEL00096	01 - Corrective Maintenance	Defects	REF WO-004-555	12/07/2023	Completed	Unchecked
WO-GFN-004-665	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	REF WO-GFN-004-666 FOR COMPLETION	12/26/2023	Completed	Unchecked
WO-GFN-004-555	Goldfields North	FEL00096	01 - Corrective Maintenance	Defects	1. MINE RADIO HAS BEEN SECURED(YAKA) 7. CONSOLE HAS BEEN SECURED IN PLACE REF WO-GFN-004-661	12/26/2023	Completed	Unchecked
WO-GFN-004-448	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (B service)	REF WO-GFN-004-666	12/26/2023	Completed	Unchecked
WO-GFN-004-740	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	INSPECTION COMPLETED BY YAKA SERVICEMAN	01/09/2024	Completed	Unchecked
WO-GFN-004-662	Goldfields North	FEL00096	01 - Corrective Maintenance	Defects	REF WO-GFN-004-752 FOR COMPLETION	01/09/2024	Completed	Unchecked
WO-GFN-004-797	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	INSPECTION COMPLETED BY YAKA SERVICEMAN	01/16/2024	Completed	Unchecked
WO-GFN-004-781	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	INSPECTION COMPLETED BY YAKA SERVICEMAN	01/16/2024	Completed	Unchecked
WO-GFN-004-666	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (B service)	SERVICE COMPLETE	01/16/2024	Completed	Unchecked
WO-GFN-004-836	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	INSPECTION COMPLETED BY YAKA SERVICEMAN	01/23/2024	Completed	Unchecked
WO-GFN-004-860	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	01/30/2024	Completed	Unchecked
WO-GFN-004-899	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	As per work order	02/01/2024	Completed	Unchecked
WO-GFN-004-752	Goldfields North	FEL00096	01 - Corrective Maintenance	Defects	As per work order	02/01/2024	Completed	Unchecked
WO-GFN-004-560	Goldfields North	FEL00096	01 - Corrective Maintenance	BUCKET TEETH WORN	New bucket ordered	02/01/2024	Completed	Unchecked
WO-GFN-004-905	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	02/05/2024	Completed	Unchecked
WO-GFN-004-955	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	02/12/2024	Completed	Unchecked
WO-GFN-005-010	Goldfields North	FEL00096	00 - Preventative Maintenance	Mirror repairs	Mirror repairs	02/13/2024	Completed	Unchecked
WO-GFN-005-002	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	02/19/2024	Completed	Unchecked
WO-GFN-005-095	Goldfields North	FEL00096	00 - Preventative Maintenance	Fire Suppression Systems Inspection	Inspections carried out on a weekly basis	02/20/2024	Completed	Unchecked
WO-GFN-005-000	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (C service)	Service asset as per attached service sheet	02/20/2024	Completed	Unchecked
WO-GFN-005-046	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	02/26/2024	Completed	Unchecked
WO-GFN-005-197	Goldfields North	FEL00096	01 - Corrective Maintenance	Replace wiper motor	Replace wiper motor	02/29/2024	Completed	Unchecked
WO-GFN-005-144	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	03/04/2024	Completed	Unchecked
WO-GFN-005-218	Goldfields North	FEL00096	01 - Corrective Maintenance	Wiper motor replace	Wiper motor replace	03/05/2024	Completed	Unchecked
WO-GFN-005-148	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	03/12/2024	Completed	Unchecked
WO-GFN-005-153	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	03/19/2024	Completed	Unchecked
WO-GFN-005-349	Goldfields North	FEL00096	01 - Corrective Maintenance	SITCCH - FEL96 CALIBRATION 23.03.24 & 24.03.24	ADAM GALE - COMPLETED CALIBRATION	03/24/2024	Completed	Unchecked
WO-GFN-005-343	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	As per work order	03/26/2024	Completed	Unchecked
WO-GFN-005-339	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	03/26/2024	Completed	Unchecked
WO-GFN-005-389	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	04/01/2024	Completed	Unchecked
WO-GFN-005-404	Goldfields North	FEL00096	01 - Corrective Maintenance	REPLACEMENT BUCKET	As per work order	04/02/2024	Completed	Unchecked
WO-GFN-005-449	Goldfields North	FEL00096	00 - Preventative Maintenance	FEL0096 Goanna bars Westrac 04/04/24	FEL0096 Goanna bars Westrac 04/04/24	04/04/2024	Completed	Unchecked
WO-GFN-005-441	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	04/08/2024	Completed	Unchecked
WO-GFN-005-483	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As Per Work Order	04/15/2024	Completed	Unchecked
WO-GFN-005-097	Goldfields North	FEL00096	00 - Preventative Maintenance	felo0096 Oil leaks	As per work order	04/21/2024	Completed	Unchecked
WO-GFN-005-515	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	04/22/2024	Completed	Unchecked
WO-GFN-005-586	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	04/29/2024	Completed	Unchecked
WO-GFN-005-638	Goldfields North	FEL00096	01 - Corrective Maintenance	Auto greaser replacement	Auto greaser replacement	05/03/2024	Completed	Unchecked
WO-GFN-005-649	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As Per work order	05/07/2024	Completed	Unchecked
WO-GFN-005-674	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	05/13/2024	Completed	Unchecked
WO-GFN-005-703	Goldfields North	FEL00096	01 - Corrective Maintenance	BEZEL & HORN	ordered	05/16/2024	Completed	Unchecked

WO-GFN-005-720	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (B service)	As per work order	05/21/2024	Completed	Unchecked
WO-GFN-005-729	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	05/21/2024	Completed	Unchecked
WO-GFN-005-794	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	05/28/2024	Completed	Unchecked
WO-GFN-005-816	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	06/04/2024	Completed	Unchecked
WO-GFN-005-866	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	06/12/2024	Completed	Unchecked
WO-GFN-005-931	Goldfields North	FEL00096	04 - Operations Support	Load rite supply	Load rite supply	06/18/2024	Completed	Unchecked
WO-GFN-005-946	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	06/18/2024	Completed	Unchecked
WO-GFN-005-978	Goldfields North	FEL00096	01 - Corrective Maintenance	Auto greaser fault	Check fuse Check power supply Reset pump Remove grease line to confirm operation Carlo Jacob	06/21/2024	Completed	Unchecked
WO-GFN-006-044	Goldfields North	FEL00096	01 - Corrective Maintenance	Remove & replace Seat airbag Seat compressor Seat tilt rod (@ front of seat cushion) Dash plastics Inspect Step (Please let Dylan know what parts are required)	As per Work order Blake - Yaka	07/10/2024	Completed	Unchecked
WO-GFN-006-025	Goldfields North	FEL00096	01 - Corrective Maintenance	Seat suspension fault	As per work order	07/11/2024	Completed	Unchecked
WO-GFN-006-216	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	07/16/2024	Completed	Unchecked
WO-GFN-006-197	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (A service)	As per work order Yaka team.	07/22/2024	Completed	Unchecked
WO-GFN-006-217	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	07/23/2024	Completed	Unchecked
WO-GFN-005-901	Goldfields North	FEL00096	01 - Corrective Maintenance	L/H mirror Brocken	Double up work order	07/23/2024	Completed	Unchecked
WO-GFN-006-552	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	08/06/2024	Completed	Unchecked
WO-GFN-006-085	Goldfields North	FEL00096	01 - Corrective Maintenance	damaged steps	Replaced rear step	08/07/2024	Completed	Unchecked
WO-GFN-005-953	Goldfields North	FEL00096	01 - Corrective Maintenance	LH rear step bent	Rear steps replaced	08/07/2024	Completed	Unchecked
WO-GFN-006-583	Goldfields North	FEL00096	00 - Preventative Maintenance	Caterpillar 980K front end loader (D service)	As per work order	08/11/2024	Completed	Unchecked
WO-GFN-006-576	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	08/13/2024	Completed	Unchecked
WO-GFN-006-540	Goldfields North	FEL00096	01 - Corrective Maintenance	Dog bone pin siezed	As per work order	08/16/2024	Completed	Unchecked
WO-GFN-006-629	Goldfields North	FEL00096	01 - Corrective Maintenance	Auto Greaser Sensor	Auto Greaser Sensor supply	08/26/2024	Completed	Unchecked
WO-GFN-006-652	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	08/27/2024	Completed	Unchecked
WO-GFN-006-706	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	09/03/2024	Completed	Unchecked
WO-GFN-005-937	Goldfields North	FEL00096	01 - Corrective Maintenance	Mirrors Broken	Refer to WO-GFN-006-679	09/04/2024	Completed	Unchecked
WO-GFN-006-733	Goldfields North	FEL00096	00 - Preventative Maintenance	Fire Suppression Systems Inspection	Not required	09/10/2024	Completed	Unchecked
WO-GFN-006-737	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	09/10/2024	Completed	Unchecked
WO-GFN-006-764	Goldfields North	FEL00096	00 - Preventative Maintenance	B SERVICE	COMPLETED	09/21/2024	Completed	Unchecked
WO-GFN-006-757	Goldfields North	FEL00096	00 - Preventative Maintenance	FEL00096 BELT-ELEMENT -LUBE	As per work order	09/21/2024	Completed	Unchecked
WO-GFN-006-763	Goldfields North	FEL00096	01 - Corrective Maintenance	BATTERY BIGFOOT CARTRIDGE PLUG 2 PIN CONNECTOR	DONE	09/24/2024	Completed	Unchecked
WO-GFN-006-774	Goldfields North	FEL00096	00 - Preventative Maintenance	Inspection - Front End Loader	As per work order	09/25/2024	Completed	Unchecked
WO-GFN-006-758	Goldfields North	FEL00096	01 - Corrective Maintenance	Alternator bracket worn	As per work order	09/25/2024	Completed	Unchecked
WO-GFN-006-679	Goldfields North	FEL00096	01 - Corrective Maintenance	Mirrors Broken	Replaced - Kyle rodgers	09/25/2024	Completed	Unchecked