

Job Card

Elecnor Australia

Job Card

13831

elecnor
australia

Asset Information

Asset No / Rego: 5EHV042 / X052XL								Down Time:
Line 1	Line 2	Line 4	Line 5	Subs 1	Subs 2	Subs 3	Camp	Repair Time: 1. HR
Hours / Kms:								Travel Time:
Last Service Kms / Hours:								Name: Dom / Nick
Next Service Kms / Hours:								Date: 27/03/24
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)								Fire Ext Date:

Fault

TRUCK HIT A GAZ KANGAROO
ASKING FOR INSPECTION

Repairs Carried Out

- 1 INSPECT THE VEHICLE
- RESULT = 1. WINDSHIELD IS BROKEN
ON LOWER LEFT NEAR THE END FRAME
2. 2 WAY RADIO ANTENNA IS
BROKEN NEED TO BE REPLACE COMPLETE
- 3 BULL BAR IS DENTED
- 4 FRONT TYRES NEED TO REPLACE
DUE TO WORN OUT

Spare Parts / Materials / Consumables Used

DOMINIC = 1. HR
NICK, B = 1. HR

Trade Hours

Elecnor Australia

Job Card

14547



Asset No / Rego: SEHV042								Down Time:
Line 1	Line 2	Line 4	Line 5	Subs 1	Subs 2	Subs 3	Camp	Repair Time: 6
Hours / Kms: 41926 km								Travel Time: -
Last Service Kms / Hours:								Name: Cory Simon
Next Service Kms / Hours: 60 000 km								Date: 19-12-25
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)								Fire Ext Date: Jan 2025

Fault

Service

UHF Broken

blown lead light globes.

WindScreen is cracked

Bull bar damaged

RHS Front door damaged

Repairs Carried Out

Replaced engine oil

Replaced engine oil filter

Replaced x3 Fuel Filters

Replaced air cleaner

Replaced cab filter

Remove + fit new complex WFE design

Hard x 4 new types fitted.

inspect all brakes

Inspect Suspension and wheel bearings

Inspect (cont) + fear diff 0.15

inspect transmission and transfer case oil

Replace RHS headlight globe.

Repaired Interior Lights

grease all grease points

General check over

inspected intake generator all OK

Eng hours = 35.04

Spare Parts / Materials / Consumables Used

Trade Hours

Copy - 19-4-25 - 36

Simon - 19-4-25 - \$15