

Search Work Orders - All History(All work types)

Assigned To	Scheduled Date	WO #	Entity Name	Problem Description	Location	Status Date	Type
Anthony Magri	5/7/2026	21068	HT29	RR Solenoid troubleshoot suspension	26-1008	5/19/2026	Non PM
Anthony Magri	4/23/2026	20918	HT29	remove solenoid	26-1008	5/6/2026	Non PM
John Kiley, Anthony Magri, Michael McCarthy	4/16/2026	20762	HT29	Move unit to east of yard. troubleshoot codes/leaks/test run	26-1008	5/6/2026	Non PM
Anthony Magri	2/26/2026	20503	HT29	Troubleshoot code.	26-1008	3/10/2026	Non PM
Jose Gallegos	12/4/2025	18984	HT29	Power washing	26-1008	2/12/2026	Non PM
		18828	HT29	n/a	26-1008	11/3/2025	Non PM
Pedro Suarez	12/13/2024	15395	HT29	Replace a headlight bulb	26-1008	3/11/2025	Non PM
				1st A60H serial # is VCE0A60HK00340050 Claystone unit # should be RHT27 (current Rango unit # 12603 stenciled in red on truck) PS 2.0 FE 2nd A60H serial # is VCE0A60HK00340062 Claystone unit # should be RHT28 (current Rango unit # 12605 stenciled in red on truck) PS 2.0 FE TW/SW 4.8 Start 3rd A60H serial # is VCE0A60HE00340105 Claystone unit # should be RHT29 (current Rango unit # 12607 stenciled in red on truck) NP 5.0 PS 1.5 FE 4th A60H serial # is VCE0A60HE00340115 Claystone unit # should be RHT30 (current Rango unit # 12612 stenciled in red on truck) NP 2.5 PS 2.0 FE 5Th A60H serial # is VCE0A60HK00340143 Claystone unit			

Noel Pavon, Pedro Suarez, Stormy Wetherington, Troy Wetherington	1/25/2024	11772	RHT VOLVO	# should be RHT31 (current Rango unit # 12614 stenciled in red on truck) NP 1.5 PS 1.0 FE TW/SW 6.8 Start 6th A60H serial # is VCE0A60HJ00350009 Claystone unit # should be RHT32 (current Rango unit # 12618 stenciled in red on truck) PS 2.0 FE TW/SW 4.8 Start NP 1.0 tire PSI 7th A60H serial # is VCE0A60HA00350029 Claystone unit # should be RHT33 (current Rango unit # 12619 stenciled in red on truck) PS 2.5 FE SW 1.0 Mirror 8th A60H serial # is VCE0A60HA00350032 Claystone unit # should be RHT34 (current Rango unit # 12622 stenciled in red on truck) PS 2.0 FE TW/SW 4.8 Start 9th A60H serial # is VCE0A60HJ00350053 Claystone unit # should be RHT35 (current Rango unit # 12629 stenciled in red on truck) PS 2.0 FE 10th A60H serial # is VCE0A60HJ00350074 Claystone unit # should be RHT36 (current Rango unit # 12632 stenciled in red on truck)		11/16/2024	Non PM
Anthony Magri, Noel Pavon	10/4/2024	14831	HT29	Troubleshoot suspension	26-1008	11/16/2024	Non PM
Anthony Magri, Noel Pavon	9/27/2024	14790	HT29	Troubleshoot reduced shift function From: Inspections Recorder: Carlos Quiroz Martinez Job: 24-1001 Reported: 7/29/2024 Form: Claystone Equipment Inspection (Espanol) Item: Transmission Note: Al meter R o D truena como un diferencial	26-1008	11/16/2024	Non PM
Anthony Magri, Noel Pavon	9/19/2024	14678	HT29	R&R Air line, R&R Repair seat switch.	26-1008	11/16/2024	Non PM
Anthony Magri, Noel Pavon, Stormy Wetherington	9/27/2024	14649	HT29	A/C evaporator R&R charge sys Recharge A/C	26-1008	11/16/2024	Non PM
Anthony Magri, Emanuel Munoz Alcala, Noel Pavon	8/30/2024	14463	HT29	Troubleshoot no start Overheating From: Inspections Recorder: Erik Rojas Loyola Job: 24-1001 Reported: 8/13/2024 Form: Claystone Equipment Inspection Item: Overheats Note:	26-1008	11/16/2024	Non PM
Anthony Magri, Emanuel Munoz Alcala, Noel Pavon	8/15/2024	14346	HT29	Top off trans fluid	26-1008	11/16/2024	Non PM

Anthony Magri, Noel Pavon	8/8/2024	14273	HT29	Troubleshoot oil leak	26-1008	11/16/2024	Non PM
Anthony Magri, Noel Pavon	8/2/2024	14221	HT29	Troubleshoot brake pressure code	26-1008	11/2/2024	Non PM
Anthony Magri, Noel Pavon	8/2/2024	14219	HT29	Change A/C From: Inspections Recorder: Carlos Quiroz Martinez Job: 24-1001 Reported: 7/26/2024 Form: Claystone Equipment Inspection (Espanol) Item: Acondiciona dor de airo Note: No funciona bien Recorder: Carlos Quiroz Martinez Job: 24-1001 Reported: 7/27/2024 Form: Claystone Equipment Inspection (Espanol) Item: Acondiciona dor de airo Note: No funciona muy bien	26-1008	9/10/2024	Non PM
		14045	HT29	Ht29 rear right front tire wheel seal leak Repaired by Chris ETI. Requested By: Francisco Moreno Requested Date: 3/12/2024 12:58:04 PM From: HCSS Field	26-1008	7/12/2024	Non PM
Noel Pavon	3/21/2024	12154	HT29	Ht29 started with regen problems now. Parked regen complete. Requested By: Francisco Moreno Requested Date: 3/11/2024 1:55:11 PM From: HCSS Field	26-1008	4/1/2024	Non PM
Noel Pavon	3/15/2024	12142	HT29	Inspect finial right front. Sample.	26-1008	4/1/2024	Non PM
Pedro Suarez	2/9/2024	11900	HT29	Sticker.	26-1008	2/26/2024	Non PM

Filter:

Wednesday, September 9, 2026