

Detroit Rebuild Specialist, LLC
1817 Meredith Park Drive
McDonough, GA 30253
770-262-9110
mccreachesex@yahoo.com
https://detroitrebuildspecialist.com



INVOICE

INVOICE # 259906
DATE 12/16/2025
DUE DATE 12/16/2025

BILL TO

Komi sogbo
Komi sogbo

JN 2485

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Labor	Drop oil pan to suction manifold. Replace suction manifold, tube orings, oil pan drain plug seals and oil pan gasket. ✓	4	185.00	740.00
Gen 5 Oil Manifold	Gen 5 Oil Suction Manifold ✓		254.19	254.19T
Pick Up Tube Orings	Oil pick up tube orings ✓		65.00	65.00T
DD13 Oil Pan Gasket	Oil pick up tube orings ✓		69.12	69.12T
Oil Pan Drain Plug Seal	DD13 Oil pan gasket ✓	2	13.89	27.78T
Valve Adjustment	Oil Pan Drain Plug Seal ✓		599.99	599.99
Labor	Adjust all valves back to factory specs ✓		185.00	185.00
Front Injector Harness	Replace injector harnesses and valve cover gasket while valve cover is off. ✓		116.04	116.04T
Rear Injector Harness	Front Injector Harness ✓		116.04	116.04T
DD13 Valve Cover Gasket	Rear Injector Harness ✓		67.84	67.84T
Labor	DD13 Valve Cover Gasket ✓	2.50	185.00	462.50
75w 90 Synthetic Gear Oil	Perform pm service. Change transmission fluid and both differential fluids. ✓	3	185.85	557.55T
15w40 Engine Oil	75W 90 Synthetic Gear Oil ✓	11	21.99	241.89T
Oil Filter	15w40 Synthetic Blend Engine Oil ✓		44.13	44.13T
2 Fuel Filter Kit	Oil Filter ✓		97.63	97.63T
Air Filter	2 Fuel Filter Kit ✓		120.90	120.90T
Cabin air filter	Air Filter ✓	1	17.76	17.76T
Grease	Cabin air filter ✓		8.99	8.99T
Labor	Lubricating Grease ✓	1.50	185.00	277.50
Injector Fuel Line Seal	Replace 3 leaking injector fuel line seals. ✓	3	12.99	38.97T
Labor	Injector Fuel Line Seal ✓	2	185.00	370.00
Power Steering Gasket	Replace leaking power steering pump gasket. Replace air dryer filter ✓		9.98	9.98T
Air Dryer Filter	Power Steering Pump Gasket ✓		110.83	110.83T
Labor	Air dryer cartridge ✓	2.50	185.00	462.50
Crank Case Breather Seal	Replace squealing accessory belt and fan belt. Check for coolant leaks. Check Egr pipes. Replace crankcase seal at block. ✓		48.19	48.19T

DISCLAIMER OF W: The seller hereby is expressing all W, either expressed or implied.

All invoices paid by credit or debit card will be subject to a 3% fee. A 3% fee on total labor will be applied to cover the cost of non-billable items used during repairs. These include but are not limited to: Starting Fluid, Brake Cleaner, Shop Towels, Silicone, Buffing Pads, Bolts, Nuts Waste Disposal, Etc

ACTIVITY

Accessory Drive Belt
Fan Belt
Labor
3/4 Union
1/2x5/8 Fitting
3/8 Union
3/8 Y Fitting
DOT Inspection
Shop Supplies
Processing Fee

DESCRIPTION

Accessory Drive Belt ✓
Fan Belt ✓
Fix 4 leaking air like fittings. Inspect potential flickering tail light. ✓
3/4 air line union ✓
1/2x5/8 90 Degree air line fitting ✓
3/8 Quick Connect Union ✓
3/8 Air line Y fitting ✓
DOT Inspection ✓
Shop Supplies ✓
Card processing fee. (This fee is charged by the CARD PROCESSING COMPANY) ✓

QTY	RATE	AMOUNT
	69.84	69.84T
	49.71	49.71T
2	185.00	370.00
	41.65	41.65T
	27.13	27.13T
	10.98	10.98T
	14.89	14.89T
	185.00	185.00
	45.00	45.00T
1	183.19	183.19

Thank you for your business.

Pay invoice

SUBTOTAL 6,107.71
TAX 181.76
TOTAL 6,289.47
BALANCE DUE

\$6,289.47

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
70824536	JN2485
DATE 12-18-25	

MOTOR CARRIER OPERATOR TOGO Freight	INSPECTOR'S NAME (PRINT OR TYPE) Casey McCran
ADDRESS 19 Millstream Ct	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE Newman, GA 30263	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 3AKJG6D19JSN2465
VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED							
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
☒			1. BRAKE SYSTEM	☒			6. SAFE LOADING
☒			a. Service Brakes	☒			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.
☒			b. Parking Brake System	☒			b. Protection against shifting cargo.
☒			c. Brake Drums or Rotors	☒			c. Container securement devices on intermodal equipment.
☒			d. Brake Hose	☒			7. STEERING MECHANISM
☒			e. Brake Tubing	☒			a. Steering Wheel Free Play
☒			f. Low Pressure Warning Device	☒			b. Steering Column
☒			g. Tractor Protection Valve	☒			c. Front Axle Beam and All Steering Components Other Than Steering Column
☒			h. Air Compressor	☒			d. Steering Gear Box
☒			i. Electric Brakes	☒			e. Pitman Arm
☒			j. Hydraulic Brakes	☒			f. Power Steering
☒			k. Vacuum Systems	☒			g. Ball and Socket Joints
☒			l. Antilock Brake System	☒			h. Tie Rods and Drag Links
☒			m. Automatic Brake Adjusters	☒			i. Nuts
☒			2. COUPLING DEVICES	☒			j. Steering System
☒			a. Fifth Wheels	☒			8. SUSPENSION
☒			b. Pintle Hooks	☒			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.
☒			c. Drawbar/Towbar Eye	☒			b. Spring Assembly
☒			d. Drawbar/Towbar Tongue	☒			c. Torque, Radius or Tracking Components
☒			e. Safety Devices	☒			9. FRAME
☒			f. Saddle-Mounts	☒			a. Frame Members
☒			3. EXHAUST SYSTEM	☒			b. Tire and Wheel Clearance
☒			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.	☒			c. Adjustable Axle Assemblies (Sliding Subframes)
☒			b. Bus exhaust system leaking or discharging in violation of standard.	☒			
☒			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	☒			
☒			4. FUEL SYSTEM	☒			
☒			a. Visible leak.	☒			
☒			b. Fuel tank filler cap missing.	☒			
☒			c. Fuel tank securely attached.	☒			
☒			5. LIGHTING DEVICES	☒			
☒			All lighting devices and reflectors required by Part 393 shall be operable.	☒			
☒				☒			10. TIRES
☒				☒			a. Tires on any steering axle of a power unit.
☒				☒			b. All other tires.
☒				☒			c. Installation of speed-restricted tires unless specifically designated by motor carrier.
☒				☒			11. WHEELS AND RIMS
☒				☒			a. Lock or Side Ring
☒				☒			b. Wheels and Rims
☒				☒			c. Fasteners
☒				☒			d. Welds
☒				☒			12. WINDSHIELD GLAZING
☒				☒			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
☒				☒			13. WINDSHIELD WIPERS
☒				☒			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
☒				☒			14. MOTORCOACH SEATS
☒				☒			Any passenger seat that is not securely fastened to the vehicle structure.
☒				☒			15. OTHER
☒				☒			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.