

Print Report



Experian AutoCheck Report

Report run: 06/10/2026 10:07:11 EDT

2015 Honda Accord EX-L / EX-L w/Navi
Sedan 4D (2.4L I4 DI Gasoline)


VIN:	1HGCR2F85FA210545
Class:	Car - Midsize
Country of Assembly:	United States
Vehicle Age:	11 year(s)
Estimated In Service:	07/23/2015
Last Reported Odometer:	85,402 (03/25/2021)

Owners - 4



Vehicle Usage
Personal

[View Vehicle Label](#)



78
65
82

AutoCheck Score

Similar vehicles usually range between 65 and 82

More Information

Vehicle History at a Glance

State
Title
Brand




Clean





No Issue




Accider
/
Damag

No
Accider
or
Damag
Reporte



No Issue






1 Open Recall(s)





No Issue






No Issue





No CPO Info Available





No Issue





Events Reported




This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)

Accident & Damage [Back To Top](#)

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Airbag Deployed



Structural Damage



Overtuned



No Damage



Info
Repa
Auto
four
reca
It is
reco
that
vehi
take
near
to h
reca
com
repl
fixe
bulle
avail
not |
oper
and
four
vehi
deta

Recall Date - 06/30/2017

Recall Type - Safety

NHTSA / OEM Recall No. - 17V-418 / KG0

Campaign Description - Safety Recall: BMS SENSOR REPAIR/REPLACE

Status: Remedy Available

[More information](#) including remedy or risk factors. Locate your nearest authorized [Honda Dealer](#) to schedule repair.

Service History [Back To Top](#)

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.



Regular Oil Changes

- **6** oil services reported
- Last oil service reported **10/31/2020**



Fluids Maintained

- **3** coolant flushes
- Last fluid maintained **08/24/2019**



Brakes Maintained

- **1** brake pad replacements
- Brake last maintained on **11/13/2020**



Tires Maintained

Information not available.



A/C & Climate Control
Information not available.



Other Services

- Cabin air filter replaced on **10/31/2020**
- Battery replaced on **12/19/2019**

OEM Recommended Services




85000 Mile Service

- Adjust parking brake (if applicable)
- Adjust Tire Pressure
- Alignment

90000 Mile Service Not Yet Due

- Adjust parking brake (if applicable)
- Adjust Tire Pressure
- Alignment



[See more](#)

Odometer Check [Back To Top](#)

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check
No issues reported



Auction Odometer Check
No issues reported



Odometer Calculation Check
No issues reported

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2015 Honda Accord EX-L / EX-L w/Navi (1HGCR2F85FA210545) **Report Run Date:** 06/10/2026 10:07:11 EDT

2015

[Owner 1](#)

Location: IL

Owned From: 07/2015

Usage: Personal

Event Date - 07/23/2015

Location - BOLINGBROOK, IL

Odometer - 35

Data Source - Motor Vehicle Dept.

Details - Title(Title #:152047019760) (Lien Reported)

Event Date - 07/23/2015

Location - BOLINGBROOK, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 02/16/2016

Location - BOLINGBROOK, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/05/2016

Location - DES PLAINES, IL

Odometer - 18,822

Data Source - Honda Authorized Dealer

Details - Vehicle Sold as Honda Certified Vehicle

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

2016

[Owner 2](#)

Location: IL

Owned From: 04/2016

Usage: Personal

Event Date - 04/25/2016

Location - ARLINGTON HEIGHTS, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/28/2016

Location - ARLINGTON HEIGHTS, IL

Odometer - 18,822

Data Source - Motor Vehicle Dept.

Details - Title(Title #:161196907100) (Lien Reported)

Event Date - 05/01/2017

Location - ARLINGTON HEIGHTS, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 06/30/2017

Location -

Data Source - Manufacturer

Details - Manufacturer Recall

NHTSA Recall 17V-418 / Mfr. Recall KGO

Safety Recall: BMS SENSOR REPAIR/REPLACE

LOCATE YOUR NEAREST AUTHORIZED

[HONDA DEALER](#) TO SCHEDULE REPAIR.

Status: Remedy Available

Event Date - 10/04/2017

Location - ELMHURST, IL

Odometer - 42,718

Data Source - Honda Authorized Dealer

Details - Vehicle Listed for Sale as Honda Certified Vehicle(COLOR REPORTED AS WHITE)

Event Date - 10/04/2017

Location - ELMHURST, IL

Data Source - Honda Authorized Dealer

Details - Vehicle Listed for Sale as Honda Certified Vehicle(COLOR REPORTED AS WHITE)

Event Date - 11/28/2017

Location - ELMHURST, IL

Odometer - 42,739

Data Source - Honda Authorized Dealer

Details - Vehicle Sold as Honda Certified Vehicle

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

Location: IL

Owned From: 12/2017

Usage: Personal

Event Date - 12/12/2017

Location - SOMONAUK, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 12/14/2017

Location - SOMONAUK, IL

Odometer - 42,739

Data Source - Motor Vehicle Dept.

Details - Title(Title #:173486915510) (Lien Reported)

Event Date - 12/14/2018

Location - SOMONAUK, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 12/20/2018

Location - OTTAWA, IL

Odometer - 58,785

Data Source - Service Record

Details - Engine Serviced
Recommended Maintenance Performed

Event Date - 12/20/2018

Location - OTTAWA, IL

Data Source - Service Record

Details - Transmission Serviced

Event Date - 12/20/2018

Location - OTTAWA, IL

Data Source - Service Record

Details - Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Vehicle Fluids Serviced

Event Date - 01/08/2019

Location - IL

Data Source - Service Record

Details - Recommended Maintenance Performed

Event Date - 04/20/2019

Location - IL

Odometer - 64,015

Data Source - Service Record

Details - Fuel System Serviced
Emission System Serviced

Event Date - 04/20/2019

Location - OTTAWA, IL

Data Source - Service Record

Details - Engine Serviced
Recommended Maintenance Performed
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Vehicle Fluids Serviced

Event Date - 08/24/2019

Location - OTTAWA, IL

Odometer - 69,459

Data Source - Service Record

Details - Engine Serviced
Recommended Maintenance Performed
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Vehicle Fluids Serviced

Event Date - 12/18/2019

Location - SOMONAUK, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 12/19/2019

Location - IL

Odometer - 73,687

Data Source - Service Record

Details - Vehicle Inspected

Event Date - 12/19/2019

Location - OTTAWA, IL

Data Source - Service Record

Details - Battery Serviced or Replaced
Multiple Point Vehicle Inspection
Engine Serviced

Event Date - 12/19/2019

Location - IL

Data Source - Service Record

Details - Recommended Maintenance Performed

Event Date - 12/19/2019

Location - OTTAWA, IL

Data Source - Service Record

Details - Electrical System Serviced

Event Date - 12/19/2019

Location - IL

Data Source - Service Record

Details - Promotional Service Performed

Event Date - 01/25/2020

Location - OTTAWA, IL

Odometer - 75,117

Data Source - Service Record

Details - Multiple Point Vehicle Inspection

Engine Serviced

Lube, Oil And/Or Filter Changed

Event Date - 03/31/2020

Location - OTTAWA, IL

Odometer - 76,499

Data Source - Service Record

Details - Multiple Point Vehicle Inspection

Engine Serviced

Electrical System Serviced

Event Date - 04/03/2020

Location - IL

Data Source - Service Record

Details - Vehicle Inspected

Engine Serviced

Recommended Maintenance Performed

Promotional Service Performed

Event Date - 04/07/2020

Location - OTTAWA, IL

Odometer - 76,577

Data Source - Service Record

Details - Multiple Point Vehicle Inspection

Electrical System Serviced

Event Date - 04/10/2020

Location - IL

Data Source - Service Record

Details - Vehicle Inspected

Recommended Maintenance Performed

Electrical System Serviced

Promotional Service Performed

Event Date - 06/15/2020

Location - IL

Odometer - 80,050

Data Source - Service Record

Details - Vehicle Inspected

Event Date - 06/15/2020

Location - OTTAWA, IL

Data Source - Service Record

Details - Multiple Point Vehicle Inspection
Engine Serviced

Event Date - 06/15/2020

Location - IL

Data Source - Service Record

Details - Recommended Maintenance Performed

Event Date - 06/15/2020

Location - OTTAWA, IL

Data Source - Service Record

Details - Lube, Oil And/Or Filter Changed

Event Date - 06/15/2020

Location - IL

Data Source - Service Record

Details - Promotional Service Performed

Event Date - 10/31/2020

Location - OTTAWA, IL

Odometer - 85,023

Data Source - Service Record

Details - Air Filter Changed
Multiple Point Vehicle Inspection
Engine Serviced
Lube, Oil And/Or Filter Changed

Event Date - 11/09/2020

Location - OTTAWA, IL

Odometer - 85,403

Data Source - Service Record

Details - Multiple Point Vehicle Inspection
Engine Serviced
Transmission Serviced
Brakes Serviced
Starting or Charging System Service Performed
Tires or Wheels Service Performed

Event Date - 11/13/2020

Location - IL

Data Source - Service Record

Details - Vehicle Inspected

Vehicle Recall Service Performed

Engine Serviced

Recommended Maintenance Performed

Transmission Serviced

Brakes Serviced

Electrical System Serviced

Tires or Wheels Service Performed

Promotional Service Performed

Event Date - 03/03/2021

Location - PERU, IL

Data Source - Dealer Record

Details - Vehicle in Dealer Inventory

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

2021

[Owner 4](#)

Location: IL

Owned From: 03/2021

Usage: Personal

Event Date - 03/15/2021

Location - SENECA, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 03/25/2021

Location - SENECA, IL

Odometer - 85,402 †

Data Source - Motor Vehicle Dept.

Details - Title(Title #:210847000060) (Lien Reported)

Event Date - 12/13/2022

Location - COTTAGE HILLS, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/07/2025

Location - STREATOR, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/17/2026

Location - STREATOR, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.



Warranty Check [Back To Top](#)

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Enter Mileage:

miles

Show My Coverage

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic 	-	-		36 months / 36000 miles
Battery 	-	-	-	Contact a certified dealer to verify coverage

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Corrosion ⓘ	-	-	✘	60 months / Unlimited miles
Powertrain ⓘ	-	-	✘	60 months / 60000 miles
Roadside Assistance ⓘ	-	-	✘	36 months / 36000 miles
Safety Restraint ⓘ	-	50 months	✘	180 months / 150000 miles Honda will repair or replace, at its option, any Honda seat belt component that fails to function properly during normal use. This includes all parts and labor charges.

This Vehicle's Glossary [Back To Top](#)

More information is available in the full [AutoCheck glossary](#).

Term - State Title Brand

Section Location - Vehicle History at a Glance

Definition - A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

Term - Auction Issue

Section Location - Vehicle History at a Glance

Definition - This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Term - Accident/Damage Check

Section Location - Vehicle History at a Glance

Definition - This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Term - Insurance Loss/Title Transfer

Section Location - Vehicle History at a Glance

Definition - This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Term - Additional History

Section Location - Vehicle History at a Glance

Definition - This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Term - Odometer Check

Section Location - Vehicle History at a Glance

Definition - This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Term - Open Recall Check

Section Location - Vehicle History at a Glance

Definition - This section lists any open safety or emission recalls on the vehicle that may need to be fulfilled.

Term - Loan/Lien

Section Location - Additional History

Definition - A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Term - Personal Use

Section Location - Owner Type

Definition - This vehicle was driven for personal use.

Term - Open Recall

Section Location - Open Recall Check

Definition - A recall is considered 'open' for a vehicle when it has not received the required service to correct the identified recall. The vehicle will need to be taken to a repair center that has been authorized by the manufacturer to correct any open recall conditions.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1HGCR2F85FA210545) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbptterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.