

# Experian AutoCheck Report

Report run: 06/04/2026 11:55:25 EDT

## 2017 Mack Granite


Chassis 2D (12.7L I6 DI Diesel)

VIN:	1M2AX07CXHM035869
Class:	Medium/Heavy Truck
Country of Assembly:	United States
Estimated In Service:	12/29/2016
Last Reported Odometer:	165,565 (08/08/2023)

Owners - 3



Vehicle Usage  
Lease, Livery



## AutoCheck Score

AutoCheck Score Not Available

### Vehicle History at a Glance

<p><b>State Title Brand</b></p> <p>CLEAN</p>	<p><b>Auction Brand / Issues</b></p> <p>NO ISSUE</p>	<p><b>Accident / Damage</b></p> <p>No Accidents or Damage Reported</p> <p>NO ISSUE</p>
<p><b>Open Recall Check</b></p> <p>Recall Information not received from manufacturer</p> <p>NOT AVAILABLE</p>	<p><b>Insurance Loss / Transfer</b></p> <p>NO ISSUE</p>	<p><b>Odometer Check</b></p> <p>Last reported odometer: 165,565 (08/08/2023)</p> <p>NO ISSUE</p>
<p><b>Certified Pre-Owned</b></p> <p>NO CPO INFO AVAILABLE</p>	<p><b>Service / Repair</b></p> <p>3 Service Record(s) Reported</p> <p>NO ISSUE</p>	<p><b>Additional History</b></p> <p>Lien Reported, Corrected Title</p> <p>EVENTS REPORTED</p>



**This vehicle is not eligible for Buyback Protection**

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)

### Accident & Damage



**Your Vehicle Checks Out** There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Airbag Deployed



Structural Damage



Overturned



No Damage

## Service History

### Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.



#### Regular Oil Changes

Information not available.



#### Fluids Maintained

Information not available.



#### Brakes Maintained

Information not available.



#### Tires Maintained

Information not available.



#### A/C & Climate Control

- 1 A/C services reported
- A/C system last serviced 08/08/2023



#### Other Services

Information not available.

### OEM Recommended Services

Please contact your local dealer or visit the OEM's website for details.

## Odometer Check



### Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



#### State Title Odometer Check

No issues reported



#### Auction Odometer Check

No issues reported



#### Odometer Calculation Check

No issues reported

## Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.  
Vehicle: 2017 Mack Granite (1M2AX07CXHM035869) Report Run Date: 06/04/2026 11:55:25 EDT

2016

### Owner 1

Location: MS

Owned From: 12/2016

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
12/29/2016	SOUTHAVEN, MS		Motor Vehicle Dept.	Title(Title #:H925733-01) (Lien Reported)
12/29/2016	SOUTHAVEN, MS		Motor Vehicle Dept.	Registration Event/Renewal
12/29/2016	SOUTHAVEN, MS		Motor Vehicle Dept.	Excluded/Exempt
12/29/2016	SOUTHAVEN, MS		Motor Vehicle Dept.	Pro-Rated Registration

2018

### Owner 2

<span>Location: PA</span> <span>Owned From: 04/2018</span> <span>Usage: Livery</span>				
Event Date	Location	Odometer	Data Source	Details
04/23/2018	EXPORT, PA	64,017	Motor Vehicle Dept.	Title(Title #:78858878) (Lien Reported)
04/25/2018	EXPORT, PA		Motor Vehicle Dept.	Registration Event/Renewal
04/25/2018	MS		Motor Vehicle Dept.	Excluded/Exempt
02/11/2019	EXPORT, PA		Motor Vehicle Dept.	Registration Event/Renewal
02/10/2020	EXPORT, PA		Motor Vehicle Dept.	Registration Event/Renewal
03/13/2020	PA	125,442	Service Record	Vehicle Inspected Electrical System Serviced Lights or Signals Serviced
03/23/2020	PA		Service Record	Vehicle Inspected Exhaust System Serviced Electrical System Serviced
03/02/2021	EXPORT, PA		Motor Vehicle Dept.	Registration Event/Renewal
01/25/2022	EXPORT, PA		Motor Vehicle Dept.	Registration Event/Renewal
01/24/2023	EXPORT, PA		Motor Vehicle Dept.	Registration Event/Renewal
08/08/2023	PA	165,565	Service Record	Cooling System Serviced Heat or Air Conditioning Serviced Emission System Serviced Exhaust System Serviced Transmission Replaced
08/16/2023	CLEVELAND, OH		Motor Vehicle Dept.	Title(Title #:4304732600) Excluded/Exempt
10/10/2023	CINCINNATI, OH		Motor Vehicle Dept.	Title(Title #:4304766603) Livery Use Excluded/Exempt

2023

### Owner 3

<span>Location: OH</span> <span>Owned From: 11/2023</span> <span>Usage: Lease, Livery</span>				
Event Date	Location	Odometer	Data Source	Details
11/28/2023	CINCINNATI, OH		Motor Vehicle Dept.	Title(Title #:0906438319) Duplicate Title
11/28/2023	CINCINNATI, OH		Motor Vehicle Dept.	Registration Event/Renewal
11/28/2023	CINCINNATI, OH		Motor Vehicle Dept.	Livery Use Excluded/Exempt
02/02/2024	CINCINNATI, OH		Motor Vehicle Dept.	Title(Title #:6702954935) (Lien Reported) Corrected Title(Lien Reported) Livery Use Excluded/Exempt
02/28/2024	CINCINNATI, OH		Motor Vehicle Dept.	Registration Event/Renewal
12/03/2024	CINCINNATI, OH		Motor Vehicle Dept.	Registration Event/Renewal

Event Date	Location	Odometer	Data Source	Details
03/10/2025	CINCINNATI, OH		Motor Vehicle Dept.	Registration Event/Renewal
09/12/2025	CINCINNATI, OH		Motor Vehicle Dept.	Registration Event/Renewal
01/05/2026	CINCINNATI, OH		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)

**AutoCheck Terms and Conditions**

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at [www.autocheck.com/terms](http://www.autocheck.com/terms) or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

**Buyback Protection Terms and Conditions**

This vehicle (1M2AX07CXHM035869) does not qualify for AutoCheck Buyback Protection.

**About AutoCheck**

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

**Patent Notice**

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.