



Vehicle Standards and Inspection

## Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A341641

Station #: 70041

Station Name: Karst Holdings Inc

Technician #: 81055

Technician Name: Don Rivard

Signing Officer #: 91698

Signing Officer Name: Scott Fender

### Customer Details:

Name: [REDACTED]

Address: [REDACTED]

Inspection Completed Date: 25May2026

Inspection Expiry Date: 30Nov2026

### Vehicle Details:

VIN: 4V4NC9KK5CN542822

Odometer Reading: 592239 km

Year: 2012

Vehicle Make/Model: VOLVO/HEAVY VEHICLE

Plate: 532 JZE

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

### Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70041

Station Name: Karst Holdings Inc

Technician #: 81055

Technician Name: Don Rivard

Signing Officer #: 91698

Signing Officer Name: Scott Fender

Customer Details:

Name: [REDACTED]

Address: [REDACTED]

Vehicle Details:

VIN: 4V4NC9KK5CN542822

Odometer Reading: 592239 km

Year: 2012

Vehicle Make/Model: VOLVO HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
		x		Attached Equipment (8)	REPAIR RH SIDE LOCKS FOR SIDE FAIRING
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
------	----------	-----------	----------	---------	----------

x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	REPLACE RH BRAKES AND WHEEL SEAL ON REAR DRIVE AXLE, REPLACE GLADHAND SEALS, REPLACE LH BRAKE POT ON REAR DRIVE AXLE, REPLACE BOTH STEER AXLE BRAKE POTS, REPLACE BOTH SLACK ADJUSTERS ON REAR DRIVE AXLE, REPAIR AIR LEAK UPON BRAKE APPLICATION
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
		x		Tires/Wheels (9)	REPAIR RH INNER TIRE ON REAR DRIVE AXLE
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

**Axle 1-Pass**

Wheel1-On : Tire Tread Depth: 13/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .745 in • Cam Rotation: 42.0 degrees • Brake Stroke: 1 1/2 in

Wheel2-On : Tire Tread Depth: 13/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .750 in • Cam Rotation: 40.0 degrees • Brake Stroke: 1 1/2 in

**Axle 2-Pass**

Wheel1 : Tire Tread Depth: 15/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 15/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .750 in • Cam Rotation: 40.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 15/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .750 in • Cam Rotation: 40.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 15/32 in

Brake(1): No Brake

N/A

**Axle 3-Pass**

Wheel1 : Tire Tread Depth: 15/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 15/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .750 in • Cam Rotation: 40.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 15/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .750 in • Cam Rotation: 40.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 13/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A341641

Inspection Completed Date: 25May2026