

**A209952**

Station #: 71095  
Technician #: 83671  
Signing Officer #: 87242

Station Name: Prairie Diesel Inc.  
Technician Name: Joseph J. Dosch  
Signing Officer Name: Amanda Dosch

**Customer Details:**

Name: [REDACTED]

Address: [REDACTED]

Inspection Completed Date: 14Jan2026

Inspection Expiry Date: 31Jan2027

**Vehicle Details:**

VIN: 4L5AB5333MF055105

Hubometer Reading:

Year: 2021

Vehicle Make/Model: BEHNKE/TRAILER

Plate:

Jurisdiction:

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

## Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71095

Station Name: Prairie Diesel Inc.

Technician #: 83671

Technician Name: Joseph J. Dosch

Signing Officer #: 87242

Signing Officer Name: Amanda Dosch

### Customer Details:

Name: [REDACTED]

Address: [REDACTED]

### Vehicle Details:

VIN: 4L5AB5333MF055105

Hubometer Reading:

Year: 2021

Vehicle Make/Model: BEHNKE TRAILER

### Inspection Details:

| Pass | Rejected | Corrected | Req Attn | DRIVERS COMPARTMENT          | Comments |
|------|----------|-----------|----------|------------------------------|----------|
| x    |          |           |          | Vehicle Identification (5)   |          |
| x    |          |           |          | Fire Extinguisher (5)        |          |
| x    |          |           |          | Auxiliary Controls/Equip (5) |          |

| Pass | Rejected | Corrected | Req Attn | BODY EXTERIOR                 | Comments |
|------|----------|-----------|----------|-------------------------------|----------|
| x    |          |           |          | Lamps (6)                     |          |
| x    |          |           |          | Reflex Reflectors (6)         |          |
| x    |          |           |          | Retro Reflective Markings (6) |          |
| x    |          |           |          | Trailer Hitch (10)            |          |
| x    |          |           |          | Attached Equipment (8)        |          |
| x    |          |           |          | Cargo Bodies/Vessels (8)      |          |
| x    |          |           |          | Mud Flaps/Fenders (8)         |          |
| x    |          |           |          | Landing Gear (8)              |          |
| x    |          |           |          | Rear Impact Guard (8)         |          |
| x    |          |           |          | Trailer Power Cord (7)        |          |

| Pass | Rejected | Corrected | Req Attn | ENGINE COMPARTMENT           | Comments |
|------|----------|-----------|----------|------------------------------|----------|
| x    |          |           |          | Fuel System (1)              |          |
| x    |          |           |          | Battery/Wiring Condition (7) |          |

| Pass | Rejected | Corrected | Req Attn | CHASSIS                                 | Comments |
|------|----------|-----------|----------|---|----------|
| x    |          |           |          | Hyd Brake System/Components (3.1)       |          |
| x    |          |           |          | Air Brake System/Components (3.2)       |          |
| x    |          |           |          | Elec Brake System/Components (3.1)      |          |
| x    |          |           |          | Wheel Bearings (9)                      |          |
| x    |          |           |          | Tires/Wheels (9)                        |          |
| x    |          |           |          | Self-Steering Axle (2&4)                |          |
| x    |          |           |          | Frame/Crossmembers/Mounts (8)           |          |
| x    |          |           |          | Suspension/Axles (2)                    |          |
| x    |          |           |          | Exhaust/Emission System (1)             |          |
| x    |          |           |          | Sliding Axle Assembly (if equipped) (8) |          |

#### Brake/Tire Measurements

##### Axle 1-Pass

Wheel1-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 21 mm • Cam Rotation: 35 degrees • Brake Stroke: 1.25 in

Wheel2-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 21 mm • Cam Rotation: 35 degrees • Brake Stroke: 1.25 in

Wheel3-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 21 mm • Cam Rotation: 35 degrees • Brake Stroke: 1.25 in

Wheel4-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 21 mm • Cam Rotation: 35 degrees • Brake Stroke: 1.25 in

##### Axle 2-Pass

Wheel1-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 21 mm • Cam Rotation: 35 degrees • Brake Stroke: 1.25 in

Wheel2-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 21 mm • Cam Rotation: 35 degrees • Brake Stroke: 1.25 in

Wheel3-On : Tire Tread Depth: 17 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 21 mm • Cam Rotation: 36 degrees • Brake Stroke: 1.25 in

Wheel4-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 21 mm • Cam Rotation: 36 degrees • Brake Stroke: 1.25 in

##### Axle 3-Pass

Wheel1-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 21 mm • Cam Rotation: 32 degrees • Brake Stroke: 1.25 in

Wheel2-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 21 mm • Cam Rotation: 32 degrees • Brake Stroke: 1.25 in

Wheel3-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 21 mm • Cam Rotation: 33 degrees • Brake Stroke: 1.25 in

14-On : Ti  
ke(1): S-CAM  
Min Brake Lin  
PASS

1.0 in : Tire Tread Depth: 15 mm  
1.0 in : S-CAM Brake  
1.0 in : Brake Lining/Pad: 21 mm • Cam Rotation: 33 degrees • Brake Stroke: 1.25 in

PASS - vehicle passes inspection

Decal # A209952

Inspection Completed Date: 14Jan2026