



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EDGE ENVIROMENTAL/GRINDSTONE GRAIN
COMBINE #1

Invoice To: EDGE ENVIRONMENTAL FARM/GRINDSTONE GRAIN CORP
BOX 356
UNITY SK S0K 4L0

Branch N. BATTLEFORD		
Date 10/29/25	Time 09:25:27 (O)	Page 01
Account No EDGE001	Phone No	Inv No W03380
Ship Via		Purchase Order
Tax ID No		887067502
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
001046 LEXION 8700 8700	339 252	C8910940		
SEGMENT# 1 S 130 NA 10/14/25 10/14/25				
POST HARVEST INSPECTION				
CORRECTION:				
130- oct 15				
perform the inspection on pilot and take oil sample				
ADDITIONAL DESCRIPTION:				
PERFORM CLAAS ONLINE INSPECTION PILOT INCLUDING OIL SAMPLES				
320271103	SOS	2	42.80	85.60
SOS KIT (50 PK)				
			PARTS	85.60
			LABOR	1813.40
10110000			SEGMENT TOTAL==>	1899.00

SEGMENT# 2 S 190 NA 10/16/25 10/16/25

#1 ANNUAL SERVICE

CORRECTION:

PERFORMED ANNUAL SERVICE

- CHANGED ENGINE OIL AND FILTER
- CHANGED FUEL FILTERS
- CHANGED DEF FLUID FILTER
- CHANGED AIR FILTER
- TOPPED UP LOW COOLANT
- TOPPED UP LOW HYDRAULIC OIL
- CLEANED ROTOR GEARBOX BREATHERS
- TOPPED UP RADIAL SPREADER GEARBOX OILS AND CLEANED OUT HOUSING
- INSTALLED 6 TUBES OF GREASE INTO AUTO GREASER AND GREASED ALL MANUAL GREASE POINTS
- REMOVED RH SIDE SHIELD. INSPECTED WHY REAR CHOPPER DOOR IS

CONTINUED ON PAGE 02

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EDGE ENVIROMENTAL/GRINDSTONE GRAIN
COMBINE #1

Invoice To: EDGE ENVIRONMENTAL FARM/GRINDSTONE GRAIN CORP
BOX 356
UNITY SK S0K 4L0

Branch N. BATTLEFORD		
Date 10/29/25	Time 09:25:27 (O)	Page 02
Account No EDGE001	Phone No	Inv No W03380
Ship Via		Purchase Order
Tax ID No		887067502
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
001046	LEXION 8700	339 C8910940		
	8700	252		

NOT SEALING CORRECTLY ON THE BOTTOM FLAP (PRESENT CODE).
CHECKED SENSORS, CONNECTORS AND POWER. CHECKED DOOR.
DIAGNOSED THE REAR CHOPPER DOOR IS INSTALLED INCORRECTLY,
OVER STRAW BLOCKAGE WARNING SENSOR PLATE. REMOVED DOOR AND
INSTALLED IN CORRECTLY POSITION. TEACHED END STOPS OF
DISTRIBUTION SYSTEM. FOUND DAMAGED PLASTIC STOP PAWL ON RH
SIDE. REMOVED, FLIPPED AROUND AND INSTALLED IT. INSTALLED
SHIELD.

-FILLED OUT SERVICE BOOKLET UNDER SEAT

ADDITIONAL DESCRIPTION:

PERFORM ANNUAL SERVICE

-CHANGE ENGINE OIL AND FILTER

-CHANGE FUEL FILTERS

-CHANGE DEF FLUID FILTER

-CHANGE AIR FILTER

-TOP UP LOW COOLANT

-TOP UP LOW HYDRAULIC OIL

-CLEAN ROTOR GEARBOX BREATHERS

-TOP UP RADIAL SPREADER GEARBOX OILS AND CLEAN OUT HOUSING

-INSTALL 6 TUBES OF GREASE INTO AUTO GREASER AND LUBE ALL
MANUAL GREASE POINTS

FILL OUT SERVICE BOOKLET UNDER SEAT*

ENV1	ENVIRO FEE OIL	42	.20	8.40
FILO8	ENVFEE	1	2.00	2.00
1461020	COOLANT	1	51.05	51.05
1462031L	10W40 AGRI SYN	40	16.16	646.40
1474460L	HY OIL LIT	2	7.75	15.50
	HYDRAULIC OIL BY LITRE			
19863920	OIL FILTER	1	146.41	146.41
	OIL FILTER CARTRIDGE			

CONTINUED ON PAGE 03

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EDGE ENVIROMENTAL/GRINDSTONE GRAIN
COMBINE #1

Invoice To: EDGE ENVIRONMENTAL FARM/GRINDSTONE GRAIN CORP
BOX 356
UNITY SK S0K 4L0

Branch N. BATTLEFORD		
Date 10/29/25	Time 09:25:27 (O)	Page 03
Account No EDGE001	Phone No	Inv No W03380
Ship Via		Purchase Order
Tax ID No		887067502
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
001046	LEXION 8700	339	C8910940		
	8700	252			
19886630	FUEL FILTER	1		312.07	312.07
19896710	FILTER	1		313.53	313.53
2417931	AGRIGREASE	7		8.84	61.88
	AGRIGREASE EP 3				
26476960	AIR CLEANER	1		549.05	549.05
	AIR CLEANER ELEMENT				
27673620	FILTER ELE	1		143.67	143.67
	FILTER ELEMENT				
				PARTS	2249.96
				LABOR	1074.00
10110000				SEGMENT TOTAL==>	3323.96

SEGMENT# 3 S 190 NA 10/16/25 10/28/25

#2 HORIZONTAL COOLING PACK

CORRECTION:

WASHED OUT DIRTY HORIZONTAL COOLING PACK. CLEANED SPILLED
WATER.

ADDITIONAL DESCRIPTION:

WASH OUT DIRTY HORIZONTAL COOLING PACK

	LABOR	179.00
10110000	SEGMENT TOTAL==>	179.00

SEGMENT# 4 S 190 NA 10/16/25 10/28/25

#10 THRESHING VARIABLE SPEED PULLEYS

CORRECTION:

CLEANED ALL DEBRIS FROM V/S THRESHING PULLEYS

ADDITIONAL DESCRIPTION:

CLEAN ALL DEBRIS FROM V/S THRESHING PULLEYS

	LABOR	268.50
10110000	SEGMENT TOTAL==>	268.50

CONTINUED ON PAGE 04

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EDGE ENVIROMENTAL/GRINDSTONE GRAIN
COMBINE #1

Invoice To: EDGE ENVIRONMENTAL FARM/GRINDSTONE GRAIN CORP
BOX 356
UNITY SK S0K 4L0

Branch N. BATTLEFORD		
Date 10/29/25	Time 09:25:27 (O)	Page 04
Account No EDGE001	Phone No	Inv No W03380
Ship Via		Purchase Order
Tax ID No		887067502
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
001046	LEXION 8700	339	C8910940		
	8700	252			

SEGMENT# 5 S 190 NA 10/16/25 10/28/25

#12 ROTOR VARIABLE SPEED PULLEYS

CORRECTION:

CHANGED SPEEDS, STOPPED AND CLEANED ALL DEBRIS FROM ROTOR
V/S PULLEYS AT DIFFERENT PULLEYS POSITIONS.

ADDITIONAL DESCRIPTION:

CLEAN ALL DEBRIS FROM ROTOR V/S PULLEYS

	LABOR	268.50
10110000	SEGMENT TOTAL==>	268.50

SEGMENT# 6 S 190 NA 10/16/25 10/21/25

#13 UNLOAD AUGER CHAINS

CORRECTION:

LUBRICATED UNLOAD AUGER CHAINS AND RETURN ELEVATOR HEAD
DRIVE CHAIN.

ADDITIONAL DESCRIPTION:

LUBE UNLOAD AUGER CHAINS

	LABOR	53.70
10110000	SEGMENT TOTAL==>	53.70

SEGMENT# 7 S 190 NA 10/16/25 10/16/25

#16 CAB FILTERS

CORRECTION:

CLEANED OUT FILTER HOUSING AND REPLACED DIRTY CAB FILTERS

ADDITIONAL DESCRIPTION:

REPLACE DIRTY CAB FILTERS

27172332	FILTER ELEMENT	1	67.72	67.72
27172350	FILTER	1	146.94	146.94
27412911	POCKET FILTER	2	89.49	178.98

CONTINUED ON PAGE 05

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EDGE ENVIROMENTAL/GRINDSTONE GRAIN
COMBINE #1

Invoice To: EDGE ENVIRONMENTAL FARM/GRINDSTONE GRAIN CORP
BOX 356
UNITY SK S0K 4L0

Branch N. BATTLEFORD		
Date 10/29/25	Time 09:25:27 (O)	Page 05
Account No EDGE001	Phone No	Inv No W03380
Ship Via		Purchase Order
Tax ID No		887067502
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
001046	LEXION 8700	339	C8910940			
	8700	252				
				PARTS		393.64
				LABOR		134.25
10110000				SEGMENT TOTAL==>		527.89

SEGMENT# 8 S 190	NA	10/16/25	10/16/25		
#17 FEEDERCHAIN					
<u>CORRECTION:</u>					
REMOVED FRONT AND SIDE SHIELDS. REMOVED CENTER CONVEYOR					
BAR, CUT OFF LINKS AND INSTALLED 1/2 LINKS. INSTALLED					
CENTER BAR, TIGHTENED FEEDER CHAIN AND INSTALLED SHIELDS.					
<u>ADDITIONAL DESCRIPTION:</u>					
INSTALL 1/2 LINKS IN FEEDERCHAIN, ALMOST OUT OF ADJUSTMENT					
0030530	LOCK WIRE	2	1.61		3.22
6804931	CONNECTING	2	18.78		37.56
	CONNECTING LINK				
6805841	CHAIN LOCK	4	19.87		79.48
	CHAIN LOCK BEND.				
				PARTS	120.26
				LABOR	393.80
10110000				SEGMENT TOTAL==>	514.06

SEGMENT# 9 S 190	NA	10/16/25	10/21/25		
#18 FEEDERHOUSE SPEED TONE WHEEL					
<u>CORRECTION:</u>					
190-REPOSITION TONE WHEEL TO RUN IN THE CENTER OF THE					
SENSOR, TEST OPERATION...OK					
<u>ADDITIONAL DESCRIPTION:</u>					
REPOSITION TONE WHEEL					
				LABOR	35.80
10110000				SEGMENT TOTAL==>	35.80

CONTINUED ON PAGE 06

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EDGE ENVIROMENTAL/GRINDSTONE GRAIN
COMBINE #1

Invoice To: EDGE ENVIRONMENTAL FARM/GRINDSTONE GRAIN CORP
BOX 356
UNITY SK S0K 4L0

Branch N. BATTLEFORD		
Date 10/29/25	Time 09:25:27 (O)	Page 06
Account No EDGE001	Phone No	Inv No W03380
Ship Via		Purchase Order
Tax ID No		887067502
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
001046	LEXION 8700	339	C8910940		
	8700	252			

SEGMENT#10 S 190 NA 10/16/25 10/16/25

#20 APS DRUM

CORRECTION:

REMOVED APS DRUM DOOR, DISCONNECTED BATTERIES, BROUGHT
WELDING MACHINE AND INSPECTED APS DRUM MOUNTS. CUT OFF 1
BENT APS MOUNT, SANDED APS DRUM, INSTALLED CUP ON NEW MOUNT
AND WELDED TO DRUM. STRAIGHTENED 1 BENT MOUNT.
INSTALLED DOOR, RETURNED WELDING MACHINE AND CONNECTED
BATTERIES.

ADDITIONAL DESCRIPTION:

REPLACE 1 BENT APS MOUNT

6176310	PADDLE	1	22.98	22.98
			PARTS	22.98
			LABOR	179.00
10110000			SEGMENT TOTAL==>	201.98

SEGMENT#11 S 190 NA 10/16/25 10/27/25

#20A CONCAVE

CORRECTION:

PERFORMED CONCAVE CLEARANCE ADJUSTMENT. ADJUSTED CONCAVE
POSITION SENSOR.

ADDITIONAL DESCRIPTION:

LEVEL AND ADJUST CONCAVE

10110000			LABOR	358.00
			SEGMENT TOTAL==>	358.00

SEGMENT#12 S 190 NA 10/16/25 10/22/25

#21 YEILD SENSOR

CORRECTION:

CONTINUED ON PAGE 07

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EDGE ENVIROMENTAL/GRINDSTONE GRAIN
COMBINE #1

Invoice To: EDGE ENVIRONMENTAL FARM/GRINDSTONE GRAIN CORP
BOX 356
UNITY SK SOK 4L0

Branch N. BATTLEFORD		
Date 10/29/25	Time 09:25:27 (O)	Page 07
Account No EDGE001	Phone No	Inv No W03380
Ship Via		Purchase Order
Tax ID No		887067502
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
001046	LEXION 8700	339	C8910940		
	8700	252			

190-CLEAN DIRTY YEILD SENSOR

ADDITIONAL DESCRIPTION:

CLEAN DIRTY/GUMMED UP YEILD SENSOR

10110000

LABOR	89.50
SEGMENT TOTAL==>	89.50

SEGMENT#13 S 190 NA 10/16/25 10/24/25

#25 STATIONARY KNIVES

CORRECTION:

CLEANED ALL DEBRIS FROM PLUGGED STATIONARY KNIVES AND

CLEANED FLOOR FROM DEBRIS.

ADDITIONAL DESCRIPTION:

CLEAN ALL DEBRIS FROM PLUGGED STATIONARY KNIVES

10110000

LABOR	89.50
SEGMENT TOTAL==>	89.50

SEGMENT#14 S 190 NA 10/16/25 10/22/25

#26 CHOPPER KNIVES

CORRECTION:

FLIPPED ALL CHOPPER KNIVES AND INSTALLED NEW LOCK NUTS.

REPLACED 6 BENT KNIVES. CLEANED WORK AREA.

ADDITIONAL DESCRIPTION:

FLIP ALL CHOPPER KNIVES AND INSTALL NEW LOCK NUTS

2380060	NUT SECURI	54	2.11	113.94
	NUT SECURING			
5538602	FREE-SWING	6	40.69	244.14
	FREE-SWINGING KNIFE			

10110000

PARTS	358.08
LABOR	537.00
SEGMENT TOTAL==>	895.08

CONTINUED ON PAGE 08

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EDGE ENVIROMENTAL/GRINDSTONE GRAIN
COMBINE #1

Invoice To: EDGE ENVIRONMENTAL FARM/GRINDSTONE GRAIN CORP
BOX 356
UNITY SK S0K 4L0

Branch N. BATTLEFORD		
Date 10/29/25	Time 09:25:27 (O)	Page 08
Account No EDGE001	Phone No	Inv No W03380
Ship Via		Purchase Order
Tax ID No		887067502
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
001046	LEXION 8700	339	C8910940		
	8700	252			

SEGMENT#15 S 190 NA 10/16/25 10/16/25

#30 CLEAN GRAIN ELEVATOR CHAIN

CORRECTION:

CLEAN GRAIN ELEVATOR CHAIN OUT OF ADJUSTMENT. REMOVED
SHIELD BEHIND BATTERY BOX, LOOSENED TENSION AND REMOVED 3RD
STAGE SIEVE DRIVE BELT. LOOSENED ELEVATOR CHAIN TENSION AND
REMOVED 1 HALF LINK AND INSTALLED NEW LOCK NUT. TENSIONED
CLEAN GRAIN ELEVATOR CHAIN AND INSTALLED MISSING SPRING
CLIP.

ADDITIONAL DESCRIPTION:

INSTALL 1/2 LINK IN CLEAN GRAIN ELEVATOR CHAIN....OUT OF
ADJUSTMENT

6656660	SPRING CLI	1	1.31	1.31
	SPRING CLIP			
	PARTS			1.31
	LABOR			214.80
10110000	SEGMENT TOTAL==>			216.11

SEGMENT#16 S 190 NA 10/16/25 10/21/25

#32 HOPPER SENSOR HARNESS

CORRECTION:

TIED UP UNSECURED HOPPER LEVEL SENSOR HARNESS

ADDITIONAL DESCRIPTION:

TIE UP UNSECURED HOPPER LEVEL SENSOR HARNESS

	LABOR			35.80
10110000	SEGMENT TOTAL==>			35.80

SEGMENT#17 S 190 NA 10/16/25 10/28/25

#35 FINAL RUN UP

CONTINUED ON PAGE 09

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EDGE ENVIROMENTAL/GRINDSTONE GRAIN
COMBINE #1

Invoice To: EDGE ENVIRONMENTAL FARM/GRINDSTONE GRAIN CORP
BOX 356
UNITY SK S0K 4L0

Branch N. BATTLEFORD		
Date 10/29/25	Time 09:25:27 (O)	Page 09
Account No EDGE001	Phone No	Inv No W03380
Ship Via		Purchase Order
Tax ID No		887067502
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
001046	LEXION 8700	339	C8910940		
	8700	252			

CORRECTION:

PERFORMED FINAL RUN UP AFTER ALL REPAIRS ARE COMPLETED.
TEACHED AND LEARNED MACHINE. NO CODES. PARKED MACHINE IN
YARD.

ADDITIONAL DESCRIPTION:

PERFORM FINAL RUN UP AFTER ALL REPAIRS ARE COMPLETED

	LABOR	358.00
10110000	SEGMENT TOTAL==>	358.00

***** WORK ORDER TOTALS *****

PARTS	3231.83
LABOR	6082.55
SHOP SUPPLIES	300.00
DISCOUNT	258.54-
SUB TOTAL==>	9355.84
GST 5%	480.75
CUSTOMER TOTAL	9836.59

X

Authorized By