



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # P264728

Station #: 71852

Station Name: 5K Truck and Trailer Repair Ltd.

Technician #: 90976

Technician Name: Jonathan N. Sison

Signing Officer #: 91036

Signing Officer Name: Jaspal Singh

Customer Details:

Name: PBTL Transport Inc.

Address: 338 Mill St., RM of Sherwood, Saskatchewan, S4K 0A8

Inspection Completed Date: 10May2025

Inspection Expiry Date: 30Nov2025

Vehicle Details:

VIN: 1FUJHHDR7NLMW8679

Odometer Reading: 1289595 km

Year: 2022

Vehicle Make/Model: FREIGHTLINER/HEAVY VEHICLE

Plate: 496 MGB

Jurisdiction: Saskatchewan

Unit: PB679

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.