



109 Keystone Industrial Park
Dunmore, PA 18512
Phone: (570) 347-5671
Fax: (570) 963-9133

REMIT TO:
KENWORTH OF PENNSYLVANIA
4909 Louise Drive Suite 105
Mechanicsburg, PA 17055

Sold To:

Ship To:

PARTS INVOICE NUMBER

DIAZ STONE & PALLET "Y"
7686 sr 167
KINGSLEY PA 18826

DIAZ STONE & PALLET "Y"
7686 sr 167
KINGSLEY PA 18826

DBA151256

Date: 07-27-26

Tax ID: 8912057

Authorization #:

Page: 1 of 1

Customer Acct Number		Phone Number	Salesman		Ship Via			Customer Purchase Order		
151670		570 289-8760	RD*ROS/bz		YELLOW ROUTE			488		
Loc	Part #	Description			Ord	Ship	B/O	List	Unit Price	Extension
18K6	2298833PEX	ENGINE CONTROL MODULE, MX			1	1			2800.11	2800.11
18K6	2298833PEX#	CORE			1	1			371.25	371.25

STOCK PARTS MUST BE RETURNED WITHIN 10 DAYS
OR NO RETURNS WILL BE ACCEPTED.
ALL RETURNS SUBJECT TO A 10% MINIMUM HANDLING CHARGE.
PARTS ORDERED ON AN EMERGENCY BASIS ARE NOT RETURNABLE.
ELECTRICAL PARTS ARE NOT RETURNABLE.
ORIGINAL INVOICE MUST ACCOMPANY ALL RETURNS.
09:00AM PARTS NTX

CO 430488 Stone
PO# 430488 430488
Approved By _____
Entered By _____

Signature: _____



How Did We Do?

Print Name: _____ Date: _____

2200000 CUSTOMER	Sub Total	3171.36
	Freight	0.00
	Sales Tax	0.00
	Please Pay	3171.36

Terms: Net 10th E.O.M. Our finance charge is computed by a single periodic rate of 1.5% per month, which is an annual percentage rate of 18%. Stock parts must be returned within 10 days or no returns will be accepted. All returns subject to a 10% minimum handling charge. Parts ordered on an emergency basis are not returnable. Original invoice must accompany all returns.

MOTOR TRUCK EQUIPMENT COMPANY - SINCE 1933
CARLISLE • NEW STANTON • DUNMORE • CLINTONVILLE • SHARTLESVILLE • YORK • LANCASTER • PITTSBURGH



Vehicle Number:	488
Department:	STONE
Technician Name:	Brown - Donnie
Date:	7-28-20
Mileage / Engine Hours:	254562

Service:

Service - Changed engine oil + Filter - Changed Fuel
Filters - Greased - Checked tires + lights -

Repaired wiring to RR marker light

Replaced 4/8 steer tire with good used.

Replaced CRI drive tire with good used.

Installed new engine ECM & Programmer.

Cleaned interior - Removed GPS & Plate

Washed unit - Parked in Mill.