

COASTLINE Equipment

1930 E. Lockwood St.
Oxnard, CA 93036
Phone: (805) 485-2108
Fax: (805) 485-7963
www.coastlineequipment.com

Oxnard, CA (805) 485-2108
Lake Forest, CA (714) 266-6600
Sylmar, CA (818) 890-3353
Bakersfield, CA (805) 399-3600
Long Beach, CA (562) 272-7400
Santa Maria, CA (805) 922-8329
Meridian, ID (208) 888-3337
Jerome, ID (208) 324-2900
McCall, ID (208) 634-3903
N. Las Vegas, NV (702) 399-2700
Elko, NV (775) 777-7070
gas, NV (702) 253-1789



JOHN DEERE

Remit Payment To:
P.O. Box 22732 Long Beach, CA 90801-5732
Pay Online At: www.coastlineequipment.com/customer-portal

Deliver To: **Estimate Expires: 11/13/2025**

SERVICE ESTIMATE

Invoice To Account No: Bus Phone: Prv Phone:	Make/Model: 2020 JOHN DEERE 844L	Meter: 17450	Serial Number: 1DW844LXKLF707440	EQ Id: LF707440	Fleet No: 10/14/2025 Location: 1 Work Order Number: 221858 Payment Type: Account Page: 1 of 3
--	-------------------------------------	-----------------	-------------------------------------	--------------------	--

Service Reminders:

/TRAVEL Misc

COMPLAINT:

FIELD TRAVEL/MILEAGE CHARGE

CAUSE:

CORRECTION:

OF MILES TRAVELED:

FIVE TRIPS NEEDED TO COMPLETE REPAIRS

Labor: \$1,650.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,650.00
-------------------	---------------	--------------	--------------	-----------------------

OX/GEN1 Misc

COMPLAINT:

DIAGNOSE TRANSMISSION

CUSTOMER STATES THAT TRANSMISSION IS NOT SHIFTING CORRECTLY.
TRANSMISSION IS NOT CALIBRATING

DTAC CASE# 3507561

CAUSE:

RAN PRESSURE TESTS ON TRANSMISSION AND TORQUE CONVERTER. TOOK TRANSMISSION OIL SAMPLE. REMOVE MACHINE CAB TO ACCESS TRANSMISSION CONTROL VALVE. REMOVE VALVE ASSEMBLY TO INSPECT INTERNAL PARTS FOR DAMAGE OR DEBRIS.

CORRECTION:

Labor: \$2,640.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,640.00
-------------------	---------------	--------------	--------------	-----------------------

OX/GEN2 Misc

COASTLINE Equipment

1930 E. Lockwood St.
Oxnard, CA 93036
Phone: (805) 485-2106
Fax: (805) 485-7963
www.coastlineequipment.com

Oxnard, CA (805) 485-2106
Lake Forest, CA (714) 266-6500
Sylmar, CA (818) 890-3353
Bakersfield, CA (861) 399-3800
Long Beach, CA (562) 272-7400
Santa Maria, CA (805) 922-8329
Meridian, ID (208) 888-3337
Jerome, ID (208) 324-2900
McCall, ID (208) 834-3903
N. Las Vegas, NV (702) 399-2700
Elko, NV (775) 777-7070
gas, NV (702) 253-1789



Remit Payment To:
P.O. Box 22732 Long Beach, CA 90801-5732
Pay Online At: www.coastlineequipment.com/customer-portal

Deliver To: **Estimate Expires: 11/13/2025**

SERVICE ESTIMATE

Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 10/14/2025 Location: 1 Work Order Number: 221856 Payment Type: Account Page: 2 of 3
Make/Model: 2020 JOHN DEERE 844L Meter: 17450 Serial Number: 1DW844LXKLF707440 EQ Id: LF707440 Fleet No:	

Service Reminders:

COMPLAINT:

REMOVE AND REPLACE TRANSMISSION

USING LISTED PARTS AS NEEDED.
REMOVE AND REPLACE TRANSMISSION OIL COOLER.

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
38H5174	Adapter Fitting	1.00	18.16	\$18.16	N
51M7039	O-RING	4.00	1.93	\$7.72	N
51M7048	O-RING	4.00	3.82	\$15.28	N
51M7049	O-RING	1.00	4.64	\$4.64	N
AT464536	Control Valve	1.00	459.40	\$459.40	N
AT468647	OIL FILTER	2.00	58.86	\$117.72	N
AT472148	Transmission	1.00	64,567.75	\$64,567.75	N
AT472148-CR	CORE for:Transmission	-1.00	3,000.00	-\$3,000.00	N
AT505635	Oil Cooler	1.00	2,790.30	\$2,790.30	N
R29936	O-RING (#16 ORB)	4.00	3.62	\$14.48	N
T107883	O-RING	3.00	4.62	\$13.86	N
T174529	O-Ring	3.00	13.30	\$39.90	N
T76938	O-RING (#16 ORF)	9.00	2.29	\$20.61	N
T77814	O-RING (#4 ORF)	6.00	1.33	\$7.98	N
T77858	O-RING (#12 ORF)	1.00	1.67	\$1.67	N
T78612	O-RING (#20 ORF)	6.00	0.12	\$0.72	N
T78784	O-RING (#24 ORF)	1.00	3.00	\$3.00	N
TY22062	HY-GARD 2.5 GAL	5.00	62.61	\$313.05	N
U12331	O-RING	3.00	5.44	\$16.32	N
Labor: \$13,200.00		Parts: \$65,412.56	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$78,612.56

OX/GEN3 Misc

COMPLAINT: