



Vehicle Standards and Inspection

A238781

### Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A238781

Station #: 70904	Station Name: [REDACTED]
Technician #: [REDACTED]	Technician Name: [REDACTED]
Signing Officer #: [REDACTED]	Signing Officer Name: [REDACTED]

Customer Details:	
Name: [REDACTED]	Address: [REDACTED]

Inspection Completed Date: 19Aug2025	Inspection Expiry Date: 31Aug2026
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 5V8VA5328FM506249	Hubometer Reading:
Year: 2015	Vehicle Make/Model: VANGUARD TRAILER/
Plate: 061JVA	Jurisdiction: Saskatchewan
Unit: 1206233	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station # [REDACTED]	Station Name: [REDACTED]
Technician # [REDACTED]	Technician Name: [REDACTED]
Signing Officer #: [REDACTED]	Signing Officer Name: [REDACTED]

Customer Details:

Name: [REDACTED] Address: [REDACTED]

Vehicle Details:

VIN: 5V8VA5328FM506249 Hubometer Reading:

Year: 2015 Vehicle Make/Model: VANGUARD TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axes (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

**Brake/Tire Measurements**

**Axle 1-Pass**

Wheel1 : Tire Tread Depth: 8/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 8/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 43 degrees • Brake Stroke: 1 in

Wheel3-On : Tire Tread Depth: 8/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 70 degrees • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 8/32 in

Brake(1): No Brake

N/A

**Axle 2-Pass**

Wheel1 : Tire Tread Depth: 8/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 8/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 43 degrees • Brake Stroke: 1 in

Wheel3-On : Tire Tread Depth: 8/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 43 degrees • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 8/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A238781

Inspection Completed Date: 19Aug2025