



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: [REDACTED]	Station Name: [REDACTED]
Technician #: [REDACTED]	Technician Name: [REDACTED]
Signing Officer #: [REDACTED]	Signing Officer Name: [REDACTED]

Customer Details:	
Name: [REDACTED]	Address: [REDACTED]

Vehicle Details:	
VIN: 2DEALBE32N4043032	Hubometer Reading:
Year: 2022	Vehicle Make/Model: DOEPKER TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	1ST AXLE (BOTH SIDES), 2ND AXLE (P/S), 3RD AXLE (BOTH SIDES) - BRAKES ARE SEPARATING, 2ND AXLE BRAKE LINES RUBBING MUD FLAP BAR
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 7 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 80.0 degrees • Brake Stroke: 1.5 in

Wheel2 : Tire Tread Depth: 7 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 7 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 7 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 100.0 degrees • Brake Stroke: 1.5 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 4 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 90.0 degrees • Brake Stroke: 1.5 in

Wheel2 : Tire Tread Depth: 8 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 10 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 11 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 103.0 degrees • Brake Stroke: 1.5 in

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 10 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 90.0 degrees • Brake Stroke: 1.5 in

Wheel2 : Tire Tread Depth: 4 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 13 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 13 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 85.0 degrees • Brake Stroke: 1.5 in

PASS - vehicle passes inspection	Decal # A246734	Inspection Completed Date: 22Sep2025
----------------------------------	-----------------	--------------------------------------