



Vehicle Standards and Inspection

Heavy Truck Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A335732

Station #: [REDACTED]	Station Name: [REDACTED]
Technician #: [REDACTED]	Technician Name: [REDACTED]
Signing Officer #: [REDACTED]	Signing Officer Name: [REDACTED]

Customer Details:	
Name: [REDACTED]	Address: [REDACTED]

Inspection Completed Date: 21Apr2026	Inspection Expiry Date: 30Apr2027
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 3ALHGND6XFDGE2738	Odometer Reading: 498856 km
Year: 2015	Vehicle Make/Model: FREIGHTLINER/HEAVY VEHICLE
Plate: 904 NHD	Jurisdiction: Saskatchewan
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Heavy Truck Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: [REDACTED]	Station Name: [REDACTED]
Technician #: [REDACTED]	Technician Name: [REDACTED]
Signing Officer #: [REDACTED]	Signing Officer: [REDACTED]

Customer Details:

Name: [REDACTED] Address: [REDACTED]

Vehicle Details:

VIN: 3ALHGND6XFDGE2738 Odometer Reading: 498856 km

Year: 2015 Vehicle Make/Model: FREIGHTLINER HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)		
x				Seats/Seat Belts/SRS (8)		
x				Steering Column/Components (4)		
x				Auxiliary Controls/Equip (5)		
x				Speedometer/Odometer (5)		
x				Steering Lash/Travel (5)		
x				Accelerator Pedal/Actuator (1)		
x				Engine Shut Down Control (1)		
x				Engine Start Feature (1)		
x				Body Interior/Fixtures (8)		

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 6/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 45 degrees • Brake Stroke: 1 in

Wheel2-On : Tire Tread Depth: 13/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 35 degrees • Brake Stroke: 1 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 19/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 19/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 60 degrees • Brake Stroke: 1 1/8 in

Wheel3-On : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 100 degrees • Brake Stroke: 1 1/8 in

Wheel4 : Tire Tread Depth: 20/32 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 14/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 12/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 60 degrees • Brake Stroke: 1 1/8 in

Wheel3-On : Tire Tread Depth: 14/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/16 in • Cam Rotation: 110 degrees • Brake Stroke: 1 1/8 in

Wheel4 : Tire Tread Depth: 17/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection	Decal # A335732	Inspection Completed Date: 21Apr2026
----------------------------------	-----------------	--------------------------------------