



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A245317

Station #:	Station Name:
Technician #:	Technician Name:
Signing Officer #:	Signing Officer Name:

Customer Details:	
Name:	Address:

Inspection Completed Date: 04Sep2025	Inspection Expiry Date: 30Sep2026
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 89017CL25DET60097	Hubometer Reading:
Year: 1989	Vehicle Make/Model: TRAILER/TRAILER
Plate:	Jurisdiction: Saskatchewan
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: [REDACTED]	Station Name: [REDACTED]
Technician #: [REDACTED]	Technician Name: [REDACTED]
Signing Officer #: [REDACTED]	Signing Officer Name: [REDACTED]

Customer Details:	
Name: [REDACTED]	Address: [REDACTED]

Vehicle Details:	
VIN: 89017CL25DET60097	Hubometer Reading:
Year: 1989	Vehicle Make/Model: TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
		x		Cargo Bodies/Vessels (8)	
		x		Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
		x		Frame/Crossmembers/Mounts (8)	
			x	Suspension/Axles (2)	ALL TORQUE ARMS WHEATHER CRACKNG, NO MOVEMENT AT THIS TIME MONITOR
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 40.0 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 7 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 60.0 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 8 mm

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 16 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 40.0 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 10 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 75.0 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 12 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 50.0 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 8 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 105.0 degrees • Brake Stroke: 1.5 in

- Wheel4 : Tire Tread Depth: 14 mm
Brake(1): No Brake
N/A

PASS - vehicle passes inspection

Decal # A245317

Inspection Completed Date: 04Sep2025