



Vehicle Standards and Inspection

### Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A302277

Station #: 71222

Station Name: Mackie Equipment Ltd

Technician #: 88984

Technician Name: Kristoffer Mackie

Signing Officer #: 87286

Signing Officer Name: Cheryl Mackie

**Customer Details:**

Name:

Address:

Inspection Completed Date: 20May2026

Inspection Expiry Date: 31May2027

**Vehicle Details:**

VIN: 2DEGBSE35K2037441

Hubometer Reading:

Year: 2019

Vehicle Make/Model: DOEPKER TRAILER/TRAILER

Plate:

Jurisdiction: Saskatchewan

Unit: UNIT 02A

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

### Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71222  
Technician #: 88984  
Signing Officer #: 87286

Station Name: Mackie Equipment Ltd  
Technician Name: Kristoffer Mackie  
Signing Officer Name: Cheryl Mackie

**Customer Details:**

Name

Address:

**Vehicle Details:**

VIN: 2DEGBSE35K2037441

Hubometer Reading:

Year: 2019

Vehicle Make/Model: DOEPKER TRAILER TRAILER

**Inspection Details:**

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
		x		Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
		x		Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

### Brake/Tire Measurements

#### Axle 1-Pass

Wheel1 : Tire Tread Depth: 10/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 10/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 17.0 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 6/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 18.0 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 6/32 in

Brake(1): No Brake

N/A

#### Axle 2-Pass

Wheel1 : Tire Tread Depth: 8/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 7/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 16.0 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 11/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 16.0 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 11/32 in

Brake(1): No Brake

N/A

#### Axle 3-Pass

Wheel1 : Tire Tread Depth: 8/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 9/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 17.0 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 8/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 16.0 degrees • Brake Stroke: 1.5 in

• Wheel4 : Tire Tread Depth: 9/32 in  
Brake(1): No Brake  
N/A

PASS - vehicle passes inspection

Decal # A302277

Inspection Completed Date: 20May2026

KOS-1 or KOS-2?