



Vehicle Standards and Inspection

### Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A302278

Station #: [REDACTED]	Station Name: [REDACTED]
Technician #: [REDACTED]	Technician Name: [REDACTED]
Signing Officer #: [REDACTED]	Signing Officer Name: [REDACTED]

Customer Details:	
Name: [REDACTED]	Address: [REDACTED]

Inspection Completed Date: 20May2026	Inspection Expiry Date: 31May2027
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 2DEGBSA20K2037442	Hubometer Reading:
Year: 2019	Vehicle Make/Model: DOEPKER TRAILER/TRAILER
Plate: 476MMV	Jurisdiction: Saskatchewan
Unit: UNIT 02B	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

# Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station # [REDACTED] Station Name [REDACTED]  
 Technician # [REDACTED] Technician Name: [REDACTED]  
 Signing Officer #: [REDACTED] Signing Officer Name: [REDACTED]

Customer Details:  
 Name: [REDACTED] Address: [REDACTED]

Vehicle Details:  
 VIN: 2DEGBSA20K2037442 Hubometer Reading:  
 Year: 2019 Vehicle Make/Model: DOEPKER TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
		x		Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

**Axle 1-Pass**

Wheel1 : Tire Tread Depth: 10/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 11/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 76.0 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 10/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 75.0 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 10/32 in

Brake(1): No Brake

N/A

**Axle 2-Pass**

Wheel1 : Tire Tread Depth: 9/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 12/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 76.0 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 10/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 77.0 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 10/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A302278

Inspection Completed Date: 20May2026