SGI

Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

A340034

Station #: 71968
Station Name: Bamrah Truck Repair Inc
Technician #: 91870
Technician Name: Surinder Singh
Signing Officer #: 91869
Signing Officer Name: Sukhpal Bumrah

Customer Details:
Name: [redacted]
Address: [redacted]

Inspection Completed Date: 22May2026
Inspection Expiry Date: 31May2027

Vehicle Details:
VIN: 1UYVS253XR7126306
Hubometer Reading:
Year: 2024
Vehicle Make/Model: UTILITY TRAILER/UTILITY TRAILER
Plate: [redacted]
Jurisdiction: Saskatchewan
Unit: 88114

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

SGIII

Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71968

Station Name: Bamrah Truck Repair Inc

Technician #: 91870

Technician Name: Surinder Singh

Signing Officer #: 91869

Signing Officer Name: Sukhpal Bumrah

Customer Details:

Name: [redacted]

Address: [redacted]

Vehicle Details:

VIN: 1UYVS253XR7126306

Hubometer Reading:

Year: 2024

Vehicle Make/Model: UTILITY TRAILER UTILITY TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 14/32 in
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 14/32 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 16 mm • Cam Rotation: 45 degrees • Brake Stroke: 1.5 in
Wheel3-On : Tire Tread Depth: 12/32 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 19 mm • Cam Rotation: 25 degrees • Brake Stroke: 1.5 in
Wheel4 : Tire Tread Depth: 12/32 in
Brake(1): No Brake
N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 11/32 in
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 8/32 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 20 mm • Cam Rotation: 20 degrees • Brake Stroke: 1.5 in
Wheel3-On : Tire Tread Depth: 6/32 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 20 mm • Cam Rotation: 20 degrees • Brake Stroke: 1.5 in
Wheel4 : Tire Tread Depth: 6/32 in
Brake(1): No Brake
N/A

PASS - vehicle passes inspection	Decal # A340034	Inspection Completed Date: 22May2026