A281331

Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A281331

Station #: 71393
Technician #: 87614
Signing Officer #: 87615

Station Name: Jas Truck & Trailer Repair Inc.
Technician Name: Jaspal Uppal
Signing Officer Name: Iqbal Uppal

Customer Details:

Name: [redacted] LOAD TRUCKING LTD

Address: [redacted] GREEN ALDERWAY, REGINA, Saskatchewan, S4V 3M7

Inspection Completed Date: 19Feb2026

Inspection Expiry Date: 28Feb2027

Vehicle Details:

VIN: 1UYVS2536P3893705

Year: 2023

Plate: [redacted]

Unit: [redacted]

Hubometer Reading:

Vehicle Make/Model: UTILITY TRAILER/UTILITY TRAILER

Jurisdiction: Saskatchewan

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

Vehicle Standards and In. ction

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71393
Technician #: 87614
Signing Officer #: 87615

Station Name: Jas Truck & Trailer Repair Inc.
Technician Name: Jaspal Uppal
Signing Officer Name: Iqbal Uppal

Customer Details:

Name: [redacted]

Address: [redacted]

Vehicle Details:

VIN: 1UYVS2536P3893705

Year: 2023

Hubometer Reading:

Vehicle Make/Model: UTILITY TRAILER UTILITY TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Control Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reactive Markings (6)	
x				Trailer Hitch (10)	
		x		Attached Equipment (8)	REPLACE DOCK BUMPER
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (3)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	ADJUST BRAKES
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
		x		Tires/Wheels (9)	REPLACE TIRES
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (If equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 10/10 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 55.0 degrees • Brake Stroke: 1 in
Wheel2-On : Tire Tread Depth: 6/6 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 56.0 degrees • Brake Stroke: 1 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 8/6 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 54.0 degrees • Brake Stroke: 1 in
Wheel2-On : Tire Tread Depth: 6/6 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 55.0 degrees • Brake Stroke: 1 in

PASS - vehicle passes inspection	Decal # A281331	Inspection Completed Date: 19Feb2026