

04124288

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba
C109854

Date Inspection Started
31 08 26
DAY MO. YR.

Date Inspection Completed
02 09 26
DAY MO. YR.

Inspection Expiry Date
30 09 27
DAY MO. YR.

Station Number
A5434

Station Name
TOTAL WORKS TRUCK & EQUIP

City
[redacted]

Province
[redacted]

Postal Code
[redacted]

Phone
[redacted]

Mechanic Number
M10433

Mechanic Signature
[redacted]

Station Phone Number
204-728-3821

Vehicle Owner
[redacted]

Address
[redacted]

City
[redacted]

Province
[redacted]

Postal Code
[redacted]

Phone
[redacted]

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number
[redacted]

Prov.
MB

NSC #
[redacted]

Odometer Reading
245450

Odom. Type
☒ km ☐ mi

Vehicle Identification Number
1FD0X5HT3K1E177157

Make
FORD

Model
F350

Year
19

Unit #
03157

☐ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck ☐ KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X	X	Section 1 - Power Train: Defects (if any) 1,4(CA) AXLE #1 HUB LOCKS ARE SEIZED
X		1,4(CA) AXLE #1 LH+RH U-JOINTS ARE BLEEDING RUST & ARE LOOSE
		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H 3A
		Defects (if any) Circle Brake Type
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X	X	Section 8 - Body: Defects (if any) 8,13(B) WINDSHIELD IS CRACKED
X	X	Section 9 - Tire & Wheel: Defects (if any) 9,3(B) AXLE #2 RH OUTER TIRE IS CUT
		9,3(B) AXLE #2 RH INNER TIRE HAS A BULGE
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	17	17			100	100		
2	16	16	16	16	100	100	100	100
3								
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____

Signature _____